



Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio
Parts & Labour	Miscellaneous	Summary	Claim Amount \$8,445.60

Labour

\$1,570.00

\$1,570.00

Spare Parts

\$5,935.60

\$5,935.60

Miscellaneous

\$940.00

\$940.00

Submit for Review



Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary
- Add
- Approve
- Deny



1

FINAL LUMP SUM

Reviewing

6750





Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio
Parts & Labour	Miscellaneous	Summary	Claim Amount \$6,750.00

Miscellaneous

\$6,750.00

\$6,750.00

Submit for Review

Serviceable

0

10

0

Reviewing



7

1

BUMPER RETAINER LH REAR

Damaged

44.99

10

BUMPER BEAM REAR

Bent

777.52

10

699.77

Reviewing



10

1

BUMPER BEAM BRACKET LH REAR

Repair

-

12

1

BOOT REAR

Repair

0

10

0

Reviewing



13

1

BOOT FINISHER



15

1

BOOT REFLECTOR LAMP LH

Serviceable

0

10

0

Reviewing



16

1

Reviewing



18

1

BOOT BADGE

Serviceable

0

10

0

Reviewing



10

0

Reviewing



21

1

BOOT INNER TRIM

Serviceable

0

10

0

Reviewing



Repair

0

10

0

Reviewing



24

1

BOOT LOCK CATCH

Repair

0

10

0

Serviceable

0

10

0

Reviewing



27

1

FENDER PANEL INNER TRIM REAR LH

Serviceable

0

10

WHEELARCH REAR LH

Serviceable

0

10

0

Reviewing



30

1

FENDER PANEL REAR RH

Repair

-

32

1

TAILLAMP PANEL LH

Repair

0

10

0

Reviewing



33

1

OUTER PANEL REAR (END PANEL)

AAA

Labour



1

PUTTY AND SPRAY PAINTING OF THE
AFFECTED PORTION.

660

0

0

Reviewing



2

PANEL BEATING, KNOCKING AND
STRAIGHTENING THE NECESSARY PORTION,
REMOVE AND RENEWAL OF PARTS, ADJUST
AND REALIGN THE SAME.

600

0

Reviewing



5

TO REINSTALL REAR BUMPER PARKING
SENSOR.

60

0

0

Reviewing



6

TO TRANSFER OF REAR END PANEL FITTINGS,
ATTACHMENT AND PERFORM WATER SEEPAGE
TEST. }

100

Reviewing



9

TO TRANSFER OF REAR WINDSCREEN
FITTINGS AND CONDUCT WATER SEEPAGE
TEST.

120

0

0

Reviewing



10

TO CHECK STEERING GEOMETRY AND
COMPUTER WHEEL ALIGNMENT.

0

Home

My Claims



Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

1

SET PARKING AID

Reviewing

700

SHORTED



2

SET REAR BUMPER CLIP

Reviewing

66

NECESSARY





6

SET BUMPER BRACKET SIDE CLIP LH RR

Reviewing

0

NOT NECESSARY



7

SET BUMPER RETAINER CLIP LH RR

Reviewing

0

NOT NECESSARY



8

-

11

BOOT STICKER "TRANS-CAB"

Reviewing

0

NOT NECESSARY



12

BOOT STICKER "6555-3333"

Reviewing

0

NOT NECESSARY



13

BOOT INNER TRIM CLIP

Reviewing

Reviewing

5

NECESSARY



17

REAR WINDSCREEN SEALANT

Reviewing

40

NECESSARY



18

WINDSCREEN MOULDING

Reviewing

30

NECESSARY

SERVICEABLE

