

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17018815/WVBS2-1
Date: 05/01/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A28695601MKC
Claimant Vehicle No :	GZ2179K	Insured Vehicle No :	YN1975K
Date of Loss:	28/09/2017	Nature of Claim:	TP
		Claim No:	531386

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GZ2179K		
Make & Model:	MITSUBISHI L300 HR M, 2.5 D (M)	Engine No:	4D56LA6130
Reg. Date:	20/01/2006 (Man. Year: 2005)	Chassis No:	JMAJNP15V6A000744
Colour:	White	Odometer:	616274 km
Engine Capacity:	2477 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R14C	Rear Tyre Size:	195 R14LT
Front Left Side:	CST 4 mm	Rear Left Side:	Brightway 4 mm
Front Right Side:	CST 4 mm	Rear Right Side:	Brightway 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,290.00	1,128.60	1,161.40	50.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	1,380.00	1,120.00	44.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,790.00	2,508.60	2,281.40	47.63
Approved Total (Overridden) (S\$)		2,000.00		
Nett Amount (S\$)	4,790.00	2,000.00	2,790.00	58.25

INSPECTION

Date of Assignment:	02/10/2017		
Date Inspected:	06/10/2017	Inspected At:	Michelin Engineering Pte Ltd (HQ) 56 Loyang Way., #06-07 Loyang Enterprise Building, Singapore 508775
Estimated Period of Repair:	3.0 days		

Adjuster: Teo Cheng Ming Wilson

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 05 Jan 2018)
Parts:	N/A MITSUBISHI L300 HR M 2.5 D (M) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	LKK Auto Consultants Pte Ltd/GZ2179K/05/01/2018 14:45
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PANEL	Dented	715.00 F	*715.00 FN
2	1		*FRONT PANEL LOGO	Necessary	48.00 F	*48.00 FN
3	1		*FRONT PANEL PROTECTOR	Damaged	85.00 F	*85.00 FN
4	1		*FRONT HEADLAMP	Not Necessary	165.00 F	*- FN
5	2		*FRONT HEADLAMP RIM C/W SIDE LAMPS	Scratched	210.00 F	*210.00 FN
6	1		*FRONT BUMPER (Dented/Scratched)	Not Consistent with the impact	641.00 F	-
7	1		*FRONT BUMPER REINFORCEMENT (Repair)	Not Consistent with the impact	185.00 F	*- FN
8	1		*FRONT WINDSCREEN RUBBER	Necessary	196.00 F	*196.00 FN
9	1		*FRONT NUMBER PLATE (Dented)	Not Consistent with the impact	45.00 FS	-

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	2,290.00	1,254.00
- Nett Item Discount on N Items 0.00/10.00% (\$\$)	0.00	125.40
Total Parts (\$\$)	2,290.00	1,128.60

LKK Auto Consultants Pte Ltd/GZ2179K/05/01/2018 14:45. Not valid without Reference section.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT DAMAGE PARTS, TEST FOR PROPER FUNCTIONING AND FOCUS HEADLAMPS.	New	50.00	30.00
2	TO REMOVE AND REFIT FRONT WINDSCREEN GLASS.	New	150.00	60.00
3	TO REMOVE AND REFIT DASHBOARD, METERS INSTRUMENT, DISCONNECT WIRINGS, DUCTINGS, CONNECTORS TO FACILITATE THE REPAIRS.	New	400.00	200.00
4	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TP THE ORIGINAL POSITION USING POWER TOOLS.	New	900.00	660.00
5	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.	New	900.00	400.00
6	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.	New	100.00	30.00
			Gross Labour Cost (\$\$)	2,500.00
				1,380.00

LKK Auto Consultants Pte Ltd/GZ2179K/05/01/2018 14:45. Not valid without Reference section.

< END OF ESTIMATES >