



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2006 TOYOTA VIOS 1.5E A (SGK5890Z)

Date of Loss

14 November 2017

Time of Loss

10.25

Loss Description

SGK5890Z(INS) HIT REAR OF GBG2069D(TP)

Comment

Workshop Details

Total Rebate Amount

16736

Nett Loss Amount

\$8,264.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

09/08/2018



Days of work completion *

260



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

SGK5890Z

Registration State

SINGAPORE

Mileage

125530

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2006

ASSESSMENT INFO...

2006

Purchase Date

dd/mm/yyyy



Registration Date *

18/08/2006



Age of Vehicle

11

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

RIDWAN BIN AWANG CHIK

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... TOYOTA

ASSESSMENT INFO... TOYOTA

CATEGORY Model

POLICY INFORMAT... VIOS 1.5E A

ASSESSMENT INFO... VIOS 1.5E A

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... MR053HY4204199956

CATEGORY Date of Birth

FNOL INFORMATI... 28 December 1979

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 38

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO...

CATEGORY Engine No

POLICY INFORMAT... 1NZX464897

ASSESSMENT INFO...

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO...

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO...

FNOL INFORMATI... 8

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI... 1 January 2010

POST SURVEY INF... 

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... 

CATEGORY Address

FNOL INFORMATI... BLK 439B SENGKNG WEST AVE, #02-315, 792439, Singapore

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI... Personal Correspondence

POST SURVEY INF...

CATEGORY Gender

FNOL INFORMATI... Male

POST SURVEY INF...

CATEGORY Marital status

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Identification #

FNOL INFORMATI... S7938136E



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

22/11/2017



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

175/65R14

Condition of Vehicle at time of survey

General condition

Fair



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair



Tyre Condition

Spare wheel

Rear Tyre Size

175/65R14

Front left side

FALKEN5mm

Front right side

FALKEN5mm

Rear left side

FALKEN5mm

Rear right side

FALKEN5mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Paint Material Ratio

80

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

Add

Approve

Deny

Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PART)
		1	1			BONNET			Bent	150				150	Review
		2	2			BONNET HINGE			Serviceable	0	0	0	0	0	Deny
		3	1			BONNET INSULATION			Serviceable	0	0	0	0	0	Deny
		4	10			BONNET INSULATION CLIPS			Necessary	1.5				15	Review
		5	2			BONNET RUBBER STOPPER			Necessary	15				30	Review
		6	10			BONNET RUBBER BEADING C/W CLIPS			Necessary	1.5				15	Review
		7	1			BONNET LOCK			Bent	18				18	Review
		8	1			FRONT GRILLE			Broken	75				75	Review
		9	10			FRONT GRILLE CLIPS			Necessary	1.5				15	Review
		10	1			FRONT BRACE PANEL			Bent	12				12	Review
		11	2			HEADLAMP			Cracked	80				160	Review
		12	1			FRONT BUMPER			Deformed	100				100	Review
		13	1			FRONT BUMPER CENTRE GRILLE			Serviceable	0	0	0	0	0	Deny

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PART)
		14	10			FRONT BUMPER CENTRE GRILLE CLIPS			Serviceable	0	0	0	0	0	Deny
		15	2			FRONT FOG LAMP COVER			Serviceable	0	0	0	0	0	Deny
		16	2			FRONT BUMPER SIDE RETAINER			Necessary	15				30	Review
		17	1			RHS FRONT FENDER SPLASH SHIELD			Serviceable	0	0	0	0	0	Deny
		18	10			RHS FRONT FENDER SPLASH SHIELD CLIPS			Serviceable	0	0	0	0	0	Deny
		19	1			LHS FRONT FENDER SPLASH SHIELD			Serviceable	0	0	0	0	0	Deny
		20	10			LHS FRONT FENDER SPLASH SHIELD CLIPS			Necessary	1.5				15	Review
		21	1			FRONT BUMPER REINFORCEMENT			Bent	115				115	Review
		22	2			FRONT CHASSIS MEMBER BRACKET			Serviceable	0	0	0	0	0	Deny
		23	2			HEADLAMP TOP PANEL			Serviceable	0	0	0	0	0	Deny
		24	2			RADIATOR SIDE VERTICAL PANEL			Serviceable	0	0	0	0	0	Deny
		25	1			FRONT UPPER PANEL			Repair	0	0	0	0	0	Deny
		26	1			A/C CONDENSER C/W RECEIVER DRYER			Serviceable	0	0	0	0	0	Deny

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PART)
		27	1			A/C HOSE			Serviceable	0	0	0	0	0	Deny
		28	1			A/C SUCTION HOSE			Serviceable	0	0	0	0	0	Deny
		29	1			A/C DISCHARGE HOSE			Serviceable	0	0	0	0	0	Deny
		30	1			RADIATOR			Bent	320				320	Review
		31	2			RADIATOR TOP MOUNTING			Necessary	15				30	Review
		32	1			RADIATOR ELECTRIC FAN C/W COWLING ASSY			Deformed	75				75	Review
		33	2			FRONT FENDER			Repair	0	0	0	0	0	Deny

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	RI
		1		LABOUR CHARGES TO REMOVE & INSTALL FRONT END ATTACHMENTS AND FITTINGS TO ENABLE REPAIRS; TO CUT & WELD FRONT PANNELLING AS LISTED ABOVE;]	700	0	0	Reviewing		1
		2		TO STRAIGHTEN & REPAIRS RHS & LHS FRONT FENDERS SUPPORT PANELS AND WHEELHOUSINGS; TO REMOVE & REPLACE DAMAGED PARTS AS LISTED ABOVE AND REPOSITION AND ALIGN SAME]	0	0	0	Reviewing		1
		3		TO SPRAY PAINTING ON BONNET (INNER & OUTER), RHS & LHS FRONT FENDERS, RHS & LHS FRONT WHEELHOUSINGS, FRONT UPPER PANEL, RHS & LHS HEADLAMPS PANELS.]	1000	0	0	Reviewing		1

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	RI
 	4		FRONT CHASSIS MEMBERS, FRONT BUMPER REINFORCEMENT, RHS & LHS RADIATOR VERTICAL PANELS AND FRONT BUMPER }	0	0	0	Reviewing		1
 	5		TO REMOVE & REPLACE A/C CONDENSER & A/C PARTS AS LISTED ABOVE; TO VACUUM & CHARGE UP GAS	100	0	0	Reviewing		1
 	6		TO REMOVE & REPLACE RADIATOR, ELECTRIC FAN ASSY AND REFIX HOSES; TO PRESSURIZE COOLING SYSTEM	60	0	0	Reviewing		1
 	7		TO CHECK ELECTRICAL WIRINGS & FOCUS HEADLIGHTS	0	0	0	Deny		1
 	8		TO JACK, STRAIGHTEN & ALIGN FRONT CHASSIS MEMBERS ACCORDING TO FACTORYS SPECIFICATION	100	0	0	Reviewing		1
 	9		TOWING CHARGES	60	0	0	Reviewing		1

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR
NO

NAME

ACTION

AMOUNT

COMMENT

REMOVE



1

DAYS OF
REPAIR : 7
DAYS

Reviewing



2

FRONT
REGISTRATION
PLATE C/W
HOLDER

Reviewing

60

CRACKED



3

PANEL SEALER

Deny

0

SERVICEABLE



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount \$3,255.00

Claim Amount \$3,255.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$2,020.00	\$2,020.00
Miscellaneous	\$60.00	\$60.00
Spare Parts	\$1,175.00	\$1,175.00

[Submit for Review](#)