

ASS. REC. BY:

REF: 033/MSG17022255/R1b574 Special Instruction: change

Surveyor: Ravi ASSIGNMENT (Office)

From (Person): Jasmine Lok of MSU1 Date/Time: 22.11.2017 9:20am

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: EZ 3663 X Insured: YP 3664 J

at Workshop m/s Yeo & Partner Tel: 6269 2776

of 74 Sungai Kadut St 1

Policy No: 28966510 MKC Claim No: 537502

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 18.11.2017  
(Client's Record)

CA / REV / REP. / REV 24 HRS 1wpi after 2pm H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 22.11.2017 10:36am Person Contacted: Sandy Vehicle IN / OUT

Date/Time	Action/Instruction ( X ) Estimate
	EZ 3663 X - 007 / A2613015611 / Chg 2 <span style="float: right;">2A: 220813</span>
	YP 3664 J - X
	Dismantle Part: 23.11.2017
	After repair: 27.11.2017
02.12.17 1:23pm	Email to Jasmine Lok thru me/men.

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: E2 3663X  
 at Workshop m/s Yto & Partners  
 of 74, Sungai Kadah St 1  
 Insured: MSIK / PRS  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rport: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

N/S	O/S

Veh No: E2 3663X Yr Regn: 2016 / MYN  
 Type:  M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Honda ODYSSEY ABS 24A.c 2356  
 Colour: BLACK A/C: Insured / Std / NI / NA  
 Sp. Reading: 031459 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: RC1108712  
 Gen. Cond: Good /  Fair / Poor / Burnt  
 Steering:  Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake:  Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: Nil /  R/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 215/55R17  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO /  YOKO or \_\_\_\_\_  
 Front Rear  
 R/Bal. 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. 18/1/17 D.O.I. 22/1/17 @ 5:30pm  
 Survey held at YTO & PARTNERS  
 Des. of Damages:  Frt / Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Est. repair range \$3,000 - \$4,000.
	 8/1/2018
	RECEIVED 09 JAN 2018

Date/Time, File Pass to?  : Preli. Report  
 1) 08-01-2018  : Final Report  
 Date/Time, File Return to?  
 2) \_\_\_\_\_  
 Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_ Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 Add Fee:  : Site Insp (\$ \_\_\_\_\_) ) \$ + RS. SI  
 : Interview (\$ \_\_\_\_\_) ) Photos  
 : Tech. Invs (\$ \_\_\_\_\_) ) Others  
 : Weekend (\$ \_\_\_\_\_) )  
 Report Format : PRS  
 Lump Sum / I.B.I: (\$ \_\_\_\_\_)  
 TOTAL

## Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin** ( ): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code	✓			
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

**Surveyor** ( ): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

**(2) System - (Views/Merimen)**

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

**(3) Workshop Estimate/Assignment Form**

N	ALL Parts condition				
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair				
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

**(4) System - (Views/Merimen)**

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: 

--	--

  
Case Handler
Date

\*C: Critical \*N: Non-Critical



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG17022255/R1b	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 22-11-2017	
		Code : MSG	
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>			
Insured Veh.	YP 3664J	Veh. Inspected	EZ 3663X
Policy No.	28966510MKC	Coverage (\$)	0.00
Claim No.	537502	Excess (\$)	0.00
Assign From	MERIMEN (JASMINE LOK)	Assign Date	22/11/2017
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	c.c		0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	Colour		
Odometer	-	Steering	
Brakes	Modification		
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	18/11/2017	Inspection Date	22/11/2017
Survey held at	YEO & PARTNER 74 SUNGEI KADUT ST 1 SINGAPORE 729374		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	20/11/2017 17:01
Date Of Accident	18/11/2017 16:40
Exact Location Of Accident	ENTRANCE TO THE CARPARK OF BLK336 WOODLAND AVE 1
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	EZ3663X
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ONG SU LING
NRIC No	S8229774Z
Email Address	CINDYONG8282@GMAIL.COM
Mobile Phone No	(LOCAL) +65-92373077
Alternative Phone No	OFFICE-92373077
<b>Vehicle Particulars</b>	
Manufacturer	HONDA
Model	ODYSSEY-2.4 ABSOLUTE (RC1) (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P1911305
Cover Note Number	

### Driver

Name of Driver	ONG SU LING
NRIC No	S8229774Z
Date Of Birth	10/09/1982
Occupation	INDOOR
Date Of Driving Pass	01/12/2003
Driving Experience	13 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-92373077
Fax Number	
Contact Number	OFFICE-92373077
EMail Address	CINDYONG8282@GMAIL.COM



## View Sent Message

This mail is associated with :

**\*EZ3663X (537502)**  
**[YP36643]**  
TP  
ONG SU LING  
Nov 18 2017 4:00PM  
[SIN CHIP HUP TENTAGE SERVICES]  
Yeo & Partner

Resend View Recipients Print Message Delete Message Forward

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on 02/12/2017 13:23 PM.  
**To** MSIG\_JLKK  
**Subject** Pre-repair Inspection

Dear Jasmine,

Refer to your assignment on 22.11.2017 at 9.20AM.

Please be informed that we have inspected the vehicle EZ 3663X on 22.11.2017 at 5.43PM.

At the time of inspection the repairer did not present their estimation to the damaged vehicle.

We will submit our report accordingly.

Best Regards,  
Catherine Chong | Admin  
LKK Auto Consultants Pte Ltd  
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

### DOCUMENTS SUMMARY

There are no documents.

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Nov 2017		22 Nov 2017 09:20 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

**CLAIM SUBFOLDER DETAILS** [Created by insurer]

Insured: **SIN CHIP HUP TENTAGE SERVICES, Co. Reg. No.: 53287405J**

Main Claimant: **ONG SU LING, ID: S8229774Z**

Vehicle Reg. No.:	<b>EZ3663X</b>	Date of Loss:	18/11/2017 16:00 - :59
Claim Type:	<b>TP / 537502</b>	Policy/Cover Note No.:	28966510MKC (Comprehensive) Coverage: 28/07/2017 - 27/07/2018
Vehicle Reg. No. (Insured):	<b>YP3664J</b>	Policy No. (Claimant):	
		Excess:	

Repairer: **Yeo & Partner (Sungei Kadut) 74 SUNGEEI KADUT STREET 1, 729374 Sungei Kadut - Tel:**

Handling Insurer: **MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]**

Adjuster: **LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Imm.Advice due 23/11/2017]**

---

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

There are no mail for this case.

---

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*EZ3663X (537502)**  
**[YP3664J]**  
**TP**  
**ONG SU LING**  
**Nov 18 2017 4:00PM**  
**[SIN CHIP HUP TENTAGE SERVICES]**  
**Yeo & Partner**

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>		<b>View</b> <a href="#">View in Browser</a> <input type="button" value="v"/>		
<b>Assessment Reports</b>		1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>		
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	<b>Thumbnail</b>	<b>Print</b>
1	04/12/17 14:03	<b>Accident Statement</b> <small>From: SC - Reg. No: YP3664J, Claimant: SIN CHIP HUP TENTAGE SERVICES</small>	<input checked="" type="checkbox"/> Load HTM	<input type="checkbox"/>
<b>Photos/Images</b>		3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	<b>Thumbnail</b>	<b>Print</b>
1	08/01/18 11:42	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
2	08/01/18 11:42	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
3	08/01/18 11:42	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
4	08/01/18 11:42	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
5	08/01/18 11:42	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
6	08/01/18 11:42	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
7	08/01/18 11:42	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
8	08/01/18 11:42	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
9	08/01/18 11:42	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
10	08/01/18 11:42	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
11	08/01/18 11:42	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
12	08/01/18 11:42	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
13	08/01/18 11:42	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
14	08/01/18 11:42	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
15	08/01/18 11:42	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
16	08/01/18 11:42	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
17	08/01/18 11:42	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
18	08/01/18 11:42	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
19	08/01/18 11:42	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
20	08/01/18 11:42	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
21	08/01/18 11:42	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
22	08/01/18 11:42	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
23	08/01/18 11:42	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
24	08/01/18 11:42	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
25	08/01/18 11:42	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
26	08/01/18 11:42	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
27	08/01/18 11:42	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
28	08/01/18 11:42	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
29	08/01/18 11:42	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
30	08/01/18 11:42	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
31	08/01/18 11:42	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>

32	08/01/18 11:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
33	08/01/18 11:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
34	08/01/18 11:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
35	08/01/18 11:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
36	08/01/18 11:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
37	08/01/18 11:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
38	08/01/18 11:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
39	08/01/18 11:45	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
40	08/01/18 11:45	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
41	08/01/18 11:45	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
42	08/01/18 11:45	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
43	08/01/18 11:45	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
44	08/01/18 11:45	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
45	08/01/18 11:45	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
46	08/01/18 11:45	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
47	08/01/18 11:45	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
48	08/01/18 11:45	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
49	08/01/18 12:08	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
50	08/01/18 12:08	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
51	08/01/18 12:08	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
52	08/01/18 12:08	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
53	08/01/18 12:08	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
54	08/01/18 12:08	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
55	08/01/18 12:08	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
56	08/01/18 12:08	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
57	08/01/18 12:08	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
58	08/01/18 12:08	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
59	08/01/18 12:08	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
60	08/01/18 12:08	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
61	08/01/18 12:08	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
62	08/01/18 12:08	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
63	08/01/18 12:08	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
64	08/01/18 12:08	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
65	08/01/18 12:08	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
66	08/01/18 12:08	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
67	08/01/18 12:08	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
68	08/01/18 12:08	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
69	08/01/18 12:08	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
70	08/01/18 12:08	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
71	08/01/18 12:08	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
72	08/01/18 12:08	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
73	08/01/18 12:08	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
74	08/01/18 12:08	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
75	08/01/18 12:08	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	21/11/17 16:12	Fax From Third Party	1	Load PDF	
2	21/11/17 16:12	TP GIA Rep - EZ3663X	1	Load PDF	
3	04/12/17 14:03	E-FILE REPORT (EZ3663X) From:SC - Reg. No: YP3664J, Claimant: SIN CHIP HUP TENTAGE SERVICES	1	Load PDF	

### Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/MSG17022255/R1BS2  
**Date:** 09/01/2018

#### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28966510MKC
Claimant Vehicle No : EZ3663X	Insured Vehicle No :	YP3664J
Date of Loss: 18/11/2017	Nature of Claim:	TP
		Claim No: 537502

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>EZ3663X</b>	Engine No:	K24W1408859
Make & Model:	HONDA ODYSSEY, 2.4 Absolute (RB1) (A)	Chassis No:	RC11108712
Reg. Date:	18/03/2016 (Man. Year: 2015)	Odometer:	31459 km
Colour:	Black		
Engine Capacity:	2356 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

#### CONDITION OF TYRES

Front Tyre Size:	215/55R17	Rear Tyre Size:	215/55R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

#### INSPECTION

Date of Assignment:	22/11/2017	Inspected At:	Yeo & Partner (Sungei Kadut)
Date Inspected:	22/11/2017		74 SUNGEI KADUT STREET 1
			Singapore 729374

Estimated Period of Repair: 0.0 days

**Adjuster:** MOHD RASUL

**Manager:** CATHERINE CHONG KAI LING

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 09 Jan 2018)	
<b>Parts:</b> M1-MPV	HONDA ODYSSEY 2.4 Absolute (RB1) (A) (Catalogue:Merimen Singapore 1.0)	
<b>Labour:</b> Repairer's	(Price-denominated Standard List)	
<b>Print Code:</b>	(Unsubmitted, no print-code for EZ3663X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >