

ASS. REC. BY:

REF: OS/MSL17022264 / TTB22 Special Instruction:

Surveyor:

Tawlich

ASSIGNMENT (Office)

From (Person):

Christina Wang

of

MSLH

Date/Time: 22-11-2017 11:27am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKF 6891T

Insured:

GBF 1627E

at Workshop m/s

Hitachi Capital

Tel:

6466 3022

of

No. 8 Fourth Lok Yang Road

Policy No:

28814942MKC

Claim No:

537563

Sum Insured:

Excess:

Make of Veh:

D.O.A

17-11-2017

(Client's Record)

CA / REV / REP. / REV 24 HRS WP

H.O.D. Endorsement:

Date/Time:

22-11-2017 12:06pm

Person Contacted:

Szu Mei

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKF 6891T - X

GBF 1627E - X

Part by Part \$4796.58 (red: 3373.52 : 41%)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17022264/T1tb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 22-11-2017	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBF 1627E	Veh. Inspected	SKF 6891T
Policy No.	28814942MKC	Coverage (\$)	0.00
Claim No.	537563	Excess (\$)	0.00
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	22/11/2017
2. Vehicle Particulars & Condition			
Make & Model	c.c 0		
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	17/11/2017	Inspection Date	22/11/2017
Survey held at	HITACHI CAPITAL (S) PTE LTD JUN TAIYO SERVICE CENTRE NO. 8 FOURTH LOK YANG ROAD SINGAPORE 629705		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Nov 2017 11:50 Sendback Est	21 Nov 2017 13:39 S\$8,001.05	22 Nov 2017 11:27 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	GUTHRIE ENGINEERING (S) PTE LTD, Co. Reg. No.: 195100006K		
Main Claimant:	NISHIO RENT ALL SINGAPORE PTE LTD, Co. Reg. No.: 197802279K		
Vehicle Reg. No.:	SKF6891T	Date of Loss:	17/11/2017 08:00 - :59
Claim Type:	TP / 537563	Policy/Cover Note No.:	28814942MKC (Comprehensive) Coverage: 20/08/2017 - 04/01/2018
Vehicle Reg. No. (Insured):	GBF1627E	Policy No. (Claimant):	17-MD003995-R05
		Excess:	S\$600.00
Repairer:	Hitachi Capital Asia Pacific Pte. Ltd (HQ) No 8 Fourth Lok Yang Road, 629705 Pioneer - Tel: 64663022		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 23/11/2017]		
Driver/Custodian (Insured):	Priscilla mon lian pheng (), NRIC: S7503774J, Tel: +6591391022		

ASSOCIATED MAIL RECEIVED

View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/11/2017 10:34
Date Of Accident	17/11/2017 08:25
Exact Location Of Accident	AYE TOWARDS TUAS BEFORE CORPORATION ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKF6891T
Insured/Policyholder	
Name Of Registered Owner	NISHIO RENT ALL SINGAPORE PTE LTD
Co Reg No	197802279K
Email Address	PRECILLA@NRAS.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-68613939

Vehicle Particulars

Manufacturer	SUZUKI
Model	SWIFT-1.4 GLX (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	17-MD003995-R05
Cover Note Number	

Driver

Name of Driver	PRISCILLA MON LIAN PHENG (WAN LIANPING)
NRIC No	S7503774J
Date Of Birth	11/02/1975
Occupation	INDOOR
Date Of Driving Pass	29/04/2003
Driving Experience	14 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91391022
Fax Number	
Contact Number	OFFICE-68613939
Email Address	PRECILLA@NRAS.COM.SG

Address
 Postcode
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE
 Weather Conditions RAINING
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name TRAFFIC POLICE DIVISION HQ
 Police Station Address ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 65470000 - FAX NO:
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO THE TRAFFIC POLICE REPORT.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBF1627E
 Vehicle Make/Model/Colour
 Details Of Properties
 Name of Driver MARIAPPAN GANBSAN
 NRIC/Passport Number
 Contact Number 64239868
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number

Email Address

DETAILS OF INJURED PERSON 1

Name PRISCILLA MON LIAN PHENG (WAN LIANPING)

Approximate Age

Injuries Sustain

Injured person in which vehicle? SKF6891T

Were seat belts worn?

Was injured conveyed to hospital by ambulance? YES

Address

Postcode

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



AYE TOWARDS B4 CORPORATION ROAD

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20171117/2062

1 of 3

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20171117/2062

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 17/11/2017 13:47	Vide Report No.: D/20171117/0045	Station Diary No.:
--	-------------------------------------	--------------------

Informant's Particulars

Name of Informant: PRISCILLA MON LIAN PHENG	Address: APT BLK 214 CHOA CHU KANG CENTRAL #10-236 HDB- CHOA CHU KANG SINGAPORE 680214
ID Type / ID No.: NRIC NO / S7503774J	Contact No.: Home/Office: Mobile: 91391022
Nationality: SINGAPORE CITIZEN	Email:
Sex: Male Age: 42 Date of Birth: 11/02/1975	Type of Informant: Driver
Race: Chinese	Language: Institution / School Name:
Occupation: SALES EXECUTIVE	Driving Licence Information: Class: 3 Date of Expiry:

General Information of the Accident

General Information of the Accident:				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 17/11/2017 08.25	Type of Location: Straight Road
Location: Along Road 1 CORPORATION ROAD				
AYE TWRDS TUAS BEF CORPORATION ROAD EXIT				
Weather: Raining		Road Surface: Wet		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBF1627E	Lorry				Slightly Damaged	2
SKF6891T	Car				Slightly Damaged	1

Details of Person Involved

Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL	



**SINGAPORE
POLICE FORCE**



T/20171117/2062

2 of 3

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20171117/2062

CONTINUATION OF REPORT

Driver			
Name	PRISCILLA MON LIAN PHENG	ID No.	S7503774J
Related Vehicle	NIL	Contact No.	91391022
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

ON THE ABOVE MENTIONED DATE AND TIME,

I WAS FROM CLEMENTI HEADING TUAS FOR WORK. I WAS DRIVE ALONG AYE TWRDS TUAS. I WAS AT THE FIRST LANE, THE TRAFFIC WASN'T HEAVY, IT WAS QUITE SMOOTH. I WAS TRAVELLING AT A MODERATE SPEED HOWEVER THE LORRY FROM THE SECOND LANE DECIDED TO JUST CHANGED HIS LANE TO MY LANE. I REMEMEBED CLEARLY THAT HE DID NOT GIVE ME ANY SIGNAL BEFORE CHANGING HIS LANE. HE SWERVED INTO MY LANE AND HIT ONTO MY VEHICLE. I DID APPLIED MY BRAKES IMMEDIATELY BUT IT'S NOT MUCH OF A HELP. WE CAME OUT TO CHECK ON OUR VEHICLE. I CALLED FOR POLICE ASSISTANCE. WE EXCHANGED PARITICULARS. MY PASSENGER AND MYSELF DIDN'T FEEL GOOD AFTER THE IMPACT FROM THE ACCIDENT, SO WE BOTH WERE CONVEYED BY AMBULANCE TO NG TENG FONG HOSPITAL. I GOT 4 DAYS OF MEDICAL LEAVE AND MY PASSENGER HAD 2 DAYS OF MEDICAL LEAVE. I WAS TOLD BY THE TRAFFIC POLICE OFFICERS TO LODGE A TRAFFIC ACCIDENT REPORT AND TO SEE IO TAN AT TPHQ.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20171117/2062

3 of 3

Report No. T/20171117/2062

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
TP /
NICHOLAS HO YE HAO

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /
SSI TAN CHIN YONG
Contact No.: 65476178

Authentication Stamp
NP168

Signature Of Informant:

[Handwritten Signature]

Date/Time:
17/11/2017 13:47

Classification Of Case:



**SINGAPORE
POLICE FORCE**

Signature: *[Handwritten Signature]*

HITACHI
 Inspire the Next

TP INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)
 Nishio rent all singapore pte ltd
 NA
 Singapore

194736

205/50 R16 Fel/Kay

Claimant Insurer: Tokio Marine Insurance Singapore Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	17/11/2017
Vehicle Reg. No.:	SKF6891T	Driveable?	
Party At Fault:	THIRD PARTY		
Driver (TP):	PRISCILLA MON LIAN PHENG (WAN LIANPING)	Driver (Insured):	PRISCILLA MON LIAN PHENG
Make/Model:	SUZUKI SWIFT, 1.4 GLX (A)	Vehicle Reg. Date:	27/06/2012
Vehicle Colour:	WHITE		
Engine No:	K14B1040787	Chassis No:	JSAFZC82S00126624
Odometer:	60000 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		

Tauhin 97495749
 WP
 27/11/17 Resurvey before paint
 surv @ 1klauto.com
 6 days
 23/11/17

Description of Accident/Loss: PLEASE REFER TO THE TRAFFIC POLICE REPORT.

Present Location: HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ)

COST OF CLAIMS

	Amount
Parts	4,411.05
Miscellaneous Items	0.00
Labour	3,590.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	8,001.05
+ GST 7.00% (S\$)	560.07
Nett Amount (S\$)	8,561.12

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This claim is handled by: GRANT CHONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Nov 2017)
 Parts: 144 SUZUKI SWIFT 1.4 GLX (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Hitachi Capital Asia Pacific Pte. Ltd/SKF6891T/21/11/2017 13:39
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front bumper <i>de</i>	0.00	0.00	✓420.00 F
2	10		*Front bumper clips <i>nee</i>	0.00	0.00	✓15.00 F
3	2		*Front bumper retainer outer LH/RH <i>nee</i>	0.00	0.00	✓22.00 F
4	2		*Front bumper retainer inner LH/RH <i>nee</i>	0.00	0.00	✓12.00 F
5	1		*Front number plate with casing <i>bt</i>	0	0.00	✓45.00 FS
6	2		*Front fog lamp LH / RH ?	0.00	0.00	<i>nnx</i> ✓196.00 F
7	2		*Front fog lamp cover LH / RH ?	0.00	0.00	✓22.00 F <i>de</i>
8	1		*Front grille <i>nee</i>	0.00	0.00	✓45.00 F
9	1		*Front grille logo <i>nee</i>	0.00	0.00	✓13.00 F
10	1		*Front bumper center lower grille <i>de</i>	0.00	0.00	✓34.00 F
11	1		*Front bumper towing cover <i>cut</i>	0.00	0.00	✓17.00 F
12	2		*Headlamp LH / RH <i>nee</i>	0.00	0.00	✓510.00 F
13	1		*Bonnet <i>bt</i>	0.00	0.00	✓295.00 F
14	2		*Bonnet hinge LH / RH <i>RY</i>	0.00	0.00	✓40.00 F
15	1		*Bonnet insulator <i>de</i>	0.00	0.00	✓48.00 F
16	1		*Bonnet insulator clips <i>nee</i>	0.00	0.00	<i>15</i> ✓1.50 F
17	1		*Bonnet rubber <i>nee</i>	0.00	0.00	✓16.50 F
18	1		*Support panel <i>bt</i>	0.00	0.00	<i>63</i> ✓62.00 F
19	1		*brace panel <i>nee</i>	0.00	0.00	-
20	1		*Bonnet lock <i>bt</i>	0.00	0.00	✓35.00 F
21	1		*Aircon condensor ?	0.00	0.00	✓350.00 F
22	1		*Radiator ?	0.00	0.00	✓454.00 F
23	1		*Aircon fan cowling ?	0.00	0.00	✓72.00 F
24	1		*Radiator fan motor ?	0.00	0.00	✓260.00 F
25	1		*Radiator fan blade ?	0.00	0.00	✓42.00 F
26	1		*Wiper tank ?	0.00	0.00	✓46.00 F
27	1		*Front reinforcement ?	0.00	0.00	✓225.00 F
28	2		*Front reinforcement bracket LH / RH ?	0.00	0.00	✓66.00 F
29	1		*Engine undercover center ?	0.00	0.00	✓20.00 F
30	1		*Horn ?	0.00	0.00	✓51.00 F
31	1		*Front fender LH <i>RY</i>	0.00	0.00	✓150.00 F
32	1		*Front fender RH <i>RY</i>	0.00	0.00	✓150.00 F
33	1		*Coolant ?	0	0.00	✓80.00 FS
34	2		*Support panel side beam LH/RH ?	0.00	0.00	<i>36</i> ✓37.00 F

F=Franchise part. S=SpcNett.

Sub Total (S\$) **3,852.00**
 + Margin on L,N Items 15.00% (S\$) **559.05**
Total Parts (S\$) 4,411.05

Hitachi Capital Asia Pacific Pte. Ltd/SKF6891T/21/11/2017 13:39. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Panel beat, cut, weld, re-align & replace damaged parts of affected area	New ✓ 900	1,600.00
2	Putty, blend and paint affected area	New ✓ 800/1000	1,400.00
3	Check Wiring, re-align headlamps and ensure proper function	New ✓ 30	80.00
4	Refill compressor oil, vacuum and refill aircond gas	New ✓ 100	180.00
5	Cavity Treatment on New Parts	New ✓ 30	150.00
6	Conduct four wheel alignment / side slip test	New ✓ 111 X X	180.00
Gross Labour Cost (S\$)			3,590.00

Hitachi Capital Asia Pacific Pte. Ltd/SKF6891T/21/11/2017 13:39. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Ⓜ Hitachi Capital Asia Pacific Pte. Ltd. (Main Office) Co. Reg. No. 199400399N

111 Somerset Road #11-05 Singapore 238164 Tel: (65) 6734 1222 Fax : 6734 8835
www.hitachi-capital.com.sg

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705 Tel: (65) 6466 3022 Fax: (65) 6896 6591

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Nov 2017)
 Parts: 144 SUZUKI SWIFT 1.4 GLX (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Hitachi Capital Asia Pacific Pte. Ltd/SKF6891T/21/11/2017 13:39
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front bumper <i>de</i>	0.00	0.00	*420.00 F ✓
2	10		*Front bumper clips <i>de</i>	0.00	0.00	*15.00 F ✓
3	2		*Front bumper retainer outer LH/RH <i>de</i>	0.00	0.00	*22.00 F ✓
4	2		*Front bumper retainer inner LH/RH <i>de</i>	0.00	0.00	*12.00 F ✓
5	1		*Front number plate with casing <i>bt</i>	0	0.00	*45.00 FS ✓
6	2		*Front fog lamp LH / RH	0.00	0.00	*196.00 F X
7	②		*Front fog lamp cover LH / RH ?	0.00	0.00	*22.00 F ✓
8	1		*Front grille <i>Chr</i>	0.00	0.00	*45.00 F ✓
9	1		*Front grille logo <i>de</i>	0.00	0.00	*13.00 F ✓
10	1		*Front bumper center lower grille <i>de</i>	0.00	0.00	*34.00 F ✓
11	1		*Front bumper towing cover <i>Chr</i>	0.00	0.00	*17.00 F ✓
12	2		*Headlamp LH / RH <i>Chr</i>	0.00	0.00	*510.00 F ✓
13	1		*Bonnet <i>bt</i>	0.00	0.00	*295.00 F ✓
14	2		*Bonnet hinge LH / RH <i>Ry</i>	0.00	0.00	*40.00 F X
15	1		*Bonnet insulator <i>de</i>	0.00	0.00	*48.00 F ✓
16	1-10		*Bonnet insulator clips <i>Chr</i> 10 x \$1.50	0.00	0.00	\$15 *1.50 F ✓
17	1		*Bonnet rubber <i>Chr</i>	0.00	0.00	*16.50 F ✓
18	1		*Support panel <i>bt</i> top	0.00	0.00	*63 *62.00 F ✓
19	1		*brace panel	0.00	0.00	
20	1		*Bonnet lock <i>bt</i>	0.00	0.00	*35.00 F ✓
21	1		*Aircon condensor ?	0.00	0.00	*350.00 F ✓
22	1		*Radiator ?	0.00	0.00	*454.00 F X
23	1		*Aircon fan cowling ?	0.00	0.00	*72.00 F X
24	1		*Radiator fan motor ?	0.00	0.00	*260.00 F X
25	1		*Radiator fan blade ?	0.00	0.00	*42.00 F X
26	1		*Wiper tank ?	0.00	0.00	*46.00 F X
27	1		*Front reinforcement ?	0.00	0.00	*225.00 F ✓
28	2		*Front reinforcement bracket LH / RH ?	0.00	0.00	*66.00 F X
29	1		*Engine undercover center ?	0.00	0.00	*20.00 F X
30	1		*Horn ?	0.00	0.00	*51.00 F X
31	1		*Front fender LH <i>Ry</i>	0.00	0.00	*150.00 F X
32	1		*Front fender RH <i>Ry</i>	0.00	0.00	*150.00 F X
33	1		*Coolant ?	0	0.00	*80.00 FS X
34	②		*Support panel side beam LH/RH ? \$18 x 2 = \$36	0.00	0.00	\$36 *37.00 F ✓
F=Franchise part. S=SpcNett.						
Sub Total (\$\$)						3,852.00
+ Margin on L,N Items 15.00% (\$\$)						559.05
Total Parts (\$\$)						4,411.05

Hitachi Capital Asia Pacific Pte. Ltd/SKF6891T/21/11/2017 13:39. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Panel beat, cut, weld, re-align & replace damaged parts of affected area	New 900	1,600.00
2	Putty, blend and paint affected area	New 800/000	1,400.00
3	Check Wiring, re-align headlamps and ensure proper function	New 35	80.00
4	Refill compressor oil, vacuum and refill aircond gas	New 100	180.00
5	Cavity Treatment on New Parts	New 30	150.00
6	Conduct four wheel alignment / side slip test	New	180.00
Gross Labour Cost (S\$)			3,590.00

Hitachi Capital Asia Pacific Pte. Ltd/SKF6891T/21/11/2017 13:39. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

© Hitachi Capital Asia Pacific Pte. Ltd. (Main Office) Co. Reg. No. 199400399N

111 Somerset Road #11-05 Singapore 238164 Tel: (65) 6734 1222 Fax: 6734 8835
www.hitachi-capital.com.sg

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705 Tel: (65) 6466 3022 Fax: (65) 6896 6591

Supplementary \$ 147 + 15% = \$ 169.05
parts \$ 2193.50 + 15% = \$ 2522.53

Slip \$ 45

labour \$ 2060

* Total P/P \$ 4796.58 @ 6 days

Estimate Report

HITACHI
 Inspire the Next

TP INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)
 Nishio rent all singapore pte ltd
 NA
 Singapore

144736

205/50 R16 Fel/R44

Claimant Insurer: Tokio Marine Insurance Singapore Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	17/11/2017
Vehicle Reg. No.:	SKF6891T	Driveable?	
Party At Fault:	THIRD PARTY		
Driver (TP):	PRISCILLA MON LIAN PHENG (WAN LIANPING)	Driver (Insured):	PRISCILLA MON LIAN PHENG
Make/Model:	SUZUKI SWIFT, 1.4 GLX (A)	Vehicle Reg. Date:	27/06/2012
Vehicle Colour:	WHITE	Chassis No:	JSAFZC82S00126624
Engine No:	K14B1040787		
Odometer:	60000 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		

Description of Accident/Loss: PLEASE REFER TO THE TRAFFIC POLICE REPORT.
 Present Location: HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ)

Taighin 97495749
 22/11/17
 Resurvey before paint
 540 @ 1k km auto. com
 6 days

COST OF CLAIMS		Amount
Parts		4,411.05
Miscellaneous Items		0.00
Labour		3,590.00
Paintwork Labour		0.00
Towing		0.00
Gross Total (S\$)		8,001.05
+ GST 7.00% (S\$)		560.07
Nett Amount (S\$)		8,561.12

This claim is handled by: GRANT CHONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

HITACHI
 Inspire the Next

(SUPPLEMENTARY)

TP INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)
 GUTHRIE ENGINEERING (S) PTE LTD
 6 Aljunied Avenue 3 #04-00
 Singapore 389932
 Singapore

Claimant Insurer: Tokio Marine Insurance Singapore Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:	28814942MKC	Date of Loss:	17/11/2017
Vehicle Reg. No.:	SKF6891T	Driveable?	
Party At Fault:	THIRD PARTY		
Driver (TP):	PRISCILLA MON LIAN PHENG (WAN LIANPING)	Driver (Insured):	PRISCILLA MON LIAN PHENG
Make/Model:	SUZUKI SWIFT, 1.4 GLX (A)	Vehicle Reg. Date:	27/06/2012
Vehicle Colour:	WHITE		
Engine No:	K14B1040787	Chassis No:	JSAFZC82S00126624
Odometer:	60000 KM		

Paint Type:
 Total Loss? NO
 Est. Duration of Repair (day) 10

Description of Accident/Loss: PLEASE REFER TO THE TRAFFIC POLICE REPORT.

Present Location: HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ)

COST OF CLAIMS	Amount
Parts	169.05
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	169.05
+ GST 7.00% (S\$)	11.83
Nett Amount (S\$)	180.88

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Mar 2018)
 Parts: 144 SUZUKI SWIFT 1.4 GLX (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Hitachi Capital Asia Pacific Pte. Ltd/SKF6891T/21/03/2018 21:10
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*Front bumper sponge Upper	0.00	0.00	*55.00 F	de ✓
2	1		*Front bumper sponge Lower	0.00	0.00	*92.00 F	de ✓
						Sub Total (\$\$)	147.00
						+ Margin on L,N Items 15.00% (\$\$)	22.05
						Total Parts (\$\$)	169.05

F=Franchise part.

Hitachi Capital Asia Pacific Pte. Ltd/SKF6891T/21/03/2018 21:10. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

M/S: HITACHI CAPITAL ASIA PACIFIC PTE.LTD

8 FOURTH LOK YANG ROAD

SINGAPORE 629705

SKF6891T

TAX INVOICE

NO: MLI9047760

PAGE: 1

DATE: 23/11/2017

A/C CODE: LDHC008

TERMS: CR

P/O NO: skf6891t

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
(D/O No: MDO9001234					
1 S71711-71L00-799	FRT BUMPER	MUVW 2	1	420.00	420.00
2 S09409-08327	CLIP BUMPER FRT	MSIC79	10	1.50	15.00
3 S71731-71L00	FRT BUMPER SYDE HOLDER RH	MU1N37-17	1	11.00	11.00
4 S71732-71L00	FRT BUMPER SIDE HOLDER LH	MU1N37-18	1	11.00	11.00
5 S71733-68L00	FRT BUMPER HOLDER RH	MU1M42-10	1	6.00	6.00
6 S71734-68L00	FRT BUMPER HOLDER LH	MU1M42-10	1	6.00	6.00
7 S71741-71L00-5PK	RAD UPPER GRILLE	MU1N28	1	45.00	45.00
8 S77811-54GC0-0PG	EMBLEM, MARK (S) FR	MSIC159	1	13.00	13.00
9 S71721-68L00-5PK	RAD LOWER GRILLE	MU1M32	1	34.00	34.00
10 S71712-68L00-ZMT	CAP FRT BUMPER	MSIE6-5	1	17.00	17.00
11 S35120-71L30	H/LAMP RH	MU1Y1	1	255.00	255.00
12 S35320-71L30	H/LAMP LH	MU1T1	1	255.00	255.00
13 S57300-61P00	FRT BONNET	MUX16 2	1	295.00	295.00
14 S72440-71L01	SILENCER FRT HOOD	MU2GS	1	48.00	48.00
15 S72361-68L00	FRT HOOD SEAL	MU1K20-10	1	16.50	16.50
16 S09409-07340	BONNET SILENCER CLIPS	MSIC30	10	1.50	15.00
17 S58230-71L00	TOP PANEL	MU1L6	1	63.00	63.00
18 S72340-71L00	MEMBER LAMP SUPPORT RH	MU1M12-1	1	18.00	18.00
19 S72350-71L00	MEMBER LAMP SUPPORT LH	MU1M42-6	1	18.00	18.00
20 S82110-68L00	LATCH HOOD	MS1D6-6	1	35.00	35.00

Print / KEONG / 23/11/2017 2:34:10 PM

Cont'd





合興汽車零件私人有限公司 HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: HITACHI CAPITAL ASIA PACIFIC PTE.LTD


NO: ML19047760

PAGE 2

TOTAL QUANTITY:	38	TOTAL	SIN 1,596.50
		ADD GST @ 7%	111.76
		GRAND TOTAL	<u>SIN 1,708.26</u>

O/R-102694

1 GEN



Print / KEONG / 23/11/2017 2:34:10 PM

SALESMAN: KEONG

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

Wm


(Signature)



Eco-Office
PARTS



GOODS RECEIVED BY





合興汽車零件私人有限公司 HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: HITACHI CAPITAL ASIA PACIFIC PTE.LTD

8 FOURTH LOK YANG ROAD

SINGAPORE 629705
SKF6891T

NO: MLI9047767
PAGE: 1
DATE: 24/11/2017
A/C CODE: LDHC008
TERMS: CR
P/O NO: skf6891t

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1	S71751-71L10-5PK	FOG LAMP COVER RH	MU1N37-8	1 11.00	11.00
2	S71761-71L10-5PK	FOG LAMP COVER LH	MU1N37-8	1 11.00	11.00
3	S95310-71L00	A/C CONDESER ASSY	MDS	1 350.00	350.00
4	S58270-71L01	FRT BUMPER BEAM TOP	MUZ15	1 225.00	225.00
5	S72460-71L01	ABS.F/BUMPER LOWER	MU2G10	1 92.00	92.00
6	S72451-71L01	ABS.FRT BUMPER UPPER	MU1M32	1 55.00	55.00
TOTAL QUANTITY:			6	TOTAL	SIN 744.00
				ADD GST @ 7%	52.08
				GRAND TOTAL	<u>SIN 796.08</u>

O/R-102694

Reprint:2 / KEONG / 24/11/2017 4:46:33 PM

SALESMAN: KEONG

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE



E & O: ECT
PARTS



GOODS RECEIVED BY



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd
Main	21 Nov 2017 11:50	21 Nov 2017 13:39	22 Nov 2017 11:27	S\$4,796.58	S\$4,796.58	
	Sendback Est	S\$8,001.05	Edit Adj Rpt	Edit Estimates	View Rpt	Pending for Survey Report Cancel Case
Supp #1	21 Mar 2018 21:00	21 Mar 2018 21:10	21 Mar 2018 21:10			(Combined) Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	GUTHRIE ENGINEERING (S) PTE LTD , Co. Reg. No.: 195100006K		
Main Claimant:	NISHIO RENT ALL SINGAPORE PTE LTD , Co. Reg. No.: 197802279K		
Vehicle Reg. No.:	SKF6891T	Date of Loss:	17/11/2017 08:00 - :59 [64 Months and 21 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 537563	Policy/Cover Note No.:	28814942MKC (Comprehensive) Coverage: 20/08/2017 - 04/01/2018
Vehicle Reg. No. (Insured):	GBF1627E	Policy No. (Claimant):	17-MD003995-R05
		Excess:	S\$600.00
Repairer:	Hitachi Capital Asia Pacific Pte. Ltd (HQ) No 8 Fourth Lok Yang Road, 629705 Pioneer - Tel: 64663022		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Imm.Advice due 23/11/2017]		
Driver/Custodian (Insured):	Priscilla mon lian pheng (), NRIC: S7503774J, Tel: +6591391022		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS



















































[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)



Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents




SKF6891T (537563)
[GBF1627E]
TP
NISHIO RENT ALL SINGAPORE PTE LTD
Nov 17 2017 8:00AM
[GUTHRIE ENGINEERING (S) PTE LTD]
Hitachi Capital Asia Pacific Pte. Ltd















Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Assessment Reports									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)							Thumbnail	Print	
1	20/11/17 19:53	Accident Statement							Load HTM		
2	21/11/17 13:39	Repairer Estimates							Load HTM		
3	21/03/18 21:10	Repairer Estimates Suppl. #1							Load HTM		
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)							Thumbnail	Print	
1	22/11/17 11:29	Accident Statement From: SC - Reg. No: GBF1627E, Claimant: GUTHRIE ENGINEERING (S) PTE LTD							Load HTM		
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	13/04/18 15:45	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
2	13/04/18 15:45	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
3	13/04/18 15:45	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
4	13/04/18 15:45	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
5	13/04/18 15:45	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
6	13/04/18 15:45	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
7	13/04/18 15:45	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
8	13/04/18 15:45	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
9	13/04/18 15:45	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
10	13/04/18 15:45	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
11	13/04/18 15:45	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
12	13/04/18 15:45	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
13	13/04/18 15:45	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
14	13/04/18 15:45	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
15	13/04/18 15:45	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
16	13/04/18 15:45	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
17	13/04/18 15:45	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
18	13/04/18 15:45	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
19	13/04/18 15:45	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
20	13/04/18 15:45	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
21	13/04/18 15:45	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
22	13/04/18 15:45	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
23	13/04/18 15:45	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
24	13/04/18 15:45	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
25	13/04/18 15:45	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
26	13/04/18 15:45	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
27	13/04/18 15:45	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
28	13/04/18 15:45	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
29	13/04/18 15:45	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
30	13/04/18 15:45	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	


Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
31	13/04/18 15:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
32	13/04/18 15:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	13/04/18 15:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	13/04/18 15:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	13/04/18 15:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	13/04/18 15:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	13/04/18 15:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	13/04/18 15:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	13/04/18 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
40	13/04/18 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
41	13/04/18 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
42	13/04/18 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
43	13/04/18 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
44	13/04/18 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
45	13/04/18 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
46	13/04/18 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
47	13/04/18 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
48	13/04/18 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
49	13/04/18 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
50	13/04/18 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
51	13/04/18 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
52	13/04/18 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
53	13/04/18 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
54	13/04/18 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
55	13/04/18 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
56	13/04/18 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
57	13/04/18 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
58	13/04/18 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
59	13/04/18 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
60	13/04/18 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
61	13/04/18 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
62	13/04/18 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
63	13/04/18 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
64	13/04/18 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
65	13/04/18 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
66	13/04/18 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
67	13/04/18 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
68	13/04/18 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
69	13/04/18 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
70	13/04/18 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
71	13/04/18 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
72	13/04/18 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
73	13/04/18 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
74	13/04/18 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
75	13/04/18 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
76	13/04/18 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
77	13/04/18 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
78	13/04/18 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
79	13/04/18 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
80	13/04/18 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
81	13/04/18 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
82	13/04/18 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			View	View in Browser	<input checked="" type="checkbox"/>
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print	
1	20/11/17 19:53	Accident Statement	 Load HTM		
2	28/11/17 15:25	Addendum Sheet	 Load TIF		
3	28/11/17 15:25	Accident Statement Addm. #1	 Load HTM		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
1	18/11/17 11:01	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	18/11/17 11:01	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	18/11/17 11:01	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	18/11/17 11:01	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	18/11/17 11:01	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	18/11/17 11:01	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	18/11/17 11:01	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	18/11/17 11:01	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	18/11/17 11:01	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	18/11/17 11:01	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	18/11/17 11:01	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	18/11/17 11:01	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	18/11/17 11:01	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	18/11/17 11:01	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
1	20/11/17 19:53	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17022264/T1TBE2

Date: 24/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28814942MKC

Claimant Vehicle No: SKF6891T

Insured Vehicle No: GBF1627E

Date of Loss: 17/11/2017

Nature of Claim: TP

Claim No: 537563

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKF6891T

Make & Model: SUZUKI SWIFT, 1.4 GLX (A)

Engine No: K14B1040787

Reg. Date: 27/06/2012 (Man. Year: 2012)

Chassis No: JSAFZC82S00126624

Colour: White

Odometer: 194736 km

Engine Capacity: 1372 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50 R16

Rear Tyre Size: 205/50 R16

Front Left Side: Falken 6 mm

Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm

Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,580.10	2,736.58	1,843.52	40.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,590.00	2,060.00	1,530.00	42.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,170.10	4,796.58	3,373.52	41.29
+ GST 7.00/7.00% (S\$)	571.90	335.76	236.14	41.29
Nett Amount (S\$)	8,742.00	5,132.34	3,609.66	41.29

INSPECTION

Date of Assignment: 22/11/2017 Present Location:

Hitachi Capital Asia Pacific Pte. Ltd (HQ)

Date Inspected: 22/11/2017 Inspected At:

No 8 Fourth Lok Yang Road
Singapore 629705

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 24 Apr 2018)
Parts: 144	SUZUKI SWIFT 1.4 GLX (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKF6891T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front bumper (WCP)	Deformed	420.00 F	*420.00 F
2	10		*Front bumper clips (WCP)	Necessary	15.00 F	*15.00 F
3	2		*Front bumper retainer outer LH/RH (WCP)	Necessary	22.00 F	*22.00 F
4	2		*Front bumper retainer inner LH/RH (WCP)	Necessary	12.00 F	*12.00 F
5	1		*Front number plate with casing	Bent	45.00 FS	*45.00 FS
6	2		*Front fog lamp LH / RH (WCP)	Not Necessary	196.00 F	*- F
7	2		*Front fog lamp cover LH / RH (WCP)	Deformed	22.00 F	*22.00 F
8	1		*Front grille (WCP)	Cracked	45.00 F	*45.00 F
9	1		*Front grille logo (WCP)	Necessary	13.00 F	*13.00 F
10	1		*Front bumper center lower grille (WCP)	Deformed	34.00 F	*34.00 F
11	1		*Front bumper towing cover (WCP)	Cut	17.00 F	*17.00 F
12	2		*Headlamp LH / RH (WCP)	Cracked	510.00 F	*510.00 F
13	1		*Bonnet (WCP)	Bent	295.00 F	*295.00 F
14	2		*Bonnet hinge LH / RH (WCP)	Repair	40.00 F	*- F
15	1		*Bonnet insulator (WCP)	Deformed	48.00 F	*48.00 F
16	1		*Bonnet insulator clips (WCP)	Necessary	1.50 F	*15.00 F
17	1		*Bonnet rubber (WCP)	Twisted	16.50 F	*16.50 F
18	1		*Support panel (WCP)	Bent	62.00 F	*63.00 F
19	1		*brace panel (WCP)	Not Necessary	-	*- F
20	1		*Bonnet lock (WCP)	Bent	35.00 F	*35.00 F
21	1		*Aircon condensor (WCP)	Bent	350.00 F	*350.00 F
22	1		*Radiator (WCP)	Not Necessary	454.00 F	*- F
23	1		*Aircon fan cowling (WCP)	Not Necessary	72.00 F	*- F
24	1		*Radiator fan motor (WCP)	Not Necessary	260.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
25	1		*Radiator fan blade (WCP)	Not Necessary	42.00 F	*- F
26	1		*Wiper tank (WCP)	Not Necessary	46.00 F	*- F
27	1		*Front reinforcement (WCP)	Bent	225.00 F	*225.00 F
28	2		*Front reinforcement bracket LH / RH (WCP)	Not Necessary	66.00 F	*- F
29	1		*Engine undercover center (WCP)	Not Necessary	20.00 F	*- F
30	1		*Horn (WCP)	Not Necessary	51.00 F	*- F
31	1		*Front fender LH (WCP)	Repair	150.00 F	*- F
32	1		*Front fender RH (WCP)	Repair	150.00 F	*- F
33	1		*Coolant	Not Necessary	80.00 FS	*- FS
34	2		*Support panel side beam LH/RH (WCP)	Bent	37.00 F	*36.00 F
Supplementary #1						
35	1		*Front bumper sponge Upper (WCP)	Deformed	55.00 F	*55.00 F
36	1		*Front bumper sponge Lower (WCP)	Deformed	92.00 F	*92.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	3,999.00	2,385.50
+ Margin on L,N Items 15.00/15.00% (\$\$)	581.10	351.08
Total Parts (\$\$)	4,580.10	2,736.58

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Panel beat, cut, weld, re-align & replace damaged parts of affected area	New	1,600.00	900.00
2	Putty, blend and paint affected area	New	1,400.00	1,000.00
3	Check Wiring, re-align headlamps and ensure proper function	New	80.00	30.00
4	Refill compressor oil, vacuum and refill aircond gas	New	180.00	100.00
5	Cavity Treatment on New Parts	New	150.00	30.00
6	Conduct four wheel alignment / side slip test	New	180.00	0.00
Gross Labour Cost (S\$)			3,590.00	2,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >