

ISS. REC. BY:

REF: CS/FCL17022271 / Utbnz Special Instruction:

Surveyor: Marcus ASSIGNMENT (Office)

From (Person): LWS Joanne Yong of FCL Date/Time: 22-11-2017 9:18am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLM 9711L Insured: SH 6607T

at Workshop m/s Pegasus Tel: 6858 1846

of 51 Defu Lane 10

Policy No: _____ Claim No: D17010832 MESH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 20-11-2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS' H.O.D. Endorsement: _____

Date/Time: 22-11-2017 10:27am Person Contacted: Alvin Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate	
	SLM 9711L - 006 / AL17013071 / Web3q2	DA: 020717
	SH 6607T - 003 / FCL17001092 / P7h3m2	DA: 13012017



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17022271/Utb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 22-11-2017	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 6607T	Veh. Inspected	SLM 9711L
Policy No.		Coverage (\$)	0.00
Claim No.	D17010832MFSH	Excess (\$)	0.00
Assign From	CWS (JOANNE YONG)	Assign Date	22/11/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	20/11/2017	Inspection Date	22/11/2017
Survey held at	51 DEFU LANE 10		
Repairer	PEGASUS ENGINEERING & TRADING PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Job Sheet (/ClaimWS/Surveyor/JobSheet/230479)

PRI Documents

Close

PRI Header Details

Claim No	D17010832MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & PEG TRADING
Workshop Name	PEGASUS ENGINEERING & TRADING PTE LTD (Contact Person : ALVIN LOW)	Survey Location & Contact Details	51 DEFU LANE 10 Mobile: 68581846 , Phone: 68581846 , Fax: EmailId: CLAIMS@PEGASUSENGR.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH6607T	TP Vehicle No	SLM97
PRI Recieved Date	21-11-2017 06:25:28 PM	Surveyor Appointed Date	22-11-2017 09:18:24 AM	Surveyor Accept Date	22-11-

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	22-11-2017	Upload Survey Report *:	<input type="text"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	----------------------

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 29 November, 2017 12:09 PM
To: Admin-D (LKKAuto); 'Claim Workflow System'; assignments
Cc: JOANNEYONG@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17010832MFSH/1
Attachments: PRELI ADVISED SLM 9711L.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLM 9711L**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Wednesday, 22 November, 2017 10:29 AM

To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>

Cc: JOANNEYONG@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D17010832MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]

Sent: Wednesday, 22 November, 2017 9:18 AM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; JOANNEYONG@FIRST-INSURANCE.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D17010832MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

First Capital Insurance Limited

Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17010832MFSH

Date: 29/11/2017

Our Ref: CS/FCI17022271/Utb

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLM 9711L

Please be informed that we had conducted the inspection of the abovementioned vehicle 22/11/2017 at the premises of M/s Pegasus at and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 2,789.20</u>
Revised Estimate Amount	: <u>S\$ 2,294.40</u>
"Check" Items Amount	: <u>S\$ -</u>
Market Value	: <u>S\$ -</u>
LTA Reimbursement Value	: <u>S\$ -</u>
Nett Value	: <u>S\$ -</u>

Description of Damage:
The vehicle sustained damages
At front rear portion.



Repair days: 3

Yours faithfully

Marcus

Motor Surveyor

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	7200G
Vehicle Details	
Vehicle No.	SLM9711L
Vehicle to be Exported	Yes
Intended De-registration Date	20 Nov 2017
Vehicle Make	MAZDA
Vehicle Model	MAZDA3 SEDAN 1.5 AT EU6
Primary Colour	Grey
Manufacturing Year	2017
Engine No.	P520441855
Chassis No.	JM6BN22A8H0150165
Maximum Power Output	88.0 kW (118 bhp)
Open Market Value	\$14,476.00
Original Registration Date	19 Apr 2017
First Registration Date	19 Apr 2017
Transfer Count	0
Actual ARF Paid	\$9,476.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	18 Apr 2027
PARF Rebate Amount	\$7,107.00
Intended COE Rebate Details	
COE Expiry Date	18 Apr 2027
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$51,765.00
COE Rebate Amount	\$41,412.00
Total Rebate Amount	\$48,519.00

The information contained herein is correct as at 20 Nov 2017

OK

Email on 20.11.2017 @ 12:28hrs



Not Authorized
LKK
22/11/17
P/P #2294.40
3 day.

Third Party Insurer : First Capital
Insured's Veh No : SH6607T
Date of accident : 20.11.2017

LKK Marcus
22-11-2017 @ 09:35hrs
Date 20.11.2017

Messrs Grab Rentals Pte Ltd

Estimate To Repair Mazda 3 Sedan 1.5
Vehicle No : SLM9711L
Chassis No : MTGRAB20171177

Confirmed on 22/11/17

Pages: 1 of 1

S/No	Quantity	Description	Unit price	Amount
LIST ITEMS				
1	1 pc	rear bumper <i>Drs</i>	\$ 1,075.00	\$ 1,075.00
2	2 ps	rear bumper reflector <i>11</i>	\$ 55.00	\$ 110.00
3	10 ps	rear bumper clips <i>10</i>	\$ 5.00	\$ 50.00
4	1 pc	rear bumper reinforcement <i>TD</i>	\$ 538.00	\$ 538.00
5	2 ps	rear bumper side retainer <i>0/5 bar</i>	\$ 46.00	\$ 92.00
6	2 ps	rear bumper tow cover <i>Torn</i>	\$ 17.00	\$ 34.00
		Less 20%		\$ 1,899.00
				\$ 379.80
				\$ 1,519.20
SPECIAL NETT ITEMS				
7	1 set	rear bumper parking sensor <i>Shut</i>	\$ 450.00	\$ 450.00
				\$ 450.00
LABOUR & MISC. CHARGES				
1		To reinstall of rear bumper parking sensor.		\$ 120.00
2		Panel beating, knocking and straighten the necessary portion,		\$ 350.00
3		remove and renewal of parts, adjust and realign the same.		\$ 350.00
		Putty and spray painting of the affected portion.		\$ 820.00
		Grand total		\$ 2,789.20

X
✓
✓
✓
✓
1743
1394.4
200
50
300
✓
2294.40

Please conduct the survey at Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51, Defu Lane 10 Singapore 539216

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17022271/Utbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 01-12-2017	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 6607T	Veh. Inspected	SLM 9711L
Policy No.	D-15072701MFSH	Coverage (\$)	0.00
Claim No.	D17010832MFSH	Excess (\$)	0.00
Assign From	JOANNE YONG	Assign Date	22/11/2017
2. Vehicle Particulars & Condition			
Make & Model	MAZDA 3 (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JM6BN22A8H0150165	Colour	GREY
Odometer	38743	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	TOYO	6 mm
L/H Front Tyre	205/60 R16	TOYO	6 mm
R/H Rear Tyre	205/60 R16	TOYO	6 mm
L/H Rear Tyre	205/60 R16	TOYO	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	20/11/2017	Inspection Date	22/11/2017
Survey held at	51 DEFU LANE 10		
Repairer	PEGASUS ENGINEERING & TRADING PTE LTD		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 9711L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DISTORTED	1,075.00	1,075.00
2	REAR BUMPER REFLECTOR @\$55.00	NOT NECESSARY	110.00	-
10	REAR BUMPER CLIPS @\$5.00	NECESSARY	50.00	50.00
1	REAR BUMPER REINFORCEMENT	DENTED	538.00	538.00
2	REAR BUMPER SIDE RETAINER @\$46.00	O/S BENT	92.00	46.00
2	REAR BUMPER TOW COVER @\$17.00	TORN	34.00	34.00
	LESS 20% DISCOUNT		-379.80	-348.60
			1,519.20	1,394.40
SPECIAL NETT ITEMS				
1	SET REAR BUMPER PARKING SENSOR (SN)	SHORTED	450.00	200.00
			450.00	200.00
LABOUR				
	TO REINSTALL OF REAR BUMPER PARKING SENSOR.		120.00	50.00
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.		350.00	300.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		350.00	350.00
			820.00	700.00
GRAND TOTAL			2,789.20	2,294.40
RECOMMENDED COST OF REPAIRS				2,294.40

Report Ref No. CS/FC117022271/Utn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.