surveyor:	GIL	_ <u>A</u>	SSIGNME	NT (Office,		
From (Person)	Jenny	Lew of		UVL	Date/	Time: 22.112017 427 pm
Estimated Cos				Bill to:		
OD (T) / WS To Inspect Ve	TP RES / OD R	res/eva/1	NV/MV/CS	\$	Insured:	3KW 3811H
at Workshop r	v/s	Think	The second second second		Tel:	908 8488
of		18 Deh	1 Ave 2			
Policy No:				Claim No:	MUDO	24/17/17
Sum Insured:				Excess:		
Make of Veh:		W			D.O.	A. 20:11207
	REP. / REV 24	i HRS II AALI	- 6	710211-60	п	D.D. Endorsement:
	22-112011 HEP		Contacted: _	KUMn_		
Date/Time	Action/Instruction	on (/)	Estimate	Estimat	e nutyet o	
	GBA 52X	- CC6 /F	1(116003	604 Kpb3	391 -	DOA: 18
	SKM 38114	- X			nomen les es	

4000

Lump Sum / 19



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

			ationale Des Experts En Autom		
UNITED OVERSEAS INSURANCE LTD			Ref : CS/UOI17022305/qb		
3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909		Date: 22-11-2017 Code: UOI2			
1.		Policy Particula	ars :- THIRD PARTY CLA	M	
	Insured Veh.	SKM 3811H	Veh. Inspected	GBA 52X	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	1700	Excess (\$)	0.00	
	Assign From	JENNY LEW	Assign Date	22/11/2017	
2.		Vehicle P	articulars & Condition		
	Make & Model		c.c	0	
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour		
	Odometer - Brakes		Steering		
			Modification		
	General				
3.		Cor	ditions of Tyres		
		Size	Make	Balance	
	R/H Front Tyre			mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre			mm	
	L/H Rear Tyre			mm	
4.	A CHERNING	Descr	iption of Damages		
5.		Ger	neral Information		
	Accident Date	20/11/2017	Inspection Date	23/11/2017	
	Survey held at	THINK ONE AUTOCARE P	TE LTD		
		NO.18 DEFU AVENUE 2 SINGAPORE 539522			
5a.			Remarks		

Survey Department Check List (Case Handler) Policy Type: OD / TP / TP RES / TL / EVA Case Handler Typist Admin (after): Case handler to make sure all Information created by the assignment team are ACCURATE. Y-Date N-Date Y-Date N-Date (1) Office Assign Form Reference No. C C Customer Code Assign From N. C Assign Date Veh No (Inspected) C C Veh No (Insured) C D.O.A Policy No. C C Claim No Insurance Authorisation (CA /REV/REP) C C Report Type Weekend Charges Survey held at/Repairer N C Excess Guo Riany): Case handler to make sure the surveryor completed all required information. Surveyor ((1) Assignment Form C Vehicle No C Regn Month/Year N . Vehicle Type Make & Model C Engine Capacity. (C.C) N Colour Odometer. (Sp.Reading) C C Chassis No Ν General Condition Steering N Brake Modification (Modi) N Tyre Size C Tyre Make N C Tyre Balance C Date of Inspection Survey held N Des.of Damages N (2) System - (Views/Merimen) Damaged Vehicle Photographs Uploaded C (3) Workshop Estimate/Assignment Form ALL Parts condition C Market Value for OD cases Estimate Repair Cost for PRI (RSI, TMI, MSIG) C

Check By: 28/2/8

Re-inspection Cases to Finalize within 5 Days

Days of repair Finalised Amount

Resurvey photo Uploaded.

(4) System - (Views/Merimen)

C

C

Catherine Chong (LKK Auto)

From:

LEW JENNY < jennylew@uoi.com.sg>

Sent:

Wednesday, 22 November, 2017 4:27 PM

To:

Karen Tan; assignments@lkkauto.com; sur@lkkauto.com

Cc:

LEE KATIE

Subject:

RE: Survey for GBA52X & SKM3811H Accident dated on 20.11.2017 along Junction

Of Sumang Crescent

WITHOUT PREJUDICE

Dear Karen,

We will appoint LKK as per requested.

Dear Shiau Chan,

Please arrange to survey the vehicle at Think One Autocare Pte Ltd.

Thank You.

Warmest Regards

Jenny

Claims Department

DID: 6 4909 329 Fax: 6 327 3869/72 United Overseas Insurance Limited

Company Registration Number: 197100152-R

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

From: Karen Tan [mailto:karentan@thinkone.com.sg] Sent: Wednesday, 22 November, 2017 4:21 PM

To: LEW JENNY < jennylew@uoi.com.sg>
Cc: LEE KATIE < katielee@uoi.com.sg>

Subject: RE: Survey for GBA52X & SKM3811H Accident dated on 20.11.2017 along Junction Of Sumang Crescent

Importance: High

Hi Jenny,

Able to proceed with LKK Auto Consultants Pte Ltd.

Yours Sincerely,

Karen Tan Claim Advisor Think One Autocare Pte Ltd No.18 Defu Avenue 2 Singapore 539522 HP: 9128 8488

DID: 6844 3300 FAX: 6842 4988

From: LEW JENNY [mailto:jennylew@uoi.com.sg]
Sent: Wednesday, 22 November, 2017 4:06 PM

To: karentan@thinkone.com.sg

Cc: LEE KATIE <katielee@uoi.com.sg>

Subject: RE: Survey for GBA52X & SKM3811H Accident dated on 20.11.2017 along Junction Of Sumang Crescent

Without Prejudice

Dear Karen,

We attach herewith our list of surveyors for your attention.

Please advise who you want to appoint as SJE for this case.

We reserve all our rights in relation to this matter.

Thanks.

Warmest Regards

Jenny Claims Department

DID: 6 4909 329 Fax: 6 327 3869/72 United Overseas Insurance Limited

Company Registration Number: 197100152-R

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

From: Karen Tan [mailto:karentan@thinkone.com.sg]
Sent: Wednesday, 22 November, 2017 2:26 PM

To: LEE KATIE <katielee@uoi.com.sg>

Subject: RE: Survey for GBA52X & SKM3811H Accident dated on 20.11.2017 along Junction Of Sumang Crescent

Importance: High

Dear Sir/ Mdm,

I would like to arrange a surveyor to survey our client's vehicle GBA52X for the above mentioned.

Yours Sincerely,

Karen Tan Claim Advisor Think One Autocare Pte Ltd No.18 Defu Avenue 2 Singapore 539522 HP: 9128 8488 DID: 6844 3300 FAX: 6842 4988

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type	Company
Owner ID	0773N
Vehicle Details	
Vehicle No.	GBA52X
Vehicle to be Exported	No
ntended De-registration Date	24 Nov 2017
Vehicle Make	TOYOTA
Vehicle Model	HIACE MANUAL
Primary Colour	Silver
Manufacturing Year	2006
Engine No.	1KD1531094
Chassis No.	JTFHT02P600001827
Maximum Power Output	•
Open Market Value	\$24,590.00
Original Registration Date	09 Jan 2007
First Registration Date	09 Jan 2007
Transfer Count	1
Actual ARF Paid	\$0.00
Intended PARF Rebate Details	
PARF Eligibility	No
PARF Eligibility Expiry Date	•
PARF Rebate Amount	\$0.00
Intended COE Rebate Details	
COE Expiry Date	31 Jul 2021
COE Category	C - Goods Vehicle & Bus
COE Period(Years)	5
PQP Paid	\$22,247.00
COE Rebate Amount	\$16,398.00
Total Rebate Amount	\$16,398.00
Message	

The information contained herein is correct as at 24 Nov 2017

Your NCD will be affected due to late reporting Actual e-Filling Submission Date & Time: 22/11/2017 11:27

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT		
Date Of Report	21/11/2017 12:40		
Date Of Accident	20/11/2017 19:40		
Exact Location Of Accident	JUNCTION OF SUMANG CRESCENT		
Country/State of Loss	SINGAPORE		
	DETAILS OF OWN VEHICLE		
Vehicle Registration Number	GBA52X		
Insured/Policyholder			
Name Of Registered Owner	AEROHUB LOGISTICS PTE. LTD.		
Co Reg No	200410773N		
Email Address	NOEMAIL		
Mobile Phone No			
Alternative Phone No	OFFICE-63382929		
Vehicle Particulars			

TOYOTA Manufacturer HIACE-2.0 (M) Model **DELIVERY USE**

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken

Vehicle Category

NO

THIRD PARTY

COMMERCIAL VEHICLE

Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD Name of Insurance Company

THIRD PARTY FIRE AND/OR THEFT Type Of Coverage

NO Fleet Policy

5084148064-01 Policy Number

24/07/2017 TO 23/07/2018 Cover Note Number

Driver

JUMAHAD BIN ZAINOL Name of Driver

S1808130Z NRIC No 20/10/1967 Date Of Birth OUTDOOR Occupation 05/01/2007 Date Of Driving Pass

10 YEARS AND 10 MONTHS **Driving Experience**

MALE Gender

(LOCAL) +65-93390490 Mobile Number

Fax Number Contact Number

JUMYNROZY@GMAIL.COM EMail Address

BLOCK 541 SERANGOON NORTH AVENUE 4

#02-129

Postcode 550451

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Address

-

Insurance Company of Driver's Own Vehicle

.

General Information of the Accident

Type Of Accident COLLISION - CROSS JUNCTION

Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO
Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

2

Details of Police Action

Was the accident reported to the police?

NO

NO

If Yes, Please state which Police Station

Number of Passengers (Including Driver)

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

On 20/11/2017 at about 1940hrs, I was driving my vehicle (A: GBA52X) on the outer lane along Sumang Crescent heading towards SAFRA. The traffic light was green in my favour, upon reaching the junction suddenly the vehicle (B: SKM3811H) which was travelling from my opposite direction make a right turn without green arrow and hit onto my vehicle's right front portion. Nobody was injured in this accident. Vehicle A (GBA52X) - 1 female adult passenger on board. Vehicle B (SKM3811H) - 1 female adult and 1 children on board.

Attachment(s)

Are accident photos available for attachment? YES Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKM3811H
Vehicle Make/Model/Colour BMW 523I

Details Of Properties SALOON CAR

Name of Driver ONG CHI YANG, EDWIN

NRIC/Passport Number S8828550F Contact Number 9100 2331

Address Postcode

Insurance Company Name

Nature Of Damage RIGHT FRONT PORTION

3

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

KIM HOE TYRE & BATTERY KAKI BUKIT AUTOHUB #01-10 SINGAPORE 417921

TEL: 67472427

Work Order:

R008007

License:

GBA52X

Date

11.12.17 13:39

Toyota: Hiace: TRH/KDH/LH(200,210,220) Series: KDH200L-RBMDY: 2015_01-

Thrust Line Alignment

Front : Left

Actual	Before	Specified Range
-0°37"		-1°03' 0°27'
		1°39' 3°09'
0°09'		0°02' 0°07'
0 00		11°51' 13°21'
		10°48' 13°48'

Camber Caster Toe SAI Included Angle Turning Angle Diff.

Actual	Before	Specified Range
-0°33'		-1°03' 0°27'
		1°39' 3°09'
-0°05'		0°02' 0°07'
0.00		11°51' 13°21'
		10°48' 13°48'

Front

Cross Camber **Cross Caster** Cross SAI **Total Toe** Cross Turn Diff.

Actual	Before	Specified Range
-0°04'		-0°30' 0°30'
		-0°30' 0°30'
		-0°30' 0°30'
0°04'		0°00' 0°19'

Rear : Left

Actual	Before	Specified Range
0°02'		
-0°09'		

Camber Toe

Actual	Before	Specified Range
-0°08'		
0°01'		

Rear : Right

Rear

Cross Camber Total Toe Thrust Angle

Actual	Before	Specified Range
0°10'		
-0°07'		
-0°05'		Versenere

Think One Autocare Pte Ltd No.18 Defu Avenue 2 Singapore 539522

Tel: 6844 3300 Fax: 6842 4988

GBA52X To	vota Hiace
-----------	------------

GDP	IJLA	Toyota Hiace	Estimated
			Parts Price
No		Parts Description	\$ 1,886.00 623.
1	1	Front bumper assy Front bumper reinforcement Front bumper reinforcement	\$ 84.00 53.9
2	1	Front bumper rainforcement 67	\$ 455.00 379, 2
3	1	Front bumper reinforcement Front bumper reinforcement Front bonnet assy Front bonnet logo Front bonnet lock mechanism Front grille assy Regar	\$ 2,618.00 X
	1	Front bonnet assy	S 110.00
5	1	Front houset look mechanism X	s 106.00 X
6	1	Front smile easy 2 38	\$ 655.00 467.9
7	1	Front grille assy 7 / 3R Front right door inner panel X Pagar.	\$ 1,662.00 X
8	1	Front right door linier paner	\$ 1,675.00 764
9	1	Front right headlamp	\$ 1,858.00 726
10	1	Front right door binger	\$ 220.00 [9]
11	2	Front right door hinges / BT Front right door lower step garnish / BC	s 267.00 228 1
12	2		\$ 1,624.00
13	1	Front air con condenser X /	\$ 1,211.00 X
14	1	Front air-con condenser X Front ABS module unit X	\$ 3,800.00 ×
15	1	Front ABS module unit X 7	\$ 288.00 X
16	1	Front ABS module unit X 7 Front windscreen glass moulding X Front right door inner board V AR AR AR AR AR AR AR AR AR A	\$ 310.00
17	1	Front right door inner board ? / PIC	s 480.00 ×
18	1	Front right door inner board ? / / / / / / / / / / / / / / / / / /	s 175.00 X
19		Tront right door care	\$ 225.00 X
20		Front right door lock mechanism	s 470.00 ×
21	1	Front right wing mirror assy	\$ 120.00 X
22		Front right wheel rim cover	\$ 655.00 /
23		Front right 'A' pillar	s 850.00 ×
24		Front right 'B' pillar ×	\$ 178.00 ×
25		Front right knuckle ball joint X	\$ 685.00 X
26		Front right shock absorber X	s 421.00 X
27		Front right lower arm X	\$ 529.00 X
28		Front right upper arm X	s 451.00 ×
29		Front right knuckle arm X	\$ 351.00 X
30		Front right wheel hub bearing	\$ 175.00 X
31		Front right stabilizer link	\$ 165.00 X
32		Front right tie rod	\$ 330.00 \(\)
33	1	Front stabilizer bar 🗡	\$ 25,089.00 4398. 2
			\$ 25,089.00 4378, 2 \$ 6,272.25 \$ 18,816.75 2,398,65
		Less 25%	\$ 18,816.75 2298.65
			\$ 10,010.73

Think One Autocare Pte Ltd No.18 Defu Avenue 2 Singapore 539522

Tel: 6844 3300 Fax: 6842 4988

GBA52X Toyota Hiace

No. Otv		Parts Description	Estimated Parts Price
10	4.3	C 1 N -44 I tomas	
1	12	Front bumper clips Front grille clips	\$ 50.00
2	8	Front grille clips 2 / MC	\$ 30.00
3	1	Front air-con gas X	\$ 80.00
4	1	Front radiator coolant	\$ 80.00
5	1	Front brake fluid X	\$ 50.00
	1	Front right wheel rim X	\$ 450.00
6	1	Front right tyre X	\$ 300.00
8	1	Front right door sticker / Cut	\$ 30.00 /
9	1	Front no plate	\$ 80.00
1			\$ 1,150.00
		Total Parts	\$ 19,966.75

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Think One Autocare Pte Ltd No.18 Defu Avenue 2 Singapore 539522

Tel: 6844 3300 Fax: 6842 4988

				labour Charges	
No	Description	Control anno		1,400.00	
1	Labour for panel beating, cut, weld, straighten front right af and replace accident damaged parts.	tected area	S	1,400.00	Se Ros
2	To putty and spray painting front right portion.		\$	1,400.00	
3	To check wiring and focus front headlamp.		S		30
4	To remove and install air con system to facilitate the repair	and refill	\$	150.00	X NN
5	gas. To remove and install cooling system to facilitate the repair	and check	\$	150.00	K NN K NN
-	for leakage. To remove and install front bonnet lock mechanism.		S	60.00	× NN
5			S	100.00	50
7	To apply anti rust proofing to front right affected area. To transfer front right door lock mechanism.		\$	60.00	기구 하는데 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그
8	To remove and install front right side inner garnish and trin	n to	S	120.00	x y N
9	facilitate the repair.				2 1.58
0	To transfer front right door glass to new door.		\$	60.00 \$,0
1	To conduct wheel alignment.		S	80.00	50
12	To balance front right wheel.		\$	50.00	X I
13	To remove and install front right undercarriage parts.		\$	250.00	x (.
14	To remove and install front brake ABS module unit.		S	150.00	× /
15	1. U.S L	on.	S	60.00	×
300	Towing service.		\$	100.00	2
10	To	tal labour :	\$	4,240.00	1600
m	pem Rejair.	Total parts :	\$	19,966.75	2.30
	1000	tal labour :		4,240.00	

Total repair cost: \$ 24,206.75

6 Days.
Gu. Qiany - 8288 0282
After repair
23/11/17.

5008.65 29.: 4000

22826.25

KIM HOE TYRE & BATTERY KAKI BUKIT AUTOHUB #01-10 SINGAPORE 417921

TEL: 67472427

Work Order:

R007817

License:

GBA52X

Date

23.11.17 17:42

Toyota: Hiace: TRH/KDH/LH(200,210,220) Series: KDH200L-RBMDY: 2010_08-2015_01

Thrust Line Alignment

Front: Left

Actual	Before	Specified Range
-0°38'		-1°05' 0°25'
0 00		1°40' 3°10'
0°30'		0°02' 0°07'
0 00		11°50' 13°20'
		10°45' 13°45'

Camber Caster Toe SAI Included Angle Turning Angle Diff.

Front : Right					
Actual Before Specified Ran					
-1°21'		-1°05' 0°25'			
1 2.1		1°40' 3°10'			
2°23'		0°02' 0°07'			
2 20		11°50' 13°20'			
		10°45' 13°45'			

Front

Cross Camber Cross Caster Cross SAI **Total Toe** Cross Turn Diff.

Actual	Before	Specified Range
0°43'		-0°30' 0°30'
0.40		-0°30' 0°30'
		-0°30' 0°30'
2°53'		0°00' 0°19'

Rear : Left

Actual	Before	Specified Rang	
0°01'			
-0°14'			

Camber Toe

	Rear:	Right
Actual	Before	Specified Range
-0°10'		
0°10'		

Rear

Cross Camber Total Toe **Thrust Angle**

Actual	Before	Specified Range
0°11'		942
-0°05'		
-0°12"		



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	THE RESERVE OF THE PERSON NAMED IN	Ref: CS/UOI170223	
INITED OVERSEAS I	NSURANCE LTD	Ref : CS/UOI170223	005/Gqb112
B ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909		Date: 01-03-2018 Code: UOI2	
	Policy Particul	ars :- THIRD PARTY CLA	IM
Insured Veh.	SKM 3811H	Veh. Inspected	GBA 52X
Policy No.		Coverage (\$)	0.00
Claim No.	M11D02411712	Excess (\$)	0.00
Assign From	JENNY LEW	Assign Date	22/11/2017
2.	Vehicle P	articulars & Condition	
Make & Model	TOYOTA HIACE	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	JTFHT02P600001827	Colour	SILVER
Odometer	2	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3.	Cor	nditions of Tyres	
	Size	Make	Balance
R/H Front Tyre	195 R15	OHTSU	6 mm
L/H Front Tyre	195 R15	OHTSU	6 mm
R/H Rear Tyre	195 R15	OHTSU	6 mm
L/H Rear Tyre	195 R15	OHTSU	6 mm
4.		ription of Damages	
THE VEHICLE SI DUE TO COLLIS	USTAINED DAMAGES AT THI ION.	E O/S FRONT PORTION.THE	UNDERCARRIAGE AFFECTI
DAMAGES SEE			THE RESERVE OF THE PARTY OF THE
5.		neral Information	23/11/2017
Accident Date		Inspection Date	23/11/2017
Survey held at		TELIU	
	NO.18 DEFU AVENUE 2 SINGAPORE 539522		
5a.		Remarks	当 是在"集"的
A)THE INSPECT B)IN ACCORDA	ION WAS CONDUCTED ON A NCE TO YOUR INSTRUCTION	NS, WE HAVE NOT AUTHOR	ASIS. RISED REPAIRS.
5b.		mate Days of Repair	
ESTIMATED NO	RMAL PERIOD FOR REPAIR	6 Working D	ays



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBA 52X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER ASSY	CRACKED	1,886.00	623.10
11	FRONT BUMPER RIGHT BRACKET	DISTORTED	84.00	53.90
	FRONT BUMPER REINFORCEMENT	BENT	455.00	379.20
- 22	FRONT BONNET ASSY	TO REPAIR SEE LABOUR	2,618.00	-
1	FRONT BONNET LOCK MECHANISM	NOT NECESSARY	106.00	
	FRONT GRILLE ASSY	BROKEN	655.00	467.90
	FRONT RIGHT DOOR INNER PANEL	TO REPAIR SEE LABOUR	1,662.00	000000000000000000000000000000000000000
1	FRONT RIGHT HEADLAMP	CRACKED	1,675.00	
	FRONT RIGHT DOOR PANEL	BUCKLED	1,858.00	
	FRONT RIGHT DOOR HINGES	BENT	220.00	
	FRONT RIGHT DOOR LOWER STEP GARNISH	DEFORMED	267.00	228.10
	FRONT AIR-CON CONDENSER	NOT NECESSARY	1,211.00	
- 31	FRONT ABS MODULE UNIT	NOT NECESSARY	3,800.00	
4	FRONT WINDSCREEN GLASS MOULDING	NOT NECESSARY	288.00	No consei
4	FRONT RIGHT DOOR INNER BOARD	BROKEN	310.00	310.00
	FRONT RIGHT DOOR REGULATOR LINKAGE WITH MOTOR	NOT NECESSARY	480.00	
	FRONT RIGHT DOOR OUTER HANDLE	NOT NECESSARY	175.00	P
	FRONT RIGHT DOOR LOCK MECHANISM	NOT NECESSARY	225.00	P
128	FRONT RIGHT WING MIRROR ASSY	NOT NECESSARY	470.00	o
	FRONT RIGHT WHEEL RIM COVER	NOT NECESSARY	120.00	D .
13	FRONT RIGHT "A" PILLAR	BUCKLED	655.0	655.0
	FRONT RIGHT "B" PILLAR	NOT NECESSARY	850.0	0
	FRONT RIGHT KNUCKLE BALL JOINT	NOT NECESSARY	178.0	0
	FRONT RIGHT SHOCK ABSORBER	NOT NECESSARY	685.0	
	1 FRONT RIGHT LOWER ARM	NOT NECESSARY	421.0	0
	1 FRONT RIGHT UPPER ARM	NOT NECESSARY		(i)
	1 FRONT RIGHT KNUCKLE ARM	NOT NECESSARY		
	1 FRONT RIGHT WHEEL HUB BEARING	NOT NECESSARY		31
	1 FRONT RIGHT STABILIZER LINK	NOT NECESSARY		
	1 FRONT RIGHT TIE ROD	NOT NECESSARY	10.000	
	1 FRONT STABILIZER BAR	NOT NECESSARY	330.0	00

Report Ref No. CS/UOI17022305/Gqbn2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-5,838.75	-1,099.55
	LEGG 20% BIOGGGW		17,516.25	3,298.65
	SPECIAL NETT ITEMS			
12	FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
	FRONT GRILLE CLIPS (SN)	NECESSARY	30.00	30.00
1	FRONT AIR-CON GAS (SN)	NOT NECESSARY	80.00	-
1	FRONT RADIATOR COOLANT (SN)	NOT NECESSARY	80.00	-
1	FRONT BRAKE FLUID (SN)	NOT NECESSARY	50.00	1 -
1	FRONT RIGHT WHEEL RIM (SN)	NOT NECESSARY	450.00	-
1	FRONT RIGHT TYRE (SN)	NOT NECESSARY	300.00	1 1
1	FRONT RIGHT DOOR STICKER (SN)	CUT	30.00	
35	19 1 - 12 18 1 20 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		1,070.00	110.00
	LABOUR			
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN FRONT RIGHT AFFECTED AREA AND REPLACE ACCIDENT DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRONT BONNET ASSY AND FRONT RIGHT DOOR INNER PANEL.		1,400.00	600.00
	TO PUTTY AND SPRAY PAINTING FRONT RIGHT PORTION.		1,400.00	
	TO CHECK WIRING AND FOCUS FRONT HEADLAMP.		50.00	30.00
	TO REMOVE AND INSTALL AIR CON SYSTEM TO FACILITATE THE REPAIR AND REFILL GAS.	NOT NECESSARY	150.00	
	TO REMOVE AND INSTALL COOLING SYSTEM TO FACILITATE THE REPAIR AND CHECK FOR LEAKAGE.	NOT NECESSARY	150.00	
	TO REMOVE AND INSTALL FRONT BONNET LOCK MECHANISM.	NOT NECESSARY	60.00	
	TO APPLY ANTI RUST PROOFING TO FRONT RIGHT AFFECTED AREA.		100.0	
	TO TRANSFER FRONT RIGHT DOOR LOCK MECHANISM.		60.0	0
	TO REMOVE AND INSTALL FRONT RIGHT SIDE INNER GARNISH AND TRIM TO FACILITATE THE REPAIR.	NOT NECESSARY	120.0	
	TO TRANSFER FRONT RIGHT DOOR GLASS TO NEW DOOR.		60.0	
	TO CONDUCT WHEEL ALIGNMENT.		80.0	
	TO BALANCE FRONT RIGHT WHEEL.	NOT NECESSARY	50.0	
	TO REMOVE AND INSTALL FRONT RIGHT UNDERCARRIAGE PARTS.	NOT NECESSARY	250.0	
	TO REMOVE AND INSTALL FRONT BRAKE ABS MODULE UNIT.	NOT NECESSARY	150.0	

Report Ref No. CS/UOI17022305/Gqbn2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
100000	TO REMOVE AND INSTALL FRONT RIGHT CENTRAL LOCKING FOR FUNCTION.	NOT NECESSARY	60.00	-
	TOWING SERVICE.	NOT NECESSARY	100.00	31
			4,240.00	1,600.00
	GRAND TOTAL		22,826.25	5,008.65

RECOMMENDED COST OF LUMP SUM REPAIRS	4,000.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/UOI17022305/Gqbn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.