

ASS. REC. BY:

REF: CS/7CL17022340/RHber

Special Instruction:

Surveyor: Rahul

ASSIGNMENT (Office)

From (Person): CWS Serene Lee

of FCL

Date/Time: 23-11-2017 12:56pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: S6X 221U

Insured: SHD 6779G

at Workshop m/s 21 Autolink

Tel: 8444 8883

of 6D Manilai Estate #07-01

Policy No:

Claim No: D17010776MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 14-11-2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time: 23-11-2017 1:52pm

Person Contacted:

Kif

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	S6X 221U - CS/TP18018620 / Accl DCA: 030608
	SHD 6779G - X
	Unconfirm Lump Sum \$6000/- (Red: 65466.56; 90%)

Surveyor: Zame

REF:

0066J

COE XPRY: 2020/Dec

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGX 2214

at Workshop m/s 21, Autolink

of 65, MANNAI ESTATE # 07-01

Insured: FCU/UP

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

[Handwritten Diagram]	
N/S	O/S

Bal. or Market Value: 24K x 1K = 25K

IDAC Accident Rport: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SGX 2214 Yr Regn: 2005 / Dec

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: HONDA INTEGRA 2-0 c.c. 1998

Colour: PINK A/C: Insured / Std / NI / NA

Sp. Reading: 236028 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMOC 53506S 200323

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/45 R17

R: 2 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 14/11/17 D.O.I. 23/11/17

Survey held at Autolink

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

market value \$25,000-
LTA : \$18,100-
NETT VALUE \$6,900-

RECEIVED 23 MAY 2017

Date/Time, File Pass to? Preli. Report

1) 29/11 Typist Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 12

Resurvey No. of Trip: 1

Survey Fee:	62x15=930
Transportation:	170+930
	50
	50
	129
TOTAL	1329

Add Fee: Site Insp (\$ _____) S + RS _____

Interview (\$ _____) Photos _____

Tech. Invs (\$ _____) Others _____

Weekend (\$ _____) _____

Report Format: TP

Lump Sum / I.B.I: (\$) -



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17022340/R1tb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 23-11-2017	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 6779G	Veh. Inspected	SGX 221U
Policy No.		Coverage (\$)	0.00
Claim No.	D17010776MFSH	Excess (\$)	0.00
Assign From	CWS (SERENE LER)	Assign Date	23/11/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	14/11/2017	Inspection Date	23/11/2017
Survey held at	21 AUTOLINK PTE. LTD. 6D MANDAI ESTATE #07-01 M-SPACE SINGAPORE 729938		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

MOTOR SURVEY ASSIGNMENT

Date	20-11-2017	Our Ref No. D17010776MFSH
Accident Date	14-11-2017	Claim Type. Third Party
Insured Vehicle	SHD6779G	Third Party Vehicle. SGX221U
Survey Location	NO 6D MANDAI ESTATE#07-01 M-SPACE	
Contact Person.	KIF TAN	
Contact No.	62663821/ 84448883	Fax No. 62663321
Survey Type	WITHOUT PREJUDICE: NO EST. PROVIDED	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	21 AUTOLINK PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/230423)  PRI Documents  Close 

PRI Header Details

Claim No	D17010776MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & 21
Workshop Name	21 AUTOLINK PTE LTD (Contact Person : KIF TAN)	Survey Location & Contact Details	NO 6D MANDAI ESTATE#07-01 M-SPACE Mobile: 84448883 , Phone: 62663821 , Fax: EmailId: KIF.21AUTOLINK@GMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: NO EST. PROVIDED		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD6779G	TP Vehicle No	SGX22
PRI Recieved Date	22-11-2017 02:18:31 PM	Surveyor Appointed Date	23-11-2017 12:55:45 PM	Surveyor Accept Date	23-11-

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	23-11-2017	Upload Survey Report *:	<input type="text"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	----------------------

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name	Action
-----------	--------

Surveyor Job Remarks

D.O.A. 14/11/17

3 yrs 1.5 mths

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0066J
Vehicle Details	
Vehicle No.:	SGX221U
Vehicle to be Exported:	No
Intended De-registration Date:	20 Dec 2017
Vehicle Make:	HONDA
Vehicle Model:	INTEGRA 2.0M
Primary Colour:	Black
Manufacturing Year:	2005
Engine No.:	K20A35800256
Chassis No.:	JHMDC53506S200323
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$21,397.00
Original Registration Date:	31 Dec 2005
First Registration Date:	31 Dec 2005
Transfer Count:	3
Actual ARF Paid:	\$23,537.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	

COE Expiry Date:	30 Dec 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$29,899.00
COE Rebate Amount:	\$18,100.00
Total Rebate Amount:	\$18,100.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 20 Dec 2017

OK

Handwritten calculation:
 $24,000 + 1,000$
 $18,100$

 $59,000 + 1,000 = 60,000$

(Draft)

MSAT17151349 / Sng Ah Tee Motor & Panel Service Pte Ltd - Pioneer
ENTRY DATE & TIME: 15/11/2017 11:45

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 15/11/2017 11:45
Date Of Accident 14/11/2017 21:20
Exact Location Of Accident JURONG WEST ST 63 TO PIONEER RD NORTH
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SGX221U
Insured/Policyholder
Name Of Registered Owner TAN BOCK KIM
NRIC No S1270066J
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-92353997
Alternative Phone No Office-NOPHONE

Vehicle Particulars

Manufacturer HONDA
Model INTEGRA-2.0 GSR

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AXA INSURANCE PTE LTD
Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
Fleet Policy NO
Policy Number GA150993/1

Cover Note Number

Driver

Name of Driver TAN WEI ZHONG
NRIC No S87033271
Date Of Birth 23/01/1987
Occupation INDOOR
Date Of Driving Pass 14/02/2007
Driving Experience 10 YEARS AND 9 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-90927745
Fax Number
Contact Number

E Mail Address	NOEMAIL
Address	BLK 987B JURONG WEST ST 93 #05-567
Postcode	642987
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	JURONG WEST NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 700 CORPORATION ROAD , POSTCODE: 649818 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2689999 - FAX NO: 62672438
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER POLICE REPORT NO: T/20171114/2206

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD6779G
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name

Phone Number

Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA) I understand, acknowledge, agree and consent that :
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

I AM AWARE THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.


x

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

As per police report No: 7/2017/1114/mob.


Declaration


I/We declare the foregoing particulars are true in every respect.

Claim own policy
 Claim third party
 Claim OD/EP at other workshop TBA
 For record purpose

Policy No. PA 1509931
 Insurer AXA Veh.No. CGX 2211

X
Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

21 Autolink Pte Ltd

Co.Reg: 201621106W
 6D Mandai Estate
 #07-01 M-Space
 Singapore 729938
 Tel: (+65) 6266 3821 Fax(+65) 62663321



We serve WITH INTEGRITY

FIRST CAPITAL INSURANCE LIMITED
 36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877
 ATTN: MOTOR CLAIMS DEPARTMENT

Date: 12/13/2017
 Your Ref: PLS ADVISE
 Our Ref: 21-SGX221U-17
 Make: HONDA
 Model: INTERGA DC5

S/N	Description (Parts)	Qty	Unit price	Amount	Remarks
1	FRONT BUMPER	1	900	\$1,450.00	DE /
2	FRONT BUMPER SIDE RETAINER (LHS)	1	37.40	\$80.00	na /
3	FRONT BUMPER SIDE RETAINER (RHS)	1	37.40	\$80.00	na /
4	FRONT GRILLE	1	172.70	\$480.00	DE -
5	FRONT LOWER GRILLE	1		\$220.00	DE AN
6	FRONT EMBLEM "HONDA"	1	50	\$95.00	na /
7	FRONT FOG LAMP COVERS (LHS)	1	75.70	\$120.00	DE /
8	FRONT FOG LAMP COVERS (RHS)	1		\$120.00	X
9	FRONT FOG LAMP ASSY (LHS)	1		\$225.00	X
10	FRONT FOG LAMP ASSY (RHS)	1		\$225.00	X
11	FRONT WINDSCREEN	1		\$2,250.00	X
12	FRONT WINDSCREEN MOULDING	1		\$250.00	X
13	FRONT AFTER MARKET OPEN PODS HEAT GUARD	1		\$480.00	X AN
14	FRONT BUMPER LOWER PLASTICS GRILLE (CENTRE LHS)	1		\$90.00	X AN
15	FRONT BUMPER LOWER PLASTICS GRILLE (CENTRE RHS)	1		\$90.00	X
16	FRONT BUMPER LOWER PLASTICS GRILLE TOW HOOK COVER	1		\$50.00	X
17	FRONT SPORTS AFTER MARKET BODYKITS (MUGEN)	1	800 s/n	\$1,550.00	✓ X CR / s/w
18	FRONT AFTER MARKET OPEN PODS AIR CLEANER	1	200	\$1,200.00	✓ DE /
19	FRONT IMPACT SENSOR	1		\$144.00	X NA SU
20	FRONT REINFORCEMENT BAR	1	426.20	\$680.00	PT /
21	FRONT SUPPORT GUARD (BRACE PANEL)	1	90.70	\$2,550.00	PT /
22	FRONT TOP PANNEL	1	446	\$1,250.00	PT /
23	FRONT RENIFORCEMENT HOLDER (LHS)	1		\$120.00	PT X AN
24	FRONT RENIFORCEMENT HOLDER (RHS)	1		\$120.00	PT X AN
25	FRONT BUMPER NUTS AND SCREWS	1		\$180.00	X AN
26	FRONT MAIN FRAME (LHS) (CLASSIS)	1	380	\$2,550.00	PT /
27	FRONT AIR CON PIPES	1		\$120.00	X SU
28	FRONT OIL COOLER	1		\$1,550.00	AFTERMARKET X AN
29	FRONT RAIDATOR	1		\$1,200.00	PT /
30	FRONT RADIATOR HOSE	1 SETS		\$150.00	PT X SU
TOTAL PARTS (A)				\$19,639.00	

4010 110

21 Autolink Pte Ltd

Co.Reg: 201621106W

6D Mandai Estate

#07-01 M-Space

Singapore 729938

Tel: (+65) 6266 3821 Fax(+65) 62663321



we serve WITH INTEGRITY

FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

ATTN: MOTOR CLAIMS DEPARTMENT

Date: 12/13/2017

Your Ref: PLS ADVISE

Our Ref: 21-SGX221U-17

Make: HONDA

Model: INTERGA DCS

S/N	Description (Parts)	Qty	Unit price	Amount	Remarks
31	FRONT HEAD LAMPS BRACKETS (LHS)	1	154.20	\$1,580.00	PA/
32	FRONT HEAD LAMPS MOUNTINGS (LHS)	1		\$150.00	X 2 n1
33	FRONT SIDE MEMBER CONNECTING PIECE (LHS)	1		\$80.00	X 1
34	FRONT WHEEL ARCH PANNEL (LHS) (FENDER)	1	320	\$550.00	PA/
35	FRONT WHEEL ARCH PANNEL LOWER BRACKET (LHS)	1		\$80.00	na X n1
36	FRONT POWER STEERLING RESERVIOR BRACKETS (LHS)	1		\$65.00	X n1
37	FRONT WHEEL ARCH PANNEL BRACKETS (SIDE) (LHS)	1		\$250.00	na X 2 n1
38	FRONT CROSS MEMBER BRACKETS	1		\$80.00	PA X 1
39	FRONT WHEEL ARCH MAIN CONNECTING BRACKET	1		\$178.00	X n1
40	FRONT FENDER WATER DRAIN FUNNEL (washer tank)	1	46	\$90.00	PA/
41	FRONT FENDERS SIDE INDICATOR (LHS)	1		\$80.00	X 2 n1
42	FRONT FENDERS SIDE INDICATOR (RHS)	1		\$80.00	X 1 n1
43	FRONT BONNET HINGES (LHS)	1	28.80	\$120.00	bt/
44	FRONT BONNET HINGES (RHS)	1	28.80	\$120.00	PA/
45	FRONT SPORTS BONNET	1	900	\$1,450.00	na/
46	FRONT ENGINE STAND	1		\$95.00	X 2 n1
47	FRONT BONNET STAND CLIPS	1		\$12.00	X 2
48	FRONT BONNET SECURE HOOK	1	90.50	\$65.00	PA/
49	FRONT BONNET RELEASE LEVER HOUSING	1		\$180.00	PA/
50	FRONT LOCK STRIKER	1		\$82.00	PA/
51	FRONT BONNET LATCH ASSY	1	80	\$155.00	PA/
52	FRONT CABLE CLIPS	1		\$20.00	X 1
53	FRONT BONNET CABLE	1		\$90.00	X 1
54	FRONT POWER STEERLING PUMP	1		\$1,050.00	X 1
55	FRONT ALTERNATOR	1		\$980.00	X 1
56	FRONT AIR CON COMPRESSOR	1		\$550.00	X 1
57	FRONT FAN BELT	1		\$80.00	X 1
58	FRONT GEAR BOX	1		\$2,550.00	X 1
59	FRONT LOWER CROSS MEMBER ASSY	1		\$3,500.00	X 1
60	FRONT POWER STEERLING RACK ASSY	1		\$2,500.00	X 1
61	FRONT HEADLAMP ASSY(RHS)	1	373	\$1,550.00	PA/

TOTAL PARTS (B)

\$18,382.00

2063.30

21 Autolink Pte Ltd

Co.Reg: 201621106W

6D Mandai Estate

Singapore 729938

Tel: (+65) 6266 3821 Fax(+65) 62663321



We serve WITH INTEGRITY

FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
SINGAPORE 068877
ATTN: MOTOR CLAIMS DEPARTMENT

Date: 12/13/2017
Your Ref: PLS ADVISE
Make: HONDA
Model: INTERGA DC5

S/N	Description (Parts)	Qty	Unit price	Amount	Remarks
62	AIR CON GASKET	1		\$8.00	X } mn
63	FRONT AIR .CON DISTRIBUTION HOUSING	1		\$550.00	X } mn
64	FRONT AIR CLEANER INTAKE DUCT	1		\$155.00	DE ✓
65	FRONT AIR CON DUCT HOLDER BRACKETS	1		\$8.00	Bf ✓
66	FRONT AIR CLEANER INTAKE DUCT HOUSING	1		\$95.00	DE ✓
67	AIR CON FAN MOTOR	1	262170	\$1,550.00	*. mn ✓
68	AIR CON HOSE	1		\$185.00	X
69	AIR CON DRYER	1		\$155.00	X
70	AIR CON O RING SETS	1		\$3.00	X
71	AIR CON HEAT EXCHANGER	1		\$255.00	X
72	AIR CON HEAT EXCHANGER HOLDER BRACKETS	1		\$80.00	X
73	AIR CON HEAT EXCHANGER PIPE SETS	1		\$33.00	X
74	FRONT SERVO MOTOR	1		\$1,550.00	X
75	TEMPERTURE SENSOR	1		\$233.00	X } mn
76	WATER DRAIN VALVE	1		\$80.00	X
77	FRONT ENGINE SOUND PROOF ASSY	1		\$180.00	X
78	FRONT FUEL RAIL	1		\$365.00	X
79	FRONT FUEL REGUALTOR	1		\$180.00	X
80	FRONT INTAKE MANIFOLD	1		\$1,850.00	X
81	FRONT AFTER MARKET THROTTLE BODY (S90)	1		\$550.00	X
82	FRONT NUMBER PLATE	1		\$80.00	'Bao } 95 s/n
83	FRONT NUMBER PLATE HOLDER	1		\$50.00	
84	ENGINE OVERHAUL KITS	1		\$3,500.00	X
85	ENGINE MOUNTING ASSY SETS	1		\$1,050.00	X
86	GEARBOX MOUNTING ASSY SETS	1		\$350.00	X
87	FULL UPPER LOWER WHEEL ASSY (LHS)	1		\$1,750.00	X } mn
88	FULL UPPER LOWER WHEEL ASSY (RHS)	1		\$1,750.00	X } mn
90	FRONT LOWER OIL SUMP	1		\$250.00	X
91	FRONT ALL NECESSARY OIL COOLANT GASKET SEALANT	1		\$1,000.00	X

AIR-CON CONDENSOR - 688.20 71/ ✓ **TOTAL PARTS (C) \$17,845.00**

1208.90

s/n 835

21 Autolink Pte Ltd

Co.Reg: 201621106W

#07-01 M-Space

Singapore 729938



We serve WITH INTEGRITY

LKK

FIRST CAPITAL INSURANCE LIMITED

Date: 12/13/2017

#16-01 CITY HOUSE

Our Ref: 21-SGX221U-17

SINGAPORE 068877

Make: HONDA

ATTN: MOTOR CLAIMS DEPARTMENT

Model: INTERGA DC5

S/N	Description (LABOUR)	Qty	Unit price	Amount	Remarks
01	TO CUT / REPLACE / PULL / WELD / SPOT WELD / ALIGHT / PANNEL BEAT / FRONT ACCIDENT AFFECTED AREA			\$5,000.00	1000
02	TO PUTTY /PRIMEER /PAINT REAR ACCIDENT AFFECTED AREA			\$2,500.00	SPECIAL PAINT } 1000
03	TO PUTTY /PRIMEER / PAINT REAR INNER ACCIDENT AFFECTED AREA			\$1,200.00	
04	TO REMOVE AND REFIX MAIN FRAME CHASSIS			\$1,500.00	150
05	LABOUR FEES FOR OVERHUAL ENGINE INTERNAL			\$1,800.00	X n
06	LABOUR FEES FOR REPLACE GEAR BOX			\$650.00	X n
06	LABOUR TO REMOVE LOWER CROSSMEMBER			\$480.00	X n
08	TO REMOVE AND REFIT REAR WINDSCREEN			\$300.00	X n
09	LABOUR FEES TO REPAIR /REFIX/ REPLACE FRONT MAIN WIRE			\$800.00	60
10	TUFF KOTE			\$250.00	100
11	TO PROVIDE WHEEL ALIGHTMENT			\$120.00	60
12	OBD SCANNINGS (TO RESET ERROR CODE)			\$150.00	X n
13	LABOUR FEES FOR SPECIAL CPU PROGRAMMING			\$1,200.00	X n

TOTAL LABOUR	\$15,950.00
TOTAL PARTS	\$55,866.00
GRAND TOTAL	\$71,816.00

2370

72366.52

KIF TAN G.K

KIF TAN G.K
21 AUTOLINK PTE LTD
Operation Manager

*Rasul
Hp 90010068*

12 days

HS

23/11/17 @ 1630

Recovery after repair

7282.30

20%

5825.84

72504.20

Repair limit 6K

5825.84

835.00

2370.00

9030.84

20%

7224.67

12 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17022340/R1tbe2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 29-01-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 6779G	Veh. Inspected	SGX 221U
Policy No.	D-15072701MFSH	Coverage (\$)	0.00
Claim No.	D17010776MFSH	Excess (\$)	0.00
Assign From	SERENE LER	Assign Date	23/11/2017
2. Vehicle Particulars & Condition			
Make & Model	HONDA INTEGRA 2.0	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2005
Chassis No.	JHMDC53506S200323	Colour	PINK
Odometer	236028	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/45 R17	BRIDGESTONE	6 mm
L/H Front Tyre	235/45 R17	BRIDGESTONE	6 mm
R/H Rear Tyre	235/45 R17	BRIDGESTONE	6 mm
L/H Rear Tyre	235/45 R17	BRIDGESTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	14/11/2017	Inspection Date	23/11/2017
Survey held at	21 AUTOLINK PTE. LTD. 6D MANDAI ESTATE #07-01 M-SPACE SINGAPORE 729938		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGX 221U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED	1,450.00	900.00
1	FRONT BUMPER SIDE RETAINER (LHS)	NECESSARY	80.00	37.40
1	FRONT BUMPER SIDE RETAINER (RHS)	NECESSARY	80.00	37.40
1	FRONT GRILLE	DEFORMED	450.00	172.70
1	FRONT LOWER GRILLE	NOT NECESSARY	220.00	-
1	FRONT EMBLEM "HONDA"	NECESSARY	95.00	50.00
1	FRONT FOG LAMP COVERS (LHS)	DEFORMED	120.00	75.70
1	FRONT FOG LAMP COVERS (RHS)	NOT NECESSARY	120.00	-
1	FRONT FOG LAMP ASSY (LHS)	NOT NECESSARY	225.00	-
1	FRONT FOG LAMP ASSY (RHS)	NOT NECESSARY	225.00	-
1	FRONT WINDSCREEN	NOT NECESSARY	2,250.00	-
1	FRONT WINDSCREEN MOULDING	NOT NECESSARY	250.00	-
1	FRONT FATER MARKET OPEN PODS HEAT GUARD	NOT NECESSARY	480.00	-
1	FRONT BUMPER LOWER PLASTICS GRILLE (CENTRE LHS)	NOT NECESSARY	90.00	-
1	FRONT BUMPER LOWER PLASTICS GRILLE (CENTRE RHS)	NOT NECESSARY	90.00	-
1	FRONT BUMPER LOWER PLASTICS GRILLE TOW HOOK COVER	NOT NECESSARY	50.00	-
1	FRONT AFTER MARKET OPEN PODS AIR CLEANER	DEFORMED	1,200.00	200.00
1	FRONT IMPACT SENSOR	SERVICEABLE	144.00	-
1	FRONT REINFORCEMENT BAR	BENT	680.00	426.20
1	FRONT SUPPORT GUARD (BRACE PANEL)	BENT	2,550.00	90.70
1	FRONT TOP PANNEL	BENT	1,250.00	440.00
1	FRONT REINFORCEMENT HOLDER (LHS)	NOT NECESSARY	120.00	-
1	FRONT REINFORCEMENT HOLDER (RHS)	NOT NECESSARY	120.00	-
1	FRONT BUMPER NUTS AND SCREWS	NOT NECESSARY	180.00	-
1	FRONT MAIN FRAME (LHS) (CHASSIS)	BENT	2,550.00	380.00
1	FRONT AIR CON PIPES	SERVICEABLE	120.00	-
1	FRONT OIL COOLER	NOT NECESSARY	1,550.00	-
1	FRONT RADIATOR	BENT	1,200.00	1,200.00
1	SETS FRONT RADIATOR HOSE	SERVICEABLE	150.00	-

Report Ref No. CS/FCI17022340/R1tbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT HEAD LAMPS BRACKETS (LHS)	BENT	1,550.00	154.20
1	FRONT HEAD LAMPS MOUNTINGS (LHS)	NOT NECESSARY	150.00	-
1	FRONT SIDE MEMBER CONNECTING PIECE (LHS)	NOT NECESSARY	80.00	-
1	FRONT WHEEL ARCH PANNEL (LHS) (FENDER)	BENT	550.00	320.00
1	FRONT WHEEL ARCH PANNEL LOWER BRACKET (LHS)	NOT NECESSARY	80.00	-
1	FRONT POWER STEERLING RESERVIOR BRACKETS (LHS)	NOT NECESSARY	65.00	-
1	FRONT WHEEL ARCH PANNEL BRACKETS (SIDE) (LHS)	NOT NECESSARY	250.00	-
1	FRONT CROSS MEMBER BRACKETS	NOT NECESSARY	80.00	-
1	FRONT WHEEL ARCH MAIN CONNECTING BRACKET	NOT NECESSARY	178.00	-
1	FRONT FENDER WATER DRAIN FUNNEL (WASHER TANK)	CRACKED	90.00	46.00
1	FRONT FENDERS SIDE INDICATOR (LHS)	NOT NECESSARY	80.00	-
1	FRONT FENDERS SIDE INDICATOR (RHS)	NOT NECESSARY	80.00	-
1	FRONT BONNET HINGES (LHS)	BENT	120.00	28.80
1	FRONT BONNET HINGES (RHS)	BENT	120.00	28.80
1	FRONT SPORTS BONNET	BUCKLED	1,450.00	900.00
1	FRONT ENGINE STAND	NOT NECESSARY	95.00	-
1	FRONT BONNET STAND CLIPS	NOT NECESSARY	12.00	-
1	FRONT BONNET SECURE HOOK }	BENT	65.00	90.50
1	FRONT BONNET RELEASE LEVER HOUSING }	BENT	180.00	-
1	FRONT LOCK STRIKER	BENT	82.00	82.00
1	FRONT BONNET LATCH ASSY	BENT	155.00	80.00
1	FRONT CABLE CLIPS	NOT NECESSARY	20.00	-
1	FRONT BONNET CABLE	NOT NECESSARY	90.00	-
1	FRONT POWER STEERLING PUMP	NOT NECESSARY	1,050.00	-
1	FRONT ALTERNATOR	NOT NECESSARY	980.00	-
1	FRONT AIR CON COMPRESSOR	NOT NECESSARY	550.00	-
1	FRONT FAN BELT	NOT NECESSARY	80.00	-
1	FRONT GEAR BOX	NOT NECESSARY	2,550.00	-
1	FRONT LOWER CROSS MEMBER ASSY	NOT NECESSARY	3,500.00	-
1	FRONT POWER STEERLING RACK ASSY	NOT NECESSARY	2,500.00	-
1	FRONT HEADLAMP ASSY (RHS)	CRACKED	1,550.00	333.00
1	AIR CON GASKET	NOT NECESSARY	8.00	-

Report Ref No. CS/FCI17022340/R1tbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT AIR CON DISTRIBUTION HOUSING	NOT NECESSARY	550.00	-
1	FRONT AIR CLEANER INTAKE DUCT	DEFORMED	155.00	155.00
1	FRONT AIR CON DUCT HOLDER BRACKETS	BENT	8.00	8.00
1	FRONT AIR CLEANER INTAKE DUCT HOUSING	DEFORMED	95.00	95.00
1	AIR CON FAN MOTOR	NOT WORKING	1,550.00	262.70
1	AIR CON HOSE	NOT NECESSARY	185.00	-
1	AIR CON DRYER	NOT NECESSARY	155.00	-
1	SETS AIR CON O RING	NOT NECESSARY	3.00	-
1	AIR CON HEAT EXCHANGER	NOT NECESSARY	255.00	-
1	AIR CON HEAT EXCHANGER HOLDER BRACKETS	NOT NECESSARY	80.00	-
1	SETS AIR CON HEAT EXCHANGER PIPE	NOT NECESSARY	33.00	-
1	FRONT SERVO MOTOR	NOT NECESSARY	1,550.00	-
1	TEMPERATURE SENSOR	NOT NECESSARY	233.00	-
1	WATER DRAIN VALVE	NOT NECESSARY	80.00	-
1	FRONT ENGINE SOUND PROOF ASSY	NOT NECESSARY	180.00	-
1	FRONT FUEL RAIL	NOT NECESSARY	365.00	-
1	FRONT FUEL REGULATOR	NOT NECESSARY	180.00	-
1	FRONT INTAKE MANIFOLD	NOT NECESSARY	1,850.00	-
1	FRONT AFTER MARKET THROTTLE BODY (S90)	NOT NECESSARY	550.00	-
1	ENGINE OVERHAUL KITS	NOT NECESSARY	3,500.00	-
1	SETS ENGINE MOUNTING ASSY	NOT NECESSARY	1,050.00	-
1	SETS GEARBOX MOUNTING ASSY	NOT NECESSARY	350.00	-
1	FULL UPPER LOWER WHEEL ASSY (LHS)	NOT NECESSARY	1,750.00	-
1	FULL UPPER LOWER WHEEL ASSY (RHS)	NOT NECESSARY	1,750.00	-
1	FRONT LOWER OIL SUMP	NOT NECESSARY	250.00	-
1	FRONT ALL NECESSARY OIL COOLANT GASKET SEALANT	NOT NECESSARY	1,000.00	-
1	AIR CON CONDENSOR	BENT	688.20	688.20
	LESS 20% DISCOUNT		-	-1,456.46
			54,874.20	5,825.84
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT SPORTS AFTER MARKET BODYKITS (MUGEN) (SN)	CRACKED	1,550.00	800.00

Report Ref No. CS/FCI17022340/R1tbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT NUMBER PLATE (SN) }	BROKEN	80.00	35.00
1	FRONT NUMBER PLATE HOLDER (SN) }		50.00	-
			1,680.00	835.00
	LABOUR			
	TO CUT / REPLACE / PULL / WELD / SPOT WELD / ALIGHT / PANNEL BEAT / FRONT ACCIDENT AFFECTED AREA.		5,000.00	1,000.00
	TO PUTTY / PRIMEER / PAINT REAR ACCIDENT AFFECTED AREA. }		2,500.00	1,000.00
	TO PUTTY / PRIMEER / PAINT REAR INNER ACCIDENT AFFECTED AREA. }		1,200.00	-
	TO REMOVE AND REFIX MAIN FRAME CHASSIS.		1,500.00	150.00
	LABOUR FEES FOR OVERHUAL ENGINE INTERNAL.	NOT NECESSARY	1,800.00	-
	LABOUR FEES FOR REPLACE GEAR BOX.	NOT NECESSARY	650.00	-
	LABOUR TO REMOVE LOWER CROSSMEMBER.	NOT NECESSARY	480.00	-
	TO REMOVE AND REFIT REAR WINDSCREEN.	NOT NECESSARY	300.00	-
	LABOUR FEES TO REPAIR / REFIX / REPLACE FRONT MAIN WIRE.		800.00	60.00
	TUFF KOTE.		250.00	100.00
	TO PROVIDE WHEEL ALIGHTMENT.		120.00	60.00
	OBD SCANNINGS (TO RESET ERROR CODE)	NOT NECESSARY	150.00	-
	LABOUR FEES FOR SPECIAL CPU PROGRAMMING.	NOT NECESSARY	1,200.00	-
			15,950.00	2,370.00
	GRAND TOTAL		72,504.20	9,030.84

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (UN-CONFIRMED)				6,000.00
--	--	--	--	-----------------

Report Ref No. CS/FC117022340/R1tbe2

MARKET VALUE: \$25,000.00(EST)-LTA REIMBURSEMENT VALUE: \$18,100.00=NETT VALUE: \$6,900.00

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.