



Your Ref : S7M004KU

Date: 13th December 2017

Our Ref : CS/AXA17022355/Uqbs2

M/s AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811
(The Motor Claims Department)

Attn: Jas Tan

Dear Sir/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE EW 8382P
ACCIDENT ON 01/11/2017**

Instruction was received to inspect the vehicle Reg. No. EW 8382P. The inspection was conducted on 23/11/2017 at the premises of M/s SME Motor Pte Ltd, 1 Kaki Bukit Ave 6 #02-15 (Autobay @Kaki Bukit) Singapore 417883.

The following information was recorded: -

Registration Number	: EW 8382P
Make & Model	: Honda Odyssey 2.4A
Year of Registration	: 2006
Body Colour	: Grey
Chassis Number	: JHMRB18506C200740
Engine Capacity	: 2354cc
Speedometer Reading	: Burnt

The vehicle caught fire. (Details see photographs enclosed).

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as "**Total Loss**".

Market Value (est)	S\$ 57,000.00
Less: LTA Reimbursement Value (RV)	(S\$ 42,210.00)
Nett Liability	<u>S\$ 14,790.00</u>

Vehicle Inspected By:



CHUA KANG SENG
Licensed Appraiser



K.K. LAU
*MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),
AM CATARI(CAN), M. MATA(USA), M. MdATA(USA),
Licensed Appraiser*

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.