


GOLDBELL
ENGINEERING

 Industrial Vehicles.
 20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894

Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)

Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)

Website: www.goldbell.com.sg

Co. Reg. No.: 198003963G

 INSURER: **AIG Asia Pacific Insurance Pte. Ltd. (SG)**
PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	GBE/SVC/SALES-4473/171101
Policy No:	1700045623	Date of Loss:	20/10/2017
Vehicle Reg. No.:	YN4105K	Driveable?	
Driver Age/Info:	37 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	C K DEPARTMENT STORE	Contact No:	+6594492526
Driver:	SHI JIANGUO		
Make/Model:	MITSUBISHI CANTER, 3.0 D FEB71ER4SDEC (CBU) (M)	Vehicle Reg. Date:	19/09/2013
Vehicle Colour:	WHITE	Chassis No:	FEC91HA00003
Engine No:	4P10A14604		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	15		
Description of Accident/Loss	HIT BY LORRY CRANE REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE AUTOMOTIVE PTE LTD TEL 6741 5336		

Tanjin 97495749
Ex : to be advise.
** Resurvey new parts*
23/11/17 @ 1615
12 days. 'Revert'

 Remarks: **VEHICLE AT 29 TANJONG PENJURU (S) 609026**

Present Location: GOLDBELL ENGINEERING PTE LTD (TUAS)

COST OF CLAIMS

Parts		Amount
Miscellaneous Items		
Labour		
Paintwork Labour		
Towing		
	Calculated Gross Total (S\$)	22,760.00
	- Excess (S\$)	1,000.00
	Nett Amount (S\$)	21,760.00

LKK Auto Consultants' hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

 This claim is handled by: **WILLIAM GO SHAN CHAN - 97557336**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source:	(Last Synchronised: 22 Nov 2017)	
Parts:	N/A	MITSUBISHI CANTER 3.0 D FEB71ER4SDEC (CBU) (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Goldbell Engineering Pte Ltd/YN4105K/22/11/2017 17:02	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*CARGOBOX FRONT PANEL <i>bt</i>	0	0.00	*800.00 FS
2	1		*CARGOBOX FRONT PANEL SIDE PILLAR LHS <i>bt</i>	0	0.00	*850.00 FS
3	1		*CARGOBOX ROOF PANEL <i>huc</i>	0	0.00	*2,800.00 FS
4	5		*CARGOBOX ROOF RAILING HORIZONTAL BAR <i>bt</i>	0	0.00	*3,250.00 FS
5	4		*CARGOBOX ROOF RAILING VERTICAL BAR <i>?</i>	0	0.00	*1,800.00 FS
6	1		*CARGOBOX ROOF SIDE RAILING <i>bt</i>	0	0.00	*900.00 FS
7	1		*CARGOBOX ROOF SIDE J-BAR <i>bt</i>	0	0.00	*650.00 FS
8	1		*CARGOBOX ROOF FRONT J-BAR <i>bt</i>	0	0.00	*500.00 FS
9	1		*CARGOBOX SLIDING DOOR LHS <i>?</i>	0	0.00	*2,000.00 FS
10	1		*CARGOBOX SIDE PANEL LHS <i>bt</i>	0	0.00	*2,000.00 FS
11	1		*COMPANY STICKER <i>nel</i>	0	0.00	*800.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **16,350.00**

Goldbell Engineering Pte Ltd/YN4105K/22/11/2017 17:02. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REMOVE, REFIX & REALIGN REAR CARGOBOX ASSY. TO REPLACE ALL DAMAGED PARTS	New	4,200.00
2	TO PUTTY, CLEAN SPRAY PAINT & POLISH, ETC.	New	2,100.00
3	SUNDRIES	New	100.00
Gross Labour Cost (S\$)			6,400.00

Goldbell Engineering Pte Ltd/YN4105K/22/11/2017 17:02. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >