



Lim Tan Motor Pte Ltd

Block 176 Sin Ming Drive # 03-09/10/06 Sin Ming Autocare Singapore 575721

Tel : 65-64520893 Fax : 65-64589127 Email : sales@ltm.sg

Website : www.ltm.sg

Co.Reg No. : 199307277D GST Reg No. : M2-0119086-0

Survey By : _____

INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)**

Date / Time : **24 NOV 2017 , 10.30am**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	B28636916MKC	Date of Loss:	20/11/2017
Vehicle Reg. No.:	GBC2955S	Driveable?	
Driver Age/Info:	50 / MALE / OTHERS: -	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	NO
Insured/Claimant:	P.I.L CONSORTIUM PTE LTD	Contact No:	+6588766759
Driver:	LOW KHENG LEE		

Make/Model:	MITSUBISHI FB70BB1SRDEA, 3.0 D (M)	Vehicle Reg. Date:	21/11/2011
-------------	------------------------------------	--------------------	------------

Vehicle Colour: White

Engine No: 4M42A89379

Odometer: 261782 KM

RM

Chassis No: FB70BBA20428

Paint Type:

Total Loss? NO

Est. Duration of Repair (day) *45 9 days*



*Not Authored
1. B1*

*Resurvey by point ex @ 750
Fax: 82564315*

Description of Accident/Loss: AS PER ATTACHED POLICE REPORT. (REPORT NO. T/20171120/2038) ON 19/11/2017 AT ABOUT 2315HRS, I PARKED MY COMPANY LORRY OF PLATE NUMBER GBC2955S AT BLOCK 163 ANG MO KIO AVENUE 4 AT LOT 86, EVERYTHING WAS INTACT AT THAT POINT OF TIME. ON 20/11/2017 AT ABOUT 0445HRS, WHILE I WAS GOING TO MY LORRY, I DISCOVERED THAT THE LEFT PORTION AREA INCLUDE THE WINDSCREEN WAS CRACKED AND DENTED. NO ONE LEFT ANY NOTE BEHIND AND I BELIEVED SOMEONE HAS HIT AND RUN. I DO NOT HAVE IN CAR CAMERA IN MY LORRY AND THE SAID CAR PARK ELECTRONIC PARKING HAS BEEN INSTALLED BUT HAS NOT BE ACTIVATED YET. I HAVE NO SUSPECT IN MIND. AT ABOUT 1115HRS, TP CAME AND TOOK PHOTOS OF THE SCENE. THE TP OFFICER THAN GAVE ME A CASE CARD TO LODGE A TRAFFIC REPORT UNDER TP SIO JEMY, 65476213. I AM LODGING THE IS TRAFFIC REPORT FOR ASSISTANCE. THAT'S ALL.

Present Location: LIM TAN MOTOR PTE LTD (HQ)

COST OF CLAIMS	Amount
Parts	9,499.90
Miscellaneous Items	0.00
Labour	1,720.00
Paintwork Labour	1,000.00
Towing	0.00
Calculated Gross Total (\$\$)	12,219.90

- Excess (S\$)	750.00
(S\$)	11,469.90
+ GST 7.00% (S\$)	802.89
Nett Amount (S\$)	12,272.79

This claim is handled by: MANDY LIM

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 23 Nov 2017)
Parts: N/A MITSUBISHI FB70BB1SRDEA 3.0 D (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Lim Tan Motor Pte Ltd/GBC2955S/23/11/2017 10:34
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BUMPER	B ₁ 0.00	0.00	*400.00 F	✓
2	2		*FRONT BUMPER BRACKET	B ₁ 0.00	0.00	*110.00 F	✓
3	1		*FRONT GRILLE	0.00	0.00	*320.00 F	
4	1		*FRONT PANEL	B ₁ 0.00	0.00	*480.00 F	✓
5	1		*N/S FRONT CORNER PANEL	B ₁ 0.00	0.00	*260.00 F	✓
6	1		*FRONT WIPER GARNISH	CM 0.00	0.00	*280.00 F	✓
7	1		*FRONT WIPER GARNISH CANTER STICKER	0.00	0.00	*65.00 F	✓
8	1		*FRONT WINDSCREEN GLASS	CM 0.00	0.00	*380.00 F	✓
9	1		*FRONT WINDSCREEN RUBBER	0.00	0.00	*160.00 F	✓
10	1		*N/S FRONT WING MIRROR BRACKET COVER	CM 0.00	0.00	*32.00 F	✓
11	1		*N/S FRONT WING MIRROR ROUND	0.00	0.00	*15.00 F	✓
12	1		*N/S FRONT SIDE LAMP	B ₁ 0.00	0.00	*105.00 F	✓
13	1		*N/S FRONT SIGNAL LAMP	B ₁ 0.00	0.00	*130.00 F	✓
14	1		*N/S HEADLAMP	B ₁ 0.00	0.00	*350.00 F	✓
15	1		*N/S HEADLAMP LOWER RUBBER	0.00	0.00	*12.00 F	✓
16	1		*N/S FRONT DOOR	B ₁ 0.00	0.00	*900.00 F	✓
17	1		*N/S FRONT DOOR INNER LOCK	0.00	0.00	*530.00 F	?
18	2		*N/S FRONT DOOR HINGES	R 0.00	0.00	*320.00 F	X
19	1		*N/S FRONT DOOR STEP GARNISH	CM 0.00	0.00	*250.00 F	✓
20	1		*N/S FRONT DOOR ARCH GARNISH	0.00	0.00	*40.00 F	?
21	1		*FRONT CABIN SUB-TUBE	0.00	0.00	*150.00 F	?
22	1		*FRONT CABIN SUB-SHAFT	0.00	0.00	*660.00 F	?
23	1		*AIR-CON BLOWER MOTOR	0.00	0.00	*700.00 F	?
24	1		*AIR-CON COOLING COIL UNIT	0.00	0.00	*1,500.00 F	?
25	1		*N/S FRONT DOOR CHECK	R 0.00	0.00	*40.00 F	X
26	1		*FRONT CABIN SUB-TAKE MOUNTING	0.00	0.00	*420.00 F	?
27	1		*FRONT WINDSCREEN IU BRACKET	0.00	0.00	*15.00 FS	✓
28	1		*N/S FRONT DOOR BODY LETTERING	0.00	0.00	*15.00 FS	✓

F=Franchise part. S=SpcNett.

Sub Total (S\$)	8,639.00
+ Margin on L,N Items 10.00% (S\$)	860.90
Total Parts (S\$)	9,499.90

Lim Tan Motor Pte Ltd/GBC2955S/23/11/2017 10:34. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO PUTTY AND SPRAY PAINTING.	New	1,000.00
<u>Labour Items</u>			
2	TO REPLACE FRONT WINDSCREEN GLASS.	New	100.00
3	TO REMOVE AND REFIX FRONT DASHBOARD ASSY. REPLACE AIR-CON BLOWER UNIT AND COOLING COIL UNIT.	New	380.00
4	TO TRANSFER DOOR FITTINGS.	New	40.00
5	LABOUR CHARGES.	New	1,200.00
Gross Labour Cost (S\$)			2,720.00

7200
601
3300
✓
10000

Lim Tan Motor Pte Ltd/GBC2955S/23/11/2017 10:34. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >