

ASS. REC. BY:

REF:

CS3/AG/707746/Gb2

Special Instruction:

SURVEYOR
MUMUKH

Gno Ramp

ASSIGNMENT (Office)

From (Person):

Chin Lee Yung

of

AG

Date/Time:

24/11/17 @ 10.39am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SCM 88860

Insured:

SLM 5280P

at Workshop m/s

Aldrin Automotive

Tel:

6846 9707

of

1 KAFI BUKIT AVE 6 # 02-22

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

14/11/17

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SCM 88860 Y
	SLM 5280P X
	Dismantle Part: 27.11.2017
	After repair: 28.11.2017

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt.: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or NoLum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: _____

Types: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: _____

Colour: _____

Sp. Reading: _____

Eng. No: _____

C. No: _____

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

R/Bal. _____

L/Bal. _____

D.O.A. _____

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 2018

Date/Time. File Pass to?

☐

Preli. Report

☐

Final Report

1) 06-03-2018

Date/Time. File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

) S + RS. Si

Photos

Others

TOTAL

Report Format: PRS.

Lump Sum / I.B.I.: (\$ _____)

Add Fee:

☐

Site Insp (\$ _____)

☐

Interview (\$ _____)

☐

Tech. Insp (\$ _____)

☐

Weekend (\$ _____)

180

20

200



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG17022416/Gb

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 24-11-2017



Code : AIG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLM 5280P	Veh. Inspected	SCM 8886D
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	24/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	14/11/2017	Inspection Date	24/11/2017
Survey held at	ALDRIN AUTOMOTIVE NO.1 KAKI BUKIT AVENUE 6 #02-22 AUTOBAY @KAKI BUKIT SINGAPORE 417883.		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

**- FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED
VEHICLE SLM5280P AND SCM8886D ON 14/11/2017**

From: Chin, Lee-Ying

To: 'assignments', 'Admin A'

Cc: Fong, Andy-SY, Fan, Winnie-LW

Sent: Friday, 24 November, 2017 10:39:28 AM

Attachments:  FaxF214.tif  (AA)SCM8886D - Notice to AIG to conduct PRI.PDF

Hi LKK,

Kindly assist to survey, vehicle in.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

Lee-Ying.Chin@aig.com | www.aig.com.sg

Our Ref : CY(AA)SCM8886D(AC)hh
Please email to helen@yoga-legal.com
Your Ref : Your insured vehicle SLM5280P

20th November 2017

The Motor Claims Department
AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #07-16
Singapore 079120

By Email

Dear Sirs

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION
ACCIDENT INVOLVING SCM8886D & SLM5280P ON 14/11/2017 @ 22:35 HRS
ALONG SENGKANG EAST ROAD

We refer to your email of even date.

Please be informed that we are not agreeable to your proposed motor surveyors. Instead we propose Mr. Alan Cheong K.H. of M/s. C L Appraiser Pte Ltd to conduct a Pre-Repair inspection.

Please be informed that the said vehicle can be inspected at:

Name of workshop : M/s. Aldrin Automotive
Address : 1 Kaki Bukit Avenue 6 #02-22
AutoBay @ Kaki Bukit, Singapore 417883
Contact person : Kelvin
Telephone number : 68469707 Fax number : 67535346

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our abovenamed motor surveyor you will be deemed to have agreed as a "single joint expert".

If you object to our motor surveyor, we will accordingly inform the claimant to instruct his choice of motor Surveyor to conduct the pre-repair survey.

Yours faithfully,


C. Yogarajah LLC

c.c. client
Poon Kok Meng
c/o M/s. Aldrin Automotive
(By Fax: 67535346)

For Surveyor

Please initial here after completion of pre-repair inspection.
Thank you.

Name:
Signature:

Date & Time of Pre-repair inspection: /

Survey Department Check List (Case Handler)

Reference No.:

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are ACCURATE

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (inspected)
- C Veh No (insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/PEP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RS), TM , MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

--

--

Case Handler Date

*C: Critical *N: Non-Critical

(01)Bent (2)Dented (3)Distorted (4)Cracked (5)Cut (6)Scratched
(07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary
(12)Missing (13)Torn (14)Unconfirmed (15)Not Working

MOTORCAR (Rear)

(1)Replace (✓) (2)Repair(R) (3)Check (C)
(4)Not Consistent (NC)

Rear Portion

Vehicle No: **SCM 88860**

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate	BT	/	
1138	993627	Rear Number Plate Base	RE	/	
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp	CPA	/	2
1141	992958	Rear Bumper	RE	/	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NC	/	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	NC	/	2
1149	993045	Rear Bumper Reinforcement	BT	/	
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper Garnish	RE	/	
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Speaker Garnish	RE	/	
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel	REPAIR		
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim Sensor	NW	/	
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	REPAIR		
1171	991328	Bootlid Emblem	NC	/	3
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate inner Board			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			

No of Items: _____ Assessor: _____

07/02/2017 (2017)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/11/2017 17:46
Date Of Accident	14/11/2017 22:35
Exact Location Of Accident	SENGKANG EAST ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCM8886D
Insured/Policyholder	
Name Of Registered Owner	POON KOK MENG
NRIC No	S7733104B
Email Address	JAMESPOON77@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96960045
Alternative Phone No	OFFICE: 96960045

Vehicle Particulars

Manufacturer	BMW
Model	M135

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P1778594
Cover Note Number	

Driver

Name of Driver	POON KOK MENG
NRIC No	S7733104B
Date Of Birth	27/11/1977
Occupation	INDOOR
Date Of Driving Pass	12/08/1997
Driving Experience	20 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96960045
Fax Number	
Contact Number	OFFICE: 96960045
Email Address	JAMESPOON77@GMAIL.COM

Address	BLK 568 HOUGANG STREET 51 #09-73
Postcode	530568
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

MY VEHICLE WAS STATIONARY AT TRAFFIC LIGHT. SUDDENLY, VEHICLE B HIT ONTO MY VEHICLE REAR.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY / 1

Vehicle Registration Number	SLM5280P
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	3104B

Vehicle Details

Vehicle No.	SCM8886D
Vehicle to be Exported	No
Intended De-registration Date	27 Nov 2017
Vehicle Make	B.M.W.
Vehicle Model	M135I 3DR AT ABS D/AIRBAG HID NAV
Primary Colour	White
Manufacturing Year	2013
Engine No.	02818561N55B30A
Chassis No.	WBA1N72010J974170
Maximum Power Output	235.0 kW (315 bhp)
Open Market Value	\$39,913.00
Original Registration Date	20 Aug 2013
First Registration Date	20 Aug 2013
Transfer Count	2
Actual ARF Paid	\$47,879.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	19 Aug 2023
PARF Rebate Amount	\$35,909.00

Intended COE Rebate Details

COE Expiry Date	19 Aug 2023
COE Category	E - Open Category
COE Period(Years)	10
QP Paid	\$77,989.00
COE Rebate Amount	\$44,453.00
Total Rebate Amount	\$80,362.00

The information contained herein is correct as at 27 Nov 2017

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Nov 2017 Edit Reg		24 Nov 2017 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	KOH HWEE CHERN METTA, ID: S8323799F		
Main Claimant:	POON KOK MENG, ID: S7733104B		
Vehicle Reg. No.:	SCM8886D	Date of Loss:	14/11/2017 22:00 - :59
Claim Type:	TP / 3871153287SG	Policy/Cover Note No.:	2100505860 (Comprehensive) Coverage: 31/03/2017 - 30/03/2018
Vehicle Reg. No. (Insured):	SLM5280P	Policy No. (Claimant):	
		Excess:	
Repairer:	Aldrin Automotive - Kaki Bukit (HQ) NO.1 KAKI BUKIT AVENUE 6 #02-22, 417883 Kaki Bukit - Tel: 9784 5529		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Mohd-Rasheed, Rashidah - 64191767] Rashidah.Mohamedrasheed@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 26/12/2017]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (15/12/2017): TP GIA REPORT

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SCM8886D (3871153287SG)
[SLM5280P]**

TP

POON KOK MENG

Nov 14 2017 10:00PM

[KOH HWEE CHERN METTA]

Aldrin Automotive - Kaki Bukit

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View
[View In Browser](#)

Assessment Reports			1 per page ▼	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	15/12/17 10:27	Accident Statement From:OD - Reg. No: SLM5280P, Claimant: KOH HWEE CHERN METTA	Load HTM	

Photos/Images			3 per page ▼	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/12/17 10:57	General View	Load JPG	
2	28/12/17 10:57	General View	Load JPG	
3	28/12/17 10:57	General View	Load JPG	
4	28/12/17 10:57	General View	Load JPG	
5	28/12/17 10:57	General View	Load JPG	
6	28/12/17 10:57	General View	Load JPG	
7	28/12/17 10:57	General View	Load JPG	
8	28/12/17 10:57	General View	Load JPG	
9	28/12/17 10:57	General View	Load JPG	
10	28/12/17 10:57	General View	Load JPG	
11	28/12/17 10:57	General View	Load JPG	
12	28/12/17 10:57	General View	Load JPG	
13	28/12/17 10:57	General View	Load JPG	
14	28/12/17 10:57	General View	Load JPG	
15	28/12/17 10:57	General View	Load JPG	
16	28/12/17 10:57	General View	Load JPG	
17	28/12/17 10:57	General View	Load JPG	
18	28/12/17 10:57	General View	Load JPG	
19	28/12/17 10:57	General View	Load JPG	
20	28/12/17 10:57	General View	Load JPG	
21	28/12/17 10:57	General View	Load JPG	
22	28/12/17 10:57	General View	Load JPG	
23	28/12/17 10:57	General View	Load JPG	
24	28/12/17 10:57	General View	Load JPG	
25	28/12/17 10:57	General View	Load JPG	
26	28/12/17 10:57	General View	Load JPG	
27	28/12/17 10:57	General View	Load JPG	
28	28/12/17 10:57	Odometer Reading	Load JPG	
29	28/12/17 10:57	Chassis Number	Load JPG	
30	28/12/17 10:57	Photographs of Damaged Parts	Load JPG	

31	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
32	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
33	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
34	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
35	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
36	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
37	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
38	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
39	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
40	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
41	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
42	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
43	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
44	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
45	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
46	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
47	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
48	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
49	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
50	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
51	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
52	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
53	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
54	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
55	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
56	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
57	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
58	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
59	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
60	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
61	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
62	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
63	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
64	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
65	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
66	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
67	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
68	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
69	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
70	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
71	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
72	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
73	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
74	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
75	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
76	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
77	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
78	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	

79	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
80	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
81	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
82	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
83	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
84	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
85	28/12/17 10:57	Photographs of Damaged Parts		Load JPG	
86	28/12/17 10:57	Photo After Spray		Load JPG	
87	28/12/17 10:57	Photo After Spray		Load JPG	
88	28/12/17 10:57	Photo After Spray		Load JPG	
89	28/12/17 10:57	Photo After Spray		Load JPG	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG17022416/GBE2**Date:** 07/03/2018**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100505860
Claimant Vehicle No : SCM8886D **Insured Vehicle No :** SLM5280P
 Date of Loss: 14/11/2017 Nature of Claim: TP Claim No: 3871153287SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SCM8886D**
 Make & Model: BMW M135i, 3.0 F20 (A) Engine No: 02818561N55B30A
 Reg. Date: 20/08/2013 (Man. Year: 2013) Chassis No: WBA1N72010J974170
 Colour: White Odometer: 81144 km
 Engine Capacity: 2979 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 24/11/2017
 Date Inspected: 24/11/2017 Inspected At: Aldrin Automotive - Kaki Bukit (HQ)
 Estimated Period of Repair: 4.0 days NO.1 KAKI BUKIT AVENUE 6 #02-22
 Singapore 417883

Adjuster: XING GUO QIANG**Manager:** CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
2	1		*REAR NUMBER PLATE BASE	Deformed	0.00 F	*- F
3	2		*REAR NUMBER PLATE LAMP	Cracked	0.00 F	*- F
4	1		*REAR BUMPER	Deformed	0.00 F	*- F
5	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
6	2		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
7	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
8	1		*REAR BUMPER GARNISH	Deformed	0.00 F	*- F
9	1		*REAR BUMPER LOWER GARNISH	Deformed	0.00 F	*- F
10	1		*REAR END PANEL	Repair	0.00 F	*- F
11	1		*REAR END PANEL SENSOR	Not Working	0.00 F	*- F
12	1		*BOOTLID	Repair	0.00 F	*- F
13	3		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >