

22/03/2002

ASS. REC. BY:

REF:

CS/MSG17022433/THB/36

Special Instruction:

Surveyor

Taufik

ASSIGNMENT (Office)

From (Person):

Jostin Lim

of

MSG

Date/Time:

24/11/17 @ 1.50 PM

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No.:

SLF 5840 K

Insured:

at Workshop m/s

Hitachi Capital

Tel:

6466 3072

of

Lok Yang

Policy No.:

MSD/VPCP/17-001833-00

Claim No.:

MSC/V/17-001814

Sum Insured:

Excess:

750

Make of Veh:

(Client's Record)

D.O.A.

20/11/17

CA / REV /

REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN / OUT

Date/Time

Action/Instruction () Estimate

SLF 5840K x

27/11-

Revert via merimen

28/11-9

56 authorise repair by kon ming shao

28/11@

10:38 inform Hitachi authorise repair excess \$750

Part by Part \$4036/- (Red: 367250 : 47%)

Signature: *Tay M*

REF:

MSLH

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: 9750
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 9137K
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLF 5840K Yr Regn: 2016 Any
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Honda odyssey c.c. 2356
Colour: white A/C: _____ Insured / Std / NI / NA
Sp. Reading: _____ T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: SHMRCIS90 G E 206009
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 215/55R17
R: _____
BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front	Rear
R/Bal. <u>0</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm

D.O.A. _____ D.O.I. 24/11/17 @ 1730
Survey held at Mitachi Cep. Tel.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frnt o/s
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 1 NOV 2018

Date/Time. File Pass to?

☐ : Prefi. Report
☒ : Final Report

1) 216 Typist

Date/Time. File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Insp (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. / S 4036

200

10

210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17022433/T1tb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 24-11-2017	
		Code : MSG	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	SLF 5840K
Policy No.	MSD/VPCP/17-001833-00	Coverage (\$)	0.00
Claim No.	MSC/V/17-001814	Excess (\$)	750.00
Assign From	JOSLIN LIM (MERIMEN)	Assign Date	24/11/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	20/11/2017	Inspection Date	24/11/2017
Survey held at	HITACHI CAPITAL (S) PTE LTD JUN TAIYO SERVICE CENTRE NO. 8 FOURTH LOK YANG ROAD SINGAPORE 629705		
5a. Remarks			
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Nov 2017 Sendback Est	23 Nov 2017 14:11 S\$7,708.50	24 Nov 2017 13:50 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	HITACHI CAPITAL ASIA PACIFIC PTE LTD, Co. Reg. No.: 199400399N		
Vehicle Reg. No.:	SLF5840K	Date of Loss:	20/11/2017 09:00 - :59
Claim Type:	OD / MSC/V/17-001814	Policy/Cover Note No.:	MSD/VPCP/17-001833-00 (Comprehensive) Coverage: 31/08/2017 - 30/08/2018
		Excess:	S\$750.00
Repairer:	Hitachi Capital Asia Pacific Pte. Ltd (HQ) No 8 Fourth Lok Yang Road, 629705 Pioneer - Tel: 64663022		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Joslin Lim - 6643 1327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 25/11/2017]		
Driver/Custodian:	NAMBU TERUTAKA (33 / Male), NRIC: G3036100N, Tel: +6582997765		
Adj Asg. Remarks:	Please revert.		

ASSOCIATED MAIL RECEIVED

View All | Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Zhu mei
(1W)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Company
Owner ID	0399N

Vehicle Details

Vehicle No.	SLF5840K
Vehicle to be Exported	No
Intended De-registration Date	27 Nov 2017
Vehicle Make	HONDA
Vehicle Model	ODYSSEY 2.4 EXV-S CVT SR
Primary Colour	White
Manufacturing Year	2016
Engine No.	K24W72012656
Chassis No.	JHMRC1890GC206009
Maximum Power Output	129.0 kW (172 bhp)
Open Market Value	\$32,140.00
Original Registration Date	31 Aug 2016
First Registration Date	31 Aug 2016
Transfer Count	0
Actual ARF Paid	\$36,996.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	30 Aug 2026
PARF Rebate Amount	\$27,747.00

Intended COE Rebate Details

COE Expiry Date	30 Aug 2026
COE Category	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$57,010.00
COE Rebate Amount	\$49,929.00
Total Rebate Amount	\$77,676.00

The information contained herein is correct as at 27 Nov 2017

OK

View Received Message

This mail is associated with :

SLF5840K (MSC/V/17-001814)

CO

Nov 20 2017 9:00AM

[HITACHI CAPITAL ASIA PACIFIC PTE LTD]

Hitachi Capital Asia Pacific Pte. Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 28/11/2017 09:56 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$4025.00) - SLF5840K - Claim Handler: Joslin Lim

Approved:4025.00:CHECK ITEMS TO BE VERIFIED AND CONFIRMED.

DOCUMENTS SUMMARY

There are no documents.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 28 November, 2017 10:38 AM
To: 'keanyap.chong@hcspl.com.sg'; 'PatrickLK.Mok@hcspl.com.sg'
Cc: SUR
Subject: SLF 5840K OD MSIG

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLF 5840K (Excess \$750/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/11/2017 18:25
Date Of Accident	20/11/2017 09:10
Exact Location Of Accident	AT CROSSING PIONEER ROAD AND TUAS ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLF5840K
Insured/Policyholder	
Name Of Registered Owner	HITACHI CAPITAL ASIA PACIFIC PTE LTD
Co Reg No	199400399N
Email Address	JUNTAIYO@HCSPL.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-64663022

Vehicle Particulars

Manufacturer	HONDA
Model	ODYSSEY-2.4 EXV-S CVT SR (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	MAS/VPCP/17-001833-00
Cover Note Number	

Driver

Name of Driver	NAMBU TERUTAKA
Passport No/FIN	G3036100N
Date Of Birth	09/12/1983
Occupation	OUTDOOR
Date Of Driving Pass	10/04/2015
Driving Experience	2 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82997765
Fax Number	
Contact Number	
EEmail Address	NAMBU-TERUTAKA@HANWA.CO.JP

Address
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - LESSEE
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD ON COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO


DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBG7268M
 Vehicle Make/Model/Colour NISSAN CABSTAR
 Details Of Properties
 Name of Driver ROSLI BIN MUHAMED
 NRIC/Passport Number S7501791Z
 Contact Number 97893904
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number
 Email Address

Sketch Plan Pg. 2



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

When I drove car (SLF5840) and I tried to turn left at cross point of Tuas Rd and Pioneer Rd. There are several truck coming and turn right from front side.

I waited for upcoming truck finished to turn right and followed last truck without taking care of upcoming truck from right side (GBG 7268M).

My careless of upcoming truck from right side I hit the left side of truck.

GBG 7268M had damaged that scratched left back side SLF 5840K had damaged right side front fender

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature
(If driver is not the policyholder)

Date & Time:

Nov 20th 5:14

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

HITACHI
 Inspire the Next

 INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)**
PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MSD/VPCP/17-001833-00	Date of Loss:	20/11/2017
Vehicle Reg. No.:	SLF5840K	Driveable?	
Driver Age/Info:	33 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant: HITACHI CAPITAL ASIA PACIFIC PTE LTD			
Driver: NAMBU TERUTAKA			
Make/Model:	HONDA ODYSSEY, 2.4 EXV-S CVT SR (A)	Vehicle Reg. Date:	31/08/2016
Vehicle Colour:	BLACK		
Engine No:	K24W72012656	Chassis No:	JHMRC1890GC206009
Odometer:	10000 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	REFER TO ATTACHMENT		
Present Location: HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ)			

Tan Jih 97495749
 'Revised' Ex 9750
 Not authorised 5 days 24/11/17 @ 1730
 Resurvey before paint
 Sur @ Tkkhaufo.com
 28/11/17

COST OF CLAIMS

	Amount
Parts	4,218.50
Miscellaneous Items	0.00
Labour	3,490.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (\$\$)	7,708.50
- Excess (\$\$)	750.00
(\$\$)	6,958.50
+ GST 7.00% (\$\$)	487.10
Nett Amount (\$\$)	7,445.60

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

 This claim is handled by: **GRANT CHONG**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG **Version:** 1.0 (Last Synchronised: 23 Nov 2017)**Parts:** M1-SUV HONDA ODYSSEY 2.4 EXV-S CVT SR (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Hitachi Capital Asia Pacific Pte. Ltd/SLF5840K/23/11/2017 14:11**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front bumper <i>de ✓</i>	0.00	0.00	*420.00 F ✓
2	10		*Front bumper clips <i>vel ✓</i>	0.00	0.00	*15.00 F ✓
3	2		*Front bumper retainer outer LH/RH <i>RH - de ✓, LH - AN ✓</i>	0.00	0.00	10 *20.00 F ✓
4	1		*Front grille <i>AN</i>	0.00	0.00	*140.00 F X
5	1		*Front bumper center lower grille <i>AN</i>	0.00	0.00	*55.00 F X
6	1		*Front fog lamp cover RH <i>at ✓</i>	0.00	0.00	*35.00 F ✓
7	1		*Front fog lamp RH <i>? AN</i>	0.00	0.00	*140.00 F X
8	1		*Front bumper side skirt RH <i>AN</i>	0.00	0.00	*55.00 F X
9	1		*Headlamp RH <i>at ✓</i>	0.00	0.00	*1,300.00 F X ✓
10	1		*Support panel <i>R ✓</i>	0.00	0.00	*270.00 F X
11	1		*Support panel outer chrome garnish <i>AN</i>	0.00	0.00	*260.00 F X
12	1		*Support panel outer chrome garnish logo <i>AN</i>	0.00	0.00	*200.00 F X
13	1		*Front fender RH <i>bt ✓</i>	0.00	0.00	*300.00 F X
14	1		*Front fender chrome lining RH <i>AN</i>	0.00	0.00	*55.00 F X
15	1		*Front pillar RH	0.00	0.00	-
			Repair			
16	1		*Front fender quarter glass RH <i>AN</i>	0.00	0.00	*240.00 F X
17	1		*Wiper washer tank <i>AN</i>	0.00	0.00	*65.00 F X
18	1		*Front reinforcement <i>bt ✓</i>	0.00	0.00	*180.00 F ✓
19	1		*Front fender shield RH <i>AN</i>	0.00	0.00	*65.00 F X
20	10		*Front fender shield clips RH <i>AN</i>	0.00	0.00	*20.00 F X

F=Franchise part.

Sub Total (S\$)	3,835.00
+ Margin on L,N Items 10.00% (S\$)	383.50
Total Parts (S\$)	4,218.50

Hitachi Capital Asia Pacific Pte. Ltd/SLF5840K/23/11/2017 14:11. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	Panel beat, cut, weld, re-align & replace damaged parts of affected area	New 700	1,600.00 ✓
2	Putty, blend and paint affected area	New 600.700	1,200.00 ✓
3	Check Wiring, re-align headlamps and ensure proper function	New 30.	80.00 ✓
4	Refill compressor oil, vacuum and refill aircond gas	New 120?	180.00 X
5	Conduct four wheel alignment / side slip test	New X	150.00 X
6	Diagnostic Check & Reset	New 120.	280.00 ✓
Gross Labour Cost (S\$)			3,490.00

Hitachi Capital Asia Pacific Pte. Ltd/SLF5840K/23/11/2017 14:11. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

© Hitachi Capital Asia Pacific Pte. Ltd. (Main Office) Co. Reg. No. 199400399N

111 Somerset Road #11-05 Singapore 238164 Tel: (65) 6734 1222 Fax : 6734 8835
www.hitachi-capital.com.sg

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705 Tel: (65) 6466 3022 Fax: (65) 6896 6591

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Nov 2017)
 Parts: M1-SUV HONDA ODYSSEY 2.4 EXV-S CVT SR (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Hitachi Capital Asia Pacific Pte. Ltd/SLF5840K/23/11/2017 14:11
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front bumper <i>de✓</i>	0.00	0.00	*420.00F ✓
2	10		*Front bumper clips <i>del</i>	0.00	0.00	*15.00F ✓
3	<i>2</i>		*Front bumper retainer outer LH/RH <i>RH-de✓, LH-x</i>	0.00	0.00	*20.00F ✓
4	1		*Front grille ?	0.00	0.00	*140.00F X
5	1		*Front bumper center lower grille	0.00	0.00	*55.00F X
6	1		*Front fog lamp cover RH <i>at✓</i>	0.00	0.00	*35.00F ✓
7	1		*Front fog lamp RH ?	0.00	0.00	*140.00F X
8	1		*Front bumper side skirt RH	0.00	0.00	*55.00F X
9	1		*Headlamp RH <i>at✓</i>	0.00	0.00	*1,300.00F ✓
10	1		*Support panel <i>R✓</i>	0.00	0.00	*270.00F X
11	1		*Support panel outer chrome garnish ?	0.00	0.00	*260.00F X
12	1		*Support panel outer chrome garnish logo ?	0.00	0.00	*200.00F X
13	1		*Front fender RH <i>bt✓</i>	0.00	0.00	*300.00F ✓
14	1		*Front fender chrome lining RH ?	0.00	0.00	*55.00F X
15	1		*Front pillar RH	0.00	0.00	
			Repair			
16	1		*Front fender quarter glass RH		0.00	*240.00F X
17	1		*Wiper washer tank ?		0.00	*65.00F X
18	1		*Front reinforcement <i>bt✓</i>		0.00	180.00F ✓
19	1		*Front fender shield RH ?	0.00	0.00	65.00F X
20	10		*Front fender shield clips RH ?	0.00	0.00	20.00F X

F=Franchise part.

Sub Total (S\$) 31 5.00
 + Margin on L,N Items 10.00% (S\$) 1 1.50
 Total Parts (S\$) 32 6.50

Hitachi Capital Asia Pacific Pte. Ltd/SLF5840K/23/11/2017 14:11. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Parts \$ 2260 + 10% = \$ 2486

labour \$ 1550

Total PIP \$ 4036 @ 5.8%

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	Panel beat, cut, weld, re-align & replace damaged parts of affected area	New 700	1,600.00 ✓
2	Putty, blend and paint affected area	New 600-700	1,200.00 ✓
3	Check Wiring, re-align headlamps and ensure proper function	New 30	80.00 ✓
4	Refill compressor oil, vacuum and refill aircond gas	New X 120?	180.00
5	Conduct four wheel alignment / side slip test	New X	150.00
6	Diagnostic Check & Reset	New 120	280.00 ✓
Gross Labour Cost (S\$)			3,490.00

Hitachi Capital Asia Pacific Pte. Ltd./SLF5840K/23/11/2017 14:11. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

© Hitachi Capital Asia Pacific Pte. Ltd. (Main Office) Co. Reg. No. 199400399N

111 Somerset Road #11-05 Singapore 238164 Tel: (65) 6734 1222 Fax : 6734 8835
www.hitachi-capital.com.sg

Jun Taiyo Service Centre (Automobile Leasing & Workshop)
8 Fourth Lok Yang Road Singapore 629705 Tel: (65) 6466 3022 Fax: (65) 6896 6591

HITACHI
Inspire the Next

INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MSD/PCP/17-001833-00	Date of Loss:	20/11/2017
Vehicle Reg. No.:	SLF5840K	Driveable?	
Driver Age/Info:	33 / MALE	Party At Fault:	UNKNOWN
TP Injury	NO	Third Party	YES
Involved?		Involved?	
Insured/Claimant:	HITACHI CAPITAL ASIA PACIFIC PTE LTD		
Driver:	NAMBU TERUTAKA		
Make/Model:	HONDA ODYSSEY, 2.4 EXV-S CVT SR (A)	Vehicle Reg. Date:	31/08/2016
Vehicle Colour:	BLACK	Chassis No:	JHMRC1890GC206009
Engine No:	K24W72012656		
Odometer:	10000 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	REFER TO ATTACHMENT		
Present Location:	HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ)		

Tanjik 97495749
Revised Ex 9750
Not authorised 5 days 24/11/17 @ 1730
Recovery before paint
Sur @ Tklauto.com

COST OF CLAIMS	Amount
Parts	4,218.50
Miscellaneous Items	0.00
Labour	3,490.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	7,708.50
- Excess (S\$)	750.00
(S\$)	6,958.50
+ GST 7.00% (S\$)	487.10
Nett Amount (S\$)	7,445.60

This claim is handled by: **GRANT CHONG**

Generated using Merimen e-Claims Internet Estimation & Adjusting System



合興汽車零件私人有限公司 HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: HITACHI CAPITAL ASIA PACIFIC PTE.LTD

8 FOURTH LOK YANG ROAD

SINGAPORE 629705

ODY

GRANT

NO: HLI9056154

PAGE: 1

DATE: 29/11/2017

A/C CODE: LDHC008

TERMS: CR

VEH NO: SLF5840K

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1	H04711-T6A-900ZZ	FR.BUMPER	1	420.00	420.00
2	H91505-TM8-003	CLIP BUMPER	10	1.50	15.00
3	H71193-T6A-003	FR.SIDE RETAINER RH	1	10.00	10.00
4	H60210-T6A-300ZZ	FR.FENDER RH	1	300.00	300.00
5	H71130-T6A-300ZZ	FR.REINFORCEMENT(305ZZ)	1	180.00	180.00
6	H71104-T6A-921	FR.FOG LAMP COVER RH	1	35.00	35.00
TOTAL			15	TOTAL	SIN 960.00
				ADD GST @ 7%	67.20
				GRAND TOTAL	<u>SIN 1,027.20</u>



O/R: 102850
MR TECK

Print / LSK / 29/11/2017 12:20:43 PM

SALESMAN: LSK

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE





合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: HITACHI CAPITAL ASIA PACIFIC PTE.LTD

8 FOURTH LOK YANG ROAD

SINGAPORE 629705

ODY

GRANT

NO: HLI9056174

PAGE: 1

DATE: 01/12/2017

A/C CODE: LDHC008

TERMS: CR

VEH NO: SLF5840K

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1 H33100-T6A-Q11	FR.HEADLAMP RH	HUS 76	1	1,300.00	1,300.00
TOTAL QUANTITY:			1	TOTAL	SIN 1,300.00
				ADD GST @ 7%	91.00
				GRAND TOTAL	SIN 1,391.00

O/R: 102850


MR TECK

Print / LSK / 1/12/2017 10:54:27 AM

SALESMAN: LSK

This document is computer generated. No signature required.


GOODS SOLD ARE NOT RETURNABLE



EC&OE
PARTS



GOODS RECEIVED BY



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Nov 2017 Sendback Est	23 Nov 2017 14:11 \$7,708.50	24 Nov 2017 13:50 Edit Adj Rpt	\$4,036.00 Edit Estimates	\$4,036.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS

Insured:	HITACHI CAPITAL ASIA PACIFIC PTE LTD, Co. Reg. No.: 199400399N		
Vehicle Reg. No.:	SLF5840K	Date of Loss:	20/11/2017 09:00 - :59 [14 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / MSC/V/17-001814	Policy/Cover Note No.:	MSD/VPCP/17-001833-00 (Comprehensive) Coverage: 31/08/2017 - 30/08/2018
		Excess:	\$750.00
Repairer:	Hitachi Capital Asia Pacific Pte. Ltd (HQ) No 8 Fourth Lok Yang Road, 629705 Pioneer - Tel: 64663022		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Joslin Lim - 6643 1327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 24/12/2017]		
Driver/Custodian:	NAMBU TERUTAKA (33 / Male), NRIC: G3036100N, Tel: +6582997765		
Adj Asg. Remarks:	Please revert.		

ASSOCIATED MAIL RECEIVED

View All | Compose Case Mail

- MSIG_SG (29/03/2018): Alert - Adj Mandate Approved (\$4036.00) - SLF5840K - Claim Handler: Joslin Lim
- MSIG_SG (28/11/2017): Alert - Adj Mandate Approved (\$4025.00) - SLF5840K - Claim Handler: Joslin Lim

ALL ASSOCIATED TASKS

View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLF5840K (MSC/V/17-001814)
 OD
 Nov 20 2017 9:00AM
 [HITACHI CAPITAL ASIA PACIFIC PTE LTD]
 Hitachi Capital Asia Pacific Pte. Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser v	
Assessment Reports				1 per page v	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)		Thumbnail	Print
1	23/11/17 14:11	Repairer Estimates		Load HTM	☐
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	27/11/17 13:52	Adjuster Immediate Advice		Load HTM	☐
2	28/03/18 16:37	Adjuster Immediate Advice		Load HTM	☐
Photos/Images				3 per page v	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	27/11/17 14:01	General View		Load JPG	☒
2	27/11/17 14:01	General View		Load JPG	☒
3	27/11/17 14:01	General View		Load JPG	☒
4	27/11/17 14:01	General View		Load JPG	☒
5	27/11/17 14:01	General View		Load JPG	☒
6	27/11/17 14:01	General View		Load JPG	☒
7	27/11/17 14:01	General View		Load JPG	☒
8	27/11/17 14:01	General View		Load JPG	☒
9	27/11/17 14:01	General View		Load JPG	☒
10	27/11/17 14:01	General View		Load JPG	☒
11	27/11/17 14:01	General View		Load JPG	☒
12	27/11/17 14:01	General View		Load JPG	☒
13	27/11/17 14:01	General View		Load JPG	☒
14	27/11/17 14:01	General View		Load JPG	☒
15	27/11/17 14:01	General View		Load JPG	☒
16	27/11/17 14:01	General View		Load JPG	☒
17	27/11/17 14:01	General View		Load JPG	☒
18	27/11/17 14:01	General View		Load JPG	☒
19	27/11/17 14:01	General View		Load JPG	☒
20	27/11/17 14:01	General View		Load JPG	☒
21	27/11/17 14:01	General View		Load JPG	☒
22	27/11/17 14:01	General View		Load JPG	☒
23	27/11/17 14:01	General View		Load JPG	☒
24	27/11/17 14:01	General View		Load JPG	☒
25	27/11/17 14:01	General View		Load JPG	☒
26	27/11/17 14:01	General View		Load JPG	☒
27	27/11/17 14:01	General View		Load JPG	☒
28	27/11/17 14:01	General View		Load JPG	☒
29	27/11/17 14:01	General View		Load JPG	☒
30	27/11/17 14:01	General View		Load JPG	☒
31	27/11/17 14:01	General View		Load JPG	☒
32	27/11/17 14:01	General View		Load JPG	☒
33	27/11/17 14:01	General View		Load JPG	☐

Assessment Reports			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
				☒
34	27/11/17 14:01	General View	 Load JPG	☒
35	27/11/17 14:01	General View	 Load JPG	☒
36	27/11/17 14:01	General View	 Load JPG	☒
37	27/11/17 14:01	General View	 Load JPG	☒
38	27/11/17 14:01	General View	 Load JPG	☒
39	27/11/17 14:01	General View	 Load JPG	☒
40	28/03/18 16:43	Reinspection Photo	 Load JPG	☒
41	28/03/18 16:43	Reinspection Photo	 Load JPG	☒
42	28/03/18 16:43	Reinspection Photo	 Load JPG	☒
43	28/03/18 16:43	Reinspection Photo	 Load JPG	☒
44	28/03/18 16:43	Reinspection Photo	 Load JPG	☒
45	28/03/18 16:43	Reinspection Photo	 Load JPG	☒
46	28/03/18 16:43	Reinspection Photo	 Load JPG	☒
47	28/03/18 16:43	Reinspection Photo	 Load JPG	☒
48	28/03/18 16:43	Reinspection Photo	 Load JPG	☒
49	28/03/18 16:43	Reinspection Photo	 Load JPG	☒
50	28/03/18 16:43	Reinspection Photo	 Load JPG	☒
51	28/03/18 16:43	Reinspection Photo	 Load JPG	☒
52	28/03/18 16:43	Reinspection Photo	 Load JPG	☒
53	28/03/18 16:43	Reinspection Photo	 Load JPG	☒
54	28/03/18 16:43	Reinspection Photo	 Load JPG	☒
55	28/03/18 16:43	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/11/17 14:02	ESTIMATE	 Load PDF	
2	04/04/18 08:46	Parts Invoice	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
1	21/11/17 20:01	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
1	21/11/17 19:56	Accident Photo	 Load JPG	☒
2	21/11/17 19:56	Accident Photo	 Load JPG	☒
3	21/11/17 19:56	Accident Photo	 Load JPG	☒
4	21/11/17 19:56	Accident Photo	 Load JPG	☒
5	21/11/17 19:56	Accident Photo	 Load JPG	☒
6	21/11/17 19:56	Accident Photo	 Load JPG	☒
7	21/11/17 19:56	Accident Photo	 Load JPG	☒
8	21/11/17 19:56	Accident Photo	 Load JPG	☒
9	21/11/17 19:56	Accident Photo	 Load JPG	☒
10	21/11/17 19:56	Accident Photo	 Load JPG	☒
11	21/11/17 19:56	Accident Photo	 Load JPG	☒
12	21/11/17 19:56	Accident Photo	 Load JPG	☒
13	21/11/17 19:56	Accident Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
14	21/11/17 19:56	Accident Photo	 Load JPG	☒
15	21/11/17 19:56	Accident Photo	 Load JPG	☒
16	21/11/17 19:56	Accident Photo	 Load JPG	☒
17	21/11/17 19:56	Accident Photo	 Load JPG	☒
18	21/11/17 19:56	Accident Photo	 Load JPG	☒
19	21/11/17 19:56	Accident Photo	 Load JPG	☒
20	21/11/17 19:56	Accident Photo	 Load JPG	☒
21	21/11/17 19:56	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
1	21/11/17 20:01	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) ^ v			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG17022433/T1TBE2

Date: 04/04/2018

REFERENCE

Insured/Claimant: HITACHI CAPITAL ASIA PACIFIC PTE LTD

Policy No: MSD/VPCP/17-001833-00

Date of Loss: 20/11/2017

Nature of Claim: OD

Claim No: MSC/V/17-001814

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLF5840K

Make & Model: HONDA ODYSSEY, 2.4 EXV-S CVT SR (A)

Engine No: K24W72012656

Reg. Date: 31/08/2016 (Man. Year: 2016)

Chassis No: JHMRC1890GC206009

Colour: White

Odometer: 0 km

Engine Capacity: 2356 cc

Market Value/New Car Price: S\$137,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Rear Tyre Size: 215/55 R17

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,218.50	2,486.00	1,732.50	41.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,490.00	1,550.00	1,940.00	55.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,708.50	4,036.00	3,672.50	47.64
- Excess (S\$)	750.00	750.00	0.00	0.00
(S\$)	6,958.50	3,286.00	3,672.50	52.78
+ GST 7.00/7.00% (S\$)	487.10	230.02	257.08	52.78
Nett Amount (S\$)	7,445.60	3,516.02	3,929.58	52.78

INSPECTION

Date of Assignment: 24/11/2017 Present Location:

Hitachi Capital Asia Pacific Pte. Ltd (HQ)

Date Inspected: 24/11/2017 Inspected At:

No 8 Fourth Lok Yang Road
Singapore 629705

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Apr 2018)
Parts: M1-SUV HONDA ODYSSEY 2.4 EXV-S CVT SR (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLF5840K)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*Front bumper (WCP)	Deformed	420.00 F	*420.00 F
2	10	*Front bumper clips (WCP)	Necessary	15.00 F	*15.00 F
3	1	*Front bumper retainer outer LH/RH (WCP)	O/S Deformed/N/S Not Necessary	20.00 F	*10.00 F
4	1	*Front grille (WCP)	Not Necessary	140.00 F	*- F
5	1	*Front bumper center lower grille (WCP)	Not Necessary	55.00 F	*- F
6	1	*Front fog lamp cover RH (WCP)	Cut	35.00 F	*35.00 F
7	1	*Front fog lamp RH (WCP)	Not Necessary	140.00 F	*- F
8	1	*Front bumper side skirt RH (WCP)	Not Necessary	55.00 F	*- F
9	1	*Headlamp RH (WCP)	Cut	1,300.00 F	*1,300.00 F
10	1	*Support panel (WCP)	Repair	270.00 F	*- F
11	1	*Support panel outer chrome garnish (WCP)	Not Necessary	260.00 F	*- F
12	1	*Support panel outer chrome garnish logo (WCP)	Not Necessary	200.00 F	*- F
13	1	*Front fender RH (WCP)	Bent	300.00 F	*300.00 F
14	1	*Front fender chrome lining RH (WCP)	Not Necessary	55.00 F	*- F
15	1	*Front pillar RH (NPA)(WCP)	Repair	-	*- F
16	1	*Front fender quarter glass RH (WCP)	Not Necessary	240.00 F	*- F
17	1	*Wiper washer tank (WCP)	Not Necessary	65.00 F	*- F
18	1	*Front reinforcement (WCP)	Bent	180.00 F	*180.00 F
19	1	*Front fender shield RH (WCP)	Not Necessary	65.00 F	*- F
20	10	*Front fender shield clips RH (WCP)	Not Necessary	20.00 F	*- F

F=Franchise part.

Sub Total (S\$)	3,835.00	2,260.00
+ Margin on L,N Items 10.00/10.00% (S\$)	383.50	226.00
Total Parts (S\$)	4,218.50	2,486.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Panel beat, cut, weld, re-align & replace damaged parts of affected area	New	1,600.00	700.00
2	Putty, blend and paint affected area	New	1,200.00	700.00
3	Check Wiring, re-align headlamps and ensure proper function	New	80.00	30.00
4	Refill compressor oil, vacuum and refill aircond gas	New	180.00	0.00
5	Conduct four wheel alignment / side slip test	New	150.00	0.00
6	Diagnostic Check & Reset	New	280.00	120.00
Gross Labour Cost (\$\$)			3,490.00	1,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >