

22/03/2002

ASS. REC. BY:

REF:

C/MSG17022448/Gb

Special Instruction:

SURVEYOR:

ASSIGNMENT (Office)

Maimed

From (Person):

Fuel Foo

of

MSG

Date/Time:

24/11/17 03:57pm

Estimated Cost:

Bill to:

OD / TP / FWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJG 5577P

Insured:

SFJ 389E

at Workshop m/s

A T Performance

Tel:

96866219

of

160 S/M Drive #07-18/19 S/M Autocity

Policy No:

MSD/VPT/17-001046

Claim No:

MSC/V/17-001806

Sum Insured:

Excess:

Make of Veh:

D.O.A.

22/11/17

(Client's Record)

CA / REV / REP. / REV 24 HRS

22/11/17

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SJG 5577P / SFJ 389E NA/MSG17022336/24 DCA 22/11/17
	Dismantle Part : 29.11.2017
	After Repair : 04.12.2017

15/12/17 11:53am Email to Fuel Foo from Maimed



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Fédération Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG17022448/Grb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 24-11-2017	
		Code : MSG	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SFJ 389E	Veh. Inspected	SJG 5577P
Policy No.	MSD/VPT/17-001046	Coverage (\$)	0.00
Claim No.	MSC/V/17-001826	Excess (\$)	0.00
Assign From	FIEVEL FOO (MERIMEN)	Assign Date	24/11/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	22/11/2017	Inspection Date	27/11/2017
Survey held at	160 SIN MING DRIVE #07-18		
Repairer	A T PERFORMANCE		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Nov 2017		24 Nov 2017 15:52 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	NAKANO SINGAPORE (PTE) LTD, Co. Reg. No.: 197501976M								
Main Claimant:	LEE ANNA, ID: S7627987Z								
Vehicle Reg. No.:	SJG5577P	Date of Loss:	22/11/2017 23:00 - :59						
Claim Type:	TP / MSC/V/17-001826	Policy/Cover Note No.:	MSD/VPT/17-001046 (Third Party Only) Coverage: 10/05/2017 - 09/05/2018						
Vehicle Reg. No. (Insured):	SFJ389E	Policy No. (Claimant):							
		Excess:							
Repairer:	A T Performance (SIN MING) 160 SIN MING DRIVE, #07-18/19 SIN MING AUTOCITY, 575722 Sin Ming - Tel: 96866219								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 25/11/2017]								
Driver/Custodian (Insured):	LIM YONG HUAT VICTOR (), NRIC: S7130269E, Tel: +6591008968								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

ma 27/11
gu-

(IN)

Confirm
of
surveyor
going
today

96910663

969

8402 8474

(Draft)

MLHM17154926 / Lai Huat (Meng Kee) Motor Pte Ltd - Sin Ming
 ENTRY DATE & TIME: 23/11/2017 11:58

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 23/11/2017 11:58
 Date Of Accident 22/11/2017 23:00
 Exact Location Of Accident SLIP ROAD TO ANG MO KIO AVENUE 1 FROM CTE
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJG5577P
Insured/Policyholder
 Name Of Registered Owner LEE ANNA
 NRIC No S7627987Z
 Email Address PRIVATEBEANIE@YAHOO.COM.SG
 Mobile Phone No (LOCAL) +65-94302737
 Alternative Phone No Others-94302737
Vehicle Particulars
 Manufacturer HONDA
 Model CRV
 Exact Purpose for which vehicle was being used at time of accident PRIVATE USE
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE CAR
Insurance Company
 Name of Insurance Company GREAT EASTERN GENERAL INSURANCE LIMITED
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number V8008131
 Cover Note Number
Driver
 Name of Driver LEE YEW KONG ALVIN
 NRIC No S7627423A
 Date Of Birth 05/09/1976
 Occupation INDOOR
 Date Of Driving Pass 30/08/1995

Driving Experience	22 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93676768
Fax Number	
Contact Number	
EMail Address	ALVINLEE76@GMAIL.COM
Address	143 SERANGOON AVENUE 3 #13-04
Postcode	556121
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFJ389E
Vehicle Make/Model/Colour	TOYOTA
Details Of Properties	
Name of Driver	LIM YONG HUAT
NRIC/Passport Number	

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

23/11/17 11AM


23 NOV 2017



Driver's Signature
(If driver is not the policyholder)
Date & Time:

23/11/17 11AM


23 NOV 2017



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Poh Kwee Choo
S6840583A

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


On 23rd Nov 2017, at around 11 pm, The driver, Atvin Lee, was driving the car, SJ65577P, a ~~toyota~~ Honda CRV, was waiting at the stop line of the filter lane before going onto the main road Ang Mo Kio Ave 1. The car was stationary as there are vehicles along the main road. A Toyota car, SFJ389E, driven by Lim Yong Huat, had a collision with my car's rear and caused an accident. Both drivers proceeded to exit the cars to check for damages. My Honda car suffered damages to the rear and Toyota car suffered frontal damages as well. Both drivers proceeded to exchanged drivers' details. My Honda car has an in car camera and I have photos of the scene and damages to both cars. The weather that night is clear and no adverse weather condition.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time: 23/11/17 11am
 23 NOV 2017


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 23 NOV 2017
 23/11/17 11am


 Reporting Centre Personnel's Signature
 Name: Poh Kwee Choo
 NRIC/FIN No.: S6840583A

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	7987Z

Vehicle Details

Vehicle No.	SJG5577P
Vehicle to be Exported	No
Intended De-registration Date	28 Nov 2017
Vehicle Make	HONDA
Vehicle Model	HONDA CRV 2.4L AT
Primary Colour	White
Manufacturing Year	2008
Engine No.	K24Z12757784
Chassis No.	JHLRE48508C210175
Maximum Power Output	125.0 kW (167 bhp)
Open Market Value	\$29,414.00
Original Registration Date	07 Jul 2008
First Registration Date	07 Jul 2008
Transfer Count	2
Actual ARF Paid	\$29,414.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	06 Jul 2018
PARF Rebate Amount	\$14,707.00

Intended COE Rebate Details

COE Expiry Date	06 Jul 2018
COE Category	B - Car (1601cc & above)
COE Period(Years)	10
QP Paid	\$14,689.00
COE Rebate Amount	\$888.00
Total Rebate Amount	\$15,595.00

The information contained herein is correct as at 28 Nov 2017

OK

View Sent Message

This mail is associated with :

***SJG5577P (MSC/V/17-001826)**
[SFJ389E]

TP

LEE ANNA

Nov 22 2017 11:00PM

[NAKANO SINGAPORE (PTE) LTD]

A T Performance

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 15/12/2017 11:53 AM.
To MSIG_FFWY1
Subject Pre-repair Inspection

Dear Fievel,

Refer to your assignment on 24.11.2017 at 3.52PM.

Please be informed that we have inspected the vehicle SJG 5577P on 27.11.2017 at 4.30PM.

At the time of inspection the repairer did not present their estimation to the damaged vehicle.

We will submit our report accordingly.

Best Regards,

Catherine Chong | Admin


LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.




PRIORITY SERVICES

Insurance Loss Adjusters And Motor Appraisers
Block 779 Yishun Avenue 2 #01-1545 Singapore 760779
Tel : 62934822 Fax : 62963283

Messrs. Lee Anna
143, Serangonn Avenue 3
#13-04
Singapore 556121

Bill No. DN/TP/17/0161/AT
5/12/2017

Dr.

To	
Survey Fee (S \$) :	
Photographs (S \$) :	
Transport (S \$) :	
Resurvey (S \$) :	
Site-Survey (S \$) :	
Services rendered including photographs and transport charges	(S \$) 665.00
Our reference : TP/0107/17	
Insured :	
Policy / Cert. No. :	
Your Claim No. : Third Party Claim	
Vehicle : Honda CR-V (A) - SJG 5577 P	
Dollars : Six Hundred Sixty Five Only	
Checked by 	for PRIORITY SERVICES 
<hr/>	<hr/>

E. & O. E.

Only our official receipt will be recognised for payment made on this account



PRIORITY SERVICES

Insurance Loss Adjusters And Motor Appraisers
Block 779 Yishun Avenue 2 #01-1545 Singapore 760779
Tel : 62934822 Fax : 62963283

VEHICLE INSPECTION REPORT

Report No. TP/0107/17	Date of Report	: 5 December 17
To : Lee Anna	Date of Request	: 28 November 17
143, Serangonn Avenue 3	Report requested by	: Lee Anna
#13-04	Date of Accident	: 22 November 17
Singapore 556121	Date of Inspection	: 28 November 17
	Claim No.	: Third Party Claim

PARTICULARS OF DAMAGED VEHICLE

Registration Plate No	: SJG 5577 P	Odometer Reading	: 234,642 km
Make	: Honda	Carrying Capacity	: 4
Model	: CR-V (A)	Radio / Cassette / CD	: Yes
Year of Manufacture	: 2008	Air-Conditioner	: Yes
Colour	: Pearl White	Wing Mirror	: Yes
Engine Capacity	: 2,354 cc	Clock	: Yes
Engine No	: --	Seat Belts	: Yes
Chassis / Frame No	: JHLRE48508C210175	Others	: Nil

TYRE CONDITION

Front Left	: 8mm	Front Right	: 8mm
Make	: Goodyear	Make	: Goodyear
Rear Left	: 8mm	Rear Right	: 8mm
Make	: Goodyear	Make	: Goodyear
Spare	:	Road Wheels Type	: Alloy

(The above represents the approximate remaining life of tyre treads)

Jack & Tools	: Intact	Spare Tyre	: Intact
--------------	----------	------------	----------

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Body Work	: Good
Paint Work	: Good
Handbrake	: Serviceable
Footbrake	: Serviceable
Steering	: Serviceable
Apparent engine modification	: Nil

This report is confidential and is given for the use of clients and their agents and any disclosure or publication of it or parts thereof shall be the responsibility of such person and no liability shall be attached to us therefore.

ASSESSMENT

	<u>Repairer's Estimate (S \$)</u>	<u>Our Recommendation (S \$)</u>
Spare Parts :	8,031.20	5,502.72
Labour Charges :	2,660.00	1,910.00
Paint Work :	1,600.00	1,350.00
Towing Charges :	0.00	0.00
Others :	0.00	0.00
Totals :	12,291.20	8,762.72

Reduction (S \$) : 5,291.20

Recommended Reserve (S \$) : 7,000.00 (Lump Sum)

Estimated Normal Period of Repairs : 10 working days

CONTRIBUTIONS BY INSURED

Excess (S \$) : N/A

Others : --

GENERAL REMARKS

WITHOUT PREJUDICE

Continuation Sheet

The Assignment

The survey was conducted at A T Performance, Block 14, Sin Ming Industrial Estate, #01-21, Singapore 575658. Follow-up inspection has been conducted.

Point of Impact

At the rear portion.

Damages

The tailgate, tailgate outer garnish, rear bumper, rear sides bumper, end panel, spare tyre panel, exhaust silencer, etc.

Other parts were also found damaged. (see schedule for details)

Adjustment / Recommendation

We have inspected thoroughly each and every item on the repairer's estimate against the actual damages found on the vehicle and we list the breakdown of our findings and our recommendation as per schedule attached.


Our adjusted amount for the cost of repairs is \$8,762.72


Conclusion

The repairer has agreed to undertake repairs at a lump sum of \$7,000.00

We now revert to you for your decision on repairs.

Very truly yours
PRIORITY SERVICES


JIMMY S. T. LEE AMSOE, AMIRTE, AMSAE-AUS, MSAAA
Motor Appraiser


LAWRENCE ENG
Motor Appraiser

Encl. Photographs of the damaged vehicle taken by us during inspection.

Vehicle No : SJG 5577 P Honda CR-V (A)

TP/0107/17

Workshop : A T Performance

Replacement of Parts	Condition	Repairer's Estimate (S \$)	Dist. %	Our Recommendation (S \$)	Dist. %
To Supply :					
1pc. Tailgate	Dented	957.70		957.70	20
1set. Tailgate windscreen glass rubber moulding	Necessary	48.60		48.60	20
1pc. Tailgate centre emblem	Not Necessary	35.10		--	20
1pc. Tailgate 'CR-V' emblem	Necessary	30.20		30.20	20
1pc. Tailgate outer lower garnish	Cracked	207.20		207.20	20
1pc. Tailgate outer lower garnish keyless sensor	Cracked	183.20		183.20	20
1pc. Tailgate lock	Bent	283.10		283.10	20
1pc. Tailgate lock catch	Bent	41.70		41.70	20
1pc. Tailgate inner trim board	Cracked	797.50		797.50	20
1pc. Tailgate weatherstrip	Bent	225.80		225.80	20
1pc. Rear centre bumper	Dented	565.70		565.70	20
1pc. Rear centre bumper RH side reflector	Cracked	30.80		30.80	20
1pc. Rear centre bumper LH side reflector	Cracked	30.80		30.80	20
1pc. Rear RH bumper	Cracked	220.80		220.80	20
1pc. Rear RH bumper side retainer	Cracked	30.70		30.70	20
1pc. Rear LH bumper	Cracked	220.80		220.80	20
1pc. Rear LH bumper side retainer	Cracked	20.70		20.70	20
1pc. RH tail-lamp	Refit	437.60		--	20
1pc. LH tail-lamp	Refit	437.60		--	20
1pc. End panel	Dented	535.00		535.00	20
1pc. End panel inner garnish	Cracked	85.10		85.10	20
1pc. Spare tyre panel	Dented / Distorted	849.30		849.30	20
1pc. Spare tyre panel insulator	Necessary	150.00		150.00	20
1 Exhaust silencer	Bent	584.20		584.20	20
2pcs. Exhaust silencer rubber hangers	Cracked / Distorted	102.00		102.00	20
Sub-Total :-		7,111.20		6,200.90	
Total Discount :-		--		1,240.18	
		7,111.20		4,960.72	
Special Nett Items :-					
1tube. Tailgate windscreen glass sealant	Necessary	70.00		40.00	
1pc. Tailgate windscreen glass inner seal	Necessary	50.00		20.00	
1set. Tailgate outer lower garnish clips	Necessary	70.00		30.00	
1set. Tailgate inner trim board clips	Necessary	70.00		35.00	
1set. Rear bumper reverse sensor (4 sensors)	Dented / Malfunction	450.00		320.00	

Vehicle No : SJG 5577 P Honda CR-V (A)

TP/0107/17

Workshop : A T Performance

Replacement of Parts	Condition	Repairer's Estimate (S \$)	Dist. %	Our Recommendation (S \$)	Dist. %
1set. Rear centre bumper clips	Necessary	70.00		30.00	
1set. End panel inner garnish clips	Necessary	60.00		15.00	
1set. Rear RH fender inner trim board clips	Necessary	40.00		26.00	
1set. Rear LH fender inner trim board clips	Necessary	40.00		26.00	
Total For Parts :-		8,031.20		5,502.72	
Labour Charges :					
Remove & replace the above listed parts, knock, straighten & reshape, cut & weld body panel parts where necessary, re-position & re-align, replacement of parts to the original position including adjustment.		1,500.00		1,200.00 900	
Apply rust coating on the replaced & repaired panels.		120.00		60 80.00	
Check wiring & lighting system on affected areas.		100.00		30 40.00	
Remove & re-install tailgate windscreen glass to assist repairs.		220.00		120.00	
Transfer & replace tailgate mechanism to new tailgate.		150.00		80.00	✓
Remove, re-install & replace rear inner trims, garnishes, boards & seats to assist repairs.		350.00		80 250.00	
Remove, adjust & replace rear bumper reverse sensor.		100.00		60.00	✓
Remove, replace & re-install exhaust silencer, rubber hangers & heat shield to assist repairs.		120.00		80.00	✓
Spray Painting :					
To putty & spray repaired & replaced body panels.		1,600.00		1,350.00 1100	
Grand Total :-		12,291.20		8,762.72	

Surveyed By : Lawrence Ng

(Signature)

▶ Honda CR-V Used Vehicle List (3 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
Honda CR-V 2.4A	\$23,800	\$19,450 /yr	04-Sep-2008	2,354 cc	-	Hua Yang Credit Pte Ltd	Available

Up To 90% Loan! Flexible Repayment With In House Financing. All Vehicle Inspected By Our Professional Team For Highest Quality With Opt Extended Warranty Available. Owning A Car Is So Much Easier With...

Office No. - 64545111

Alvin Chua - 84488354 | Edison - 82698288

Honda CR-V 2.4A	\$21,000	-	06-May-2008	2,354 cc	201,000 km	V-TEC Asia Automotive Pte Ltd	Available
-----------------	----------	---	-------------	----------	------------	-------------------------------	-----------

Excellent Condition, Car Suitable For COE Renewal. COE Loan Available. All Worn Out Parts Replaced. Drive With Assurance On Our Extended Warranty Package By Our In-House Workshop. Call To View Now. Ex...

Office No. - 96109610

Perry Yeo - 96109610 | Wayne Chua - 87771911 | Benjamin Yeo - 84028402

Honda CR-V 2.4A (New 5-yr COE)	\$44,800	\$8,960 /yr	22-Feb-2008	2,354 cc	-	Victory Cars Trading Pte Ltd	Available
--------------------------------	----------	-------------	-------------	----------	---	------------------------------	-----------

Low Depreciation And Very Well Kept, Decent Mileage, Worry Free 1 Stop Purchase For Loan/Insurance Flexibility. No Repairs Needed. Hassle Free! Comes With 6 Months Warranty Inclusive Of 24/7 Free Towi...

Office No. - 63854916

Mr Lim - 92470299 | Mr Lee - 86885879 | Mr Wong - 94591299 | Mr Tan - 90999505

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2018 sgCarMart. All rights reserved.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Nov 2017		24 Nov 2017 15:52 Edit Adj Rpt	S\$5,000.00 Edit Estimates	S\$5,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]
Insured:	NAKANO SINGAPORE (PTE) LTD , Co. Reg. No.: 197501976M			
Main Claimant:	LEE ANNA , ID: S7627987Z			
Vehicle Reg. No.:	SJG5577P	Date of Loss:	22/11/2017 23:00 - :59	
Claim Type:	TP / MSC/V/17-001826	Policy/Cover Note No.:	MSD/VPT/17-001046 (Third Party Only) Coverage: 10/05/2017 - 09/05/2018	
Vehicle Reg. No. (Insured):	SFJ389E	Policy No. (Claimant):		
		Excess:		
Repairer:	A T Performance (SIN MING) 160 SIN MING DRIVE, #07-18/19 SIN MING AUTOCITY, 575722 Sin Ming - Tel: 96866219			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 25/11/2017]			
Driver/Custodian (Insured):	LIM YONG HUAT VICTOR (), NRIC: S7130269E, Tel: +6591008968			

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS <input type="checkbox"/>										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

***SJG5577P (MSC/V/17-001826)**
[SFJ389E]
TP
LEE ANNA
Nov 22 2017 11:00PM
[NAKANO SINGAPORE (PTE) LTD]
A T Performance

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View [View in Browser](#) ▼

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	24/11/17 14:23	Accident Statement From:SC - Reg. No: SFJ389E, Claimant: NAKANO SINGAPORE (PTE) LTD	1	Load HTM	
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	27/02/18 12:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
2	27/02/18 12:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
3	27/02/18 12:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	27/02/18 12:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	27/02/18 12:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	27/02/18 12:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	27/02/18 12:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	27/02/18 12:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	27/02/18 12:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	27/02/18 12:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	27/02/18 12:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	27/02/18 12:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	27/02/18 12:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	27/02/18 12:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	27/02/18 12:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	27/02/18 12:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
17	27/02/18 12:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
18	27/02/18 12:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
19	27/02/18 12:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
20	27/02/18 12:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
21	27/02/18 12:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
22	27/02/18 12:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
23	27/02/18 12:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
24	27/02/18 12:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
25	27/02/18 12:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
26	27/02/18 12:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
27	27/02/18 12:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
28	27/02/18 12:18	Dismantled Parts	1	Load JPG	<input checked="" type="checkbox"/>
29	27/02/18 12:18	Dismantled Parts	1	Load JPG	<input checked="" type="checkbox"/>
30	27/02/18 12:18	Dismantled Parts	1	Load JPG	<input checked="" type="checkbox"/>

31	27/02/18 12:18	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
32	27/02/18 12:18	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
33	27/02/18 12:18	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
34	27/02/18 12:18	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
35	27/02/18 12:18	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
36	27/02/18 12:18	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
37	27/02/18 12:18	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
38	27/02/18 12:18	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
39	27/02/18 12:18	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
40	27/02/18 12:18	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
41	27/02/18 12:18	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
42	27/02/18 12:18	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
43	27/02/18 12:18	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
44	27/02/18 12:18	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
45	27/02/18 12:18	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
46	27/02/18 12:18	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
47	27/02/18 12:18	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
48	27/02/18 12:18	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
49	27/02/18 12:18	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
50	27/02/18 12:18	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
51	27/02/18 12:18	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
52	27/02/18 12:18	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
53	27/02/18 12:18	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
54	27/02/18 12:18	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
55	27/02/18 12:18	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
56	27/02/18 12:18	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
57	27/02/18 12:18	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
58	27/02/18 12:18	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
59	27/02/18 12:18	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
60	27/02/18 12:18	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
61	27/02/18 12:18	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page ▼	<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	24/11/17 14:31	SJG5577P E-FILE, CERT OF INS, DL & IC		Load PDF	
2	24/11/17 14:31	PRI FROM ARIDAS & ASSOCIATES		Load PDF	
3	24/11/17 15:52	Survey Disagree on SJE		Load PDF	
4	09/01/18 13:35	SURVEY REPORT		Load PDF	
5	09/01/18 13:35	SURVEY PHOTO		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

//

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17022448/GRBE2
Date: 27/02/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. **Policy No:** MSD/VPT/17-001046
Claimant Vehicle No : SJG5577P **Insured Vehicle No :** SFJ389E
Date of Loss: 22/11/2017 **Nature of Claim:** TP **Claim No:** MSC/V/17-001826

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJG5577P
Make & Model: HONDA CR-V, 2.4 L AT (A) **Engine No:** K24Z12757784
Reg. Date: 07/07/2008 (Man. Year: 2008) **Chassis No:** JHLRE48508C210175
Colour: White **Odometer:** 234642 km
Engine Capacity: 2354 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:** Yes

CONDITION OF TYRES

Front Tyre Size: 225/65 R17 **Rear Tyre Size:** 225/65 R17
Front Left Side: Goodyear 6 mm **Rear Left Side:** Goodyear 6 mm
Front Right Side: Goodyear 6 mm **Rear Right Side:** Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,031.20	3,936.00	4,095.20	50.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,260.00	2,510.00	1,750.00	41.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,291.20	6,446.00	5,845.20	47.56
Approved Total (Overridden) (S\$)		5,000.00		
Nett Amount (S\$)	12,291.20	5,000.00	7,291.20	59.32

INSPECTION

Date of Assignment: 24/11/2017
Date Inspected: 27/11/2017 **Inspected At:** A T Performance (SIN MING)
 160 SIN MING DRIVE, #07-18/19 SIN MING
 AUTOCITY
 Singapore 575722
Estimated Period of Repair: 7.0 days

Adjuster: XING GUO QIANG

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Feb 2018)
Parts: M1-SUV HONDA CR-V 2.4 L AT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJG5577P)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	957.70 F	*957.70 FL
2	1		*SET TAILGATE WINDSCREEN GLASS RUBBER MOULDING	Necessary	48.60 F	*48.60 FL
3	1		*TAILGATE CENTRE EMBLEM	Not Necessary	35.10 F	*- FL
4	1		*TAILGATE CR-V EMBLEM	Necessary	30.20 F	*30.20 FL
5	1		*TAILGATE OUTER LOWER GARNISH	Cracked	207.20 F	*207.20 FL
6	1		*TAILGATE OUTER LOWER GARNISH KEYLESS SENSOR	Not Necessary	183.20 F	*- FL
7	1		*TAILGATE LOCK	Bent	283.10 F	*283.10 FL
8	1		*TAILGATE LOCK CATCH	Serviceable	41.70 F	*- FL
9	1		*TAILGATE INNER TRIM BOARD	Cracked	797.50 F	*797.50 FL
10	1		*TAILGATE WEATHERSTRIP	Bent	225.80 F	*225.80 FL
11	1		*REAR CENTRE BUMPER	Dented	565.70 F	*565.70 FL
12	1		*REAR CENTRE BUMPER RH SIDE REFLECTOR	Cracked	30.80 F	*30.80 FL
13	1		*REAR CENTRE BUMPER LH SIDE REFLECTOR	Cracked	30.80 F	*30.80 FL
14	1		*REAR RH BUMPER	Cracked	220.80 F	*220.80 FL
15	1		*REAR RH BUMPER SIDE RETAINER	Cracked	30.70 F	*30.70 FL
16	1		*REAR LH BUMPER	Cracked	220.80 F	*220.80 FL
17	1		*REAR LH BUMPER SIDE RETAINER	Cracked	20.70 F	*20.70 FL
18	1		*RH TAIL-LAMP	Refit	437.60 F	*- FL
19	1		*LH TAIL-LAMP	Refit	437.60 F	*- FL
20	1		*END PANEL	Dented	535.00 F	*535.00 FL
21	1		*END PANEL INNER GARNISH	Cracked	85.10 F	*85.10 FL
22	1		*SPARE TYRE PANEL	Repair	849.30 F	*- FL
23	1		*SPARE TYRE PANEL INSULATOR	Not Necessary	150.00 F	*- FL
24	1		*EXHAUST SILENCER	Not Necessary	584.20 F	*- FL
25	2		*EXHAUST SILENCER RUBBER HANGERS	Cracked / Distorted	102.00 F	*102.00 FL
26	1		*TAILGATE WINDSCREEN GLASS SEALANT	Necessary	70.00 FS	*40.00 FS
27	1		*TAILGATE WINDSCREEN GLASS INNER SEAL	Necessary	50.00 FS	*20.00 FS
28	1		*SET TAILGATE OUTER LOWER GARNISH CLIPS	Necessary	70.00 FS	*30.00 FS
29	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	70.00 FS	*35.00 FS
30	1		*SET REAR BUMPER REVERSE SENSOR (4 SENSORS)	Dented / Malfunction-2pc only	450.00 FS	*200.00 FS
31	1		*SET REAR CENTRE BUMPER CLIPS	Necessary	70.00 FS	*30.00 FS
32	1		*SET END PANEL INNER GARNISH CLIPSQNEC	Necessary	60.00 FS	*15.00 FS
33	1		*SET REAR RH FENDER INNER TRIM BOARD CLIPS	Necessary	40.00 FS	*26.00 FS
34	1		*SET REAR LH FENDER INNER TRIM BOARD CLIPS	Necessary	40.00 FS	*26.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$) 8,031.20 4,814.50
- List Item Discount on L Items 0.00/20.00% (\$\$) 0.00 878.50

Total Parts (\$\$) 8,031.20 3,936.00

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
-----	-----	----------	-------------	-----------	------------	--------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REPLACE THE ABOVE LISTED PARTS, KNOCK, STRAIGHTEN & RESHAPE, CUT & WELD BODY PANEL PARTS WHERE NECESSARY, RE-POSITION & RE-ALIGN, REPLACEMENT OF PARTS TO THE ORIGINAL POSITION INCLUDING ADJUSTMENT	New	1,500.00	900.00
2	APPLY RUST COATING ON THE REPLACED & REPAIRED PANELS	New	120.00	60.00
3	CHECK WIRING & LIGHTING SYSTEM ON AFFECTED AREAS	New	100.00	30.00
4	REMOVE & RE-INSTALL TAILGATE WINDSCREEN GLASS TO ASSIST REPAIRS	New	220.00	120.00
5	TRANSFER & REPLACE TAILGATE MECHANISM TO NEW TAILGATE	New	150.00	80.00
6	REMOVE, RE-INSTALL & REPLACE REAR INNER TRIMS, GARNISHES, BOARDS & SEATS TO ASSIST REPAIRS	New	350.00	80.00
7	REMOVE, ADJUST & REPLACE REAR BUMPER REVERSE SENSOR	New	100.00	60.00
8	REMOVE, REPLACE & RE-INSTALL EXHAUST SILENCER, RUBBER HANGERS & HEAT SHIELD TO ASSIST REPAIRS	New	120.00	80.00
9	TO PUTTY & SPRAY REPAIRED & REPLACED BODY PANELS	New	1,600.00	1,100.00
Gross Labour Cost (\$\$)			4,260.00	2,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >