



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Thatcham ecribe

|  |  |                       |                  |   |
|--|--|-----------------------|------------------|---|
| NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC17022484/R1rbe2  |  |                       |                  |   |
| 73 BRAS BASAH ROAD<br>#05-01 NTUC TRADE UNION HOUSESINGAPORE<br>189556   |  |                       | Date: 08-01-2018 |  |
|  |  |                       | Code: INC4       |   |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>  |  |                       |                  |   |
| Insured Veh.   | SJV 9264L  | Veh. Inspected        | SHC 4517P        |   |
| Policy No.   | 5094491723   | Coverage (\$)         | 0.00             |   |
| Claim No.  | MT/0970758-002   | Excess (\$)           | 0.00             |   |
| Assign From  |  | Assign Date           | 23/11/2017       |   |
| <b>2. Vehicle Particulars &amp; Condition</b>  |  |                       |                  |   |
| Make & Model   | TOYOTA PRIUS   | c.c                   | 1798             |   |
| Engine No.   | HIDDEN   | Year of Reg.          | 2015             |   |
| Chassis No.  | JTDKN36UX05757934  | Colour                | MAROON           |   |
| Odometer   | 318500   | Steering              | IN ORDER         |   |
| Brakes   | IN ORDER   | Modification          | NIL              |   |
| General  | FAIR   |                       |                  |   |
| <b>3. Conditions of Tyres</b>  |  |                       |                  |   |
|  | Size   | Make                  | Balance          |   |
| R/H Front Tyre   | 195/65 R15   | FALKEN                | 5 mm             |   |
| L/H Front Tyre   | 195/65 R15   | FALKEN                | 5 mm             |   |
| R/H Rear Tyre  | 195/65 R15   | FALKEN                | 5 mm             |   |
| L/H Rear Tyre  | 195/65 R15   | FALKEN                | 5 mm             |   |
| <b>4. Description of Damages</b>   |  |                       |                  |   |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.   |  |                       |                  |   |
| <b>5. General Information</b>  |  |                       |                  |   |
| Accident Date  | 21/11/2017   | Inspection Date       | 23/11/2017       |   |
| Survey held at   | SMRT AUTOMOTIVE SERVICES PTE LTD<br>60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705 |                       |                  |   |
| <b>5a. Remarks</b>   |  |                       |                  |   |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                       |                  |   |
| <b>5b. Estimate Days of Repair</b>   |  |                       |                  |   |
| ESTIMATED NORMAL PERIOD FOR REPAIR:  |  | <b>2 Working Days</b> |                  |   |