



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2015 TOYOTA HARRIER 2.0 (SKZ5889C)

Date of Loss

24 November 2017

Time of Loss

13.10

Loss Description

SKZ5889C (INSD) C/W SMB55C (TP) WHILE FILTERING SMRT/A-PAC

Comment

Workshop Details

Total Rebate Amount

63658

Nett Loss Amount

\$50,342.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

03/04/2018



Days of work completion *

55



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
SKZ5889C

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

28/01/2016



Mileage

27073

Age of Vehicle

1

Driver Details

CATEGORY Manufacturing Year

POLICY INFORMAT... 2015

CATEGORY Driver Name

ASSESSMENT INFO... 2015

FNOL INFORMATI... SHERVONNE SEM HUI HUI

CATEGORY Make

POLICY INFORMAT... TOYOTA

ASSESSMENT INFO... TOYOTA

CATEGORY Model

POLICY INFORMAT... HARRIER 2.0

ASSESSMENT INFO... HARRIER ELEGANCE 2.0 CVT ABS D/A

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... ZSU600070127

POST SURVEY INF...

CATEGORY

Date of Birth

FNOL INFORMATI...

20 October 1971

POST SURVEY INF...

dd/mm/yyyy



CATEGORY

Age

FNOL INFORMATI...

46

POST SURVEY INF...

CATEGORY

Occupation

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Education Qualification

FNOL INFORMATI...

Other

POST SURVEY INF...

CATEGORY

Driving Experience

ASSESSMENT INFO... ZSU600070127

CATEGORY Engine No

POLICY INFORMAT... 3ZRB712159

ASSESSMENT INFO... 3ZRB712159

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 1986

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO... 114000

FNOL INFORMATI... 4

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI... 1 January 2014

POST SURVEY INF... dd/mm/yyyy



CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy



CATEGORY Address

FNOL INFORMATI... BLK 421 FAJAR ROAD, #11-483, 670421,
Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

Personal Correspondence

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

Female

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

S7136925J

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

27/11/2017



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

500

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

225/65R17

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Spare wheel

Rear Tyre Size

225/65R17

Front left side

MICHELIN7mm

Front right side

MICHELIN7mm

Rear left side

MICHELIN7mm

Rear right side

MICHELIN7mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Save

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary Parts															
Add Approve Deny															
	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
☐		1	1			FRONT BONNET			Buckled	530				530	Review
☐		2	2			FRONT BONNET HINGE LH & RH			Serviceable	0	0	0	0	0	Deny
☐		3	2			FRONT BONNET ABSORBER LH & RH			Serviceable	0	0	0	0	0	Deny
☐		4	1			FRONT BONNET LOCK			Bent	50				50	Review
☐		5	1			FRONT BONNET LOCK CABLE			Serviceable	0	0	0	0	0	Deny
☐		6	9			FRONT BONNET INSULATOR CLIPS			Serviceable	0	0	0	0	0	Deny
☐		7	1			FRONT BONNET CHROME MOULDING OUTER			Cut	90				90	Review
☐		8	1			FRONT GRILLE			Damaged	200				200	Review
☐		9	8			FRONT GRILLE CLIPS			Necessary	1				8	Review
☐		10	2			HEADLAMP WITH HID LH & RH			Cracked	900				1800	Review
☐		11	2			HEADLAMP LOWER BEAM LH & RH (NPA)			Serviceable	0	0	0	0	0	Deny
☐		12	4			HEADLAMP CLIPS			Serviceable	0	0	0	0	0	Deny

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PART)
		13	2			HEADLAMP TOP SIDE PANEL LH & RH			Bent	65				130	Review
		14	1			FRONT BUMPER			Damaged	530				530	Review
		15	2			FRONT BUMPER SIDE RETAINER LH & RH			Necessary	38				76	Review
		16	12			FRONT BUMPER CLIPS			Necessary	1.5				18	Review
		17	1			FRONT BUMPER INNER TOP BEAM CTR			Bent	100				100	Review
		18	2			FRONT BUMPER INNER TOP SIDE BRACKET LH & RH			Serviceable	0	0	0	0	0	Deny
		19	1			FRONT BUMPER REINFORCEMENT			Bent	145				145	Review
		20	2			FRONT BUMPER REINFORCEMENT BRACKET LH & RH			Serviceable	0	0	0	0	0	Deny
		21	1			FRONT BUMPER SPONGE CTR BIG			Cracked	40				40	Review
		22	2			FRONT BUMPER SIDE SPONGE SMALL LH & RH			Damaged	18				36	Review
		23	1			FRONT BUMPER TOW COVER LH			Serviceable	0	0	0	0	0	Deny
		24	1			FRONT BUMPER LOWER GRILLE CTR			Cut	85				85	Review
		25	1			FRONT BUMPER LOWER COVER			Serviceable	0	0	0	0	0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PART)
		26	1			FRONT BUMPER LOWER SPOILER BLACK			Cracked	100				100	Review
		27	1			ENGINE UNDER COVER CTR			Deformed	65				65	Review
		28	1			FOGLAMP LH			Serviceable	0	0	0	0	0	Deny
		29	1			FOGLAMP COVER OUTER LH			Serviceable	0	0	0	0	0	Deny
		30	1			RADIATOR SUPPORT PANEL			Bent	320				320	Review
		31	1			RADIATOR SUPPORT PANEL INNER SIDE AIR GUIDE BIG LH			Serviceable	0	0	0	0	0	Deny
		32	2			RADIATOR SUPPORT PANEL INNER SIDE AIR GUIDE SMALL LH & RH			Serviceable	0	0	0	0	0	Deny
		33	1			RADIATOR SUPPORT PANEL TOP GARNISH			Deformed	135				135	Review
		34	12			RADIATOR SUPPORT PANEL TOP GARNISH CLIPS			Necessary	1.5				18	Review
		35	1			BRACE PANEL			Bent	75				75	Review
		36	2			HORN			Serviceable	0	0	0	0	0	Deny
		37	1			AIR CON CONDENSER ASSY ORI			Serviceable	0	0	0	0	0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTIO (PART:
		38	1			AIR CON CONDENSER PIPE (COND- VALVE)			Bent	200				200	Review
		39	1			AIR CON CONDENSER PIPE (COND- COMP)			Serviceable	0	0	0	0	0	Deny
		40	1			AIR CON CONDENSER FAN MOTOR			Serviceable	0	0	0	0	0	Deny
		41	1			AIR CON CONDENSER FAN BLADE			Serviceable	0	0	0	0	0	Deny
		42	1			RADIATOR ASSY ORI			Serviceable	0	0	0	0	0	Deny
		43	1			RADIATOR FAN BLADE			Serviceable	0	0	0	0	0	Deny
		44	1			RADIATOR FAN MOTOR			Serviceable	0	0	0	0	0	Deny
		45	1			RADIATOR FAN COWLING			Serviceable	0	0	0	0	0	Deny
		46	1			RADIATOR SPARE TANK			Serviceable	0	0	0	0	0	Deny
		47	1			WIPER WASHER TANK RH			Serviceable	0	0	0	0	0	Deny
		48	2			FRONT FENDER LH & RH			Buckled	290				580	Review
		49	1			FRONT FENDER COWLING LH			Serviceable	0	0	0	0	0	Deny
		50	20			FRONT FENDER COWLING CLIPS			Necessary	1.5				30	Review

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PART)
		51	1			FRONT BUMPER TOW COVER RH			Damaged	12				12	Review
		52	1			FOGLAMP RH			Cracked	115				115	Review
		53	1			FOGLAMP COVER OUTER RH			Deformed	40				40	Review
		54	1			RADIATOR SUPPORT PANEL INNER SIDE AIR GUIDE BIG RH			Deformed	45				45	Review
		55	1			FRONT FENDER COWLING RH			Damaged	155				155	Review

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	RI
		1		TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING	20	0	0	Reviewing		1
		2		TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS	100	0	0	Reviewing		1
		3		TO REMOVE & REINSTALL FRONT ENGINE MOUNTING, GEARBOX MOUNTING	0	0	0	Deny		1
		4		LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT - AIR BAG LIGHT & ENGINE LIGHT	0	0	0	Deny		1

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	RI
 	5		TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL, BRACE PANEL, FRONT BUMPER REINFORCEMENT, FRT BUMPER TOP BEAM CTR, SIDE BRACKET, HEADLAMP TOP PANEL. TO KNOCK & REPAIR FRT DOOR, FRT WHEELHOUSE SIDE PANEL, FRT CHASSIS FRAME	800	0	0	Reviewing		1
 	6		TO SPRAY PAINT FRT BONNET, FRT BUMPER, FRT BUMPER REINFORCEMENT, FRT BUMPER TOP BEAM CTR, FRT BUMPER SIDE BRACKET, BRACE PANEL, RADIATOR SUPPORT PANEL, HEADLAMP TOP PANEL, FRT FENDER, FRT DOOR, FRT CHASSIS FRAME, FRT WHEELHOUSE PANEL	700	0	0	Reviewing		1

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Add

Approve

Deny

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE	
☐		1	RADIATOR SUPPORT SIDE GARNISH RH	Reviewing	20	(DEFORMED) SUPP 1 - 30/11/2017	
☐		2	WIPER GRILLE SIDE GARNISH RH	Reviewing	20	(CUT)SUPP 1 - 30/11/2017	
☐		3	RADIATOR COOLANT	Reviewing	35	NECESSARY	
☐		4	NUMBER PLATE	Deny	0	NOT NECESSARY	

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Claim Amount \$6,923.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$1,620.00	\$1,620.00
Spare Parts	\$5,728.00	\$5,728.00
Miscellaneous	\$75.00	\$75.00
Excess	-\$500.00	-\$500.00

Submit for Review