

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJD 9916J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BONNET (CONSISTENT)	BUCKLED	380.00	380.00
2	BONNET HINGE @ \$50.00 (CONSISTENT)	BENT	100.00	100.00
1	BONNET LOCK (CONSISTENT)	TWISTED	45.00	45.00
1	BONNET RUBBER (CONSISTENT)	NECESSARY	30.00	30.00
1	FRONT GRILLE (CONSISTENT)	CRACKED	160.00	160.00
3	GRILL CLIP @ \$1.50 (CONSISTENT)	NECESSARY	4.50	4.50
1	FRONT BUMPER (CONSISTENT)	DISTORTED	240.00	240.00
2	BUMPER RETAINER @ \$45.00 (CONSISTENT)	BENT	90.00	90.00
1	BUMPER CLIP (CONSISTENT)	NECESSARY	15.00	15.00
1	BUMPER SPONGE (CONSISTENT)	MISSING	60.00	60.00
1	FRONT REINFORCEMENT (CONSISTENT)	DISTORTED	165.00	165.00
2	REINFORCEMENT SUPPORT @ \$55.00 (CONSISTENT)	BENT	110.00	110.00
1	FOG LAMP COVER O/S (CONSISTENT)	MISSING	35.00	35.00
1	BUMPER LOWER TRAY (CONSISTENT)	DISTORTED	180.00	180.00
1	SUPPORT PANEL (CONSISTENT)	BENT	450.00	450.00
2	HEADLAMP @ \$280.00 (CONSISTENT)	CRACKED	560.00	560.00
1	CONDENSER (CONSISTENT)	BENT / PUNCTURE	650.00	650.00
1	RADIATOR (CONSISTENT)	CRACKED	680.00	680.00
1	RADIATOR MOTOR (CONSISTENT)	JAMMED	180.00	180.00
1	RADIATOR COWLING (CONSISTENT)	CRACKED	75.00	75.00
1	RADIATOR BLADE (CONSISTENT)	BENT	55.00	55.00
2	AIRCON PIPE (CONSISTENT)	BENT	300.00	300.00
1	RADIATOR SPARE TANK (CONSISTENT)	NOT NECESSARY	65.00	-
1	WASHER TANK (CONSISTENT)	DISTORTED	120.00	120.00
1	WASHER TANK MOTOR (CONSISTENT)	DAMAGED	90.00	90.00
12	ALTERNATOR (CONSISTENT)	NOT NECESSARY	650.00	-
1	COMPRESSOR (CONSISTENT)	NOT NECESSARY	1,200.00	-
2	FAN BLADE (CONSISTENT)	NOT NECESSARY	35.00	-
10	BATTERY TRAY (CONSISTENT)	NOT NECESSARY	50.00	-
1	BOTTOM BRACKET (CONSISTENT)	BENT	65.00	65.00
1	AIR DUCT (CONSISTENT)	NOT NECESSARY	280.00	-

Report Ref No. CS/AXA17017016/Urbs2-1



LESS EXCESS

NETT LIABILITY

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

-400.00

6,100.00

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
2	AIR BOX (CONSISTENT)	NOT NECESSARY	280.00	-
1	FRONT CROSS MEMBER (CONSISTENT)	NOT NECESSARY	750.00	-
2	FRONT FENDER @ \$210.00 (CONSISTENT)	BUCKLED	470.00	470.00
1	ENGINE MOUNTING (CONSISTENT)	TWISTED / TORN	295.00	295.00
2	WIPER GARNISH (CONSISTENT)	DISTORTED	120.00	120.00
1	AUTO OIL (CONSISTENT)	NECESSARY	45.00	45.00
1	NUMBER PLATE (CONSISTENT)	BENT	40.00	40.00
1	COOLANT (CONSISTENT)	NECESSARY	20.00	20.00
			9,139.50	5,829.50
	<u>LABOUR</u>			
	TO CHECK WIRING.		300.00	30.00
	REMOVE & REFIX ENGINE.	NOT NECESSARY	800.00	-
	TO TOP UP AIR CON GAS.		100.00	100.00
	TO DISMANTLE & REPLACING ENGINE MOUNTING.		300.00	50.00
	TO DISMANTLE DASHBOARD.	NOT NECESSARY	350.00	-
	LABOUR FOR PANEL BEATING.		1,500.00	1,200.00
	SPRAY PAINTING.		1,080.00	950.00
			-	-
			-	-
			-	-
			-	-
			-	-
			-	-
			-	-
			-	-
			-	-
			4,430.00	2,330.00
	GRAND TOTAL		13,569.50	8,159.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,500.00

Report Ref No. CS/AXA17017016/Urbs2-1



Page No.:3 of 3

Report Ref No. CS/AXA17017016/Urbs2-1

MAX MV:\$12500 LESS SAL VALUE:\$(6641) REPAIR LIMIT:\$5859

COR S:\$6500 LESS REPAIRABLE LIMIT:\$5859 DIFF:\$641

GIA GUIDELINE (50% of 641):\$320.50 EXPRESS:\$400 TOTAL PAYABLE BY INS \$720.50(BFR GST) BAL OF \$5779.50 WILL BE PAID BY AXA INSURANC

CHUA KANG SENG

Licensed Appraiser