

22/03/2002

ASS. REC. BY:

REF: CS3/CTI17022506/T1 bez

Special Instruction:

range 2 days

Survivor: Taufik
Menmen

ASSIGNMENT (Office)

From (Person): Jauyn Tay of CTI Date/Time: 27/11/2017 @ 10.01am

Estimated Cost: Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: FY 6198X Insured: SGS 7493G

at Workshop m/s Hua Chin (2000) Trading Motor Tel: 68966619

of 50 Bkt Batok street 23, # 02-02 659578

Policy No: DMPCSN 3024681700 Claim No: SNM17D06573C02

Sum Insured: Excess:

Make of Veh: D.O.A. 12/11/2017
(Client's Record)

CA / REV / REP. / REV 24 HRS 1wp H.O.D. Endorsement:

Date/Time: 11.17am @ 27/11/17 Person Contacted: Mr. Tim Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	FY 6198X - X
	SGS 7493G - X
	Dismantle: 30/11/2017

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Nov 2017		27 Nov 2017 10:01 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	RAHMAT BIN SAION, ID: S1513491G		
Main Claimant:	WONG YUAN MING, ID: S68437671		
Vehicle Reg. No.:	FY6198X	Date of Loss:	12/11/2017 13:00 - :59
Claim Type:	TP / SNM17D06573C02	Policy/Cover Note No.:	DMPCSN3024681700 (Comprehensive) Coverage: 22/03/2017 - 21/03/2018
Vehicle Reg. No. (Insured):	SGS7493G	Policy No. (Claimant):	5073831361-01
		Excess:	S\$0.00
Repairer:	Hua Chin (2000) Trading Motor Service Centre (HQ) 50 BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING, 659578 Bukit Batok - Tel: 68966619		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 06/12/2017]		
Adj Asg. Remarks:	NO ESTIMATES. ASSIGNED AS SJE FOR WP PRS		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

**GOH JP & WONG LLC****advocates & solicitors
commissioner for oaths**

GOH TECK WEE

WONG TZE ROY

WONG FUNG KWAI

SOON WEI SONG

133 New Bridge Road #16-09 Chinatown Point Singapore 059413

Tel: 6538 5868 Fax: 6538 4898 (Not for service of Court documents) Email: mail@gohjpwwong.com

Goh JP & Wong LLC is a law corporation with limited liability GST/UEN: 201406078M

YOUR REF:

OUR REF:

GTW.ACC.11T158.17.dn

WHEN REPLYING, PLEASE QUOTE OUR REFERENCE NO

DATE:

23rd November 2017

Rahmat Bin Saion
5 Jalan Machang
Singapore 759165

Dear Sirs

NOTIFICATION OF ACCIDENT**SUBJECT MATTER: TRAFFIC ACCIDENT INVOLVING FY 6198X & SGS 7493G ON 12.11.2017
ALONG FAJAR ROAD**

We act for Wong Yuan Ming in the above matter.

We are instructed to notify you of the above accident on 12th November 2017 at about 13:30 pm at Fajar Road involving our client's motorcycle FY 6198X and motorcar SGS 7493G driven by you at the material time. A copy of our client's traffic police report filed is enclosed.

As a result of the accident, our client's motorcycle FY 6198X has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days (excluding Saturdays, Sundays and Public Holidays) of your receipt of this notice whether you or your insurer would like to conduct a pre-repair inspection of the vehicle or whether you or your insurer waive the pre-repair inspection. If we do not receive any reply from you within the stipulated timeline our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully

Goh Teck Wee

Enc.

Cc China Taiping Insurance (Singapore) Pte Ltd
Singapore
Attention: Motor Claims Department

BY FAX ONLY
Fax No. 6224 7175

Cc Hua Chin (2000) Trading Motor Service Centre
Fax No. 6515 5190
Please do not proceed with repairs until further notice.



Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin () : Case handler to make sure all information created by the assignment team are **ACCURATE**

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor () : Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

Case Handler

Date

*C: Critical *N: Non-Critical

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	3767I
Vehicle Details	
Vehicle No.	FY6198X
Vehicle to be Exported	No
Intended De-registration Date	14 Dec 2017
Vehicle Make	YAMAHA
Vehicle Model	RXZ
Primary Colour	Red
Manufacturing Year	2004
Engine No.	5PV008194
Chassis No.	PMY5PV10000008194
Maximum Power Output	-
Open Market Value	\$2,500.00
Original Registration Date	12 Nov 2004
First Registration Date	12 Nov 2004
Transfer Count	6
Actual ARF Paid	\$375.00
Intended PARF Rebate Details	
PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00
Intended COE Rebate Details	
COE Expiry Date	11 Nov 2019
COE Category	D - Motorcycle
COE Period(Years)	5
PQP Paid	\$2,240.00
COE Rebate Amount	\$883.00
Total Rebate Amount	\$883.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 14 Dec 2017



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS3/CTI17022506/T1b		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 27-11-2017		
		Code : CTI		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SGS 7493G	Veh. Inspected	FY 6198X	
Policy No.	DMPCSN3024681700	Coverage (\$)	0.00	
Claim No.	SNM17D06573C02	Excess (\$)	0.00	
Assign From	MERIMEN (JOWYN TAY)	Assign Date	27/11/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	12/11/2017	Inspection Date	27/11/2017	
Survey held at	HUA CHIN (2000) TRADING MOTOR SVC CENTRE 50, BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING SINGAPORE 659578			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Nov 2017		27 Nov 2017 10:01 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	RAHMAT BIN SAION, ID: S1513491G								
Main Claimant:	WONG YUAN MING, ID: S68437671								
Vehicle Reg. No.:	FY6198X	Date of Loss:	12/11/2017 13:00 - :59 [156 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM17D06573C02	Policy/Cover Note No.:	DMPCSN3024681700 (Comprehensive) Coverage: 22/03/2017 - 21/03/2018						
Vehicle Reg. No. (Insured):	SGS7493G	Policy No. (Claimant):	5073831361-01						
		Excess:	S\$0.00						
Repairer:	Hua Chin (2000) Trading Motor Service Centre (HQ) 50 BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING, 659578 Bukit Batok - Tel: 68966619								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 06/12/2017]								
Adj Asg. Remarks:	NO ESTIMATES. ASSIGNED AS SJE FOR WP PRS								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FY6198X (SNM17D06573C02)

[SGS7493G]

TP

WONG YUAN MING

Nov 12 2017 1:00PM

[RAHMAT BIN SAION]

Hua Chin (2000) Trading Motor Service Centre

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	VAC (Bukit Batok)	Thumbnail	Print
1	22/11/17 14:19	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	VAC (Bukit Batok)	Thumbnail	Print
1	22/11/17 14:17	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
2	22/11/17 14:17	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
3	22/11/17 14:17	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
4	22/11/17 14:17	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
5	22/11/17 14:17	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
6	22/11/17 14:17	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/05/18 17:11	General View	 Load JPG	☒
2	08/05/18 17:11	General View	 Load JPG	☒
3	08/05/18 17:11	General View	 Load JPG	☒
4	08/05/18 17:11	General View	 Load JPG	☒
5	08/05/18 17:11	General View	 Load JPG	☒
6	08/05/18 17:11	General View	 Load JPG	☒
7	08/05/18 17:11	General View	 Load JPG	☒
8	08/05/18 17:11	General View	 Load JPG	☒
9	08/05/18 17:11	General View	 Load JPG	☒
10	08/05/18 17:11	General View	 Load JPG	☒
11	08/05/18 17:11	General View	 Load JPG	☒
12	08/05/18 17:11	General View	 Load JPG	☒
13	08/05/18 17:11	General View	 Load JPG	☒
14	08/05/18 17:11	General View	 Load JPG	☒
15	08/05/18 17:11	General View	 Load JPG	☒
16	08/05/18 17:11	General View	 Load JPG	☒
17	08/05/18 17:11	General View	 Load JPG	☒
18	08/05/18 17:11	General View	 Load JPG	☒
19	08/05/18 17:11	General View	 Load JPG	☒
20	08/05/18 17:11	General View	 Load JPG	☒
21	08/05/18 17:11	General View	 Load JPG	☒
22	08/05/18 17:11	General View	 Load JPG	☒
23	08/05/18 17:11	General View	 Load JPG	☒
24	08/05/18 17:11	General View	 Load JPG	☒
25	08/05/18 17:11	General View	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	VAC (Bukit Batok)	Thumbnail	Print
26	08/05/18 17:11	General View	 Load JPG	☒
27	08/05/18 17:11	General View	 Load JPG	☒
28	08/05/18 17:11	General View	 Load JPG	☒
29	08/05/18 17:11	General View	 Load JPG	☒
30	08/05/18 17:11	General View	 Load JPG	☒
31	08/05/18 17:11	General View	 Load JPG	☒
32	08/05/18 17:11	General View	 Load JPG	☒
33	08/05/18 17:11	General View	 Load JPG	☒
34	08/05/18 17:11	General View	 Load JPG	☒
35	08/05/18 17:11	General View	 Load JPG	☒
36	08/05/18 17:11	General View	 Load JPG	☒
37	08/05/18 17:11	General View	 Load JPG	☒
38	08/05/18 17:11	General View	 Load JPG	☒
39	08/05/18 17:11	General View	 Load JPG	☒
40	08/05/18 17:11	General View	 Load JPG	☒
41	08/05/18 17:11	General View	 Load JPG	☒
42	08/05/18 17:11	General View	 Load JPG	☒
43	08/05/18 17:11	General View	 Load JPG	☒
44	08/05/18 17:11	General View	 Load JPG	☒
45	08/05/18 17:11	General View	 Load JPG	☒
46	08/05/18 17:11	General View	 Load JPG	☒
47	08/05/18 17:11	General View	 Load JPG	☒
48	08/05/18 17:11	General View	 Load JPG	☒
49	08/05/18 17:11	General View	 Load JPG	☒
50	08/05/18 17:11	General View	 Load JPG	☒
51	08/05/18 17:11	General View	 Load JPG	☒
52	08/05/18 17:11	General View	 Load JPG	☒
53	08/05/18 17:11	General View	 Load JPG	☒
54	08/05/18 17:11	General View	 Load JPG	☒
55	08/05/18 17:11	General View	 Load JPG	☒
56	08/05/18 17:11	General View	 Load JPG	☒
57	08/05/18 17:11	General View	 Load JPG	☒
58	08/05/18 17:11	General View	 Load JPG	☒
59	08/05/18 17:11	General View	 Load JPG	☒
60	08/05/18 17:11	General View	 Load JPG	☒
61	08/05/18 17:11	General View	 Load JPG	☒
62	08/05/18 17:11	General View	 Load JPG	☒
63	08/05/18 17:11	General View	 Load JPG	☒
64	08/05/18 17:13	Photographs of Damaged Parts	 Load JPG	☒
65	08/05/18 17:13	Photographs of Damaged Parts	 Load JPG	☒
66	08/05/18 17:13	Photographs of Damaged Parts	 Load JPG	☒
67	08/05/18 17:13	Photographs of Damaged Parts	 Load JPG	☒
68	08/05/18 17:13	Photographs of Damaged Parts	 Load JPG	☒
69	08/05/18 17:13	Photographs of Damaged Parts	 Load JPG	☒
70	08/05/18 17:13	Photographs of Damaged Parts	 Load JPG	☒
71	08/05/18 17:13	Photographs of Damaged Parts	 Load JPG	☒
72	08/05/18 17:13	Photographs of Damaged Parts	Load JPG	☒
73	08/05/18 17:13	Photographs of Damaged Parts	Load JPG	☒
74	08/05/18 17:13	Photographs of Damaged Parts	Load JPG	☒
75	08/05/18 17:13	Photographs of Damaged Parts	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	VAC (Bukit Batok)	Thumbnail	Print
76	08/05/18 17:13	Photographs of Damaged Parts	Load JPG	☒
77	08/05/18 17:13	Photographs of Damaged Parts	Load JPG	☒
78	08/05/18 17:13	Photographs of Damaged Parts	Load JPG	☒
79	08/05/18 17:13	Photographs of Damaged Parts	Load JPG	☒
80	08/05/18 17:13	Photographs of Damaged Parts	Load JPG	☒
81	08/05/18 17:13	Photographs of Damaged Parts	Load JPG	☒
82	08/05/18 17:13	Photographs of Damaged Parts	Load JPG	☒
83	08/05/18 17:13	Photographs of Damaged Parts	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	25/11/17 11:59	Pre-Repair Survey	Load PDF	
No	Finalized On	VAC (Bukit Batok)	Thumbnail	Print
1	22/11/17 14:18	Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	22/11/17 14:18	Sketch Plan #2 [Linked Accident Report Documents]	Load TIF	
3	22/11/17 14:19	PR [Linked Accident Report Documents]	Load TIF	
4	22/11/17 14:19	PR [Linked Accident Report Documents]	Load TIF	
5	22/11/17 14:19	PR [Linked Accident Report Documents]	Load TIF	

Linked Accident Report Documents

View

View in Browser

Assessment Reports			1 per page	☒
No	Finalized On	VAC (Bukit Batok)	Thumbnail	Print
1	22/11/17 14:19	Accident Statement	Load HTM	

Photos/Images			3 per page	☒
No	Finalized On	VAC (Bukit Batok)	Thumbnail	Print
1	22/11/17 14:17	Accident Photo	Load JPG	☒
2	22/11/17 14:17	Accident Photo	Load JPG	☒
3	22/11/17 14:17	Accident Photo	Load JPG	☒
4	22/11/17 14:17	Accident Photo	Load JPG	☒
5	22/11/17 14:17	Accident Photo	Load JPG	☒
6	22/11/17 14:17	Accident Photo	Load JPG	☒

Documentation			1 per page	☒
No	Finalized On	VAC (Bukit Batok)	Thumbnail	Print
1	22/11/17 14:18	Sketch Plan	Load TIF	
2	22/11/17 14:18	Sketch Plan #2	Load TIF	
3	22/11/17 14:19	PR	Load TIF	
4	22/11/17 14:19	PR	Load TIF	
5	22/11/17 14:19	PR	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI17022506/T1BE2

Date: 09/05/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3024681700

Claimant Vehicle
No: FY6198X

Insured Vehicle
No: SGS7493G

Date of Loss: 12/11/2017

Nature of Claim: TP

Claim
No: SNM17D06573C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FY6198X**

Make & Model: YAMAHA RXZ, 133cc (M)

Reg. Date: 12/11/2004 (Man. Year: 2004)

Colour: Red

Engine Capacity: 133 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 5PV008194

Chassis No: PMY5PV10000008194

Odometer: 27448 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 80/90 R18

Rear Tyre Size: 3.60 R18

Front Left Side: Golden Boy 5 mm

Rear Left Side: Golden Boy 5 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 27/11/2017

Date Inspected: 27/11/2017 Inspected At:

Hua Chin (2000) Trading Motor Service
Centre (HQ)
50 BUKIT BATOK STREET 23, #02-02
MIDVIEW BUILDING
Singapore 659578

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500.00 - \$4,500.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 09 May 2018)	
Parts:	N/A	YAMAHA RXZ 133cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FY6198X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >