

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJH 68U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED	1,418.00	1,418.00
1	FRONT UPPER GRILLE ASSY	CRACKED	1,064.00	1,064.00
1	FRONT GRILLE LOGO	NECESSARY	142.00	142.00
1	HID HEADLAMP, LH	CRACKED	4,948.00	3,150.00
1	HID HEADLAMP, RH	CRACKED	4,948.00	3,150.00
1	FRONT BUMPER RETAINER	NOT NECESSARY	64.00	-
1	BONNET ACTIVE ACTUATOR, LH A212 906 77 01	ACTIVATED	385.00	385.00
1	BONNET ACTIVE ACTUATOR, RH A212 906 78 01	ACTIVATED	385.00	385.00
1	BONNET STOPPER	DAMAGED	32.00	32.00
1	BONNET HINGE, LH	NOT NECESSARY	124.00	-
1	BONNET HINGE, RH	NOT NECESSARY	124.00	-
	LESS 10% DISCOUNT		-1,363.40	-972.60
			12,270.60	8,753.40
	<u>LABOUR</u>			
	LABOUR TO REMOVE DAMAGED PARTS, ALIGN AND REPLACE PARTS.		400.00	250.00
	SPRAY PAINTING ON FRONT BUMPER AND FRONT BONNET.		600.00	400.00
	RESET AND REPROGRAM BONNET ACTIVE SYSTEM.		300.00	120.00
	CHECK ELECTRICAL.		80.00	30.00
			1,380.00	800.00
	GRAND TOTAL		13,650.60	9,553.40
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,600.00

Report Ref No. CS/IAS17022538/Avbs2

ADRIAN LING WAI PING**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI****Licensed Appraiser**

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.