



**SINGAPORE
POLICE FORCE**



T/20161026/2068

2 of 3

Report No. T/20161026/20

Police Station Of Origin:
Hong Kah North NPP
370 Bukit Batok Street 31 #01-201
SINGAPORE 650370
Tel No: 1800-5679999

CONTINUATION OF REPORT

GR8969A	NTUC Income Insurance Co-Operative Limited	5050559955-05	24/06/2016	23/06/2017
---------	--	---------------	------------	------------

Any Pedestrian Involved: No		Use of Pedestrian Crossing: NA	
No. of Pedestrians Injured: NIL			
Name	PHUA THIAM KENG	ID No.	S0858321H
Related Vehicle	GR8969A (Van)	Contact No.	96981907
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

I was driving V1) GR8969A along Marymount Lane and I was on the left most lane of the 4 lane road and I had stopped at the junction between Marymount Lane and Upper Thomson Road and I wanted to turn left. The traffic light was red against my favour. I was the first vehicle on the lane. Beside me on the right side (also the first car) on lane 3 was V2) SJV4585T. Out of a sudden, I saw a blue taxi V3) SHC1293D moving towards my vehicle from my right side from Upper Thomson Road. V3's front bumper hit onto V1 right front bumper. This caused both V3 and V2 to hit V1 together. I wish to state that after the accident, driver of V3 told me had hit onto another taxi V4) SHC7370A while driving along Upper Thomson Road before veering off Upper Thomson Road and hit V2 causing the subsequent accident with V2 and V1. I was unable to obtain the other drivers' particulars. V1 suffered a large dent on the right side of the vehicle.



**SINGAPORE
POLICE FORCE**



T/20161026/2068

3 of 3

Report No. T/20161026/2068

Police Station Of Origin:
Hong Kah North NPP
370 Bukit Batok Street 31 #01-201
SINGAPORE 650370
Tel No: 1800-5679999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Sgt MUHAMMAD NURSYAZWAN BIN RASIDI

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Staff Sgt MOHAMED HUSNUL TAUFIQ BIN MD
YUSOF

Contact No: 65476358

Authentication Stamp

NP168

Signature Of Informant:

Phu Huikey

Date/Time:

26/10/2016 12:45

Classification Of Case:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/10/2016 15:59
Date Of Accident	25/10/2016 09:20
Exact Location Of Accident	MARYMOUNTLANE AND UPPER THOMSON ROAD JUNCTION
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJV4585T
Insured/Policyholder	
Name Of Registered Owner	GANESAN KANNAN
Email Address	KANNANG77@YAHOO.COM
Mobile Phone No	(LOCAL) +65-91258127
Alternative Phone No	OTHERS-91258127
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	AVANTE 1.6 AT ABS D/AB 2WD 4DR
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10153726
Cover Note Number	N.A
Driver	
Name of Driver	GANESAN KANNAN
NRIC No	S2713389D
Address	

General Information of the Accident

Type Of Accident	COLLISION- CHAIN COLLISION
Weather Conditions	CLEAR

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
Number of Passengers (Including Driver)	3

Circumstances of Accident

REFER TO POLICE REPORT NO.T/20161026/2025: ON 25 OCTOBER 2016 AT ABOUT 2115HRS I WAS TRAVELLING MY CAR (SJV4585T) ALONG MARYMOUNT LANE TOWARDS UPPER THOMSON ROAD. I THEN MADE A STOP AT THE TRAFFIC LIGHT AS I WANTED TO TURN LEFT TOWARDS UPPER THOMSON ROAD. I WAS AT THAT MOMENT ON THE 2ND LANE AND THERE WAS ALSO A VEHICLE ON MY LEFT WHICH IS A VAN (GR8969A). WE WERE BOTH WAITING FOR THE TRAFFIC LIGHT TO TURN GREEN. SUDDENLY, THERE WAS TWO TAXI WHO COLLIDED AT THE CROSS JUNCTION OF UPPER THOMSON ROAD. THE TWO TAXI INVOLVED WERE (SHC1293D) AND (SHC7370A). THE TAXI'S (SHC1293D) WAS ON THE RIGHT WAY OF PATH WHEN SUDDENLY THE TAXI (SHC7370A) COLLIDED WITH IT. SUBSEQUENTLY, DUE TO BOTH THE COLLISION AND THE IMPACT, ONE OF THE TAXI (SHC1293D) DRIFT AND HIT MY CAR AND THE VAN WHICH EARLIER IS ON THE TRAFFIC LIGHT. I THEN MADE A CHECK AND REALIZED THAT MY FRONT BUMPER WERE SERIOUSLY DAMAGED WHIEL THE VAN BESIDES ME SUFFERED SLIGHT DAMAGE TO THE RIGHT PORTION. BOTH TAXIS SUFFERED SERIOUS DAMAGE TO THE FRONT BUMPERS AS WELL. I ALSO WISH TO STATE THAT THERE WAS AMBULANCE AT SCENE AND SOMEONE WAS CONVEYED BY AMBULANCE, HOWEVER I AM NOT SURE WHICH VEHICLE DRIVER WHO WAS CONVEYED. I ALSO WISH TO STATE THAT I DO NOT REMEMBER HOW MANY PASSENGERS WERE INVOLVED IN THIS ACCIDENT. TP WERE ALSO AT SCENE. I WISH TO STATE THAT I DO NOT HAVE AN INBUILT VIDEO RECORDER IN MY CAR. I WAS TASK TO LODGE A TRAFFIC REPORT VIDE THIS REPORT NO E/20161025/0113. I AM ALSO LODGING THIS REPORT FOR MY INSURANCE CLAIM PURPOSES.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHC1293D
Vehicle Make/Model/Colour COMFORT TAXI
Name of Driver
Insurance Company Name

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SHC7370A
Vehicle Make/Model/Colour YELLOW CITY CAB
Name of Driver
Insurance Company Name


DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number GR8969A
Vehicle Make/Model/Colour N.A
Name of Driver
Insurance Company Name

DETAILS OF INJURED PERSON 1

Name UNKNOWN PASSENGER
Injured person in which vehicle?

Sketch Plan



Name	DAVID L. HANNA	ID#	10000000
Related Vehicle	1964 Ford Mustang	ID#	10000000
Hospital/Glenc	NIL	ID#	10000000
Date Treated	11/11/64	ID#	10000000
No. of Orgs. treated	1	ID#	10000000

Brief Details

[illegible]



SINGAPORE
POLICE FORCE

Police Station of Origin
Road Policing Unit
Traffic Area 21/22, Singapore City
Tel: 9999 9999

INVESTIGATION REPORT

Report No. 123456789

Sketch Plan

Reference to the case file number

DEFENDANT: Please attach a copy of your vehicle's insurance certificate to this report. If you do not have the certificate with you now, please do a copy to the police station for reference.

Signature of Officer Handling the Report

Signature of Officer Handling the Report

Signature of Officer Handling the Report

Signature of Officer Handling the Report

Signature of Officer Handling the Report

Signature of Officer Handling the Report

Signature of Officer Handling the Report

Signature of Officer Handling the Report

Signature of Officer Handling the Report

Signature of Officer Handling the Report

Signature of Officer Handling the Report

Signature of Informant

Signature of Informant

Signature of Informant

Signature of Informant

Signature of Informant

Signature of Informant

Signature of Informant

Signature of Informant

Signature of Informant

Signature of Informant

Signature of Informant

Signature of Informant

Enquire Transfer Fee**Vehicle Details**

Vehicle No. : GR6969A
 Vehicle Type : A50 - Goods (Closed) Van/Van Panel (Delivery)
 Vehicle Attachment 1 : No Attachment
 Vehicle Scheme : Normal
 Vehicle Make : DAIHATSU
 Vehicle Model : S200RV-SMLK
 Chassis No. : JDAS200V001000500
 Propellant: Petrol
 Engine No. : 6443665
 Engine Capacity : 659 cc
 Maximum Power Output : -
 Maximum Laden Weight: 1370 kg
 Unladen Weight: 840 kg
 Year Of Manufacture: 2000
 Original Registration Date: 24 Jun 2000
 Lifespan Expiry Date : 23 Jun 2020
 COE Category : C - Goods Vehicle & Bus
 PQP Paid : \$86.00
 COE Expiry Date : 31 Mar 2017 *Smith*
 Road Tax Expiry Date : 23 Dec 2016
 Inspection Due Date : 23 Dec 2016
 Intended Transfer Date : 26 Oct 2016

CO2 Emission: -

The current road tax expiry is 23 Dec 2016. You may renew the road tax from 24 Sep 2016 with all pre-requisite(s) fulfilled. If the road tax is renewed after 23 Dec 2016, late renewal fee(s) will be imposed. Please use [Enquire Road Tax Payable](#) to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 24 Dec 2016 to 31 Mar 2017)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	11.00	-	11.00
Sub Total :			11.00
Nett Road Tax Amount (After Offsetting Over Payment) :	139.00	-	139.00
Total Amount Payable :			150.00

You may print this page for reference.

OK Print



BLUWEL AUTOMOTIVE SERVICE PTE LTD

Workshop: 1 Kaki Bukit Ave 6 (Unit B) #01-28
(Unit C) #01-51/53/55 Singapore 417883
Hp: 9755 2088 Tel: 6745 2088 Fax: 6841 2088
Website: www.bluwel.com.sg Email: bluwel2088@yahoo.com.sg
Co. Reg. No.: 200704951N
GST Reg. No.: 200704951N

Vehicle No : GR 8969 A
Make/Model : Daihatsu Hijet
Name : Phua Thiam Keng
Address : c/o No.1 Kaki Bukit Ave 6
#01-53/55 AutoBay@ Kaki Bukit
Singapore 417883

Date : 7-Feb-17

QTY	ITEM	AMT (\$)
-----	------	----------

Lump sum repair costs

	\$	10,700.00
GST 7 %	\$	749.00
Grand-total	\$	<u>11,449.00</u>

Dollars : Eleven Thousand Four Hundred And Forty Nine Only



QUANTUM RISK MANAGEMENT

Quantum Risk Management (S) Pte Ltd (Co.Reg.No:201415836W)

8 Ubi Road 2, #06-07 Zervex Building
Singapore 408538

Tel: 6444 2112 Fax: 6538 0121 Email: info@quantum-risk.com.sg

VEHICLE DAMAGE INSPECTION REPORT

Our File No: AV-01769
Date: 24/01/2017

REFERENCE

Handling Insurer:	Aviva Ltd	Policy No:	10153726
Claimant Vehicle No :	GR8969A	Insured Vehicle No :	SJV4585T
Date of Loss:	25/10/2016	Nature of Claim:	TP
		Claim No:	G0037945

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GR8969A	Engine No:	6443665
Make & Model:	DAIHATSU S200RV-SMLK, 659cc (M)	Chassis No:	JDAS200V001000500
Reg. Date:	24/06/2000 (Man. Year: 2000)	Odometer:	33627 km
Colour:	Silver		
Engine Capacity:	659 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	155R15C	Rear Tyre Size:	155R15C
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,077.67	1,909.19	168.48	8.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,220.00	1,440.00	780.00	35.14
Paintwork Labour	0.00	0.00	0.00	
Washing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,297.67	3,349.19	948.48	22.07
Approved Total (Overridden) (S\$)		2,700.00		
Nett Amount (S\$)	4,297.67	2,700.00	1,597.67	37.18

INSPECTION

Date of Assignment:	28/10/2016		
Date Inspected:	28/10/2016	Inspected At:	Bluwel Automotive Service Pte Ltd (KAKI BUKIT) 1 KAKI BUKIT AVE 6 (UNIT B) #01-28 Singapore 417883
Estimated Period of Repair:	5.0 days		

Adjuster: Nicholas Tey

Manager: Robin Poon

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Incident Details

The driver of the insured vehicle (Insured, Ganesan Kannan) and the driver of the Third Party vehicle (Owner, Phua Thiam Keng) were involved in a chain collision at the junction of Marymount Lane and Upper Thomson Road on 25.10.2016 @ 2115hrs.

Damage Consistency / Extent of Loss

Damage to the Third Party vehicle is consistent with the claim report and relates to a single incident.

Impact damage has been occasioned to the RH of the Third Party vehicle, damaging the rear RH fender, rear RH sliding door, rear RH rim. Further damage may be apparent upon dismantling.

No documents was provided during our initial inspection. The repairer had contacted us to conduct the post repair inspection. During the inspection, we were notified that all documents will be handled to their lawyers. No finalization was done with the repairer.

The repair time frame would be estimated at approximately 5 days upon commencement of repairs.

Economical Repair Limit and PARF/COE Rebate

The market value of this vehicle is about S\$2,500. PARF/COE Rebate is S\$3. The Economical Repair Limit is about S\$2,497.

Further Comments / Recommendations

As per your instructions, the above Survey has been carried out on a " Without Prejudice " basis and no repairs have been authorised by our office.

We hereby submit our Inspection Report and images for your perusal. We now await any further instructions.

REPAIR DETAILS**Reference**

Part Source: (Last Synchronised: 24 Jan 2017)

Parts: N/A DAIHATSU S200RV-SMLK 659cc (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Quantum Risk Management (S) Pte Ltd/GR8969A/24/01/2017 12:59

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILLAMP	Disallowed	115.85 FL	*- FL
2	1		*REAR BUMPER	Damage	426.25 FL	*426.25 FL
3	1		*REAR FENDER	Damage	895.45 FL	*895.45 FL
4	1		*O/S SLIDING DOOR	Damage	755.00 FL	*755.00 FL
5	1		*REAR TYRE	Damage	64.00 FS	*64.00 FS
6	1		*REAR RIM	Damage	150.00 FS	*80.00 FS
					Sub Total (\$\$)	
					2,406.55	2,220.70
					- List Item Discount on L Items 15.00/15.00% (\$\$)	
					328.88	311.51
					Total Parts (\$\$)	
					2,077.67	1,909.19

*Franchise part, S=SpcNett, L=ListItemDisc.

Quantum Risk Management (S) Pte Ltd/GR8969A/24/01/2017 12:59. Not valid without Reference section.

1887-59

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING, HARNESS WIRES, SOCKETS, REPLACE DAMAGED PARTS	New	30.00	20.00
2	TO CHECK RE-ADJUST (COMPUTERIZED) ALL WHEEL ALIGNMENT	New	120.00	80.00
3	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	1,100.00	800.00
4	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	880.00	500.00
5	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION	New	90.00	40.00

Gross Labour Cost (S\$)	2,220.00	1,440.00
-------------------------	----------	----------

Quantum Risk Management (S) Pte Ltd/GR8969A/24/01/2017 12:59. Not valid without Reference section.
--

< END OF ESTIMATES >

MC-COY

APPRAISER PTE LTD

No 1 Kaki Bukit Avenue 6 #01 - 28 AutoBay @ Kaki Bukit Singapore 417883 Tel: 6748 6653 Fax: 6747 1017
Registration No: 200723252D

Invoice No 16062-10/MY

Billing Name & Address

Date 7 Feb 2017

Phua Thiam Keng
c/o No.1 Kaki Bukit Ave 6
#01-53/55 AutoBay@ Kaki Bukit
Singapore 417883

Vehicle No : GR 8969 A

Model : Daihatsu Hijet

Item	Descriptions	Amount S\$
1	Date of inspection : <u>31 Oct 2016</u> A copy of the inspection / survey report Correspondence, postages and etc.	
2	Photography Services - Develop photographs - Storage of digital photographs - Submission of photographs <u>113</u> copies	
3	Transportation Charges	
	Total	<u>\$ 758.00</u>
	SDLS : SEVEN HUNDRED AND FIFTY-EIGHT ONLY	

Notes :

1. All cheque payment should be "Crossed" and made payable to "Mc-Coy Appraiser Pte. Ltd."
2. All cheque should have our "Invoice No." written on the reverse side of the cheque
3. For further enquiries on this invoice, please feel free to contact us



Official Stamp

E & O, E

Report Reference : TP / 16062-10/MY / 2016
Date of Report : 7 Feb 2017

Phua Thiam Keng
c/o No.1 Kaki Bukit Ave 6
#01-53/55 AutoBay@ Kaki Bukit
Singapore 417883

**THIRD PARTY SURVEY
ACCIDENT HAPPENED ON 25 Oct 2016**

Workshop Address : Bluwel Automotive Service Pte Ltd
No.1 Kaki Bukit Ave 6
#01-53/55 AutoBay@ Kaki Bukit
Singapore 417883

As per your instruction dated **31 Oct 2016** with regard to the above matter. We have carried out a physical inspection on the said vehicle **GR 8969 A**. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No	: GR 8969 A	Engine No	: 6443665
Model	: Daihatsu Hijet	Mileage	: 336273
Year / Capacity	: 2000/659	Colour	: Silver
Chassis No	: JDAS200V001000500		

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT O/S	: 155 R12	Gondor	4.00	mm	Normal
REAR O/S	: 155 R12	Yokohama	4.00	mm	Normal
FRONT N/S	: 155 R12	Gondor	4.00	mm	Normal
REAR N/S	: 155 R12	Yokohama	4.00	mm	Normal

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the entire o/s portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 14 working days to complete.
5. Enclosed number of photograph : 113 copies.
6. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey was done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.
7. Should you discover any discrepancy in the report, please kindly notify us **within 2 weeks**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: GR 8969 A
Report No: TP/ 16062-10/MY / 2016

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Front windscreen moulding	Intact	\$ 272.45	\$ 11 X
1	Front headlamp	Damage	\$ 581.45	\$ 581.45 ✓
1	Front bumper	Damage	\$ 561.60	\$ 561.60 ✓
1	Front fender	Damage	\$ 372.75	\$ 372.75 X
1	Front fender inner shield	Damage	\$ 191.60	\$ 191.60 X
1	Front fender inner shield clip (1 set)	Necessary	\$ 12.90	\$ 12.90 X
1	Front mudflap	Damage	\$ 172.45	\$ 172.45 ✓
1	Fuel lip cover	Damage	\$ 182.10	\$ 182.10 ✓
1	Front door	Damage	\$ 1218.40	\$ 1218.40 ✓
1	Front door checker	Damage	\$ 172.45	\$ 172.45 ✓
1	Front door glass	Damage	\$ 581.90	\$ 581.90 ✓
1	Front door glass outer moulding	Necessary	\$ 274.45	\$ 274.45 ✓
1	Front door hinge	Damage	\$ 132.25	\$ 132.25 ✓
1	Front door inner board	Damage	\$ 561.60	\$ 561.60 ✓
1	Front door lock	Damage	\$ 150.00	\$ 150.00 ✓
1	Front door regulator	Damage	\$ 291.60	\$ 291.60 ✓
1	Front door rubber	Necessary	\$ 287.70	\$ 287.70 ✓
1	Front door side mirror	Damage	\$ 561.10	\$ 561.10 X
1	Front door speaker	Intact	\$ 78.00	\$ 11 X
1	Front door inner handle	Intact	\$ 172.45	\$ 11 X
1	Front door channel	Damage	\$ 281.90	\$ 281.90 ✓
1	Centre door pillar	Damage	\$ 631.30	\$ 631.30 ✓
1	Front wheel arch panel	Damage	\$ 581.90	\$ 581.90 X
1	Rear taillamp	Damage	\$ 115.85	\$ 115.85 X
1	Rear bumper	Damage	\$ 426.25	\$ 426.25 X
1	Rear fender	Damage	\$ 895.45	\$ 895.45 ✓
1	O/s sliding door	Damage	\$ 755.00	\$ 755.00 ✓
1	O/s sliding door rubber	Necessary	\$ 323.00	\$ 323.00 X
			\$ 10839.85	\$ 10316.95
Discount 15.0%			\$ 1625.98	\$ 1547.54
			\$ 9213.87	\$ 8769.41
<u>Special Nett Items</u>				
1	Front tyre (Depreciation)	Damage	\$ 175.00	\$ 87.50 X
1	Front rim	Damage	\$ 205.00	\$ 205.00 ✓
1	Rear tyre (Depreciation)	Damage	\$ 175.00	\$ 87.50 ✓
1	Rear rim	Damage	\$ 205.00	\$ 205.00 ✓
			\$ 760.00	\$ 585.00

Spare Parts Total \$ 9973.87 \$ 9354.41

7731.6
6571.86

Vehicle No: GR 8969 A
Report No: TP/ 16062-10/MY / 2016

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 9973.87	\$ 9354.41
1	To remove and refit damage parts, test for proper functioning and focus of headlamps.	\$ 65.00	\$ 40.00 20
2	To remove and refit dashboard, meters instrument, disconnect wirings, ductings, connectors to facilitate the repairs.	\$ 300.00	\$ 1^ 250.00 X
3	To remove and refit front windscreen glass.	\$ 180.00	Not Required 1^ X
4	To remove and refit the door lock mechanism, regulator gear, window glass, handle, inner board, hinges, channel to facilitate the repairs.	\$ 130.00	\$ 80.00 60
5	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 2300.00	\$ 1980.00 1000
6	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 1600.00	\$ 1540.00 1000
7	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 210.00	\$ 120.00 100
Total		<u>\$ 14758.87</u>	<u>\$ 13364.41</u>

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 10700.00

2180
8751.86

SDLS: TEN THOUSAND SEVEN HUNDRED ONLY


Qualified Appraiser

12dy.
Sumat 1/5 5000



Your Ref: MN.IG.B1.1611246

Date: 27th December 2017

Our Ref: CS1/LAW17022572/Uvbs2

M/s M Nedumaran & Co

No. 11 Sin Ming Road

#B2-09 (Unit 2), Thomson V Two

Singapore 575629

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:

GR 8969A

INSURED VEHICLE: SJV 4585T

ACCIDENT DATE: 25/10/2016

We thank you for your instruction on 22/11/2017.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GR 8969A from M/s Quantum Risk Management (S) Pte Ltd.
- b) Survey report by MC-Coy Appraiser Pte Ltd with colour photographs.
- c) Final Repair Bill of GR 8969A from M/s Bluwel Automotive Service Pte Ltd.
- d) Singapore Accident Statement of Vehicles GR 8969A and SJV 4585T.
- e) Colour damaged vehicle photographs of GR 8969A.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: GR 8969A
Make & Model	: Daihatsu S200RV
Year of Registration	: 2000
Chassis Number	: JDAS200V001000500
Engine Capacity	: 659cc

2. We recommend that the repairs of the entire damage require about 12 (Twelve) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GR 8969A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT WINDSCREEN MOULDING	NOT NECESSARY	272.45	-
1	FRONT HEADLAMP	CRACKED	581.45	581.45
1	FRONT BUMPER	DEFORMED	561.60	561.60
1	FRONT FENDER	TO REPAIR SEE LABOUR	372.75	-
1	FRONT FENDER INNER SHIELD	NOT NECESSARY	191.60	-
1	SET FRONT FENDER INNER SHIELD CLIP	NOT NECESSARY	12.90	-
1	FRONT MUDFLAP	DEFORMED	172.45	172.45
1	FUEL LIP COVER	BENT	182.10	182.10
1	FRONT DOOR	DISTORTED	1,218.40	1,218.40
1	FRONT DOOR CHECKER	TWISTED	172.45	172.45
1	FRONT DOOR GLASS	SHATTERED	581.90	581.90
1	FRONT DOOR GLASS OUTER MOULDING	BENT	274.45	274.45
1	FRONT DOOR HINGE	BENT	132.25	132.25
1	FRONT DOOR INNER BOARD	TORN	561.60	561.60
1	FRONT DOOR LOCK	JAMMED	150.00	150.00
1	FRONT DOOR REGULATOR	BENT	291.60	291.60
1	FRONT DOOR RUBBER	NECESSARY	287.70	287.70
1	FRONT DOOR SIDE MIRROR	TO REPAIR SEE LABOUR	561.10	-
1	FRONT DOOR SPEAKER	NOT NECESSARY	78.00	-
1	FRONT DOOR INNER HANDLE	NOT NECESSARY	172.45	-
1	FRONT DOOR CHANNEL	TWISTED	281.90	281.90
1	CENTRE DOOR PILLAR	DENTED	631.30	631.30
1	FRONT WHEEL ARCH PANEL	TO REPAIR SEE LABOUR	581.90	-
1	REAR TAILLAMP (CRACKED)	NOT CONSISTENT WITH THE IMPACT	115.85	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	426.25	-
1	REAR FENDER	DENTED	895.45	895.45
1	O/S SLIDING DOOR	BENT	755.00	755.00

Report Ref No. CS1/LAW17022572/Uvbs2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	O/S SLIDING DOOR RUBBER LESS 15% DISCOUNT	NOT NECESSARY	323.00 -1,625.98 9,213.87	- -1,159.74 6,571.86
	SPECIAL NETT ITEMS			
1	FRONT TYRE (SN)	SERVICEABLE	175.00	-
1	FRONT RIM (SN)	TO REPAIR SEE LABOUR	205.00	-
1	REAR TYRE (SN)	SERVICEABLE	175.00	-
1	REAR RIM (SN)	TO REPAIR SEE LABOUR	205.00	-
			760.00	-
	LABOUR			
	REMOVE AND REFIT DAMAGE PARTS, TEST FOR PROPER FUNCTIONING AND FOCUS OF HEADLAMPS.		65.00	20.00
	TO REMOVE AND REFIT DASHBOARD, METERS INSTRUMENT, DISCONNECT WIRINGS, DUCTINGS, CONNECTORS TO FACILITATE THE REPAIRS.	NOT NECESSARY	300.00	-
	TO REMOVE AND REFIT FRONT WINDSCREEN GLASS.	NOT NECESSARY	180.00	-
	TO REMOVE AND REFIT DOOR LOCK MECHANISM, REGULATOR GEAR, WINDOW GLASS, HANDLE, INNER BOARD, HINGES, CHANNEL TO FACILITATE THE REPAIRS.		130.00	60.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS. INCLUSIVE OF THE REPAIR OF FRONT FENDER, FRONT DOOR SIDE MIRROR, FRONT WHEEL ARCH PANEL, REAR BUMPER, FRONT RIM AND REAR RIM.		2,300.00	1,000.00
	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		1,600.00	1,000.00
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.		210.00	100.00
			4,785.00	2,180.00
	GRAND TOTAL		14,758.87	8,751.86

Report Ref No. CS1/LAW17022572/Uvbs2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,000.00
---	--	--	----------

Report Ref No. CS1/LAW17022572/Uvbs2

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.