

ASS. REC. BY:

REF: CS/FCI/7022616/U v b n h Special Instruction:

SENIOR:

ASSIGNMENT (Office)

(WS)

From (Person): Karen Tan of FCI Date/Time: 12:16pm @ 28/11/17

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: XD 2975 T Insured: SHD 3186 L

at Workshop m/s Mah Tian Motor Tel: 62823336

of No. 38 Defu Lane 9

Policy No: Claim No: D17010964 MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 23/11/2017
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 12:38pm @ 28/11/17 Person Contacted: Wanroh Vehicle: IN (OUT)

Date/Time	Action/Instruction (✓) Estimate
	XD 2975 T - N/A / INC 10013393 / j1 - D.O.A.: 08/07/2010
	SHD 3186 L - X
4/1/18	Email preli revised to FCI

ASSIGNMENT

From: _____ Date: 3/1/18

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No: XD 2975 T.

at Workshop mis: Mah Lian

of: No. 38 Defu Lane 9

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

N/S	O/S

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

ICAO Accident Report: _____ Consistent? : Yes or No

GLA/PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res: Yes or No

Lum Sum: 2 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: XD2975 T Yr Regn: 9 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer CM

Make: Isuzu C/Y252L c/c 15681

Colour: white A/O: Insured / Std / NI / NA

So Reading: 979373 T/Radio: Insured / Std / NI / NA

Eng No: _____

C/No: JALCY252L 87000068

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 295/80 R22.5

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Firemax

Front: _____ Rear: _____

R/Bal: 6 mm R/Bal: 6/6 6/6 mm

L/Bal: 6 mm L/Bal: 6/6 6/6 mm

D.O.A. 23/11/17 D.O.I. 3/1/18

Survey held at: _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S R/H.

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction LTA 880

8/1/18 4/5 @ 1600 confirmed with AM Tech. (Red 5902.90, 789.0)

RECEIVED 11 JAN 2018

Date/Time: File Pass 107 ☐ : Preli. Report

11 ☐ : Final Report

Date/Time: File Return to?

11/1 typist

Report Format: CWS

Lump Sum / I.B.I. / S 1600/-

Days Of Repair: 2

Resurvey No. of Trip: -

Add Fee: ☐ Site Insp \$

☐ Interview \$

☐ Technical \$

☐ Weekend \$

Survey Fee

Transportation

US - RS \$

Photos

Copies

TOTAL

150
50
23
223

Survey Department Check List (Case Handler)

Reference No.: CS/RS/7022616/UVB

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: VERON 11/1/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17022616/Uvb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 28-11-2017	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 3186L	Veh. Inspected	XD 2975T
Policy No.		Coverage (\$)	0.00
Claim No.	D17010964MFSH	Excess (\$)	0.00
Assign From	CWS (KAREN TAN)	Assign Date	28/11/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	28/11/2017	Inspection Date	
Survey held at	MAH LIAN MOTOR VEHICLE REPAIRER 38 DEFU LANE 9 SINGAPORE 539278		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	27-11-2017	Our Ref No. D17010964MFSH
Accident Date	23-11-2017	Claim Type. Third Party
Insured Vehicle	SHD3186L	Third Party Vehicle. XD2975T
Survey Location	NO.38 DEFU LANE 9	
Contact Person.	MR GOH/MS SI HUI	
Contact No.	62823336/ 62823336	Fax No. 62893336
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MAH LIAN MOTOR VEHICLE REPAIRER	Attention. NIL
Cc : TP Solicitor	VISION LAW LLC	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/231111)



PRI Documents



Close X

PRI Header Details

Claim No	D17010964MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & VISION LA
Workshop Name	MAH LIAN MOTOR VEHICLE REPAIRER (Contact Person : MR GOH/MS SI HUI)	Survey Location & Contact Details	NO.38 DEFU LANE 9 Mobile: 62823336 , Phone: 62823336 , Fax: 62893336 EmailId: JACTAN@VISIONLAWLLC.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD3186L	TP Vehicle No	XD2975T
PRI Recieved Date	28-11-2017 02:27:27 PM	Surveyor Appointed Date	28-11-2017 12:15:19 PM	Surveyor Accept Date	28-11-2017 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	28-11-2017	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 4 January, 2018 9:26 AM
To: 'Claim Workflow System'
Cc: KARENTAN@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17010964MFSH/1, XD 2975T
Attachments: XD 2975T PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle XD 2975T
Date of survey: 3/1/2018
Number of days: 2 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 28 November, 2017 1:49 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17010964MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Tuesday, 28 November, 2017 12:15 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; KARENTAN@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17010964MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D17010964MFSH
Our ref: CS/FCI17022616/Uvb

DATE: 4/1/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam

INITIAL INSPECTION REPORT OF VEHICLE NO. XD 2975T


We thank for your instruction on 28/11/2017

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 3/1/2018 at the premises of M/s MAH LIAN MOTOR VEHICLE REPAIRER and have the following to report:-

Workshop Estimate Amount	: S\$7,502.90
Revised Estimate Amount	: S\$2,041.10
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the o/s front portion.



Comments/Present Status:
Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	9858C
Vehicle Details	
Vehicle No.:	XD2975T
Vehicle to be Exported:	No
Intended De-registration Date:	03 Jan 2018
Vehicle Make:	ISUZU
Vehicle Model:	CYZ52L
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	6WG1408623
Chassis No.:	JALCYZ52L87000068
Maximum Power Output:	-
Open Market Value:	\$82,459.00
Original Registration Date:	08 Sep 2008
First Registration Date:	08 Sep 2008
Transfer Count:	2
Actual ARF Paid:	\$4,123.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	07 Sep 2018
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$12,989.00
COE Rebate Amount:	\$880.00
Total Rebate Amount:	\$880.00

The information contained herein is correct as at 03 Jan 2018

OK

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1154370A



NAME
GOH CHIT PANG



吴 泽 榜
RACE
CHINESE
Date of Birth 79-09-1956 SEX M
Country of Birth
SINGAPORE

3056599



S1164370A



HEALTH STATUS
B+

DATE OF ISSUE
12-12-1998

RESIDENCE
APT BLK 75 WHAMPOA DRIVE
#07-350
SINGAPORE 320075

DRIVER LICENSE Pg. 1

REPUBLIC OF SINGAPORE

License Number: **S1164370A**

Name: **GOH CHIT PANG**

Birth Date: **29 Sep 1956**


Issue Date: **16 Jul 2003**

000659505H




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

		PASS DATE
Class 2B	Motorcycles not exceeding 200 cc	29 Jun 1977
Class 2C	Motorcycles between 201 cc and 400 cc	29 Jun 1977
Class 2	Motorcycles exceeding 400 cc	29 Jun 1977
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	15 Mar 1977
Class 4	Heavy Motor Cars and Motor Tractors the weight of which unladen exceeds 2500 kilograms	05 Mar 1977
Class 5	Motor Vehicles which are not constructed themselves to carry any load and the weight of which unladen exceeds 7250 kilograms	20 Mar 1992



NT 478A

MAH LIAN MOTOR VEHICLE REPAIRER

No.38 Defu Lane 9 Singapore 539278
 TEL: 62823336 FAX: 62893336 Email: mahlian@singnet.com.sg
 GST:M90362564P RCB NO:201327339E

M/S : China Taiping Insurance (Singapore) Pte Ltd

TEL: - FAX: -

ATTN: Motor Claim Department

Your Ref No: YONG LEI LOGISTICSPL

Claim Type: Others

Accident Date: 23/11/2017

Estimate No: ES1700135

Date: 25 Nov 2017

Policy No: DMCVSN1732671700

Veh Reg No: XD2975T

Make/Model: ISUZU CYZ52L

Chassis No: JALCYZ52L87000068

Engine No: 6WG1408623

Reg. Date: 08/09/2008

Estimate Repair Cost to Vehicle No :XD2975T

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 Front Bumper	1,229.00	1 PC	1,229.00	5075.50
2 Front Bumper Protector Ctr/RH	63.00	1 PC	63.00	x
3 Headlamp Assy RH	334.00	1 PC	334.00	x
4 Headlamp Rim RH	98.00	1 PC	98.00	/
5 Fog Lamp RH	128.00	1 PC	128.00	x
6 Signal Lamp RH	80.00	1 PC	80.00	x
7 Front Bumper Lower Garnish RH	155.00	1 PC	155.00	x
8 Headlamp Bracket RH	273.00	1 PC	273.00	x
9 Front Bumper Side Bracket RH	175.00	1 PC	175.00	x
10 Front Bumper Lamp Bracket	135.00	1 PC	135.00	x
11 Front Bottom Step Garnish RH	380.00	1 PC	380.00	/
12 Front Bottom Step Aluminium Mat RH	220.00	1 PC	220.00	/
13 Front Bottom Step Aluminium Bottom Garnish RH	76.00	1 PC	76.00	/
14 Front Bottom Step Aluminium Bracket RH	495.00	1 PC	495.00	x
15 Front Top Step Garnish RH	380.00	1 PC	380.00	x
16 Front Top Step Panel RH	380.00	1 PC	380.00	x
17 Front Aluminium Step Panel Inner Bracket	90.00	1 PC	90.00	x
18 Rear Aluminium Step Panel Inner Bracket	90.00	1 PC	90.00	x
			4,781.00	
		Less 10%	478.10	4,302.90
Labour				
19 To remove & refit cabin garnish ,wiring ,linging, seat to carry out repair .	200.00	1 JOB	200.00	30
20 Labour charge to cut ,weld ,dismantle ,remove & refit all above parts .	1,800.00	1 JOB	1,800.00	400
21 To spray & painting all accident area .	1,200.00	1 JOB	1,200.00	300
			3,200.00	3,200.00

not Authorized
 Lian
 L/S #1600
 2 day
 3/1/18
 Temp hls After rep-

P-774
 152
 657.50
 S.W 614.50
 Labor -730
 2002.4

MAH LIAN MOTOR VEHICLE REPAIRER

No.38 Defu Lane 9 Singapore 539278
TEL: 62823336 FAX: 62893336 Email: mahlian@singnet.com.sg
GST:M90362564P RCB NO:201327339E

M/S : China Taiping Insurance (Singapore) Pte Ltd

TEL: - FAX: -

ATTN: Motor Claim Department

Your Ref No: YONG LEI LOGISTICSPL

Claim Type: Others

Accident Date: 23/11/2017

Estimate No: ES1700135

Date: 25 Nov 2017

Policy No: DMCVSN1732671700

Veh Reg No: XD2975T

Make/Model: ISUZU CYZ52L

Chassis No: JALCYZ52L87000068

Engine No: 6WG1408623

Reg. Date: 08/09/2008

Estimate Repair Cost to Vehicle No :XD2975T

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Total				S\$ 7,502.90
Add GST @ 7%				525.20
Total Amount Payable				<u>S\$ 8,028.10</u>

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND TWENTY EIGHT AND CENTS TEN ONLY

**For MAH LIAN MOTOR VEHICLE
REPAIRER**

AUTHORISED SIGNATURE





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17022616/Uvbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 12-01-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3186L	Veh. Inspected	XD 2975T	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17010964MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	28/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	ISUZU CYZ52L (M)	c.c	15681	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JALCYZ52L87000068	Colour	WHITE	
Odometer	979373	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	FIREMAX	6 mm	
L/H Front Tyre	295/80 R22.5	FIREMAX	6 mm	
R/H Rear Tyre	295/80 R22.5 (D/D)	FIREMAX	6/6 6/6 mm	
L/H Rear Tyre	295/80 R22.5 (D/D)	FIREMAX	6/6 6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/11/2017	Inspection Date	03/01/2018	
Survey held at	MAH LIAN MOTOR VEHICLE REPAIRER 38 DEFU LANE 9 SINGAPORE 539278			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XD 2975T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER PROTECTOR CTR/RH	NOT NECESSARY	63.00	-
1	HEADLAMP ASSY RH	NOT NECESSARY	334.00	-
1	HEADLAMP RIM RH	BENT	98.00	98.00
1	FOG LAMP RH	NOT NECESSARY	128.00	-
1	SIGNAL LAMP RH	NOT NECESSARY	80.00	-
1	FRONT BUMPER LOWER GARNISH RH	NOT NECESSARY	155.00	-
1	HEADLAMP BRACKET RH	NOT NECESSARY	273.00	-
1	FRONT BUMPER SIDE BRACKET RH	NOT NECESSARY	175.00	-
1	FRONT BUMPER LAMP BRACKET	NOT NECESSARY	135.00	-
1	FRONT BOTTOM STEP GARNISH RH	CRACKED	380.00	380.00
1	FRONT BOTTOM STEP ALUMINIUM MAT RH	CRACKED	220.00	220.00
1	FRONT BOTTOM STEP ALUMINIUM BOTTOM GARNISH RH	CRACKED	76.00	76.00
1	FRONT BOTTOM STEP ALUMINIUM BRACKET RH	TO REPAIR SEE LABOUR	495.00	-
1	FRONT TOP STEP GARNISH RH	NOT NECESSARY	380.00	-
1	FRONT TOP STEP PANEL RH	NOT NECESSARY	380.00	-
1	FRONT ALUMINIUM STEP PANEL INNER BRACKET	NOT NECESSARY	90.00	-
1	REAR ALUMINIUM STEP PANEL INNER BRACKET	NOT NECESSARY	90.00	-
	LESS 10% DISCOUNT		-355.20	-
	LESS 15% DISCOUNT		-	-116.10
			3,196.80	657.90
1	FRONT BUMPER (50%)(SN)	BENT / DENTED	1,229.00	614.50
	LESS 10% DISCOUNT		-122.90	-
			1,106.10	614.50
LABOUR				
	TO REMOVE & REFIT CABIN GARNISH,WIRING,LINGING,SEAT TO CARRY OUT REPAIR.		200.00	30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LABOUR CHARGE TO CUT,WELD,DISMANTLE,REMOVE & REFIT ALL ABOVE PARTS.INCLUSIVE OF THE REPAIR OF FRONT BOTTOM STEP ALUMINIUM BRACKET RH. TO SPRAY & PAINTING ALL ACCIDENT AREA.		1,800.00	400.00
			1,200.00	300.00
			3,200.00	730.00
GRAND TOTAL			7,502.90	2,002.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,600.00

Report Ref No. CS/FCI17022616/Uvbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.