

INS. CASE OWNER:

GERALD

CC6 / LPC170 22623 / Kpa312

LKK:

IDAC:

ASSIGNMENT

Surveyor:

KENNETH

DOI:

27/11/17

Date / Time:

27/11/17

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLR 6319E

Name of Insured:

LOW BOON CHIN

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

23/11/17

Is driver the owner?

(YES ☒ NO)

Nature of Accident:

If NO, Driver Name / Age: Low SHI PING

Driver Tel No.: 9821 8379

(V/L YB / NO)

Claim No.:

17/17/17/VP05/020233

Policy No.:

217VP05015616

Make / Model:

HONDA JAZZ

Place of Accident:

JUNCTION OF TIONG BAHRU & TION.

OI GIA REPORT: YES / NO: TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SLD 8054D



INSRS:

WSP: Complete

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time	STAGE	DATE / PIC	
29/11/17 (2ayer)	Non-Reporting ltr (1st):	NA	
	Non-Reporting ltr (2nd):		
	Non-Reporting ltr (Final):		
	Notification ltr (if non-pickup):		
29-1-18	Call OI:		
	After call ltr to OI:		
	Documentation Check List:	Handler	Typist
	Notification ltr (if non-pickup)	☒	☐
	After call ltr to OI:	☒	☐
	Authorisation To Act:	☒	☐
	Release Voucher:	☒	☐
	Final Repair Bill:	☒	☐
	Car Rental Invoice:	☒	☐
	Towing Invoice:	☒	☐
	LTA / GIA:	☒	☐
	Medical Bill:	☒	☐
	PIR:	☒	☐
	Mandate/Reject Instruction:	☒	☐
	LOD	☒	☐
	Payment Breakdown Form:	☐	☐
	Post-Repair Photos:	☐	☐
	Others:	☐	☐

PRELIMINARY ADVICE Date/Time: 28/11/17

Sent By:

Shirley Hwee

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

NIL CCTV

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

4,933.50

Loss of Rental (LOR):

S\$

600.00 x 4 days x 100

Loss of Use (LOU):

S\$

— (\$ x days)

Loss of Income (LOI):

S\$

— (\$ x days)

LOU only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

5.35

Medical:

S\$

—

Disbursement:

S\$

—

(e.g. Tow/ Independent)

Legal Cost

S\$

—

Total:

S\$

4,938.85

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

4,938.85

Name 1:

COMPLETE VMS PTE LTD

Payee 2: (Strike if N.A.)

S\$

X

Name 2:

X

Payee 3: (Strike if N.A.)

S\$

X

Name 3:

X

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT 20/6/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC6/LPC17022623/Kza3		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 28-11-2017		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLR 6319E	Veh. Inspected	SLD 8054D	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	28/11/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	23/11/2017	Inspection Date	27/11/2017	
Survey held at	COMPLETE VMS PTE LTD BLK 176 SIN MING DRIVE #03-14 SIN MING AUTOCARE COMPLEX SINGAPORE 575721			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 17/17/17/VP05/020233
Our ref: CC6/LPC17022623/Kza3

Date: 28.11.2017

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLD 8054D

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 27.11.2017 at the premises of M/s Complete Vms Pte Ltd (Sin Ming Drive) have the following to report:-

Workshop Estimate Amount	: S\$	7,088.92
Revised Estimate Amount	: S\$	2,198.56
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
O/S Front portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4.0 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser



COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

TAN KHENG GEE
30 BRISTOL ROAD #02-01
SINGAPORE 219860

Attention : THE OWNER
Contact : 91172927

Not Authorised
11 hrs 87
Repair After Police

Estimate : ES006217

Date : 24/11/2017
Vehicle Num. : SLD8054D
Make/Model : HONDA SHUTTLE 1.5G-2015
Chassis/Eng# : GK81002778/L15B3533348
Accident Date : 23/11/2017
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | |
|-----|---|--------------------------------|
| 1. | 1 | LIST ITEMS : |
| 2. | 1 | FRONT BUMPER R/H |
| 3. | 1 | FRONT BUMPER SIDE RETAINER R/H |
| 4. | 1 | FRONT BUMPER CLIP |
| 5. | 1 | FRONT BUMPER LOWER LIP |
| 6. | 1 | FRONT SPORT RIM R/H |
| 7. | 1 | FRONT WHEEL BEARING R/H |
| 8. | 1 | FRONT KNUCKLE ARM |
| 9. | 1 | FRONT LOWER ARM |
| 10. | 1 | FRONT SHOCK ABSORBER |
| 11. | 1 | FRONT FENDER R/H |
| 12. | 1 | FRONT FENDER SPLASH SHIELD R/H |
| | | HEADLAMP (HID) R/H |

List Total S\$:
20.00% Discount S\$:

LABOUR :
REMOVE & REINSTALL FRONT SUSPENSION R/H
COMPUTER FRONT WHEEL ALIGNMENT
RUST PROOFING TREATMENT
SPRAY PAINT DAMAGED AREA AFFECTED
TO PRESS OUT & IN WHEEL BEARING
CHANGE HEAD LAMP AND CHECK LIGHTING
TO KNOCK OUT AND STRAIGHTEN FRONT CHASSIS FRAME AND
CHANGE ALL NECCESARY PARTS

Labour Total S\$:

SingDollars : Seven Thousand Eighty-Eight & Cents Ninety-Two Only

Total S\$: 7,088.92

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun

But Not 1,050.90 ✓
in 16.70 ✓
in 3.90 ✓
Not in 180.90 ✓
in 923.70 *3500*
15.90 *2*
330.60 *7*
260.90 *7*
420.10 *7*
in 435.00 *X*
in 110.50 *X*
2,230.80 *2*
5,979.90
1,195.98
4,783.92
250.00 *4600*
in 90.00 *600*
in 80.00 *X*
780.00 *500*
60.00 *200*
65.00 *200*
980.00 *300*
2,305.00



COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

TAN KHENG GEE
30 BRISTOL ROAD #02-01
SINGAPORE 219860

Attention : THE OWNER
Contact : 91172927

*NOT Authorised
11/11/17
Recovery After Pairs*

Estimate : ES006217

Date : 24/11/2017
Vehicle Num : SLD8054D
Make/Model : HONDA SHUTTLE 1.5G-2015
Chassis/Eng# : GK81002778/L15B3533348
Accident Date : 23/11/2017
Claim No :
Reference :
Policy No :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	FRONT BUMPER R/H		
2.	1	FRONT BUMPER SIDE RETAINER R/H		
3.	1	FRONT BUMPER CLIP		
4.	1	FRONT BUMPER LOWER LIP		
5.	1	FRONT SPORT RIM R/H		
6.	1	FRONT WHEEL BEARING R/H		
7.	1	FRONT KNUCKLE ARM		
8.	1	FRONT LOWER ARM		
9.	1	FRONT SHOCK ABSORBER		
10.	1	FRONT FENDER R/H		
11.	1	FRONT FENDER SPLASH SHIELD R/H		
12.	1	HEADLAMP (HID) R/H		
List Total S\$:				5,979.90
20.00% Discount S\$:				1,195.98
				4,783.92

Butler
1,050.90 ✓
16.70 ✓
3.90 ✓
180.90 ✓
923.70 3500
15.90 ✓
330.60 ✓
260.90 ✓
420.10 ✓
435.00 X
110.50 X
2,230.80 ✓

LABOUR :
REMOVE & REINSTALL FRONT SUSPENSION R/H
COMPUTER FRONT WHEEL ALIGNMENT
RUST PROOFING TREATMENT
SPRAY PAINT DAMAGED AREA AFFECTED
TO PRESS OUT & IN WHEEL BEARING
CHANGE HEAD LAMP AND CHECK LIGHTING
TO KNOCK OUT AND STRAIGHTEN FRONT CHASSIS FRAME AND
CHANGE ALL NECESSARY PARTS

250.00 ?
90.00 600
80.00 X
780.00 500
60.00 ?
65.00 ?
980.00 300

Labour Total S\$:

2,305.00

SingDollars : Seven Thousand Eighty-Eight & Cents Ninety-Two Only

Total S\$: 7,088.92

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun



K7

COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

TAN KHENG GEE
30 BRISTOL ROAD #02-01
SINGAPORE 219860

Attention : THE OWNER
Contact : 91172927

Not Authorised
Lily @ 4050h
Recovery After Paint
4 days

Estimate : ES006217

Date : 24/11/2017
Vehicle Num. : SLD8054D
Make/Model : HONDA SHUTTLE 1.5G-2015
Chassis/Eng# : GK81002778/L15B3533348
Accident Date : 23/11/2017
Claim No. :
Reference :
Policy No. :

S/N Quantity Particular Unit Price Amount S\$

1.	1	LIST ITEMS :		
2.	1	FRONT BUMPER R/H	1050.20	
3.	1	FRONT BUMPER SIDE RETAINER R/H		
4.	1	FRONT BUMPER CLIP		
5.	1	FRONT BUMPER LOWER LIP		
6.	1	FRONT SPORT RIM R/H		
7.	1	FRONT WHEEL BEARING R/H		
8.	1	FRONT KNUCKLE ARM		
9.	1	FRONT LOWER ARM		
10.	1	FRONT SHOCK ABSORBER		
11.	1	FRONT FENDER R/H		
12.	1	FRONT FENDER SPLASH SHIELD R/H		
		HEADLAMP (HID) R/H	1650.00	

List Total S\$:
20.00% Discount S\$:

1,290.90 ✓
46.70 X
5.90 ✓
460.90 ✓
923.70 350.00
195.90 ✓
410.60 ✓
370.90 ✓
480.10 ✓
545.00 X
110.50 X
2,230.80 ✓
7,071.90
1,414.38
5,657.52

LABOUR :
REMOVE & REINSTALL FRONT SUSPENSION R/H
COMPUTER FRONT WHEEL ALIGNMENT
RUST PROOFING TREATMENT
SPRAY PAINT DAMAGED AREA AFFECTED
TO PRESS OUT & IN WHEEL BEARING
CHANGE HEAD LAMP AND CHECK LIGHTING
TO KNOCK OUT AND STRAIGHTEN FRONT CHASSIS FRAME AND
CHANGE ALL NECESSARY PARTS

Labour Total S\$:

160
250.00
90.00 600
80.00 X
780.00 500
60.00 200
65.00 200
980.00 300
2,305.00

SingDollars Seven Thousand Nine Hundred Sixty-Two & Cents Fifty-Two Only

COMPLETE VMS PTE LTD

This is only an estimate based on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun

Total S\$: 7,962.52

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Any additional item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Fork Order: R022223
 IN: SLD8054D
 Year: 08
 Date: 25.11.17 11:45



SLD8054D

Factory Japan 2017.0.1 : Honda : Shuttle : GK8

Front : Left

Actual	Before	Specified Range
-0°51'	-0°51'	-1°00' 1°00'
5°18'	5°18'	4°00' 6°00'
-0°06'	-0°06'	-0°09' 0°09'
10°05'	10°06'	
9°14'	9°14'	

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
2°18'	2°19'	-1°00' 1°00'
5°19'	5°19'	4°00' 6°00'
-0°10'	-0°10'	-0°09' 0°09'
6°27'	6°26'	
8°44'	8°44'	

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
-3°09'	-3°10'	-1°00' 1°00'
-0°01'	-0°01'	
3°39'	3°40'	
-0°16'	-0°16'	-0°17' 0°17'

Rear : Left

Actual	Before	Specified Range
-2°03'	-2°03'	-2°45' -0°45'
0°03'	0°02'	0°00' 0°17'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-1°49'	-1°49'	-2°45' -0°45'
0°16'	0°16'	0°00' 0°17'

Rear

Cross Camber
 Total Toe
 Thrust Angle
 Axle Offset

Actual	Before	Specified Range
-0°14'	-0°14'	-1°00' 1°00'
0°18'	0°18'	0°00' 0°34'
-0°07'	-0°07'	
0mm	0mm	

Joy Irene (LKKAUTO)

From: Lily Leow <lily@completevms.com.sg>
Sent: Thursday, 1 March 2018 3:05 PM
To: Joy Irene (LKKAUTO)
Subject: Re: Your ref: SLD 8054D ON 23.11.2017 / LONPAC SLR 6319E

WITHOUT PREJUDICE

Dear
Joy

With reference to your email, we accept your offer as follows:-

Cost of Repairs + 7% GST	\$ 4,333.50
Loss of Rental	\$ 600.00 (\$100 x 6 days)
GIA/LTA Search Fee	\$ 5.35
TOTAL	\$ 4,938.85

Please send us your discharge voucher for our client to sign asap.

Thank you and best regards
Lily Leow
Tel: 64550012
Complete VMS Pte Ltd
Blk 176 Sing Ming Drive #03-14
Sin Ming Autocare Complex
Singapore 575721
E-mail: lily@completevms.com.sg

On Thu, Mar 1, 2018 at 1:24 PM, Joy Irene (LKKAUTO) <JoyIrene@lkkauto.com> wrote:

WITHOUT PREJUDICE

Dear Sirs,

For a quick and amicable settlement on your client's claim, please accept our offer below:

Cost of Repairs + 7% GST	\$ 4,333.50
Loss of Rental	\$ 600.00 (\$100 x 6 days)
GIA/LTA Search Fee	\$ 5.35

COMPLETE VMS PTE LTD

176 Sin Ming Drive, #03-14 / 07, Sin Ming Autocare Complex, S575721
Tel: 6455 0012 Fax: 6554 0012 Email: main@completevms.com.sg
Business Reg. No. 200416180E GST Reg. No.: 200416180E



LONPAC INSURANCE BHD
100 BEACH ROAD #19-00 SHAW TOWER
SINGAPORE 189702

Attention : MOTOR CLAIMS DEPT
Contact : 62507388 Fax No. : 62963767

Proforma Invoice : TP006217

Date : 09/01/2018
Vehicle Num. : SLD8054D
Make/Model : HONDA SHUTTLE 1.5G-2015
Chassis/Eng# : GK81002778/L15B3533348
Accident Date : 23/11/2017
Claim No. :
Reference :
Policy No. :

	Amount S\$
COST OF REPAIR AS AGREED	4,050.00

SingDollars : Four Thousand Three Hundred Thirty-Three & Cents Fifty Only

COMPLETE VMS PTE LTD

Total S\$:	4,050.00
GST S\$:	283.50
Amount Due S\$:	4,333.50

=====

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC6/LPC17022623/Kja3n2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 22-06-2018



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLR 6319E	Veh. Inspected	SLD 8054D
Policy No.	Z17VP05015616	Coverage (\$)	0.00
Claim No.	17/17/17/VP05/020233	Excess (\$)	0.00
Assign From		Assign Date	27/11/2017

2. Vehicle Particulars & Condition

Make & Model	HONDA SHUTTLE (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	GK81002778	Colour	METALLIC PEARL WHITE
Odometer	39884	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/45Z R16	PIRELLI	7 mm
L/H Front Tyre	205/45Z R16	PIRELLI	7 mm
R/H Rear Tyre	205/45Z R16	PIRELLI	7 mm
L/H Rear Tyre	205/45Z R16	PIRELLI	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/11/2017	Inspection Date	27/11/2017
Survey held at	COMPLETE VMS PTE LTD BLK 176 SIN MING DRIVE #03-14 SIN MING AUTOCARE COMPLEX SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 8054D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER R/H	BUCKLED / DENTED	1,290.90	1,050.20
1	FRONT BUMPER SIDE RETAINER R/H	SERVICEABLE	46.70	-
1	FRONT BUMPER CLIP	NECESSARY	5.90	5.90
1	FRONT BUMPER LOWER LIP	DENTED / CUT	460.90	460.90
1	FRONT WHEEL BEARING R/H	NECESSARY	195.90	195.90
1	FRONT KNUCKLE ARM	BENT	410.60	410.60
1	FRONT LOWER ARM	DISTORTED	370.90	370.90
1	FRONT SHOCK ABSORBER	BENT	480.10	480.10
1	FRONT FENDER R/H	TO REPAIR SEE LABOUR	545.00	-
1	FRONT FENDER SPLASH SHIELD R/H	SERVICEABLE	110.50	-
1	HEADLAMP (HID) R/H	MTG CRACKED	2,230.80	1,650.00
	LESS 20% DISCOUNT		-1,229.64	-924.90
			4,918.56	3,699.60
1	FRONT SPORT RIM R/H (SN)	DENTED	923.70	350.00
	LESS 20% DISCOUNT		-184.74	-
			738.96	350.00
LABOUR				
	REMOVE & REINSTALL FRONT SUSPENSION R/H .	NOT NECESSARY	250.00	160.00
	COMPUTER FRONT WHEEL ALIGNMENT .		90.00	60.00
	RUST PROOFING TREATMENT .		80.00	-
	SPRAY PAINT DAMAGED AREA AFFECTED.		780.00	500.00
	TO PRESS OUT & IN WHEEL BEARING .		60.00	20.00
	CHARGE HEAD LAMP AND CHECK LIGHTING.		65.00	20.00
	TO KNOCK OUT AND STRAIGHTEN FRONT CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS.INCLUSIVE OF THE REPAIR OF FRONT FENDER R/H .		980.00	300.00
			2,305.00	1,060.00

Report Ref No. CC6/LPC17022623/Kja3n2



GRAND TOTAL		7,962.52	5,109.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,050.00

Report Ref No. CC6/LPC17022623/Kja3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.