COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO: SHC 2772G

AIG

DATE 25/11/2017 10:28

MAKE :

MODEL : HYUNDAI SONATA

DOA: 24.11.2017

Qty	Parts Description/ Labour Type U	Jnit Price	Amount
	Boot Lid /	\$	1,349.50
	Boot Lid Rubber ×	\$	110.90
	Boot Lid Lock Upper 😾	\$	132.10
	Boot Lid Lock Lower ⊁	\$	30.30
	Boot Lid Sonata Plate	\$	43.60
	Boot Lid Hyundai Plate	\$	24.20
	Boot Lid 'H' Emblem	\$	26.10
	Boot Lid CRDI Plate	\$	22.70
	Rear Bumper	\$	578.40
	Rear Bumper Reinforcement 1	\$	483.30
	Rear Bumper Clip /	\$	22.00
	Rear Bumper Bracket * \$	49.00 \$	98.00
	Rear Bumper Sponge .	\$	137.40
	Rear Bumper Under Cover	\$	185.80
	Rear Bumper Protector (LH/RH)	38.00 \$	
	Rear Panel XH W	\$	
	Rear Panel Garnish	\$	
	Spare Tyre Holder 7	\$	27.60
	Spare Tyre Panel ?	\$	863.00
	Spare Tyre Panel Cushion ?	\$	
	Rear Towing Hook ?	8	135.30
	Member Assy- Rear Floor Centre 7	\$	163.60
	SUB TOTAL	\$	
	LESS 20%	\$	
	DISCOUNTED TOTAL LKK Auto Consultants for	ue notify	4,158.16
	the Repairer of the follows	ng:	
	Boot Lid Comfort Logo & Tel No. Sticker To resurvey before a feet survey before a survey befo	ring resurvey	30.00
	Parts prices are subject to con	ternation	25.00
	Rear No.Plate • Third party survey is on a "With Rear Bumper Reverse Sensor • No illegal mode for allow to be allowed. Sensor	hout Prejudice" basis	135.70
	Supplementary item(s) must be	e resurveyed and	155.70
	is subject to final approval from	1 Insurance Company	190.70
	Acknowledged of repairer	H	190.70
	Labour Charge		600
	Panel Beating Spray Painting Charge Wiring Charge Tuff Kote Remove/Refix Reverse Sensor Towhile (KING DOLLY) Parel 19 27/11/12 1005 hr. 4 Parys. Athe Paper pl	\$	
	Spray Painting Charge // 27/11/2 1005 km	s- S	/ /
	Wiring Charge	\$	
	Tuff Kote	\$	
	Remove/Refix Reverse Sensor	6	1
	TOWING (KING DOLLY) Ath Paper P	lo §	
	TOTAL LABOUR	9	
Larry N9	TOTAL LABOUR	3	2,320.00
-		0	(0/0.0/
	ESTIMATE TOTAL	5	6,868.86



A member of COMFORTDELGRO

K.D.

ComfortDelGro Engineering Pte Ltd

Service Centres
205 Braddell Road Singapore 578701
45 Pandan Road Singapore 603288
75 Sungel Kadut Way Singapore 728791
24 Senoko Loop Singapore 758156





JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Ich Dominition				
Job Requisition	O Makini T	4. Time of Tourings		
1. Date: 2 4/11/12 Time Received: 2 6700 2. New SPARK Kakis Name of Customer W. NG CHOON HEC	3. Vehicle Type: Private Taxi (CTPL/CCPL) Fleet	4. Type of Towing: Normal Tow King Dolly Flat Bed		
Contact No. 87 006441	STK (Boon Lay)	Crane-up		
Vehicle No. : $S + 1 = 27729$	5. Nature of Service: Jumpstart	6. Parts Replaced/Remarks:		
Make/Model/Colour: Smeda / The	Recovery Change Tyre / Batter	у		
	8	Vehicle Tow - In Workshop:		
7. Location: WCE/CPE PIE Cust 9. Preferred Workshop:	Smoky Exhaust Wheel Jammed Overheating Steering Faulty			
☐ Braddell ☐ Loyang ☐	Pandan	☐ Brake Faulty ☐ Alternator Faulty		
☐ Sin Ming ☐ Sungei Kadut ☐	Ubi	Starting Problem Loss Power		
Senoko Komoco (UBI / Leng Kee)	Cycle & Carriage (PD)	Accident Engine Stalled		
Others:		Return Taxi		
10. Odometer Reading :	11. Radio / CD Pla	11. Radio / CD Player		
Fuel Level : F 1/2 3/4 E	Faulty Not teste	d		
Job Attended		30de1		
12. Tow Truck / Recovery Van : VRS QA GA Name of Driver : Vehicle No. : VRS QA GA VRS QA GA OF STATE OF STAT	AO TZ YISHUN TOWING	OTHERS		
2010		#: Cracked X: Dented		
Time dispatch		/: Scatched O: Missing		
Time of Arrival :		Signature of Customor		
Time Completed :		Signature of Customer		
Cash Invoice Details (if applicable)				
13. Cash Invoice No. :				
Customer Acknowledgement				
 a. I have been advised to remove all valuable items in my vehicle, inclucash cards, spectacles, pen, etc. b. I understand that any items left behind are at my own risk and SPAI c. Surcharge: Towing fee will be levied if the customer decides neither 	RK Car Care™ will not be held liable	for such losses.		
Date	е	Signature of Customer		
14. WORKSHOP				
Name of Attending Staff/Guard Date & Time	of Arrival	Signature of Attending Staff/Guard WORKSHOP COF		