

ASS. REF. BY

1 REP

CS/CTI/7022682/Ken

36K

S. INV. BY

Kenneth

ASSIGNMENT OFFICE

*Minimen

From (Person)

Chang Boon Sen.

CTI

28/11/17 @ 3:47pm

Estimated Cost

Bill to

① TP/PWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

YN 9325J

Insured

at Workshop no.

S & H Motor

Tel.

6453 4730

of 160 Sing Ming Drive # 07-02, S75722

Policy No.

DM CV SN 3072781700

Claim No.

SNM17006332C01

Sum Insured

Excess

\$500.00

Make of Veh.

(Client's Record)

D.C.A. 30/10/2017

CA / REV / REP. / REV 24 HRS

Doris

H.O.D. Reference

Date/Time

8:49am @ 29/11/17

Person Contacted

Ms. Wong

Vehicle IN/OUT

Date/Time

Action/Instructions (✓) Estimate

YN 9325J-X

From: YN 9325J Date: 29/11/17 Page: 10 15

Estimated Cost: OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect vehicle No: YN 9325J

at Workshop No: S&H Motor

of 160 Sin Ming Drive #07-02 575722

Insured: Insured

Policy No: 1 FEB 21 EA 10462

Claims No: Gen. Cond. (Good) Fair / Poor / Burnt

Sum Insured: \$ 500.00

Excess: \$ 500.00

Client's Record: Nil / SIRim / STD A/Rim or

Make of Veh: 195 / 85R15 (D)

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 872k

IDAO Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lim Sum: 3 yal: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted Vehicle IN / OUT

Des. of Damages: Front / Rear / O/S / N/S / U/O / Rooftop or

The U/O / Chassis frame / Body Structure affected due to collision

Date Time Action Instruction

30/11/17 File pass to Carhome

30/11/17 REV in memo - pending COR from wksp.

5/12/17 Doris asking COR 4s \$36K.

5/12/17 2nd REV in memo - wksp asking COR at 4s \$36K.

7/12/17 mandate approved by Alfred

7/12/17 @ 5.05 pm spoke to Doris, CA, Ex: 500 - COR not more 4s \$36K & vehicle required to be sent to inspection centre for inspect before releasing to insure

15/3/17 Spoke to McDoris final amt at \$36K, will ask Kenneth to check the question mark.

16/3/17 Confirm 36K by Kenneth

20/3/17 P/P - confirm 36K \$36949.85, Rel 0.50%

Days Of Repair: 20/3/17

Resurvey No. of Trip: 250

Survey Fee: 250

Preli. Report: ☒

Final Report: ☐

Add Fee: ☐ Steinsco \$ ☐ Repairs \$ ☐ Fuel \$ ☐ Other \$

Report Form: OD

Lim Sum: 4s 36 K



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI17022682/Kgb		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 29-11-2017		
		Code : CTI		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.	Veh. Inspected		YN 9325J	
Policy No.	DMCVSN3072781700	Coverage (\$)	0.00	
Claim No.	SNM17D06332C01	Excess (\$)	500.00	
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	29/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	30/10/2017	Inspection Date	29/11/2017	
Survey held at	S & H MOTOR PTE LTD 160 SIN MING DRIVE #07-02 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

Survey Department Check List (Case Handler)

Reference No.: **CS/KTI/17022682/Khb**
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler **RTA** Typist

Admin (): Case handler to make sure all information created by the assignment team are ACCURATE

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			

Surveyor (): Case handler to make sure the surveyor completed all required information

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N* Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

--	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By: **RTA** **15/3/2018**
 Case Handler Date

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Nov 2017 Sendback Est	24 Nov 2017 18:14 S\$72,949.85	28 Nov 2017 15:47 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	SOUTH FORWARD CONSTRUCTION PTE LTD, Co. Reg. No.: -		
Vehicle Reg. No.:	YN9325J	Date of Loss:	30/10/2017 06:00 - :59
Claim Type:	OD / SNM17D06332C01	Policy/Cover Note No.:	DMCVSN3072781700 (Comprehensive)
		Excess:	S\$500.00
Repairer:	S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6453 4730		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/12/2017]		
Driver/Custodian:	SAMINATHAN KALIYAMOORTHY (42 / Male), NRIC: F7945990U		
Adj Asg. Remarks:	SURVEY REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS ☐

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	24 Nov 2017 18:03	Clim Veh Model Changed	(205007) MITSUBISHI CANTER 3.0 D FEB21ER3SDEB (M).	[R] Lum Wee Keat
2	24 Nov 2017 18:03	Clim Created	Reg No: YN9325J. Policy No: DMCVSN3072781700. Acct Date: 2017/10/30. Claim Type: OD. Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ). Workshop: S & H Motor Pte Ltd (Sin Ming). Created from SAS:MSNH17148384-02	[R] Lum Wee Keat
3	24 Nov 2017 18:04	Clim Veh Model Changed	(205007) -> (205018) MITSUBISHI CANTER 3.0 D FEB21ER3SDEB (CBU) (M).	[R] Lum Wee Keat
4	24 Nov 2017 18:14	Clim Submitted	72949.85.	[R] Lum Wee Keat
5	28 Nov 2017 15:47	Clim Registration Modified	Excess: -> 500.00.	[I] Chong Boon Sen
6	28 Nov 2017 15:47	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):SURVEY REVERT	[I] Chong Boon Sen
7	28 Nov 2017 15:47	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/12/07	[I] Chong Boon Sen
8	28 Nov 2017 15:47	Adj Mandate Set	Approved:0.00.	[I] Chong Boon Sen
9	28 Nov 2017 17:46	Assignment 1st Accessed		[A] Nivitha Govindasamy
10	29 Nov 2017 13:09	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] CATHERINE CHONG KAI LING
11	30 Nov 2017 15:38	Adj Rpt Initiated		[A] LOW AI PHING
12	30 Nov 2017 15:46	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2017/12/07	[A] LOW AI PHING
13	30 Nov 2017 15:49	Adj Mandate Request	Cur.Req:0.00:DAMAGES CONSISTENT. PENDING REPAIR COST FROM REPAIRER.	[A] LOW AI PHING
14	01 Dec 2017 11:27	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/12/07. Mandate Remarks: KINDLY SEND BACK WHEN GOT REPAIR COST AS ADVISED. THANK YOU.	[I] Chong Boon Sen
15	01 Dec 2017 11:27	Adj Mandate Set	Maintained:KINDLY SEND BACK WHEN GOT REPAIR COST AS ADVISED. THANK YOU.	[I] Chong Boon Sen
16	05 Dec 2017 11:44	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2017/12/07	[A] LOW AI PHING
17	05 Dec 2017 11:45	Adj Mandate Request	Cur.Req:36000.00:DAMAGES CONSISTENT. REPAIRER ASKING THE REPAIR COST AT LUMP SUM \$36,000.00.	[A] LOW AI PHING
18	07 Dec 2017 16:47	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2017/12/07. Mandate Remarks: PLEASE PROCEED TO AUTHORIZE REPAIRS AT \$36,000.00 (lump sum basis) before EXCESS OF \$500.00. Vehicle required to be sent to Inspection Centre for inspection BEFORE releasing to Insured.	[I] Alfred Toh
19	07 Dec 2017 16:47	Adj Mandate Set	Approved:36000.00:PLEASE PROCEED TO AUTHORIZE REPAIRS AT \$36,000.00 (lump sum basis) before EXCESS OF \$500.00. Vehicle required to be sent to Inspection Centre for inspection BEFORE releasing to Insured.Reinsp:Adj decides.	[I] Alfred Toh

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1649291	24/11/2017 18:03	Motor	S & H Motor Pte Ltd (HQ)	S & H Motor Pte Ltd (Sin Ming)	YN9325J		xx.xx
1654178	30/11/2017 15:38	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	YN9325J		10.70

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. From: LKK Auto Consultants Pte Ltd
 3 Anson Road 51 Ubi Ave 1 #01-25
 #16-00 Springleaf Tower Paya Ubi Industrial Park
 Singapore 079909 Singapore 408933

Attn: Chong Boon Sen

Date: 05 Dec 2017

Preliminary Advice

Vehicle No	: YN9325J	Accident Date	: 30/10/2017
Make	: MITSUBISHI CANTER	Policy No.	: DMCVSN3072781700
Assignment Date	: 28/11/2017	Excess	: S\$500.00
Date of Inspection	: 29/11/2017	Est. Duration of Repair	: 30.00
Inspection At	: S & H MOTOR PTE LTD (SIN MING) 160 SIN MING DRIVE #07-02, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	78,056.34
Revised Amount	:S\$	49,469.35
Check Items (Estimated)	:S\$	21,262.50
Total	:S\$	70,731.85

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	72,000.00
COE / PARF Rebate	:S\$	36,673.00
Salvage Value	:S\$	
Margin for Repair	:S\$	35,327.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Repairer asking the repair cost at Lump Sum \$36,000.00.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 30 Nov 2017

Preliminary Advice

Vehicle No	: YN9325J	Accident Date	: 30/10/2017
Make	: MITSUBISHI CANTER	Policy No.	: DMCVSN3072781700
Assignment Date	: 28/11/2017	Excess	: S\$500.00
Date of Inspection	: 29/11/2017	Est. Duration of Repair	: 30.00
Inspection At	: S & H MOTOR PTE LTD (SIN MING) 160 SIN MING DRIVE #07-02, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	78,056.34
Revised Amount	:S\$	49,469.35
Check Items (Estimated)	:S\$	21,262.50
Total	:S\$	70,731.85

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	72,000.00
COE / PARF Rebate	:S\$	36,673.00
Salvage Value	:S\$	
Margin for Repair	:S\$	35,327.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorise repair.

Repair on Lump Sum basis.

Pending repair cost from repairer.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Company
Owner ID	3371M

Vehicle Details

Vehicle No.	YN9325J
Vehicle to be Exported	No
Intended De-registration Date	30 Nov 2017
Vehicle Make	MITSUBISHI
Vehicle Model	CANTER FEB21ER3SDEB (CBU)
Primary Colour	White
Manufacturing Year	2015
Engine No.	4P10B76359
Chassis No.	FEB21EA10462
Maximum Power Output	-
Open Market Value	\$28,881.00
Original Registration Date	02 Oct 2015
First Registration Date	02 Oct 2015
Transfer Count	0
Actual ARF Paid	\$1,445.00

Intended PARF Rebate Details

PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00

Intended COE Rebate Details

COE Expiry Date	01 Oct 2025
COE Category	C - Goods Vehicle & Bus
COE Period(Years)	10
QP Paid	\$46,801.00
COE Rebate Amount	\$36,673.00
Total Rebate Amount	\$36,673.00

The information contained herein is correct as at 30 Nov 2017

OK

Enquire Transfer Fee

Vehicle Details

Vehicle No.	YN9325J
Vehicle Type	B31 - Goods (Open) Lorry (Metal Body)/Pickup
Vehicle Attachment 1	With Hood
Vehicle Scheme	Normal
Vehicle Make	MITSUBISHI
Vehicle Model	CANTER FEB21ER3SDEB (CBU)
Chassis No.	FEB21EA10462
Propellant	Diesel
Engine No.	4P10B76359
Engine Capacity	2998 cc
Maximum Power Output	-
Maximum Laden Weight	5000 kg
Unladen Weight	2500 kg
Year Of Manufacture	2015
Original Registration Date	02 Oct 2015
Lifespan Expiry Date	01 Oct 2035
COE Category	C - Goods Vehicle & Bus
Quota Premium	\$46,801.00
COE Expiry Date	01 Oct 2025
Road Tax Expiry Date	01 Apr 2018
Inspection Due Date	01 Oct 2018
Intended Transfer Date	25 Nov 2017
CO2 Emission	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use [Enquire Road Tax Payable](#) for fee (s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee	11.00	-	11.00
Total Amount Payable			11.00

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/11/2017 14:18
Date Of Accident	30/10/2017 06:15
Exact Location Of Accident	TUAS SOUTH AVE 5 NEAR TO BUS STOP B09
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YN9325J
Insured/Policyholder	
Name Of Registered Owner	SOUTH FORWARD CONSTRUCTION PTE LTD
Co Reg No	- 201013371M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67437336/67457336

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	-
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN3072781700
Cover Note Number	

Driver

Name of Driver	SAMINATHAN KALIYAMOORTHY
Work Permit No	F7945990U
Date Of Birth	01/04/1975
Occupation	OUTDOOR
Date Of Driving Pass	25/06/2012
Driving Experience	5 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Email Address

DETAILS OF INJURED PERSON 1

Name LIU GUODONG
Approximate Age
Injuries Sustain
Injured person in which vehicle? YN9325J
Were seat belts worn?
Was injured conveyed to hospital by ambulance? YES
Address
Postcode

DETAILS OF INJURED PERSON 2

Name SAMINATHAN KALIYAMOORTHY
Approximate Age
Injuries Sustain
Injured person in which vehicle? YN9325J
Were seat belts worn?
Was injured conveyed to hospital by ambulance? YES
Address
Postcode

DETAILS OF INJURED PERSON 3

Name WANG BUJUN
Approximate Age
Injuries Sustain
Injured person in which vehicle? YN9325J
Were seat belts worn?
Was injured conveyed to hospital by ambulance? YES
Address
Postcode

DETAILS OF INJURED PERSON 4

Name HAO HONGGUANG
Approximate Age
Injuries Sustain
Injured person in which vehicle? YN9325J
Were seat belts worn?
Was injured conveyed to hospital by ambulance? YES
Address
Postcode

DETAILS OF INJURED PERSON 5

Name MIAO LICHANG
Approximate Age
Injuries Sustain
Injured person in which vehicle? YN9325J
Were seat belts worn?
Was injured conveyed to hospital by ambulance? YES
Address
Postcode

DETAILS OF INJURED PERSON 6

Name XU JIANHUA
Approximate Age

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

S. Kalar
Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20171030/2134

Police Station Of Origin:
Geylang Serai NPP
111 Aljunied Crescent #01-102 SINGAPORE
380111
Tel No: 1800-7459999

1 of 9

Report No. T/20171030/2134

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 30/10/2017 18:42		Vide Report No.:		Station Diary No.: 46	
Name of Informant: SAMINATHAN KALIYAMOORTHY					
Address: APT BLK 39 KAKI BUKIT AVENUE 3 #08-25 HOMESTAY LODGE SINGAPORE 415920					
ID Type / ID No.: FIN NO / F7945990U		Contact No.: Home/Office: 6745 7336 Mobile: 8149 5731			
Nationality: INDIAN		Email:			
Sex: Male	Age: 42	Date of Birth: 01/04/1975	Type of Informant: Driver		
Race: Indian		Language: English		Institution / School Name:	
Occupation: Lorry driver		Driving Licence Information: Class: Date of Expiry:			

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 30/10/2017 06:15	Type of Location: Straight Road
Location: Along Road 1 TUAS SOUTH AVENUE 5 NEAR TO BUS STOP B09				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume:
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

XE903J	Lorry	MITSUBISHI	FUSO FV51SS3VD EA	White		0
YN9325J	Lorry	MITSUBISHI	CANTER FEB21ER3S DEB (CBU)	White	Seriously Damaged	24



**SINGAPORE
POLICE FORCE**



T/20171030/2134

Police Station Of Origin:
Geylang Serai NPP
111 Aljunied Crescent #01-102 SINGAPORE
380111
Tel No: 1800-7459999

3 of 9


Report No. T/20171030/2134

CONTINUATION OF REPORT

Name	HAO HONGGUANG		ID No.	G6930967X
Related Vehicle	YN9325J (Lorry)		Contact No.	NIL
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	30/10/2017	Date Discharge	30/10/2017	
No. of Days granted Medical Leave	03	Degree of Injury	Slight	
Name	MIAO LICHANG		ID No.	G7751970Q
Related Vehicle	YN9325J (Lorry)		Contact No.	NIL
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	30/10/2017	Date Discharge	30/10/2017	
No. of Days granted Medical Leave	03	Degree of Injury	Slight	
Name	XU JIANHUA		ID No.	G2404801U
Related Vehicle	YN9325J (Lorry)		Contact No.	NIL
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	30/10/2017	Date Discharge	30/10/2017	
No. of Days granted Medical Leave	03	Degree of Injury	Slight	
Name	WANG DAOWU		ID No.	G8085107W
Related Vehicle	YN9325J (Lorry)		Contact No.	NIL
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	30/10/2017	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight	



**SINGAPORE
POLICE FORCE**



T/20171030/2134

Police Station Of Origin:
Geylang Serai NPP
111 Aljunied Crescent #01-102 SINGAPORE
380111
Tel No: 1800-7459999

5 of 9

Report No. T/20171030/2134

CONTINUATION OF REPORT

Name	BU GUIXIANG	ID No.	G8533366L
Related Vehicle	YN9325J (Lorry)	Contact No.	NIL
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	30/10/2017	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight
Name	DEB DIPONGKOR KUMAR	ID No.	G2726421U
Related Vehicle	YN9325J (Lorry)	Contact No.	NIL
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	30/10/2017	Date Discharge	30/10/2017
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Name	ZHU MENGTAO	ID No.	G2836519K
Related Vehicle	YN9325J (Lorry)	Contact No.	NIL
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	30/10/2017	Date Discharge	30/10/2017
No. of Days granted Medical Leave	02	Degree of Injury	Slight
Name	BA CHAW	ID No.	G2581169R
Related Vehicle	YN9325J (Lorry)	Contact No.	NIL
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	30/10/2017	Date Discharge	30/10/2017
No. of Days granted Medical Leave	02	Degree of Injury	Slight



**SINGAPORE
POLICE FORCE**



T/20171030/2134

Police Station Of Origin:
Geylang Serai NPP
111 Aljunied Crescent #01-102 SINGAPORE
380111
Tel No: 1800-7459999

7 of 9

Report No. T/20171030/2134

CONTINUATION OF REPORT

Name	XUE RU JIAN		ID No.	G8314555U
Related Vehicle	YN9325J (Lorry)		Contact No.	NIL
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	30/10/2017	Date Discharge	30/10/2017	
No. of Days granted Medical Leave	03	Degree of Injury	Slight	
Name	MD MOBARAK ABDUL		ID No.	G8403464P
Related Vehicle	YN9325J (Lorry)		Contact No.	NIL
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	30/10/2017	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	Serious	
Name	CHEN XIN		ID No.	G6721960R
Related Vehicle	YN9325J (Lorry)		Contact No.	NIL
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	30/10/2017	Date Discharge	30/10/2017	
No. of Days granted Medical Leave	03	Degree of Injury	Slight	
Name	WANG QI ZUO		ID No.	G2322123W
Related Vehicle	YN9325J (Lorry)		Contact No.	NIL
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	30/10/2017	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	Serious	



**SINGAPORE
POLICE FORCE**



T/20171030/2134

Police Station Of Origin:
Geylang Serai NPP
111 Aljunied Crescent #01-102 SINGAPORE
380111
Tel No: 1800-7459999

9 of 9


Report No. T/20171030/2134

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sgt 1 SIM SENG ZHI, JORDAN	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 30/10/2017 18:42
Officer In Charge Of Case: TP / GIT / Insp NORHIDAWATI BINTE AHMAD Contact No.: 65476310	Classification Of Case:

Authentication Stamp
NP168



Signature

Singapore Police Force



INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. N
Policy No:	DMCVSN3072781700	Date of 30/10/2015
Vehicle Reg. No.:	YN9325J	Driveable
Driver Age/Info:	42 / MALE	Party At Fault: UNKNOWN
TP Injury Involved?	YES	Third Party Involved?

Insured/Claimant: SOUTH FORWARD CONSTRUCTION PTE LTD

Driver: SAMINATHAN KALIYAMOORTHY

Make/Model:	MITSUBISHI CANTER, 3.0 D FEB21ER3SDEB (CBU) (M)	Vehicle Reg. Date: 02/10/2015
-------------	---	-------------------------------

Vehicle Colour: White

Engine No: 4P10B76359


Odometer: 0 KM

Chassis No: FEB21EA10462

Paint Type:

Total Loss? NO

Est. Duration of Repair (day) ~~30~~ 30 days



NOT NOTIFIED
L1 by 87
Passing After Paint
Ex 8500

Description of Accident/Loss: REFER ATTACHED POLICE REPORT.

Fax: 62564315

Present Location: S & AMP; H MOTOR PTE LTD (SIN MING)

COST OF CLAIMS

	Amount
Parts	63,920.85
Miscellaneous Items	229.00
Labour	8,680.00
Paintwork Labour	0.00
Towing	120.00
Gross Total (S\$)	72,949.85
+ GST 7.00% (S\$)	5,106.49
Nett Amount (S\$)	78,056.34

This claim is handled by: LUM WEE KEAT

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 24 Nov 2017)
Parts: N/A MITSUBISHI CANTER 3.0 D FEB21ER3SDEB (CBU) (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: S & H Motor Pte Ltd/YN9325J/24/11/2017 18:14
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount	
1	1		*Front windscreen glass	M17	0.00	0.00	*850.00 F	)
2	1		*Front windscreen glass moulding	Gr	0.00	0.00	*230.00 F	)
3	1		*RH front windscreen pillar	B2	0.00	0.00	*680.00 F	)
4	1		*LH front windscreen pillar	B2	0.00	0.00	*680.00 F	)
5	1		*RH front windscreen pillar inner garnish	PJ / D17	0.00	0.00	*380.00 F	)
6	1		*LH front windscreen pillar inner garnish	M / D17	0.00	0.00	*380.00 F	)
7	1		*RH Front door	Bu	0.00	0.00	*1,180.00 F	)
8	1		*LH Front door	Bu	0.00	0.00	*1,180.00 F	)
9	1		*RH Front door top hinge	B2	0.00	0.00	*138.00 F	)
10	1		*RH Front door bottom hinge	B2	0.00	0.00	*138.00 F	)
11	1		*LH Front door top hinge	B2	0.00	0.00	*138.00 F	)
12	1		*LH Front door bottom hinge	B2	0.00	0.00	*138.00 F	)
13	1		*RH Front door window glass	Shower	0.00	0.00	*350.00 F	)
14	1		*LH Front door window glass	u	0.00	0.00	*350.00 F	)
15	1		*RH Front door glass inner moulding	Bu	0.00	0.00	*120.00 F	)
16	1		*LH Front door glass inner moulding	M17	0.00	0.00	*120.00 F	)
17	1		*RH Front door glass outer moulding	Bu	0.00	0.00	*110.00 F	)
18	1		*LH Front door glass outer moulding	M17	0.00	0.00	*110.00 F	)
19	1		*RH Front door front cover garnish	CMA	0.00	0.00	*190.00 F	)
20	1		*LH Front door front cover garnish	M17	0.00	0.00	*190.00 F	)
21	1		*RH Front door trim board	M17	0.00	0.00	*700.00 F	)
22	1		*LH Front door trim board	M17	0.00	0.00	*700.00 F	)
23	1		*RH Front door trim board top handle	M17	0.00	0.00	*120.00 F	)
24	1		*LH Front door trim board top handle	M17	0.00	0.00	*120.00 F	)
25	1		*RH Front door inner lock	T2	0.00	0.00	*650.00 F	)
26	1		*LH Front door inner lock	T2	0.00	0.00	*650.00 F	)
27	1		*RH front door weatherstrip	Gr	0.00	0.00	*290.00 F	)
28	1		*LH front door weatherstrip	Gr	0.00	0.00	*290.00 F	)
29	1		*RH Front door outer key lock	Sm	0.00	0.00	*180.00 F	X
30	1		*LH Front door outer key lock	M17	0.00	0.00	*180.00 F	)
31	1		*RH Front door inner handle	M17	0.00	0.00	*110.00 F	)
32	1		*LH Front door inner handle	M17	0.00	0.00	*110.00 F	)
33	1		*RH Front door entrance floor garnish	CMA	0.00	0.00	*325.00 F	)
34	1		*LH Front door entrance floor garnish	CMA	0.00	0.00	*325.00 F	)
35	1		*RH Front door entrance surround beading	Reform	0.00	0.00	*260.00 F	)
36	1		*LH Front door entrance surround beading	u	0.00	0.00	*260.00 F	)
37	1		*RH Front door step panel	B2	0.00	0.00	*380.00 F	)
38	1		*LH Front door step panel	B2	0.00	0.00	*380.00 F	)
39	1		*RH door rear mirror handle	M17	0.00	0.00	*280.00 F	)
40	1		*LH door rear mirror handle	M17	0.00	0.00	*280.00 F	)
41	1		*Front right door rear mirror	Bu	0.00	0.00	*295.00 F	)
42	2		*LH Front door rear square mirror	M17	0.00	0.00	*180.00 F	)
43	1		*LH Front door rear mirror round mirror	M17	0.00	0.00	*60.00 F	)
44	1		*RH outer mirror round garnish cover	M17	0.00	0.00	*60.00 F	)
45	1		*LH outer mirror round garnish cover	M17	0.00	0.00	*60.00 F	)
46	1		*RH Front door window regulator	B2	0.00	0.00	*700.00 F	)
47	1		*LH Front door window regulator	B2	0.00	0.00	*700.00 F	)

48	1	*RH Front door bottom garnish	CM	0.00	0.00	*90.00 F	(
49	1	*LH Front door bottom garnish	CM	0.00	0.00	*90.00 F	(
50	1	*RH Front door outer handle	Sn	0.00	0.00	*110.00 F	X
51	1	*LH Front door outer handle	Sn	0.00	0.00	*110.00 F	(
52	1	*Front right door lock	Tm	0.00	0.00	*480.00 F	(
53	1	*RH Front door window inner switch	Sn	0.00	0.00	*480.00 F	X
54	1	*LH Front door window inner switch	CM	0.00	0.00	*480.00 F	(
55	1	*RH Front door glass channel	D1	0.00	0.00	*220.00 F	(
56	1	*LH Front door glass channel	D1	0.00	0.00	*220.00 F	(
57	1	*RH Front door outer surround garnish	CM	0.00	0.00	*65.00 F	(
58	1	*LH Front door outer surround garnish	CM	0.00	0.00	*65.00 F	(
59	1	*Front large panel	B	0.00	0.00	*1,050.00 F	(
60	1	*Front wiper garnish	B	0.00	0.00	*350.00 F	(
61	1	*RH wiper arm	D1	0.00	0.00	*130.00 F	(
62	1	*LH wiper arm	D1	0.00	0.00	*130.00 F	(
63	2	*Front wiper nozzle	D1	0.00	0.00	*240.00 F	(
64	1	*Front wiper link rod	B	0.00	0.00	*480.00 F	(
65	1	*Front windscreen glass wiper motor	Sn	0.00	0.00	*490.00 F	X
66	1	*Front wiper water tank	Sn	0.00	0.00	*280.00 F	X
67	1	*Front wiper water tank motor	Sn	0.00	0.00	*190.00 F	X
68	1	*Front bumper	B	0.00	0.00	*680.00 F	(
69	1	*RH Front bumper bracket	B	0.00	0.00	*240.00 F	(
70	1	*LH Front bumper bracket	B	0.00	0.00	*240.00 F	(
71	1	*RH front bumper side rubber	M1	0.00	0.00	*240.00 F	(
72	1	*LH front bumper side rubber	Bu	0.00	0.00	*240.00 F	(
73	1	*RH headlamp	Bu	0.00	0.00	*465.00 F	(
74	1	*LH headlamp	M1 CM	0.00	0.00	*465.00 F	(
75	1	*RH headlamp bottom rubber	M1	0.00	0.00	*45.00 F	(
76	1	*LH headlamp bottom rubber	M1	0.00	0.00	*45.00 F	(
77	1	*Front grille	M1	0.00	0.00	*680.00 F	(
78	1	*Front grille clips (1 set)	Av	0.00	0.00	*35.00 F	(
79	1	*Front large panel FUSO emblem	M1	0.00	0.00	*35.00 F	(
80	1	*RH Front corner panel	B	0.00	0.00	*360.00 F	(
81	1	*LH Front corner panel	B	0.00	0.00	*360.00 F	(
82	1	*RH Front side lamp	Bu	0.00	0.00	*190.00 F	(
83	1	*LH Front side lamp	Bu	0.00	0.00	*190.00 F	(
84	1	*RH signal lamp	Bu	0.00	0.00	*220.00 F	(
85	1	*LH signal lamp	Bu	0.00	0.00	*220.00 F	(
86	1	*Front dashboard	Bu 1 CM	0.00	0.00	*1,900.00 F	(
87	1	*Front dashboard bottom garnish	CM	0.00	0.00	*1,150.00 F	(
88	1	*Front dashboard left grove cover	CM	0.00	0.00	*120.00 F	(
89	1	*Front dashboard left grove box	D1	0.00	0.00	*380.00 F	(
90	1	*Front dashboard inner reinforcement bar	B	0.00	0.00	*380.00 F	(
91	1	*Front dashboard instrument panel	B	0.00	0.00	*1,650.00 F	(
92	1	*Front dashboard central ECU	Sn	0.00	0.00	*1,800.00 F	X
93	1	*Rear view mirror	M1	0.00	0.00	*120.00 F	(
94	1	*Roof lining	Re form	0.00	0.00	*950.00 F	(
95	1	*Front oil cooler	Sn	0.00	0.00	*1,650.00 F	X
96	1	*Radiator	Sn	0.00	0.00	*2,850.00 F	X
97	1	*Engine fan clutch	Sn	0.00	0.00	*880.00 F	X
98	1	*Engine fan blade	Sn	0.00	0.00	*360.00 F	X
99	1	*Engine fan cowling rubber	Sn	0.00	0.00	*75.00 F	X
100	1	*Air con condenser	Sn	0.00	0.00	*780.00 F	X
101	1	*Air con condenser pipe inlet	Sn	0.00	0.00	*325.00 F	X
102	1	*Air con condenser pipe outlet	Sn	0.00	0.00	*280.00 F	X
103	2	*Air con pressure pipe	Sn	0.00	0.00	*490.00 F	X
104	1	*Air con cooling coil	CM	0.00	0.00	*480.00 F	X
105	1	*Air con blower box	CM	0.00	0.00	*2,850.00 F	(
106	1	*Air con blower motor	Sn	0.00	0.00	*1,950.00 F	X
107	2	*Engine mounting	Sn	0.00	0.00	*580.00 F	X
108	2	*Gear box mounting	Sn	0.00	0.00	*180.00 F	X

109	1	*Fuse box	CDL	0.00	0.00	*850.00 F	✓
110	1	*Front steering box	R	0.00	0.00	*1,350.00 F	X
111	1	*Front steering shaft	R	0.00	0.00	*1,320.00 F	✓
112	1	*Front steering coupling	R	0.00	0.00	*750.00 F	✓
113	1	*RH Front seat belt garnish	gn	0.00	0.00	*600.00 F	X
114	1	*LH Front seat belt garnish	Reform	0.00	0.00	*600.00 F	✓
115	1	*Front cabin hinge (1 set)	R	0.00	0.00	*800.00 F	✓
116	1	*Brake master pump	gn	0.00	0.00	*1,800.00 F	X
117	1	*Brake booster	SL	0.00	0.00	*1,700.00 F	R
118	1	*Front brake pipes (1 set)	Ref	0.00	0.00	*450.00 F	✓
119	1	*Rear windscreen glass	CDL	0.00	0.00	*420.00 F	✓
120	1	*Rear windscreen glass rubber	Re	0.00	0.00	*190.00 F	✓
121	1	*Brake pedal	R	0.00	0.00	*490.00 F	X
122	1	*Accelerator pedal	R	0.00	0.00	*380.00 F	X

F=Franchise part.

Sub Total (S\$)	60,877.00	538
+ Margin on L,N Items 5.00% (S\$)	3,043.85	
Total Parts (S\$)	63,920.85	

S & H Motor Pte Ltd/YN9325J/24/11/2017 18:14. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is not a 'Final Payable' basis
- No illegal modification allowed
- Supplementary work must be approved and is subject to final approval by Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	Engine coolant	40.00
2	1	Front door lettering (RH & LH)	40.00
3	1	Front number plate	35.00
4	1	Front windscreen inner seal	28.00
5	1	Front windscreen sealant	60.00
6	1	IU bracket	26.00
Sub Total (S\$)			229.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	To spray paint affected front and inner damaged portion inclusive of preparatory works and material	New	1,800.00
2	To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp	New	420.00
3	To lift up front cabin, remove interior seats and check front chassis frame	New	480.00
4	To remove and replace dashboard, instrument panels, and dashboard inner components	New	480.00
5	To remove radiator, engine fan, clutch, hoses and replace damaged parts and check engine cooling system functionality	New	380.00
6	To remove and check air con condenser, dryer, aluminium pipes, valves and reinstall components and vacuum and charge refrigerant R134a and check for leakage and full functionality	New	280.00
7	To install front windscreen glass	New	150.00
8	To install rear windscreen glass	New	80.00
9	To remove and install front brake booster, master pump, steering column, steering shaft and brake pipes	New	450.00
10	To remove and check engine, gearbox, radiator, engine & gearbox mountings, intake and exhaust manifold & for damage and reinstall components and check engine running functionality	New	380.00
11	To hire crane, for lifting and installing of cabin	New	800.00
12	To remove front cabin, , to reweld, reshape and repair cabin damaged panels, cabin bracket, to jack out front chassis, to straighten out front body and chassis alignment and adjust body panel alignment	New	2,800.00
13	To perform computer diagnostic on drivetrain, ABS systems and clear fault codes	New	180.00
Gross Labour Cost (S\$)			8,680.00

S & H Motor Pte Ltd/YN9325J/24/11/2017 18:14. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Nov 2017 Sendback Est	24 Nov 2017 18:14 S\$72,949.85	28 Nov 2017 15:47 Edit Adj Rpt	S\$36,000.00 Edit Estimates	S\$36,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS			
Insured:	SOUTH FORWARD CONSTRUCTION PTE LTD, Co. Reg. No.: -		
Vehicle Reg. No.:	YN9325J	Date of Loss:	30/10/2017 06:00 - :59
Claim Type:	OD / SNM17D06332C01	Policy/Cover Note No.:	DMCVSN3072781700 (Comprehensive)
		Excess:	S\$500.00
Repairer:	S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6453 4730		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 07/12/2017]		
Driver/Custodian:	SAMINATHAN KALIYAMOORTHY (42 / Male), NRIC: F7945990U		
Adj Asg. Remarks:	SURVEY REVERT		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
- CHINA_TAIPING (07/12/2017): Alert - Adj Mandate Approved (S\$36000.00) - YN9325J - Claim Handler: Chong Boon ... - CHINA_TAIPING (01/12/2017): Alert - Adj Mandate Maintained - YN9325J - Claim Handler: Chong Boon Sen		

ALL ASSOCIATED TASKS						View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

YN9325J (SNM17D06332C01)
OD
Oct 30 2017 6:00AM
[SOUTH FORWARD CONSTRUCTION PTE LTD]
S & H Motor Pte Ltd

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View [View in Browser](#)

Assessment Reports				1 per page	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	09/11/17 14:46	Accident Statement		Load HTM	
2	14/11/17 12:59	Addendum Sheet		Load TIF	
3	14/11/17 13:03	Accident Statement Addm. #1		Load HTM	
4	18/11/17 14:01	Addendum Sheet		Load TIF	
5	18/11/17 14:23	Accident Statement Addm. #2		Load HTM	
6	24/11/17 18:14	Repairer Estimates		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	30/11/17 15:46	Adjuster Immediate Advice		Load HTM	
2	05/12/17 11:44	Adjuster Immediate Advice		Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	18/11/17 14:04	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
2	18/11/17 14:04	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
3	18/11/17 14:04	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
4	18/11/17 14:04	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
5	18/11/17 14:04	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
6	18/11/17 14:04	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
7	18/11/17 14:04	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	30/11/17 11:52	PHOTO		Load PDF	
Documentation				1 per page	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	09/11/17 14:31	Sketch Plan [Linked Accident Report Documents]		Load TIF	
2	09/11/17 14:31	Sketch Plan #2 [Linked Accident Report Documents]		Load TIF	
3	09/11/17 14:31	Sketch Plan #3 [Linked Accident Report Documents]		Load TIF	
4	09/11/17 14:31	Sketch Plan #4 [Linked Accident Report Documents]		Load TIF	
5	09/11/17 14:31	Sketch Plan #5 [Linked Accident Report Documents]		Load TIF	
6	09/11/17 14:31	Sketch Plan #6 [Linked Accident Report Documents]		Load TIF	
7	09/11/17 14:32	Accident Sketch Plan [Linked Accident Report Documents]		Load TIF	
8	09/11/17 14:32	Accident Sketch Plan [Linked Accident Report Documents]		Load TIF	
9	09/11/17 14:32	Accident Sketch Plan [Linked Accident Report Documents]		Load TIF	
10	09/11/17 14:32	Accident Sketch Plan [Linked Accident Report Documents]		Load TIF	

11	09/11/17 14:32	Accident Sketch Plan [Linked Accident Report Documents]		Load TIF	
12	09/11/17 14:32	Accident Sketch Plan [Linked Accident Report Documents]		Load TIF	
13	09/11/17 14:32	Accident Sketch Plan [Linked Accident Report Documents]		Load TIF	
14	18/11/17 14:02	Accident Sketch Plan [Linked Accident Report Documents]		Load TIF	

Linked Accident Report Documents

View

Assessment Reports				1 per page	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	09/11/17 14:46	Accident Statement		Load HTM	
2	14/11/17 12:59	Addendum Sheet		Load TIF	
3	14/11/17 13:03	Accident Statement Addm. #1		Load HTM	
4	18/11/17 14:01	Addendum Sheet		Load TIF	
5	18/11/17 14:23	Accident Statement Addm. #2		Load HTM	
Photos/ Images				3 per page	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	18/11/17 14:04	Accident Photo		Load JPG	☒
2	18/11/17 14:04	Accident Photo		Load JPG	☒
3	18/11/17 14:04	Accident Photo		Load JPG	☒
4	18/11/17 14:04	Accident Photo		Load JPG	☒
5	18/11/17 14:04	Accident Photo		Load JPG	☒
6	18/11/17 14:04	Accident Photo		Load JPG	☒
7	18/11/17 14:04	Accident Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	09/11/17 14:31	Sketch Plan		Load TIF	
2	09/11/17 14:31	Sketch Plan #2		Load TIF	
3	09/11/17 14:31	Sketch Plan #3		Load TIF	
4	09/11/17 14:31	Sketch Plan #4		Load TIF	
5	09/11/17 14:31	Sketch Plan #5		Load TIF	
6	09/11/17 14:31	Sketch Plan #6		Load TIF	
7	09/11/17 14:32	Accident Sketch Plan		Load TIF	
8	09/11/17 14:32	Accident Sketch Plan		Load TIF	
9	09/11/17 14:32	Accident Sketch Plan		Load TIF	
10	09/11/17 14:32	Accident Sketch Plan		Load TIF	
11	09/11/17 14:32	Accident Sketch Plan		Load TIF	
12	09/11/17 14:32	Accident Sketch Plan		Load TIF	
13	09/11/17 14:32	Accident Sketch Plan		Load TIF	
14	18/11/17 14:02	Accident Sketch Plan		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT117022682/KGBE2

Date: 22/03/2018

REFERENCE

Insured/Claimant: SOUTH FORWARD CONSTRUCTION PTE LTD

Policy No: DMCVSN3072781700

Date of Loss: 30/10/2017

Nature of Claim: OD

Claim No: SNM17D06332C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YN9325J

Make & Model: MITSUBISHI CANTER, 3.0 D FEB21ER3SDEB (CBU) (M)

Engine No: 4P10B76359

Reg. Date: 02/10/2015 (Man. Year: 2015)

Chassis No: FEB21EA10462

Colour: White

Odometer: 0 km

Engine Capacity: 2998 cc

Market Value/New Car Price: S\$72,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/85 R15

Rear Tyre Size: 195/85 R15 (D)

Front Left Side: Bridgestone 3 mm

Rear Left Side: Bridgestone 9/9 mm

Front Right Side: Bridgestone 4 mm

Rear Right Side: Bridgestone 9/9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	63,920.85	42,658.35	21,262.50	33.26
Miscellaneous Items	229.00	131.00	98.00	42.79
Labour	8,680.00	6,680.00	2,000.00	23.04
Paintwork Labour	0.00	0.00	0.00	
Towing	120.00	0.00	120.00	100.00
Calculated Gross Total (S\$)	72,949.85	49,469.35	23,480.50	32.19
Approved Total (Overridden) (S\$)		36,000.00		
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	72,949.85	35,500.00	37,449.85	51.34
+ GST 7.00/7.00% (S\$)	5,106.49	2,485.00	2,621.49	51.34
Nett Amount (S\$)	78,056.34	37,985.00	40,071.34	51.34

INSPECTION

Date of Assignment: 28/11/2017 Present Location:

Date Inspected: 29/11/2017 Inspected At:

S & H Motor Pte Ltd (Sin Ming)

160 Sin Ming Drive #07-02, Sin Ming

AutoCity

Singapore 575722

Estimated Period of Repair: 30.0 days

Adjuster: KENNETH KONG**Manager:** LOW AI PHING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 22 Mar 2018)
Parts: N/A MITSUBISHI CANTER 3.0 D FEB21ER3SDEB (CBU) (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for YN9325J)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front windscreen glass (WCP)	Missing	850.00 F	*850.00 F
2	1		*Front windscreen glass moulding (WCP)	Cut	230.00 F	*230.00 F
3	1		*RH front windscreen pillar (WCP)	Bent	680.00 F	*680.00 F
4	1		*LH front windscreen pillar (WCP)	Bent	680.00 F	*680.00 F
5	1		*RH front windscreen pillar inner garnish (WCP)	Dented / Distorted	380.00 F	*380.00 F
6	1		*LH front windscreen pillar inner garnish (WCP)	Dented / Distorted	380.00 F	*380.00 F
7	1		*RH Front door (WCP)	Buckled	1,180.00 F	*1,180.00 F
8	1		*LH Front door (WCP)	Buckled	1,180.00 F	*1,180.00 F
9	1		*RH Front door top hinge (WCP)	Bent	138.00 F	*138.00 F
10	1		*RH Front door bottom hinge (WCP)	Bent	138.00 F	*138.00 F
11	1		*LH Front door top hinge (WCP)	Bent	138.00 F	*138.00 F
12	1		*LH Front door bottom hinge (WCP)	Bent	138.00 F	*138.00 F
13	1		*RH Front door window glass (WCP)	Shorted	350.00 F	*350.00 F
14	1		*LH Front door window glass (WCP)	Shorted	350.00 F	*350.00 F
15	1		*RH Front door glass inner moulding (WCP)	Buckled	120.00 F	*120.00 F
16	1		*LH Front door glass inner moulding (WCP)	Missing	120.00 F	*120.00 F
17	1		*RH Front door glass outer moulding (WCP)	Buckled	110.00 F	*110.00 F
18	1		*LH Front door glass outer moulding (WCP)	Missing	110.00 F	*110.00 F
19	1		*RH Front door front cover garnish (WCP)	Cracked	190.00 F	*190.00 F
20	1		*LH Front door front cover garnish (WCP)	Missing	190.00 F	*190.00 F
21	1		*RH Front door trim board (WCP)	Missing	700.00 F	*700.00 F
22	1		*LH Front door trim board (WCP)	Missing	700.00 F	*700.00 F
23	1		*RH Front door trim board top handle (WCP)	Missing	120.00 F	*120.00 F
24	1			Missing	120.00 F	*120.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*LH Front door trim board top handle (WCP)			
25	1		*RH Front door inner lock (WCP)	Jammed	650.00 F	*650.00 F
26	1		*LH Front door inner lock (WCP)	Jammed	650.00 F	*650.00 F
27	1		*RH front door weatherstrip (WCP)	Cut	290.00 F	*290.00 F
28	1		*LH front door weatherstrip (WCP)	Cut	290.00 F	*290.00 F
29	1		*RH Front door outer key lock (WCP)	Serviceable	180.00 F	*- F
30	1		*LH Front door outer key lock (WCP)	Missing	180.00 F	*180.00 F
31	1		*RH Front door inner handle (WCP)	Missing	110.00 F	*110.00 F
32	1		*LH Front door inner handle (WCP)	Missing	110.00 F	*110.00 F
33	1		*RH Front door entrance floor garnish (WCP)	Cracked	325.00 F	*325.00 F
34	1		*LH Front door entrance floor garnish (WCP)	Cracked	325.00 F	*325.00 F
35	1		*RH Front door entrance surround beading (WCP)	Deformed	260.00 F	*260.00 F
36	1		*LH Front door entrance surround beading (WCP)	Deformed	260.00 F	*260.00 F
37	1		*RH Front door step panel (WCP)	Bent	380.00 F	*380.00 F
38	1		*LH Front door step panel (WCP)	Bent	380.00 F	*380.00 F
39	1		*RH door rear mirror handle (WCP)	Missing	280.00 F	*280.00 F
40	1		*LH door rear mirror handle (WCP)	Missing	280.00 F	*280.00 F
41	1		*Front right door rear mirror (WCP)	Broken	295.00 F	*295.00 F
42	2		*LH Front door rear square mirror (WCP)	Missing	180.00 F	*180.00 F
43	1		*LH Front door rear mirror round mirror (WCP)	Missing	60.00 F	*60.00 F
44	1		*RH outer mirror round garnish cover (WCP)	Missing	60.00 F	*60.00 F
45	1		*LH outer mirror round garnish cover (WCP)	Missing	60.00 F	*60.00 F
46	1		*RH Front door window regulator (WCP)	Bent	700.00 F	*700.00 F
47	1		*LH Front door window regulator (WCP)	Bent	700.00 F	*700.00 F
48	1		*RH Front door bottom garnish (WCP)	Cracked	90.00 F	*90.00 F
49	1		*LH Front door bottom garnish (WCP)	Cracked	90.00 F	*90.00 F
50	1		*RH Front door outer handle (WCP)	Serviceable	110.00 F	*- F
51	1		*LH Front door outer handle (WCP)	Missing	110.00 F	*110.00 F
52	1		*Front right door lock (WCP)	Jammed	480.00 F	*480.00 F
53	1		*RH Front door window inner switch (WCP)	Serviceable	480.00 F	*- F
54	1		*LH Front door window inner switch (WCP)	Cracked	480.00 F	*480.00 F
55	1		*RH Front door glass channel (WCP)	Distorted	220.00 F	*220.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*LH Front door glass channel (WCP)	Distorted	220.00 F	*220.00 F
57	1		*RH Front door outer surround garnish (WCP)	Cracked	65.00 F	*65.00 F
58	1		*LH Front door outer surround garnish (WCP)	Cracked	65.00 F	*65.00 F
59	1		*Front large panel (WCP)	Bent	1,050.00 F	*1,050.00 F
60	1		*Front wiper garnish (WCP)	Bent	350.00 F	*350.00 F
61	1		*RH wiper arm (WCP)	Dented	130.00 F	*130.00 F
62	1		*LH wiper arm (WCP)	Dented	130.00 F	*130.00 F
63	2		*Front wiper nozzle (WCP)	Missing	240.00 F	*240.00 F
64	1		*Front wiper link rod (WCP)	Bent	480.00 F	*480.00 F
65	1		*Front windscreen glass wiper motor (WCP)	Serviceable	490.00 F	*- F
66	1		*Front wiper water tank (WCP)	Serviceable	280.00 F	*- F
67	1		*Front wiper water tank motor (WCP)	Serviceable	190.00 F	*- F
68	1		*Front bumper (WCP)	Bent	680.00 F	*680.00 F
69	1		*RH Front bumper bracket (WCP)	Bent	240.00 F	*240.00 F
70	1		*LH Front bumper bracket (WCP)	Bent	240.00 F	*240.00 F
71	1		*RH front bumper side rubber (WCP)	Missing	240.00 F	*240.00 F
72	1		*LH front bumper side rubber (WCP)	Buckled	240.00 F	*240.00 F
73	1		*RH headlamp (WCP)	Broken	465.00 F	*465.00 F
74	1		*LH headlamp (WCP)	MTG Cracked	465.00 F	*465.00 F
75	1		*RH headlamp bottom rubber (WCP)	Missing	45.00 F	*45.00 F
76	1		*LH headlamp bottom rubber (WCP)	Missing	45.00 F	*45.00 F
77	1		*Front grille (WCP)	Missing	680.00 F	*680.00 F
78	1		*Front grille clips (1 set) (WCP)	Necessary	35.00 F	*35.00 F
79	1		*Front large panel FUSO emblem (WCP)	Missing	35.00 F	*35.00 F
80	1		*RH Front corner panel (WCP)	Bent	360.00 F	*360.00 F
81	1		*LH Front corner panel (WCP)	Bent	360.00 F	*360.00 F
82	1		*RH Front side lamp (WCP)	Broken	190.00 F	*190.00 F
83	1		*LH Front side lamp (WCP)	Broken	190.00 F	*190.00 F
84	1		*RH signal lamp (WCP)	Broken	220.00 F	*220.00 F
85	1		*LH signal lamp (WCP)	Broken	220.00 F	*220.00 F
86	1		*Front dashboard (WCP)	Buckled / Cracked	1,900.00 F	*1,900.00 F
87	1		*Front dashboard bottom garnish (WCP)	Cracked	1,150.00 F	*1,150.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
88	1		*Front dashboard left grove cover (WCP)	Cracked	120.00 F	*120.00 F
89	1		*Front dashboard left grove box (WCP)	Missing	380.00 F	*380.00 F
90	1		*Front dashboard inner reinforcement bar (WCP)	Bent	380.00 F	*380.00 F
91	1		*Front dashboard instrument panel (WCP)	Bent	1,650.00 F	*1,650.00 F
92	1		*Front dashboard central ECU (WCP)	Serviceable	1,800.00 F	*- F
93	1		*Rear view mirror (WCP)	Missing	120.00 F	*120.00 F
94	1		*Roof lining (WCP)	Deformed	950.00 F	*950.00 F
95	1		*Front oil cooler (WCP)	Serviceable	1,650.00 F	*- F
96	1		*Radiator (WCP)	Serviceable	2,850.00 F	*- F
97	1		*Engine fan clutch (WCP)	Serviceable	880.00 F	*- F
98	1		*Engine fan blade (WCP)	Serviceable	360.00 F	*- F
99	1		*Engine fan cowling rubber (WCP)	Serviceable	75.00 F	*- F
100	1		*Air con condenser (WCP)	Serviceable	780.00 F	*- F
101	1		*Air con condenser pipe inlet (WCP)	Serviceable	325.00 F	*- F
102	1		*Air con condenser pipe outlet (WCP)	Serviceable	280.00 F	*- F
103	2		*Air con pressure pipe (WCP)	Serviceable	490.00 F	*- F
104	1		*Air con cooling coil (WCP)	Cracked	480.00 F	*480.00 F
105	1		*Air con blower box (WCP)	Cracked	2,850.00 F	*2,850.00 F
106	1		*Air con blower motor (WCP)	Serviceable	1,950.00 F	*- F
107	2		*Engine mounting (WCP)	Serviceable	580.00 F	*- F
108	2		*Gear box mounting (WCP)	Serviceable	180.00 F	*- F
109	1		*Fuse box (WCP)	Cracked	850.00 F	*850.00 F
110	1		*Front steering box (WCP)	Repair	1,350.00 F	*- F
111	1		*Front steering shaft (WCP)	Bent	1,320.00 F	*1,320.00 F
112	1		*Front steering coupling (WCP)	Bent	750.00 F	*750.00 F
113	1		*RH Front seat belt garnish (WCP)	Serviceable	600.00 F	*- F
114	1		*LH Front seat belt garnish (WCP)	Deformed	600.00 F	*600.00 F
115	1		*Front cabin hinge (1 set) (WCP)	Bent	800.00 F	*800.00 F
116	1		*Brake master pump (WCP)	Serviceable	1,800.00 F	*- F
117	1		*Brake booster (WCP)	Serviceable	1,700.00 F	*- F
118	1		*Fronr brake pipes (1 set) (WCP)	Dented	450.00 F	*450.00 F
119	1		*Rear windscreen glass (WCP)	Cracked	420.00 F	*420.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
120	1		*Rear windscreen glass rubber (WCP)	Necessary	190.00 F	*190.00 F
121	1		*Brake pedal (WCP)	Repair	490.00 F	*- F
122	1		*Accelerator pedal (WCP)	Repair	380.00 F	*- F

F=Franchise part.

Sub Total (S\$)	60,877.00	40,627.00
+ Margin on L,N Items 5.00/5.00% (S\$)	3,043.85	2,031.35
Total Parts (S\$)	63,920.85	42,658.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	Engine coolant (NECESSARY)	40.00	40.00
2	1	Front door lettering (RH & LH) (NECESSARY)	40.00	40.00
3	1	Front number plate (DENTED)	35.00	25.00
4	1	Front windscreen inner seal (NOT NECESSARY)	28.00	0.00
5	1	Front windscreen sealant (NOT NECESSARY)	60.00	0.00
6	1	IU bracket (NECESSARY)	26.00	26.00
Sub Total (\$\$)			229.00	131.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To spray paint affected front and inner damaged portion inclusive of preparatory works and material	New	1,800.00	1,500.00
2	To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp	New	420.00	350.00
3	To lift up front cabin, remove interior seats and check front chassis frame	New	480.00	400.00
4	To remove and replace dashboard, instrument panels, and dashboard inner components	New	480.00	320.00
5	To remove radiator, engine fan, clutch, hoses and replace damaged parts and check engine cooling system functionality	New	380.00	280.00
6	To remove and check air con condenser, dryer, aluminium pipes, valves and reinstall components and vacuum and charge refrigerant R134a and check for leakage and full functionality	New	280.00	150.00
7	To install front windscreen glass	New	150.00	80.00
8	To install rear windscreen glass	New	80.00	50.00
9	To remove and install front brake booster, master pump, steering column, steering shaft and brake pipes	New	450.00	250.00
10	To remove and check engine, gearbox, radiator, engine & gearbox mountings, intake and exhaust manifold & for damage and reinstall components and check engine running functionality	New	380.00	280.00
11	To hire crane, for lifting and installing of cabin	New	800.00	500.00
12	To remove front cabin, , to reweld, reshape and repair cabin damaged panels, cabin bracket, to jack out front chassis, to straighten out front body and chassis alignment and adjust body panel alignment	New	2,800.00	2,400.00
13	To perform computer diagnostic on drivetrain, ABS systems and clear fault codes	New	180.00	120.00
Gross Labour Cost (\$\$)			8,680.00	6,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >