



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

INSURER: EQ Insurance Company Ltd (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMPPHQ17-002776	Date of Loss:	25/11/2017
Vehicle Reg. No.:	SKT5302K	Driveable?	
Driver Age/Info:	40 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	ONG KAY CHONG	Contact No:	+6597511635
Driver:	TAN MAY YEN		
Make/Model:	TOYOTA ESTIMA, 2.4 AERAS (A)	Vehicle Reg. Date:	12/06/2015
Vehicle Colour:	WHITE	Chassis No:	ACR500183494
Engine No:	2AZJ105898		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	26 days		
Description of Accident/Loss	PLEASE REFER TO SKETCH PLAN.		
Remarks:	VEHICLE IS IN, KINDLY ARRANGE FOR SURVEY. THANK YOU.		
Present Location:	K KIM HIN AUTO PTE LTD (HQ)		

1. B. 1
Not with paint
Repair B & paint



COST OF CLAIMS

	Amount
Parts	10,754.95
Miscellaneous Items	0.00
Labour	1,950.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	12,704.95
+ GST 7.00% (S\$)	889.35
Nett Amount (S\$)	13,594.30

This claim is handled by: SHUMAN

13141.75

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version:	1.0 (Last Synchronised: 28 Nov 2017)
Parts:	M1-MPV	TOYOTA ESTIMA 2.4 AERAS (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SKT5302K)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.		

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BUMPER	CM	0.00	0.00	*220.00 F ✓
2	2		*FRONT BUMPER SIDE RETAINER (LH/RH)	DIY	0.00	0.00	*70.00 F ✓
3	1210		*FRONT BUMPER CLIPS	CM	0.00	0.00	*48.00 F ✓
4	1		*FRONT BUMPER CENTRE LOWER GRILLE	CM	0.00	0.00	*135.00 F ✓
5	1		*FRONT BUMPER CENTRE LOWER GRILLE CHROME	CM	0.00	0.00	*80.00 F ✓
6	2		*FRONT BUMPER TOWING COVER (LH/RH)	DIY DIY	0.00	0.00	*32.00 F ✓
7	1		*FRONT BUMPER SPONGE	CM	0.00	0.00	*45.00 F ✓
8	1		*FRONT BUMPER REINFORCEMENT	CM	0.00	0.00	*165.00 F ✓
9	2		*FRONT BUMPER REINFORCEMENT BRACKET (LH/RH)	CM	0.00	0.00	*250.00 F ✓
10	2		*FRONT BUMPER VERTICAL MOULDING (LH/RH)	CM	0.00	0.00	*36.00 F ✓
11	2		*FRONT BUMPER FOGLAMP (LH/RH)	CM	0.00	0.00	*250.00 F ✓
12	2		*FRONT BUMPER FOGLAMP COVER AND CHROME RIM (LH/RH)	CM	0.00	0.00	*140.00 F ✓
13	1		*FRONT GRILLE AND TOP RUBBER SEAL	CM	0.00	0.00	*165.00 F ✓
14	1		*FRONT GRILLE LOGO	CM	0.00	0.00	*35.00 F X
15	1		*FRONT GRILLE OUTER GARNISH-LOWER	CM	0.00	0.00	*50.00 F ✓
16	8		*FRONT GRILLE CLIPS	CM	0.00	0.00	*12.00 F ✓
17	2		*HEADLAMP ASSY (LH/RH)-HID	CM	0.00	0.00	*280.00 F ✓
18	1		*N/S HEADLAMP HID BULB	CM	0.00	0.00	*210.00 F X
19	1		*N/S HEADLAMP BALLAST CONTROL UNIT	CM	0.00	0.00	*270.00 F X
20	2		*HEADLAMP PANEL (LH/RH)	CM	0.00	0.00	*270.00 F ✓
21	1		*FRONT BRACE PANEL	CM	0.00	0.00	*95.00 F ✓
22	1		*FRONT SUPPORT PANEL	CM	0.00	0.00	*135.00 F ✓
23	1		*FRONT SUPPORT PANEL LOWER IMPACT DAMPER	CM	0.00	0.00	*140.00 F X
24	2		*HORN (HIGH/LOWER)	CM	0.00	0.00	*130.00 F ✓
25	1		*FRONT SUPPORT PANEL TOP GARNISH	CM	0.00	0.00	*115.00 F ✓
26	8		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	CM	0.00	0.00	*12.00 F ✓
27	1		*AIR INTAKE DUCT	CM	0.00	0.00	*60.00 F ✓
28	1		*AIR INTAKE HOSE	CM	0.00	0.00	*50.00 F ✓
29	1		*AIR RESONATOR	CM	0.00	0.00	*65.00 F ✓
30	1		*AIR CLEANER BOX ASSY	CM	0.00	0.00	*295.00 F ✓
31	1		*WIPER WASHER TANK	CM	0.00	0.00	*65.00 F X
32	1		*WIPER WASHER TANK NECK	CM	0.00	0.00	*35.00 F X
33	2		*WIPER WASHER TANK MOTOR	CM	0.00	0.00	*170.00 F X
34	1		*BONNET	CM	0.00	0.00	*180.00 F ✓
35	1		*BONNET LOCK	CM	0.00	0.00	*55.00 F ✓
36	1		*BONNET PULL LOCK CABLE	CM	0.00	0.00	*45.00 F X
37	2		*BONNET HINGES (LH/RH)	CM	0.00	0.00	*70.00 F ✓
38	1		*BONNET INSULATION	CM	0.00	0.00	*110.00 F ✓
39	5		*BONNET INSULATION CLIPS	CM	0.00	0.00	*7.50 F ✓
40	1		*BONNET STAND CLIP HOLDER	CM	0.00	0.00	*6.50 F X
41	1		*AIRCON CONDENSER	CM	0.00	0.00	*250.00 F ✓
42	1		*AIRCON LIQUID PIPE	CM	0.00	0.00	*340.00 F X
43	1		*AIRCON DISCHARGE PIPE	CM	0.00	0.00	*185.00 F X
44	1		*AIRCON SUCTION PIPE	CM	0.00	0.00	*285.00 F X
45	1		*AIRCON FAN MOTOR	CM	0.00	0.00	*185.00 F ✓

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
46	1		*AIRCON FAN BLADE	0.00	0.00	80.00 F 2
47	2		*AIRCON LOWER BUSH	0.00	0.00	36.00 F X
48	1		*RADIATOR	0.00	0.00	590.00 F 2
49	1		*RADIATOR TOP GARNISH	0.00	0.00	65.00 F ✓
50	2		*RADIATOR AIR GUIDE (LH/RH)	0.00	0.00	70.00 F 2
51	1		*RADIATOR TOP HOSE	0.00	0.00	38.00 F 2
52	1		*RADIATOR LOWER HOSE	0.00	0.00	38.00 F 2
53	1		*RADIATOR SPARE TANK	0.00	0.00	130.00 F X
54	1		*RADIATOR SPARE TANK BYPASS PIPE	0.00	0.00	125.00 F X
55	1		*RADIATOR SPARE TANK BYPASS PIPE HOSE	0.00	0.00	45.00 F X
56	2		*RADIATOR TOP MOUNTING BRACKET (LH/RH)	0.00	0.00	70.00 F 2
57	2		*RADIATOR TOP MOUNTING BRACKET BUSH (LH/RH)	0.00	0.00	26.00 F X
58	2		*RADIATOR LOWER MOUNTING BUSH	0.00	0.00	36.00 F X
59	1		*RADIATOR FAN COWLING	0.00	0.00	165.00 F 2
60	1		*RADIATOR FAN BLADE	0.00	0.00	85.00 F 2
61	1		*RADIATOR FAN MOTOR	0.00	0.00	185.00 F 2
62	1		*BATTERY TRAY	0.00	0.00	35.00 F 2
63	1		*BATTERY COVER	0.00	0.00	95.00 F X
64	1		*FRONT EXHAUST HEAT SHIELD-TOP	0.00	0.00	100.00 F 2
65	1		*FRONT EXHAUST HEAT SHIELD-LOWER	0.00	0.00	50.00 F 2
66	2		*FRONT WIPER PANEL SIDE GARNISH (LH/RH)	0.00	0.00	70.00 F X
67	1		*FRONT NUMBER PLATE	0.00	0.00	40.00 FS ✓
68	1		*FRONT BUMPER PARKING SENSOR (1SET)	0.00	0.00	220.00 FS 2
69	1		*N/S HEADLAMP LIGHT BULB	0.00	0.00	12.00 FS X
70	1		*N/S HEADLAMP SIGNAL BULB	0.00	0.00	12.00 FS X
71	1		*N/S HEADLAMP HIGH BEAM BULB	0.00	0.00	18.00 FS X
72	1		*BATTERY	0.00	0.00	180.00 FS X

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	9,415.00
+ Margin on L,N Items 15.00% (\$\$)	1,339.95
Total Parts (\$\$)	10,754.95

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS.	New	700 800.00
2	TO REMOVE AIRCON CONDENSER, PIPES AND DRIERS. VACUUM AND RECHARGE GAS.	New	100.00
3	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	900 1,000.00
4	TO FOCUS HEADLAMPS. TO CHECK WIRING AND LIGHTING OPERATION.	New	20 50.00
Gross Labour Cost (S\$)			1,950.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Supplementary

1pc Ent Super Reinforced Dumper. Pn - 380

$\$ 6372.50 - \text{Pnt}$
 $\$ 380.00 + 8\%$
 $\$ 6752.50 + 1.5\% = 7765.37$
 $\$ 260.00 - \text{sh}$
 $\$ 1720.00 - \text{ben}$
 $\$ 9745.37$

REPAIR DETAILS**Reference**

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 11 Jan 2018)
Parts: M1-MPV **TOYOTA ESTIMA 2.4 AERAS (A)** (Catalogue: Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKT5302K)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER REINFORCEMENT DAMPER	R ₁	0.00	0.00
						*380.00 F ✓
			Sub Total (S\$)			380.00
			+ Margin on L,N Items 15.00% (S\$)			57.00
			Total Parts (S\$)			437.00

Report was unsubmitted during this print-out.
 Generated using **Merimen e-Claims IEAS**



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

M/S: K.KIM HEN AUTO PTE LTD

160 SIN MING DRIVE

#02-18/19/20/21 SIN MING AUTOCITY

SINGAPORE 575722

SKT5302K

MENG HUAT

TAX INVOICE

NO: DLI9196644

PAGE: 1

DATE: 01/12/2017

A/C CODE: LDKK241

TERMS: CR

Part No	Description	Location	Qty	Unit Price	Amount
1	T52119-2J940	BUMPER FR	1	SIN	SIN
2	T52115-28170	BUMPER RETAINER FR RH	1	220.00	220.00
3	T52116-28170	BUMPER RETAINER FR LH	1	35.00	35.00
4	T52161-0K040	CLIP	1	35.00	35.00
5	T53112-28210	FR LWR GRILLE 2012	10	1.50	15.00
6	T52711-28150	BUMPER MLG FR	1	135.00	135.00
7	T52127-28430-C0	TOW COVER FR RH/H	1	80.00	80.00
8	T52611-28081	BUMPER SPONGE FR	1	16.00	16.00
9	T52021-28230	BUMPER REINF FR	1	45.00	45.00
10	T57031-12010	REINFORCEMENT SUB-ASSY,FR RH	1	165.00	165.00
11	T57032-12010	REINFORCEMENT SUB-ASSY,FR LH	1	125.00	125.00
12	T52128-28430-C0	TOW COVER FR LH	1	125.00	125.00
13	T52128-28440	FR BUMPER HOLE LH	1	16.00	16.00
14	T81220-12230	FOGLAMP ASSY LH	1	18.00	18.00
15	T52040-28010	FR BUMPER CVR LH	1	125.00	125.00
16	T53101-28381-A0	GRILLE	1	70.00	70.00
17	T53152-28030	GUIDE GRILLE	1	165.00	165.00
18	T52161-0K040	CLIP,GRILLE	1	50.00	50.00
19	T81145-28F40	HEADLAMP UNIT	8	1.50	12.00
20	T81185-28F40	HEADLAMP UNIT LH AERAS	1	640.00	640.00
21	T53202-28140	H/LAMP PANEL RH	1	640.00	640.00
			1	135.00	135.00

Print / MT / 02/12/2017 9:20:13 AM





合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE


M/S: K.KIM HIN AUTO PTE LTD

NO: DLI9196644

PAGE: 2

Part No	Description	Location	Qty	Unit Price	Amount
				<u>SIN</u>	<u>SIN</u>
22	T53203-28140	H/LAMP PANEL LH	DDS	1 135.00 ✓	135.00
23	T53209-28060	BRACE PANEL	DDS	1 95.00 ✓	95.00
24	T53205-28170	TOP PANEL	DBAA18S	1 135.00 ✓	135.00
25	T53028-28050	RAD MEMBER	DUIU4	1 115.00 ✓	115.00
26	T86510-30700	HORN RH (HIGH)	DD1S11T12	1 65.00 ✓	65.00
27	T86520-30610	HORN LH (LOW) -LEX	DD1S11T12	1 65.00 ✓	65.00
28	T53292-28070	SEAL RADIATOR	DSHOP	1 115.00 ✓	115.00
29	T55346-47010	CLIP	DD1A129	8 1.50 ✓	12.00
30	T17751-28070	INLET AIR CLEANER	DU1G23-1	1 60.00 ✓	60.00
31	T17752-28010	INLET AIR CLEANER NO#2	DU1G23-1	1 50.00 ✓	50.00
32	T17896-28010	RESONATOR	DU1AB2-3	1 65.00 ✓	65.00
33	T17700-28311	AIR CLEANER	DB2K8	1 295.00 ✓	295.00
34	T53301-28110	BONNET	DB1B45	1 180.00 ✓	180.00
35	T53510-28090	BONNET LOCK	DU1B77	1 55.00 ✓	55.00
36	T53410-28060	BONNET HINGE RH	DU1AD18-1	1 35.00 ✓	35.00
37	T53420-28060	BONNET HINGE LH	DU1AD21-1	1 35.00 ✓	35.00
38	T88460-42100-K	AIR CONDENCER	DB2C	1 250.00 ✓	250.00
39	T16363-28370	FAN MOTOR -	DUIQ8	1 185.00 ✓	185.00
40	T16361-28380	FAN BLADE	DU1AB18-4	1 80.00 ✓	80.00
41	T16400-28560	RADIATOR	DB1A32	1 590.00 ✓	590.00
42	T16712-28061	FAN SHROUD	DU1AB33-2	1 65.00 ✓	65.00
43	T52545-28050	SEAL RH	DDS	1 35.00 ✓	35.00
44	T52546-28050	SEAL LH	DU1AB22-3	1 35.00 ✓	35.00
45	T16571-28260	RAD.TOP HOSE	DDS	1 38.00 ✓	38.00
46	T16572-28220	RAD.LWR HOSE	DD2E19-5	1 38.00 ✓	38.00
47	T16533-28041	RAD TOP MTG	DU1B109	2 35.00 ✓	70.00
48	T74431-42090	BATTERY TRAY	DU1H18-8	1 35.00 ✓	35.00
49	T28899-28070	BATTERY COVER	DSHOP	1 95.00 ✓	95.00

Print / MT / 02/12/2017 9:20:15 AM





合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

M/S: K.KIM HIN AUTO PTE LTD

TAX INVOICE

NO: DLI9196644


PAGE: 3

Part No	Description	Location	Qty	Unit Price	Amount
50 T17167-28060	COVER-EX.MANIFOLD - 0H060	DU1E21-1	1	SIN 100.00	SIN 100.00
51 T25586-28090	INS/MANIFOLD COVER	DU1E18	1	50.00	50.00
52 T90467-09050	CLIP,INSULATOR	DD1AS3-6	5	1.50	7.50

TOTAL QUANTITY:

80 TOTAL SIN 6,052.50
ADD GST @ 7% 423.68
GRAND TOTAL SIN 6,476.18

02-21



Print / MT / 02/12/2017 9:20:15 AM


SALESMAN: MT

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

GOODS RECEIVED BY

E.&O.E.



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

US: K.KIM HIN AUTO PTE LTD

160 SIN MING DRIVE

#02-18/19/20/21 SIN MING AUTOCITY

SINGAPORE 575722

SKT5302K

MENG HUAT

NO: DLI9196672

PAGE: 1

DATE: 04/12/2017

A/C CODE: LDKK241

TERMS: CR

Part No	Description	Location	Qty	Unit Price	Amount
				<u>SIN</u>	<u>SIN</u>
T16711-28430	FAN SHROUD	DBAA1S	1	165.00	165.00
T16363-28300	FAN MOTOR	DUIQ27	1	185.00	185.00
T16361-28370	FAN BLADE	DUIAB18-4	1	85.00	85.00
TOTAL QUANTITY:			3	TOTAL	SIN 435.00
				ADD GST @ 7%	30.45
				GRAND TOTAL	<u>SIN 465.45</u>

#02-21

Print / MT / 04/12/2017 9:12:50 AM

SALESMAN: MT

This document is computer generated. No signature required

GOODS SOLD ARE NOT RETURNABLE

GOODS RECEIVED BY

E. & O. E.



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9939

Dept Direct: 6305 9610

Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6306 9611

Dept Direct: 6417 9756

Dept Direct: 6417 9762

Dept Direct: 6417 9762

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

K KIM HIN AUTO PTE LTD
160 SIN MING DRIVE #02-18/19/20/21
SIN MING AUTOCITY

SINGAPORE 575722
TEL : 64527018 MENG FAX : 64583895
ATTN : WENG 97178210

skt 53024-

TAX INVOICE : AR201712-02453
DATE : 05/12/2017
CUSTOMER ID : KK1001
VEH REG. NO. : SK18302K
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SQ STOCKID

1. T48691-28020
ACR50

DESCRIPTION

FRT BUMPER REINF DAMPER

Stk Loc

PA
PL2-J1-10D

QTY

1

UPRICE

380.00

AMOUNT

380.00

SUB-TOTAL : 380.00
ADD GST 7.00 % 26.60

E & OE

TOTAL AMOUNT SGD : 406.60

[P] 05/12/2017 2:26:50PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 05/12/2017 2:25:51PM

JAE Auto Pte. Ltd.

Sales Executive : LAI

This is computer generated document.

No signature is required.



* AR201712-02453 *

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Nov 2017 14:49	28 Nov 2017 16:10	29 Nov 2017 09:52	S\$9,745.38	S\$9,745.38		Pending for Survey Report
	Sendback Est	S\$12,704.95	Edit Adj Rpt	Edit Estimates	View Rpt		Cancel Case
Supp #1	11 Jan 2018 17:39	11 Jan 2018 17:39	11 Jan 2018 17:39			Combine Suppl.	Pending for Survey Report
	Sendback Est	S\$437.00	Edit Adj Rpt				Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	ONG KAY CHONG , ID: S6879345I, Tel: +6597511635, Email: KCONG7@GMAIL.COM		
Vehicle Reg. No.:	SKT5302K	Date of Loss:	25/11/2017 10:00 - :59 [29 Months and 13 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD	Policy/Cover Note No.:	DMPPHQ17-002776 (Comprehensive) Coverage: 12/06/2017 - 11/06/2018
		Excess:	S\$0.00
Repairer:	K Kim Hin Auto Pte Ltd (HQ) 160 Sin Ming Drive #02-20, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64527018		
Handling Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433 ... [Handled by Bazlin Ahmad]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 08/12/2017]		
Driver/Custodian:	TAN MAY YEN (40 / Female), NRIC: S7772495H, Tel: +6598303185		
Adj Asg. Remarks:	UN-NAMED DRIVER EXCESS \$1,500 WAIVED. VIDEO FOOTAGE ATTACHED TO GIA		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- EQI_HQ (30/11/2017): Alert - Adj Mandate Approved (S\$11804.48) - SKT5302K - Claim Handler: Bazlin Ahm...

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SKT5302K
OD
Nov 25 2017 10:00AM
[ONG KAY CHONG]
K Kim Hin Auto Pte Ltd

[Upload Documents](#) [Upload Photos](#) [Compose New Letter](#)

View [View in Browser](#) ▼

Video			1 per page ▼	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	27/11/17 18:10	Video - Accident [Linked Accident Report Documents]	Load AVI	
2	27/11/17 18:10	Video - Accident [Linked Accident Report Documents]	Load AVI	

Assessment Reports			1 per page ▼	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	28/11/17 16:10	Repairer Estimates	Load HTM	
2	11/01/18 17:39	Repairer Estimates Suppl. #1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/11/17 14:52	Adjuster Immediate Advice	Load HTM	

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/11/17 14:53	General View	Load JPG	☒
2	30/11/17 14:53	General View	Load JPG	☒
3	30/11/17 14:53	General View	Load JPG	☒
4	30/11/17 14:53	General View	Load JPG	☒
5	30/11/17 14:53	General View	Load JPG	☒
6	30/11/17 14:53	General View	Load JPG	☒
7	30/11/17 14:53	General View	Load JPG	☒
8	30/11/17 14:53	General View	Load JPG	☒
9	30/11/17 14:53	General View	Load JPG	☒
10	30/11/17 14:53	General View	Load JPG	☒
11	30/11/17 14:53	General View	Load JPG	☒
12	30/11/17 14:53	General View	Load JPG	☒
13	30/11/17 14:53	General View	Load JPG	☒
14	30/11/17 14:53	General View	Load JPG	☒
15	30/11/17 14:53	General View	Load JPG	☒
16	30/11/17 14:53	General View	Load JPG	☒
17	30/11/17 14:53	General View	Load JPG	☒
18	30/11/17 14:53	General View	Load JPG	☒
19	30/11/17 14:53	General View	Load JPG	☒
20	30/11/17 14:53	General View	Load JPG	☒
21	30/11/17 14:53	General View	Load JPG	☒
22	30/11/17 14:53	General View	Load JPG	☒
23	30/11/17 14:53	General View	Load JPG	☒
24	30/11/17 14:53	Odometer Reading	Load JPG	☒
25	30/11/17 14:53	Chassis Number	Load JPG	☒
26	30/11/17 14:53	General View	Load JPG	☒

Video			1 per page	
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
27	30/11/17 14:53	General View		Load JPG
28	12/09/18 17:23	Reinspection Photo		Load JPG
29	12/09/18 17:23	Reinspection Photo		Load JPG
30	12/09/18 17:23	Reinspection Photo		Load JPG
31	12/09/18 17:23	Reinspection Photo		Load JPG
32	12/09/18 17:23	Reinspection Photo		Load JPG
33	12/09/18 17:23	Reinspection Photo		Load JPG
34	12/09/18 17:23	Reinspection Photo		Load JPG
35	12/09/18 17:23	Reinspection Photo		Load JPG
36	12/09/18 17:23	Reinspection Photo		Load JPG
37	12/09/18 17:23	Reinspection Photo		Load JPG
38	12/09/18 17:23	Reinspection Photo		Load JPG
39	12/09/18 17:23	Reinspection Photo		Load JPG
40	12/09/18 17:23	Reinspection Photo		Load JPG
41	12/09/18 17:23	Reinspection Photo		Load JPG
42	12/09/18 17:23	Reinspection Photo		Load JPG
43	12/09/18 17:23	Reinspection Photo		Load JPG
44	12/09/18 17:23	Reinspection Photo		Load JPG
45	12/09/18 17:23	Reinspection Photo		Load JPG
46	12/09/18 17:23	Reinspection Photo		Load JPG
47	12/09/18 17:23	Reinspection Photo		Load JPG
48	12/09/18 17:23	Reinspection Photo		Load JPG
49	12/09/18 17:23	Reinspection Photo		Load JPG
50	12/09/18 17:23	Reinspection Photo		Load JPG
51	12/09/18 17:23	Reinspection Photo		Load JPG
52	12/09/18 17:23	Reinspection Photo		Load JPG
53	12/09/18 17:23	Reinspection Photo		Load JPG
54	12/09/18 17:26	Reinspection Photo		Load JPG
55	12/09/18 17:26	Reinspection Photo		Load JPG
Documentation			1 per page	
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	28/11/17 15:50	Certificate of Insurance		Load PDF
2	28/11/17 15:50	Log card (if available)		Load PDF
3	28/11/17 15:50	Driver's NRIC		Load PDF
4	28/11/17 15:50	Insured's NRIC		Load PDF
5	28/11/17 15:50	transfer fee		Load PDF
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/09/18 09:59	PARTS INVOICE		Load PDF
2	14/09/18 09:59	SUPPLEMENTARY		Load PDF

Linked Accident Report Documents

Video			1 per page	
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	27/11/17 18:10	Video - Accident		Load AVI
2	27/11/17 18:10	Video - Accident		Load AVI
Assessment Reports			1 per page	
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print

Video				1 per page ▼	✓
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)		Thumbnail	Print
1	27/11/17 18:15	Accident Statement	1	Load HTM	
Photos/Images				3 per page ▼	✓
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)		Thumbnail	Print
1	27/11/17 18:11	Accident Photo	1	Load JPG	✓
2	27/11/17 18:11	Accident Photo	1	Load JPG	✓
3	27/11/17 18:11	Accident Photo	1	Load JPG	✓
4	27/11/17 18:11	Accident Photo	1	Load JPG	✓
5	27/11/17 18:11	Accident Photo	1	Load JPG	✓
6	27/11/17 18:11	Accident Photo	1	Load JPG	✓
7	27/11/17 18:12	Accident Photo	1	Load JPG	✓
8	27/11/17 18:12	Accident Photo	1	Load JPG	✓
9	27/11/17 18:12	Accident Photo	1	Load JPG	✓
10	27/11/17 18:12	Accident Photo	1	Load JPG	✓
11	27/11/17 18:12	Accident Photo	1	Load JPG	✓
Documentation				1 per page ▼	✓
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)		Thumbnail	Print
1	27/11/17 18:10	Sketch Plan	1	Load TIF	
2	27/11/17 18:10	Sketch Plan #2	1	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

EQ Insurance Company Ltd
5 Maxwell Road, #17-00 Tower Block, MND Complex
Singapore 069110

Our File No: CS/EQ17022691/KQBS2

Date: 14/09/2018

REFERENCE

Insured/Claimant:	ONG KAY CHONG	Policy No:	DMPPHQ17-002776	Claim No:	N/A
Date of Loss:	25/11/2017	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT5302K	Engine No:	2AZJ105898
Make & Model:	TOYOTA ESTIMA, 2.4 AERAS (A)	Chassis No:	ACR500183494
Reg. Date:	12/06/2015 (Man. Year: 2014)	Odometer:	67613 km
Colour:	Metallic Pearl White		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	S\$123,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/50 ZR18	Rear Tyre Size:	225/50 ZR18
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 3 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,754.95	8,025.38	2,729.57	25.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,950.00	1,720.00	230.00	11.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,704.95	9,745.38	2,959.57	23.29
+ GST 7.00/7.00% (S\$)	889.35	682.18	207.17	23.29
Nett Amount (S\$)	13,594.30	10,427.56	3,166.74	23.29

INSPECTION

Date of Assignment:	29/11/2017		
Date Inspected:	29/11/2017	Inspected At:	K Kim Hin Auto Pte Ltd (HQ) 160 Sin Ming Drive #02-20, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	6.0 days		

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Sep 2018)

Parts: M1-MPV TOYOTA ESTIMA 2.4 AERAS (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKT5302K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Cracked	220.00 F	*220.00 F
2	2		*FRONT BUMPER SIDE RETAINER (LH/RH) (WCP)	Distorted	70.00 F	*70.00 F
3	12		*FRONT BUMPER CLIPS (WCP)	Necessary 10pcs Only	18.00 F	*15.00 F
4	1		*FRONT BUMPER CENTRE LOWER GRILLE (WCP)	Cracked	135.00 F	*135.00 F
5	1		*FRONT BUMPER CENTRE LOWER GRILLE CHROME (WCP)	Cracked	80.00 F	*80.00 F
6	2		*FRONT BUMPER TOWING COVER (LH/RH) (WCP)	Dented / Distorted	32.00 F	*32.00 F
7	1		*FRONT BUMPER SPONGE (WCP)	Cracked	45.00 F	*45.00 F
8	1		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	165.00 F	*165.00 F
9	2		*FRONT BUMPER REINFORCEMENT BRACKET (LH/RH) (WCP)	Bent	250.00 F	*250.00 F
10	1		*FRONT BUMPER VERTICAL MOULDING (LH/RH) (WCP)	N/s Distorted	36.00 F	*18.00 F
11	1		*FRONT BUMPER FOGLAMP (LH/RH) (WCP)	N/s Cracked	250.00 F	*125.00 F
12	1		*FRONT BUMPER FOGLAMP COVER AND CHROME RIM (LH/RH) (WCP)	N/s Distorted	140.00 F	*70.00 F
13	1		*FRONT GRILLE AND TOP RUBBER SEAL (WCP)	Cut	165.00 F	*165.00 F
14	1		*FRONT GRILLE LOGO (WCP)	Serviceable	35.00 F	*- F
15	1		*FRONT GRILLE OUTER GARNISH-LOWER (WCP)	Cracked	50.00 F	*50.00 F
16	8		*FRONT GRILLE CLIPS (WCP)	Necessary	12.00 F	*12.00 F
17	2		*HEADLAMP ASSY (LH/RH)-HID (WCP)	O/s Mtg Cracked / N/s Cracked	1,280.00 F	*1,280.00 F
18	1		*N/S HEADLAMP HID BULB (WCP)	Serviceable	210.00 F	*- F
19	1		*N/S HEADLAMP BALLAST CONTROL UNIT (WCP)	Repair	270.00 F	*- F
20	2		*HEADLAMP PANEL (LH/RH) (WCP)	Bent	270.00 F	*270.00 F
21	1		*FRONT BRACE PANEL (WCP)	Bent	95.00 F	*95.00 F
22	1		*FRONT SUPPORT PANEL (WCP)	Buckled	135.00 F	*135.00 F
23	1		*FRONT SUPPORT PANEL LOWER IMPACT DAMPER (WCP)	Serviceable	110.00 F	*- F
24	2		*HORN (HIGH/LOWER) (WCP)	Dented	130.00 F	*130.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
25	1		*FRONT SUPPORT PANEL TOP GARNISH (WCP)	Deformed	115.00 F	*115.00 F
26	8		*FRONT SUPPORT PANEL TOP GARNISH CLIPS (WCP)	Necessary	12.00 F	*12.00 F
27	1		*AIR INTAKE DUCT (WCP)	Dented	60.00 F	*60.00 F
28	1		*AIR INTAKE HOSE (WCP)	Dented	50.00 F	*50.00 F
29	1		*AIR RESONATOR (WCP)	Cracked	65.00 F	*65.00 F
30	1		*AIR CLEANER BOX ASSY (WCP)	Cracked	295.00 F	*295.00 F
31	1		*WIPER WASHER TANK (WCP)	Serviceable	65.00 F	*- F
32	1		*WIPER WASHER TANK NECK (WCP)	Serviceable	35.00 F	*- F
33	2		*WIPER WASHER TANK MOTOR (WCP)	Serviceable	170.00 F	*- F
34	1		*BONNET (WCP)	Buckled	180.00 F	*180.00 F
35	1		*BONNET LOCK (WCP)	Bent	55.00 F	*55.00 F
36	1		*BONNET PULL LOCK CABLE (WCP)	Serviceable	45.00 F	*- F
37	2		*BONNET HINGES (LH/RH) (WCP)	Distorted	70.00 F	*70.00 F
38	1		*BONNET INSULATION (WCP)	Serviceable	110.00 F	*- F
39	5		*BONNET INSULATION CLIPS (WCP)	Necessary	7.50 F	*7.50 F
40	1		*BONNET STAND CLIP HOLDER (WCP)	Serviceable	6.50 F	*- F
41	1		*AIRCON CONDENSER (WCP)	Bent	250.00 F	*250.00 F
42	1		*AIRCON LIQUID PIPE (WCP)	Serviceable	340.00 F	*- F
43	1		*AIRCON DISCHARGE PIPE (WCP)	Serviceable	185.00 F	*- F
44	1		*AIRCON SUCTION PIPE (WCP)	Serviceable	285.00 F	*- F
45	1		*AIRCON FAN MOTOR (WCP)	Jammed	185.00 F	*185.00 F
46	1		*AIRCON FAN BLADE (WCP)	Distorted	80.00 F	*80.00 F
47	2		*AIRCON LOWER BUSH (WCP)	Serviceable	36.00 F	*- F
48	1		*RADIATOR (WCP)	Punctured	590.00 F	*590.00 F
49	1		*RADIATOR TOP GARNISH (WCP)	Distorted	65.00 F	*65.00 F
50	2		*RADIATOR AIR GUIDE (LH/RH) (WCP)	Cracked	70.00 F	*70.00 F
51	1		*RADIATOR TOP HOSE (WCP)	Cut	38.00 F	*38.00 F
52	1		*RADIATOR LOWER HOSE (WCP)	Cut	38.00 F	*38.00 F
53	1		*RADIATOR SPARE TANK (WCP)	Serviceable	130.00 F	*- F
54	1		*RADIATOR SPARE TANK BYPASS PIPE (WCP)	Serviceable	125.00 F	*- F
55	1		*RADIATOR SPARE TANK BYPASS PIPE HOSE (WCP)	Serviceable	45.00 F	*- F
56	2		*RADIATOR TOP MOUNTING BRACKET (LH/RH) (WCP)	Distorted	70.00 F	*70.00 F
57	2		*RADIATOR TOP MOUNTING BRACKET BUSH (LH/RH) (WCP)	Serviceable	36.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
58	2		*RADIATOR LOWER MOUNTING BUSH (WCP)	Serviceable	36.00 F	*- F
59	1		*RADIATOR FAN COWLING (WCP)	Cracked	165.00 F	*165.00 F
60	1		*RADIATOR FAN BLADE (WCP)	Distorted	85.00 F	*85.00 F
61	1		*RADIATOR FAN MOTOR (WCP)	Jammed	185.00 F	*185.00 F
62	1		*BATTERY TRAY (WCP)	Cracked	35.00 F	*35.00 F
63	1		*BATTERY COVER (WCP)	Dented	95.00 F	*95.00 F
64	1		*FRONT EXHAUST HEAT SHIELD-TOP (WCP)	Dented	100.00 F	*100.00 F
65	1		*FRONT EXHAUST HEAT SHIELD-LOWER (WCP)	Dented	50.00 F	*50.00 F
66	2		*FRONT WIPER PANEL SIDE GARNISH (LH/RH) (WCP)	Serviceable	70.00 F	*- F
67	1		*FRONT NUMBER PLATE	Bent	40.00 FS	*40.00 FS
68	1		*FRONT BUMPER PARKING SENSOR (1SET)	Shorted	220.00 FS	*220.00 FS
69	1		*N/S HEADLAMP LIGHT BULB	Serviceable	12.00 FS	*- FS
70	1		*N/S HEADLAMP SIGNAL BULB	Serviceable	12.00 FS	*- FS
71	1		*N/S HEADLAMP HIGH BEAM BULB	Serviceable	18.00 FS	*- FS
72	1		*BATTERY	Serviceable	180.00 FS	*- FS
73	1		*FRONT BUMPER REINFORCEMENT DAMPER (WCP)	Bent	-	*380.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$) **9,415.00** **7,012.50**
+ Margin on L,N Items 15.00/15.00% (\$\$) 1,339.95 1,012.88

Total Parts (\$\$) 10,754.95 8,025.38

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS.	New	800.00	700.00
2	TO REMOVE AIRCON CONDENSER, PIPES AND DRIERS. VACUUM AND RECHARGE GAS.	New	100.00	100.00
3	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	1,000.00	900.00
4	TO FOCUS HEADLAMPS. TO CHECK WIRING AND LIGHTING OPERATION.	New	50.00	20.00
Gross Labour Cost (\$\$)			1,950.00	1,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >