COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO: SHD 4305D

DATE 28/11/2017 15:35

MAKE

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price		Amount]
	Boot Lid			\$	1,349.50	1
	Boot Lid Rubber 🗶			\$	110.90	
	Boot Lid Lock Upper /			\$	132.10	
	Boot Lid Lock Lower × M			\$	30.30	
	Boot Lid Sonata Plate			\$	43.60	
	Boot Lid Hyundai Plate			\$	24.20	
	Boot Lid 'H' Emblem /			\$	26.10	
	Boot Lid CRDI Plate			\$	22.70	
	Boot Lid Lamp (LH) ?			\$	230.20	
	Boot Lid Trimboard ?			\$	165.40	
	Boot Lid Trimboard Clips (10pcs) ?			\$	10.00	
	Rear Bumper /			\$	578.40	
	Rear Bumper Reinforcement /			\$	483.30	
	Rear Bumper Clip /			\$	22.00	
	Rear Bumper Sponge /			\$	137.40	
	Rear Bumper Under Cover			\$	185.80	
	Rear Bumper Protector (LH/RH) LHV RHXH	pair	\$ 38.00	\$	76.00	
	Tail Lamp (LH) ?		20.00	\$	344.00	
	Rear Panel			\$	391.80	
	Rear Panel Garnish			\$	95.80	
	Spare Tyre Holder X			\$	27.60	
	Spare Tyre Panel * **			\$	863.00	
	Spare Tyre Panel Cushion 2			\$	200.30	
	Rear Towing Hook			\$	135.30	
	Member Assy- Rear Floor Centre			\$	163.60	
	-			235,3		
	SUB TOTAL			\$	5,849.30	1
	LESS 20%	Consultants	hence notify	\$	1,169.86	
	DISCOUNTED TO TAKE	rer of the following before/after s	Owing:	\$	4,679.44	
	• To display	damaged parti	during resurvey			
	• Third party	s are subject to	confirm men 'Without Prejudice" his s	\$	30.00	Net
	Real Bumper Reverse Sensor X No illegal in	redification(s) i	allowed	\$	135.70	Net
	 Supplement is subject to 	tary item(s) mu	stibe resurveyed and from Insurance Cumpany			
			non resurance company	\$	165.70	
	Acknowledge Signature:	d by Repairer				
						1
	D ID ' D D D I	THE RESERVE OF THE PARTY OF		\$	1,600.00	80
	Panel Beating- Repair RR Fender	111.		Ψ.		
	Spray Painting Charge Kalo. (C)	CRY	_	\$	800.00	72
	Spray Painting Charge Wiring Charge	(CK) () W12	15-35 ha	\$		72
	Spray Painting Charge Wiring Charge Tuff Kote	(CK) 8 w/ v3	15-35 hz	\$ \$ \$	800.00 50.00 50.00	
	Panel Beating- Repair RR Fender Spray Painting Charge Wiring Charge Tuff Kote Remove/Refix Reverse Sensor	(CK) {	15-35 hz	\$ \$ \$ \$	50.00	20
	Panel Beating- Repair RR Fender Spray Painting Charge Wiring Charge Tuff Kote Remove/Refix Reverse Sensor	((k) f v/v) 4 Pvy L/s	15-35 hz 5.	\$ \$ \$	50.00 50.00	20
	Panel Beating- Repair RR Fender Spray Painting Charge Wiring Charge Tuff Kote Remove/Refix Reverse Sensor Total Labour	(CR) 8 f v/v + 4 Pv y 4/s 1 L/s	15-35 hrs s. Ryan oll	\$ \$ \$ \$	50.00 50.00 120.00	
	Panel Beating- Repair RR Fender Spray Painting Charge Wiring Charge Tuff Kote Remove/Refix Reverse Sensor Total Labour ESTIMATE TOTAL	((k) 8/11/14 4/15 4/15 AHh	15-35 hr 5. fyar pll	\$ \$ \$ \$ \$	50.00 50.00 120.00	20
	Spray Painting Charge Wiring Charge Tuff Kote Remove/Refix Reverse Sensor Total Labour	KKy S/u/17 4 Pry -/s Ath e above vet	15-35 hz f. fyar pll nicle. The final renair of	\$ \$ \$ \$ \$	50.00 50.00 120.00 5 0 2,620.00 7,465.14	20



A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

Service Centres

206 Braddell Road Singapore 579701

45 Pandan Road Singapore 509286

45 Pandan Road Singapore 809288

383 Sin Ming Drive Singapore 50869

383 Sin Ming Drive Singapore 50869

320 Ubi Road 3 Singapore 408649 24 Senoko Loop Singapore 753158





JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition								
1. Date: Time Received: 7.05%	2. Vehicle Type:	1 To 1 To						
, ()	3. Vehicle Type:	4. Type of Towing: Normal Tow						
2. New SPARK Kakis Name of Customer: ON & HEN & HUP	Taxi (CTPL/CCPL)	King Dolly						
,	Fleet	☐ Flat Bed						
Contact No. 97642502 /	STK (Boon Lay)	Crane-up						
Vehicle No. 5/10 43@50	5. Nature of Service:	6. Parts Replaced/Remarks:						
Make/Model/Colour: Hyundan Sonata.	Jumpstart Recovery							
Email :	Change Tyre / Battery							
7. Location: 722. (pc	1	/ - In Workshop:						
9. Preferred Workshop: Smoky Exhaust Wheel Jammed Overheating Steering Faulty								
☐ Braddell ☐ Loyang ☐ Pandan ☐ Brake Faulty ☐ Alternator Faulty								
Sin Ming Sungei Kadut		g Problem Loss Power						
Senoko Komoco (UBI / Leng Kee)	Cycle & Carriage (PD) Accide							
Others:	Return	Taxi						
10. Odometer Reading :	11. Radio CD Player	FRONT						
OK OK								
Fuel Level : F 1/4 1/2 3/4 E	Faulty							
	Not tested							
Job Attended		and the state of t						
12. Tow Truck / Recovery Van : VRS QA GAO TZ YISHUN OTHERS TOWING								
Name of Driver :		REAR (L.						
Vehicle No. : Gus 13812		# 10 11						
Time Dispatch : 7-05		#: Cracked X: Dented /: Seatched O: Missing						
Time of Arrival : 7,30	<u> </u>	A.						
Time Completed :O _		Signature of Customer						
Cash Invoice Details (if applicable)								
13. Cash Invoice No. :								
Customer Acknowledgement								
 a. I have been advised to remove all valuable items in my vehicle, includir cash cards, spectacles, pen, etc. 	ng Global Positioning System (GPS), audio cor	npact disk, thumbdrive, carpark coupons,						
b. I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses.								
c. Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care TM								
730	· k -							
	Ja.	Contract of the Contract of th						
Date Time	Signa	ature of Customer						
14. WORKSHOP								
Name of Attending Staff/Guard Date & Time of	Arrival Signature	of Attending Staff/Guard						

Signature of Attending Staff/Guard