

22/03/2003

REF: CS/FCI17022704/Urbanz

Special Instruction:

ASS. REC. BY:

Surveyor: Marcus
CWS

ASSIGNMENT (Office)

Date/Time: 6.58pm @ 28/11/17

From (Person): Aung Yin Ming

of FCI

Bill to:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

Insured: SHB 3685Z

To Inspect Vehicle No:

SKX 2627Y

Tel: 67840663

at Workshop m/s

NPH Auto

of 31K 9005 Tampines Street 93 #01-246/254

Claim No:

D17016999MFSH

Policy No:

Excess:

Sum Insured:

D.O.A. 25/11/17

Make of Veh:
(Client's Record)

lwr

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time: 154am @ 29/11/17

Person Contacted:

Peggy

Vehicle IN OUT

Date/Time	Action/Instruction (-> Estimate
	<u>SKX 2627Y - X</u>
	<u>SHB 3685Z - CS/40I16014181/H1gbd1-D.O.A.: 29/07/2016</u>



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17022704/Urb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 29-11-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 3685Z	Veh. Inspected	SKX 2627Y
Policy No.		Coverage (\$)	0.00
Claim No.	D17010999MFSH	Excess (\$)	0.00
Assign From	CWS (AUNG YIN MIN)	Assign Date	29/11/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	25/11/2017	Inspection Date	29/11/2017
Survey held at	NPH AUTO SERVICE BLK 9005 TAMPINES STREET 93 #01-246/254 SINGAPORE 528839		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	28-11-2017	Our Ref No. D17010999MFSH
Accident Date	25-11-2017	Claim Type. Third Party
Insured Vehicle	SHB3685Z	Third Party Vehicle. SKX2627Y
Survey Location	BLK 9005 TAMPINES STREET 93 #01-246/254	
Contact Person.	PEGGY FOO	
Contact No.	67840663/ 0	Fax No. 67840692
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	NPH AUTO SERVICE	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	AUNGYM	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/231152)

PRI Documents

Close X

PRI Header Details

Claim No	D17010999MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & NPH AUTC
Workshop Name	NPH AUTO SERVICE (Contact Person : PEGGY FOO)	Survey Location & Contact Details	BLK 9005 TAMPINES STREET 93 #01-246/254 Mobile: 0 , Phone: 67840663 , Fax: 67840692 EmailId: NPHAUTO@PACIFIC.NET.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHB3685Z	TP Vehicle No	SKX2627Y
PRI Recieved Date	28-11-2017 03:54:14 PM	Surveyor Appointed Date	28-11-2017 06:57:34 PM	Surveyor Accept Date	29-11-2017 1.

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	29-11-2017	Upload Survey Report *:	<input type="button" value="Choose File"/>
------------------------------------	---	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▾	Model	Please Select Model ▾	Year	Select Year ▾
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17010999MFSH

Our Ref: CS/FCI17022704/Urb

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SKX 2627Y.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 29/11/2017 at the premises of M/s NPH AUTO SERVICE and have the following to report:-

Workshop Estimate Amount	: S\$ <u>6,385.42</u> .
Revised Estimate Amount	: S\$ <u>5,740.57</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:
The vehicle sustained damages
at the rear portion.



Yours faithfully

MARCUS CHUA
Automotive Assessor

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	4537I
Vehicle Details	
Vehicle No.	SKX2627Y
Vehicle to be Exported	No
Intended De-registration Date	05 Dec 2017
Vehicle Make	TOYOTA
Vehicle Model	COROLLA AXIO 1.5X CVT ABS D/AIRBAG 2WD
Primary Colour	White
Manufacturing Year	2015
Engine No.	2NR8482636
Chassis No.	NRE1610005986
Maximum Power Output	80.0 kW (107 bhp)
Open Market Value	\$13,776.00
Original Registration Date	01 Dec 2015
First Registration Date	01 Dec 2015
Transfer Count	0
Actual ARF Paid	\$8,776.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	30 Nov 2025
PARF Rebate Amount	\$6,582.00
Intended COE Rebate Details	
COE Expiry Date	30 Nov 2025
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$59,200.00
COE Rebate Amount	\$47,277.00
Total Rebate Amount	\$53,859.00

The information contained herein is correct as at 05 Dec 2017

OK



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
 GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
 E-mail: nphauto@pacific.net.sg



Your Ref :
 Our Ref : TP0113/11/17

Page : 1/2
 Date : 28/11/2017

THIRD PARTY CLAIM
 M/S : KHONG HUEY LING
 APT BLK 450 PASIR RIS DRIVE 6
 #11-170 SINGAPORE 510450

*NOT ADDED
 here
 29/11/17
 2/5 @ 4600/-
 6-ly
 2 hybrid 11/11/17*

Attn :
 Dear Sir/Madam
 RE: ACCIDENT REPAIR ON : SKX2627Y - TOYOTA AXIO
 INSURED : KHONG HUEY LING
 DATE OF ACCIDENT : 25/11/2017
 POLICY NO : MP304374

ENGINE# :
 CHASSIS# :

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost \$	U/Price \$	Total \$	
Replacement of Parts					
1 rear boot	1@	725.00	725.00	725.00	✓
2 rear boot hinge L & R	2@	127.50	127.50	255.00	✓
3 rear boot toyota logo	1@	80.00	80.00	80.00	✓
4 rear boot axio emblem	1@	50.00	50.00	50.00	✓
5 rear boot lock top	1@	96.20	96.20	96.20	✓
6 rear boot carpet clips	11@	5.00	5.00	55.00	✓
7 rear lamp assembly L & R	2@	575.70	575.70	1,151.40	✓
8 rear boot lock lower catch	1@	24.80	24.80	24.80	✓
9 rear bumper	1@	980.00	980.00	980.00	✓
10 rear bumper side retainer L & R	2@	110.00	110.00	110.00	✓
11 rear lamp lower bumper retainer L & R	2@	75.00	75.00	150.00	✓
12 rear lamp center panel	1@	615.00	615.00	615.00	✓
13 rear bumper clips	6@	5.00	5.00	30.00	✓
14 rear lamp center panel inner garnish	1@	223.10	223.10	223.10	✓
15 rear boot rubber	1@	188.80	188.80	188.80	✓
16 rear boot corolla emblem	1@	39.60	39.60	39.60	✓
				4,773.90	
				-1,193.48	
				\$3,580.41	
Less 25%					
Total Material					
Special Nett Items					
1 rear bumper parking sensor	1@	200.00	200.00	200.00	✓
				200.00	
				0.00	
				\$200.00	

Total S/Nett Labour & Misc

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg



Registration No.: QAC / SG / 106

Your Ref :
Our Ref : TP0113/11/17

Page : 2/2
Date : 28/11/2017

THIRD PARTY CLAIM

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total
		\$	\$	\$
1 Remove and install rear boot, rear lamp, rear bumper. Cut out and renew rear lamp panel, knocking rear fender, spare tyre panel & restraighen body.	900			1,100.00
2 Spray Painting Pearl White	1080			1,200.00
3 Tuff kote	60			100.00
4 Check wiring system.				25.00 ✓
5 Renew parking sensor	50			80.00
6 Remove and install rear boot carpet.	80			100.00
				<u>2,605.00</u>

Total Labour

\$2,605.00

Nett Total Before Gst

\$6,385.42

528807

Your faithfully



NPH AUTO SERVICE
(Manager)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17022704/Urbn2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 28-12-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 3685Z	Veh. Inspected	SKX 2627Y
Policy No.	D-15072702MFSH	Coverage (\$)	0.00
Claim No.	D17010999MFSH	Excess (\$)	0.00
Assign From	AUNGYM	Assign Date	28/11/2017

2. Vehicle Particulars & Condition

Make & Model	TOYOTA COROLLA AXIO (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	NRE1610005986	Colour	WHITE
Odometer	35389	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/65 R15	DUNLOP	6 mm
L/H Front Tyre	175/65 R15	DUNLOP	6 mm
R/H Rear Tyre	175/65 R15	DUNLOP	6 mm
L/H Rear Tyre	175/65 R15	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	25/11/2017	Inspection Date	29/11/2017
Survey held at	NPH AUTO SERVICE BLK 9005 TAMPINES STREET 93 #01-246/254 SINGAPORE 528839		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 2627Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT	BENT / BUCKLED	725.00	725.00
2	REAR BOOT HINGE L & R @\$127.50	TO REPAIR SEE LABOUR	255.00	-
1	REAR BOOT TOYOTA LOGO	NECESSARY	80.00	80.00
1	REAR BOOT AXIO EMBLEM	NECESSARY	50.00	50.00
1	REAR BOOT LOCK TOP	TWISTED	96.20	96.20
11	REAR BOOT CARPET CLIPS @\$5.00	NECESSARY	55.00	55.00
2	REAR LAMP ASSEMBLY L & R @\$575.70	CRACKED	1,151.40	1,151.40
1	REAR BOOT LOCK LOWER CATCH	NOT NECESSARY	24.80	-
1	REAR BUMPER	DENTED / DEFORMED	980.00	980.00
2	REAR BUMPER SIDE RETAINER L & R	BENT	110.00	110.00
2	REAR LAMP LOWER BUMPER RETAINER L & R @\$75.00	BENT	150.00	150.00
1	REAR LAMP CENTER PANEL	BADLY DENTED	615.00	615.00
6	REAR BUMPER CLIPS @\$5.00	NECESSARY	30.00	30.00
1	REAR LAMP CENTER PANEL INNER GARNISH	TWISTED / WARPED	223.10	223.10
1	REAR BOOT RUBBER	TWISTED	188.80	188.80
1	REAR BOOT COROLLA EMBLEM	NECESSARY	39.60	39.60
	LESS 25% DISCOUNT		-1,193.48	-1,123.53
			3,580.42	3,370.57
SPECIAL NETT ITEMS				
1	SET REAR BUMPER PARKING SENSOR (SN)	SHORTED	200.00	200.00
			200.00	200.00
LABOUR				
	REMOVE AND INSTALL REAR BOOT,REAR LAMP,REAR BUMPER,CUT OUT AND RENEW REAR LAMP PANEL,KNOCKING REAR FENDER,SPARE TYRE PANEL & RESTRAIGHTEN BODY.INCLUSIVE OF THE REPAIR OF REAR BOOT HINGE L & R.		1,100.00	900.00
	SPRAY PAINTING PEARL WHITE.		1,200.00	1,080.00
	TUFF KOTE.		100.00	60.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	CHECK WIRING SYSTEM.		25.00	25.00
	RENEW PARKING SENSOR.		80.00	50.00
	REMOVE AND INSTALL REAR BOOT CARPET.		100.00	80.00
			2,605.00	2,195.00
	GRAND TOTAL		6,385.42	5,765.57
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,600.00

Report Ref No. CS/FCI17022704/Urbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.