

ASSIGNED BY RES REF CS3/A26117007286/Sg6-1
 Subject Sebastian ASSIGNMENT (Office)
 FROM (Person) Joane AUC1 Date 29.11.2017
 Estimated Cost _____ Bill to _____
 • OD / TP / WS / TP RLS / OD RLS / EVA / INV / MV / CE
 To Inspect Vehicle No SKST Insured STX 44220
 at Workshop for Italia motor Tel 6384 6568
 of 8 Kalvi Street Ave 4 # 02-46/47
 Policy No _____ Claim No 0556844960SG003
 Sum Insured _____ Excess _____
 Make of Vehr _____ DOA 7/4/2017
 (Client's Record)
 CA / REV / REP. / REV 24 HRS (up)
 Date/Time 12/12/2017 10:47am Person Contacted Rachel ROAD Endorsement _____
 Vehicle BLUOUT

Date/Time	Action/Instruction (X) Estimate
<u>15/12/2017 4pm</u>	<u>no arrangement for dismantle and after repair (confirm with Rachel)</u>
<u>15/12/17</u>	<u>submit 4/5 \$10,000 , 6 day .</u>
	<u>(Red - 4300 , 30 %).</u>


14/12/2017.

RECEIVED 15 DEC 2017.

Shreekrishna

REF:

ASSIGNMENT

From _____ Date _____

Estimated Cost _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect vehicle No _____

at Workshop No _____

of _____

Insured _____

Policy No _____

Claims No _____


Sum Insured _____ Excess _____

(Client's Record)

Make of Ven. _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Ball or Market Value _____

DAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen _____ Consistent? : Yes or No

Est. Repairs: 9 days Res: Yes or No

Lump Sum _____ % 3 Val: Yes or No

CA / REV / REP / 24 HRS

Date _____ Person Contacted _____

Vehicle IN / OUT

Date / Time _____ Action / Instruction _____

17/4/2011 - A.K. G.H.

Veh No _____ Yr Regn 3 May 2012

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make Maruti Suzuki C100 cc 1597

Colour Black 4 C Insured / Std / NI / NA

Sp Reading: 1514/2011 T. Radio: Insured / Std / NI / NA

Eng No _____

C No: 1514/2011

Gen. Cond. Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 1514/2011 R: 1514/2011

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R. Bal _____ mm R. Bal _____ mm

L. Bal _____ mm L. Bal _____ mm

D.O.A. _____ D.O.I. 1514/2011

Survey held at 1514/2011

Des. of Damages: Frt / Rear / OS / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time / File Pass to:

15-10-11

Date / Time / File Return to:

:

Report Format :

PR

Lump Sum / I.B.R. (S)

☐

: Preli. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (S)

☐

Interview (S)

☐

Tech. Insp (S)

☐

Weekend (S)

Survey Fee:

Transported:

(S + AS) (S)

(S) (S)

(S) (S)

(S) (S)

Total

180
20
200



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG17007286/Sgb-1

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 29-11-2017



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJX 4422U	Veh. Inspected	SCK 5T
Policy No.		Coverage (\$)	0.00
Claim No.	0556844960SG003	Excess (\$)	0.00
Assign From	JOANE	Assign Date	29/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	07/04/2017	Inspection Date	29/11/2017
Survey held at	ITALIA MOTORS PTE LTD 8 KAKI BUKIT AVENUE 4 PREMIER @ KAKI BUKIT #02-46/470 SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Catherine Chong (LKK Auto)

From: Boyogan, Joane <Joane.Boyogan@aig.com>
Sent: Wednesday, 29 November, 2017 2:11 PM
To: admin-d@lkkauto.com
Cc: Hsiao Tong (chewht@lkkauto.com); 'SUR'
Subject: #0556844960SG003#027#Paper resurvey request
Attachments: 0556844960SG_tp survey docs.pdf

Dear Catherine,

Enclosed is third party's survey report & damage photos

Kindly assist to review and let us have your surveyor's recommendation on repair costs & estimate number of days to repair

Thank you

Regards,

Joane Boyogan
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way AIG Building #08-16 Singapore 079120
Tel +64191898 | Fax +68357416
joane.boyogan@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

NCAA373474P1 / 3A Automobile Pte Ltd - HQ
ENTRY DATE & TIME: 11/04/2017 09:50

Your NCD will be affected due to late reporting
Actual e-Filing Submission Date & Time: 11/04/2017 10:11

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 11/04/2017 09:50
Date Of Accident 07/04/2017 19:45
Exact Location Of Accident ALONG UPPER BUKIT TIMAH ROAD
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SCK5T
Insured/Policyholder
Name Of Registered Owner VONG JUNN PIN
NRIC No S7502134H
Email Address CHERMAINEREALTY@GMAIL.COM
Mobile Phone No (LOCAL) +65-90708880
Alternative Phone No OFFICE-NOPHONE
Vehicle Particulars
Manufacturer MERCEDES-BENZ
Model C 180 KOMPRESSOR
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR
Insurance Company
Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 2100372594-02000
Cover Note Number
Driver
Name of Driver KOH LAY CHENG CHERMAINE
NRIC No S7311880H
Date Of Birth 05/04/1973
Occupation INDOOR
Date Of Driving Pass 23/06/1996
Driving Experience 20 YEARS AND 9 MONTHS
Gender FEMALE
Mobile Number (LOCAL) +65-90708880
Fax Number
Contact Number
Email Address CHERMAINEREALTY@GMAIL.COM

Address 52
CHENG SOON CRESCENT
Postcode 599924
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured SPOUSE
Vehicle Registration Number of Driver's Own Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION- CHAIN COLLISION
Weather Conditions CLEAR
Road Surface DRY
Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? YES
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name

MOUNTBATTEN NEIGHBOURHOOD POLICE POST

Police Station Address

ROAD: BLK 60 DAKOTA CRESCENT #01-213/ 215 , POSTCODE: 390060 , COUNTRY: SINGAPORE

Police Station Contact

TEL NO: 1800-3449999 - FAX NO: 64474185

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO THE ATTACHMENT

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJX4422U
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver LIM ENG CHONG
NRIC/Passport Number S00156941
Contact Number 95758735
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SGW3502U
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver LIEW KAI LIANG
NRIC/Passport Number S7071451E
Contact Number 90906962
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)
Details of Witness

Name

Phone Number

Email Address

DETAILS OF INJURED PERSON 1

Name KOH LAY CHENG CHERMAINE
Approximate Age 44
Injuries Sustain
Injured person in which vehicle? SCK5T
Were seat belts worn? YES
Was injured conveyed to hospital by ambulance? NO
Address 32 CHENG SOON CRESCENT
SINGAPORE
Postcode 599924

Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claim process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available forever.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


 - (a) my insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of this claim and any necessary investigations relating to the claim;
 - (ii) investigating the accident and/or my claim;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claim (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claim, (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


 Policyholder's Signature / Date & Time


 Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



A: 8CK 5T
 B: 8JX 4422U

C: 8GW 3502U

Sketch Plan Pg. 2


Describe Circumstances of the Accident

On mentioned date and time, I was driving along 4pp
Robert Timah Road. When I approached the traffic
junction, the front vehicle SW 35024 stopped and I
followed him. Both our vehicles were in stationary
position. Few seconds later, SJX 44224 crashed against
my vehicle with great force. My vehicle surge forward
and hit onto SW 35024. I got down to inspect and
exchange particulars and SJX 44224 driver
admitted that he couldn't stop in time and caused
the whole accident. I went to seek medical treatment
and I was given 3 days medical leave.

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date &
Time


Driver's Signature (If driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel

Sketch Plan #2 Pg. 1



**SINGAPORE
POLICE FORCE**



T201704082127

1 of 4

Police Station Of Origin:
Mountbatten NPP
60 Dakota Crescent #01-213 SINGAPORE
390060
Tel No: 1800-3449999

Report No. T201704082127

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 08/04/2017 18:43		Vide Report No.:		Station Diary No.: 14	
Informant's Particulars					
Name of Informant: KOH LAY CHENG CHERMAINE			Address: 52 CHENG SOON CRESCENT SINGAPORE 599924		
ID Type / ID No.: NRIC NO / S7311890H			Contact No.: Home/Office: Mobile: 90709880		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 44	Date of Birth: 06/04/1973	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Real estate agent			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 07/04/2017 19:50	Type of Location: Straight Road
Location: Along Road 1 UPPER BUKIT TIMAH ROAD OUTSIDE BUKIT REGENCY				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SCK5T	Car				Seriously Damaged	0
SGW3502U	Car					1
SJX4422U	Car					0


Details of Person Involved

Any Pedestrian Involved: No
No. of Pedestrians Injured: NIL | Use of Pedestrian Crossing: NA

Sketch Plan #2 Pg. 2



**SINGAPORE
POLICE FORCE**



T/20170408/2127

2 of 4

Report No. T/20170408/2127

Police Station Of Origin:
Mountbatten NPP
60 Dakota Crescent #01-213 SINGAPORE
390060
Tel No: 1800-3449999

CONTINUATION OF REPORT

Name	KOH LAY CHENG CHERMAINE	ID No.	S7311880H
Related Vehicle	SCK5T (Car)	Contact No.	90708880
Hospital/Clinic	THE DUBLIN CLINIC	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	Serious
Name	LIEW KAI LIANG	ID No.	S7071451E
Related Vehicle	SGW3502U (Car)	Contact No.	90905982
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Name	LIM ENG CHONG	ID No.	S0015894I
Related Vehicle	SJX4422U (Car)	Contact No.	96758735
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details:

On 7/4/2017 at about 1948hrs, while in my vehicle (SCK5T), waiting for the traffic light to turn green along Upper Bukit Timah Road, a vehicle from behind (SJX4422U) impacted onto my vehicle, causing my vehicle to inch forward to hit the stationary vehicle (SGW3502U) ahead of me. The vehicle behind me SJX4422U then reversed slightly and then rammed into me again. I suspect that he was in shock after the accident, I then waited for the driver of SJX4422U to exit from his vehicle before exiting mine. We then exchanged particulars and agreed on going for insurance claims. I then went to The Dublin Clinic on 8/4/2017 and was given 3 days MC for the pain in the neck and back area. I am lodging this report for record purposes.

Test Site

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 2134H

Vehicle Details

Vehicle No: SCK5T

Vehicle to be Exported: Yes

Intended De-registration Date: 17 Apr 2017

Vehicle Make: MERCEDES BENZ

Vehicle Model: C 180 KOMPRESSOR

Primary Colour: Black

Manufacturing Year: 2012

Engine No: 27191031354253

Chassis No.: WDD2040452A699017

Maximum Power Output: 115.0 kW (154 bhp)

Open Market Value: \$30,328.00

Original Registration Date: 03 May 2012

First Registration Date: 03 May 2012

Transfer Count: 0

Actual ARF Paid: \$30,328.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 02 May 2022

PARF Rebate Amount: \$22,746.00

Intended COE Rebate Details

COE Expiry Date: 02 May 2022

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$56,501.00

COE Rebate Amount: \$28,484.00

Total Rebate Amount: \$51,230.00

The information contained herein is correct as at 17 Apr 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer
Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions
Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution
Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

Condition Codes:
 (1)New (2)Used (3)Cracked (4)C/A (5)Detached (6)Delayed
 (7)Held (8)Dashed (9)Broken (10)Missing (11)Missing (12)Missing (13)Missing
 (14)Missing (15)Other

MOTOR CAR (Fr)

ACTUAL ()
 (1)Register (2) (3)Register (4) (5)Check (6)
 (7)Other Comments (8)

Reg 1001

14-2

Vehicle No:

306 51

Front Portion

NAC	INC	Item	CON	ACQ	Qty
1001	991886	Fr Number Plate	ST		
1002	991887	Fr Number Plate Base			
1003	991889	Fr Number Plate Garnish			
1004	991300	Fr Bumper	CH	SR	RL
1005	992341	Fr Bumper Clips			
1006	991325	Fr Bumper Bracket	ST		2
1007	991462	Fr Bumper Side Retainer	ST		2
1008	991433	Fr Bumper Reinforcement	ST		
1009	991318	Fr Bumper Beam	CH		
1010	991468	Fr Bumper Sponge			
1011	991427	Fr Bumper Protector			
1012	991420	Fr Bumper Pad			
1013	991363	Fr Bumper Grille	CH		
1014	991301	Fr Bumper Moulding			
1015	991407	Fr Bumper Lower Spoiler			
1016	991438	Fr Bumper Sensor			
1017	991100	Fr LH Bumper Fog Lamp Cover	CH		
1018	991355	Fr RH Bumper Fog Lamp Cover	CH		
1019	995079	Fr LH Bumper Fog Lamp	CH		
1020	995080	Fr RH Bumper Fog Lamp	CH		
1021	991793	Fr Grille	CH		
1022	991328	Fr Grille Emblem	CH		
1023	991799	Fr Grille Chrome Moulding	CH		
1024	991222	Fr Apron Panel			
1025	992013	Fr Support Panel	CH		
1026	992025	Fr Support Panel Top Garnish Cover	CH		
1027	992416	Horn			
1028	991277	Fr Brace Panel	CH		
1029	995153	Fr LH Headlamp Assy	CH		
1030	991821	Fr RH Headlamp Assy	CH		
1031	995088	Fr LH Side Lamp			
1032	995089	Fr RH Side Lamp			
1033	990248	Bonnet	CH		
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock	ST		
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990131	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992736	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Dust			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Fr Exhaust Manifold			
1064	991713	Fr Exhaust Manifold Cover			
1065	991054	Fr Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	ACQ	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Fr			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Fr LH Chassis Member			
1093	991520	Fr RH Chassis Member			
1094	990728	Fr Vertical Cross Member			
1095	991863	Fr Lower Cross Member			
1096	995070	Fr LH Fender			
1097	995072	Fr LH Fender Inner Panel			
1098	995147	Fr LH Fender Lamp			
1099	995148	Fr LH Fender Protector			
1100	991740	Fr LH Fender Inner Shield			
1101	995179	Fr LH Mudflap			
1102	995170	Fr LH Wheel Rim			
1103	994025	Fr LH Rim Cover			
1104	995065	Fr LH Tyre			
1105	995071	Fr RH Fender			
1106	991739	Fr RH Fender Inner Panel			
1107	991744	Fr RH Fender Lamp			
1108	991752	Fr RH Fender Protector			
1109	991740	Fr RH Fender Inner Shield			
1110	991884	Fr RH Mudflap			
1111	992087	Fr RH Wheel Rim			
1112	994025	Fr RH Rim Cover			
1113	995065	Fr RH Tyre			
1114	992093	Fr Windscreen Glass			
1115	992117	Fr Windscreen Rubber			
1116	992108	Fr Windscreen Moulding			
1117	992098	Fr Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Fr Wiper Arm			
1121	992142	Fr Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990884	Fr Driver Seat			
1133	991822	Fr RH Seat Belt Assy			
1134	991899	Fr Passenger Seat			
1135	995182	Fr LH Seat Belt Assy			
1136	990247	Sticker			

No of Items:

22

Assessor:

ORIGINAL COPY

2/15/2017

MOTORCAR (Rear)

Vehicle No: SKR 51

2 of 2

Rear Portion

NAC	INC	Item	CON	ACQ	QTY
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper			
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992141	Rear Bumper Clips			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	992851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	ACQ	QTY
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	995057	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994026	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993432	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993979	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993965	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993388	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992182	Fuel Tank Bracket			
1254	992181	Fuel Tank Flap			
1136	994543	Tailgate			
		LH Rear Panel Air Vent			

No of Items: 23

Assessor: _____

[Handwritten signature]
2/5/2017

LKK Auto Consultants Pte Ltd (Co. Reg No. 199507198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG17007286/SH3F2
Date: 04/05/2017

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100214229
 Claimant: SCK5T Insured Vehicle No: SJX4422U
 Vehicle No: SCK5T Nature of Claim: TP Claim No: 0556844960SG
 Date of Loss: 07/04/2017

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SCK5T
 Make & Model: MERCEDES-BENZ C180, 1.6 Kompressor (A) Engine No: 27191031354253
 Reg. Date: 03/05/2012 (Man. Year: 2012) Chassis No: WDD2040452A699017
 Colour: Black Odometer: 150448 km
 Engine Capacity: 1597 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 ZR17 Rear Tyre Size: 225/45 ZR17
 Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm
 Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 13/04/2017
 Date Inspected: 13/04/2017 Inspected At: Italia Motors Pte Ltd (HQ)
 8 Kaki Bukit Avenue 4, #02-46, Premier
 @ Kaki Bukit
 Singapore 415875

Estimated Period of Repair: 9.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: Ashley Chong Chin Yan

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRT NUMBER PLATE	Bent	0.00 F	*.F
2	1	*FRT BUMPER	Cut	0.00 F	*.F
3	1	*FRT BUMPER CLIPS	Necessary	0.00 F	*.F
4	2	*FRT BUMPER BRACKET	Bent	0.00 F	*.F
5	2	*FRT BUMPER SIDE RETAINER	Distorted	0.00 F	*.F
6	1	*FRT BUMPER REINFORCEMENT	Dented	0.00 F	*.F
7	1	*FRT BUMPER SPONGE	Cracked	0.00 F	*.F
8	1	*FRT BUMPER GRILLE LOWER	Dented	0.00 F	*.F
9	1	*FRT LH BUMPER FOG LAMP COVER	Cracked	0.00 F	*.F
10	1	*FRT RH BUMPER FOG LAMP COVER	Cracked	0.00 F	*.F
11	1	*FRT LH BUMPER FOG LAMP	Cut	0.00 F	*.F
12	1	*FRT RH BUMPER FOG LAMP	Scratched	0.00 F	*.F
13	1	*FRT GRILLE	Cracked	0.00 F	*.F
14	1	*FRT GRILLE EMBLEM	Necessary	0.00 F	*.F
15	1	*FRT GRILLE CHROME MOULDING	Necessary	0.00 F	*.F
16	1	*FRT SUPPORT PANEL	Repair	0.00 F	*.F
17	1	*FRT SUPPORT PANEL TOP GARNISH COVER	Cracked	0.00 F	*.F
18	1	*FRT LH HEADLAMP ASSY	Cut	0.00 F	*.F
19	1	*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*.F
20	1	*BONNET	Repair	0.00 F	*.F
21	1	*BONNET LOCK	Bent	0.00 F	*.F
22	1	*FRT TOW HOOK COVER	Cut	0.00 F	*.F
23	1	*REAR BUMPER	Dented	0.00 F	*.F
24	6	*REAR BUMPER CLIPS	Necessary	0.00 F	*.F
25	1	*REAR BUMPER BRACKET	Cracked/Necessary	0.00 F	*.F
26	1	*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*.F
27	1	*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*.F
28	1	*REAR BUMPER MOULDING CHROME	Missing	0.00 F	*.F
29	1	*REVERSE SENSOR	Damaged	0.00 F	*.F
30	1	*REAR END PANEL	Dented	0.00 F	*.F
31	1	*REAR LH TAILLAMP	Cracked	0.00 F	*.F
32	1	*REAR LH TAILLAMP PANEL	Bent	0.00 F	*.F
33	1	*BOOTLID	Dented	0.00 F	*.F
34	3	*BOOTLID EMBLEM	Necessary	0.00 F	*.F
35	1	*BOOTLID LOCK	Bent	0.00 F	*.F
36	1	*BOOTLID RUBBER	Necessary	0.00 F	*.F
37	1	*REAR EXHAUST PIPE	Dented	0.00 F	*.F
38	1	*REAR EXHAUST CHROME PIPE	Dented	0.00 F	*.F
39	1	*REAR EXHAUST HEAT SHIELD	Bent	0.00 F	*.F
40	1	*REAR LH FENDER	Dented	0.00 F	*.F
41	1	*REAR LH FENDER INNER SHIELD	Torn	0.00 F	*.F
42	1	*REAR RH FENDER	Repair	0.00 F	*.F
43	1	*REAR WINDSCREEN MOULDING	Necessary	0.00 F	*.F
44	1	*REAR WINDSCREEN SEALANT	Necessary	0.00 F	*.F
45	1	*LH REAR FENDER AIR VENT	Bent	0.00 F	*.F
Total Parts (\$\$)				0.00	0.00

F=Franchise part

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

ST Appraisal Services

Insurance Loss Adjusters & Licensed Appraisers

Insurance Claim Investigator

Business Address: 60 Arab Street Singapore 199757

Tel: 66523352 / 98586761; Fax: 62970270

Mailing Address : 161 Alexandra Post Office Singapore 911506

Date : 29th Sept 2017

Our Ref : TP / IMPL SCK5T/ 04.07/17

Your Ref :

Mr Vong Jiunn Pin
No 52
Cheng Soon Crescent
Singapore 599924

DAMAGED VEHICLE (SCK 5 T) INSPECTION REPORT (WITHOUT PREJUDICE)

Detailed accounts of our inspection are as follows:-

(A) Reference

Name of Claimant	: Mr Vong Jiunn Pin	Date of Request	: 17 th Apr 2017
		Referred By	: Insured
Policy No.	: Please Advice	Date of Inspection	: 17 th Apr 2017
Claim No.	: Please Advice	Date of Re-inspection	:
Accident Date	: 7 th Apr 2017	Sum Insured	: NA
Repairer	: M/s Italia Motors Pte Ltd	Excess Amount	: NA
	8 Kaki Bukit Ave 4 Premier	3 rd Party Vehicle	: Please Advice
	#02-46/47 Singapore 415875	3 rd Party Insurer	: Please Advice

(B) Particulars of Vehicle


Registration No	: SCK 5 T	Mileage	: Km
Make & Model	: MERCEDES BENZ C180	Engine No	: 27191031354253
Date of Registration	: 3 rd May 2012	Chassis No.	: WDD2040452A699017
Colour	: Black	Engine Capacity	: 1,597 cc

(C) Pre-Accident Condition (Static Test Only)

Steering	: Serviceable	Paint Work	: Good
Foot-brake	: Serviceable	Modification	: NIL
Hand-brake	: Serviceable	General Condition	: Good

(D) Tyre Condition

	Tread Depth	Make	Size
Front Left	60 %	MICHELIN	225/45 R17
Front Right	60 %	MICHELIN	225/45 R17
Rear Left	60 %	MICHELIN	225/45 R17
Rear Right	60 %	MICHELIN	225/45 R17

(E) Point of Impact**(F) General Description of Damages**

The impact of the collision has damaged/affected the rear bumper, boot lid, rear end panel, front bumper, front grille and etc.

Please refer to the Annex for a detailed account of the damages and photographs taken.

(G) Recommendation

We have inspected thoroughly the actual damages found on the vehicle, before we arrived at our recommendation as to whether the parts needed replacement or repairs.

Our adjusted cost of lump sum repair is **\$14,300.00** and an estimated **9** days are required to repair the vehicle. Please refer to the Annex for a detailed account of the cost estimates.

(H) Remarks

We have not authorised the repairs. However for information, under normal circumstances, the repairs should not exceed **9** days.

This inspection was conducted on a "**without prejudice**" basis.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Appraisal Report, which includes evidence photographs.

ST Appraisal Services



T T RAJAN
MVI, ITC (Mechanical), NTC (Motor Vehicle)
ASIET, MSAAA, Assessor/Appraiser
AD041-2007532D

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS FOR VEHICLE NO: SCK 5 T

Adjustment of Spare Parts Costs for Repairs

Item	Qty	Vehicle parts description	Condition / Remark	Estimated by workshop	Disc. (%)	Adjusted cost (S)
1	1	Rear bumper ✓ Deform	damaged	1012.00	10	910.80 ✓
2	1	Rear bumper beam ✓ BT	damaged	868.80	10	781.92 ✓
3	1	Rear bumper inner support ✓ DT	damaged	119.80	10	107.82 ✓
4	2	Rear bumper side retainer ✓ NEC	affected	98.60	10	88.74 ✓
5	1	Rear bumper side moulding ✓ ms	missing	89.10	10	80.19 ✓
6	1	Rear bumper centre moulding ✓ NEC	grazed	112.35	10	101.12 ✓
7	1	Boot lid ✓ DT	dented	1227.00	10	1104.30 ✓
8	1	Boot lid badge - C 180 ✓ NEC	necessary	53.20	10	47.88 ✓
9	1	Boot lid badge - KOMPRESSOR ✓ NEC	necessary	65.20	10	58.68 ✓
10	1	Boot lid logo ✓ NEC	necessary	56.40	10	50.76 ✓
11	1	Rear end panel R	dented	646.65	10	581.99 X
12	1	Tail lamp ✓ CRIC	damaged	351.20	10	316.08 ✓
13	1	Rear fender R	to repair	972.15	100	0.00 X
14	1	Rear fender air grille ✓ Deform	damaged	189.10	10	170.19 ✓
15	1	Exhaust tail pipe ✓ DT	dented	1383.30	10	1244.97 ✓
16	1	Exhaust heat shield ✓ Deform	damaged	89.20	10	80.28 ✓
17	1	Exhaust mounting ✓ NEC	necessary	52.00	10	46.80 ✓
18	1	Bonnet ✓ DT	damaged	1147.00	10	1032.30 ✓
19	1	Bonnet lock upper ✓ Jm	bent	49.80	10	44.82 ✓
20	1	Bonnet lock lower ✓ Jm	distorted	58.20	10	52.38 ✓
21	1	Front bumper cover ✓ Deform	damaged	1179.00	10	1061.10 ✓
22	1	Front bumper reinforcement + m	damaged	322.00	10	289.80 X
23	1	Front bumper absorber + m	damaged	132.40	10	119.16 X
24	2	Front bumper garnish moulding ✓ NEC	necessary	150.16	10	135.14 ✓
25	1	Front licence plate garnish ✓ Cmp	damaged	98.00	10	88.20 ✓
26	1	Headlamp panel R	to repair	226.00	100	0.00 X
27	1	Radiator support panel R	to repair	116.00	100	0.00 X
28	1	Radiator grille ✓ Cck	damaged	639.70	10	575.73 ✓
29	1	Radiator grille support ✓ NEC	necessary	8.68	10	7.81 ✓
30	1	Headlamp ✓ Cck	damaged	1022.25	10	920.03 ✓

Special nett item

1	1	Rear bumper sensor ✓ omg	damaged	360.00		320.00
2	1	Front number plate ✓ DT	damaged	50.00		50.00 30
3		Sundries (clips, bolts & etc)	necessary	120.00		90.00 50

1) Parts: \$ 9690.03
 2) S/Nett: \$ 400.00
 3) Labour: \$ 3060.00

13150.03

Lump Sum - 20%

10520.02

TP / IMPL SCK5T/ 04.07/17

\$ 10500 @ 6 days

Total parts 13065.24 10558.98

2) 400

Adjustment of Labour Costs for Repairs

To remove and replaced rear damaged parts including straightening and repositioning replacement parts @ \$720.00 per day.	2880.00	⁶⁰⁰ 2520.00
To remove/refit interior fittings to facilitate repair.	150.00	⁶⁰ 120.00
To remove and replace front damaged parts including straightening and repositioning replacement parts @ \$720.00 per day.	1440.00	⁶⁰⁰ 1260.00
To carry out anti rust treatment on the affected panels.	180.00	150.00 40
To supply paint materials and expandable items. To respray rear affected panels (<i>boot lid, rear end panel, rear fender & etc.</i>)	1400.00	1350.00 800
To supply paint materials and expandable items. To respray front affected panels (<i>bonnet, front bumper & etc.</i>)	1300.00	1250.00 500
To check electrical wiring system of the front and rear section for proper functions.	100.00	80.00 50
Install rear bumper sensor and check for proper functions.	80.00	60.00 30
To remove and replace exhaust system. To realign exhaust system.	120.00	100.00 60
To remove and refit rear windscreen to facilitate repair.	150.00	0.00 ✕
Carry out diagnostic test and reset memory to specifications. Focus	360.00	300.00 200
To provide towing service. 3) 3060	150.00	120.00 /
Total labour	8310.00	7310.00

Adjustment Parts and Labour Costs of Repairs

	Estimated by workshop	Adjusted cost
TOTAL PARTS COSTS	13065.24	10558.98
TOTAL LABOUR COSTS	8310.00	7310.00
TOTAL REPAIR COSTS	21375.24	17868.98

ADJUSTED REPAIR COST**14300.00**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG17007286/Sgbs2-1

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 21-12-2017



ATTN: JOANE

Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJX 4422U	Veh. Inspected	SCK 5T
Policy No.	2100214229	Coverage (\$)	0.00
Claim No.	0556844960SG	Excess (\$)	0.00
Assign From	JOANE	Assign Date	29/11/2017

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ C 180	c.c	1597
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	WDD2040452A699017	Colour	BLACK
Odometer	150448	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAULTY		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45ZR17	MICHELIN	7 mm
L/H Front Tyre	225/45ZR17	MICHELIN	7 mm
R/H Rear Tyre	225/45ZR17	MICHELIN	7 mm
L/H Rear Tyre	225/45ZR17	MICHELIN	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	07/04/2017	Inspection Date	13/04/2017
Survey held at	ITALIA MOTORS PTE LTD 8 KAKI BUKIT AVENUE 4 PREMIER @ KAKI BUKIT #02-46/470 SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCK 5T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	1,012.00	1,012.00
1	REAR BUMPER BEAM	BENT	868.80	868.80
1	REAR BUMPER INNER SUPPORT	DENTED	119.80	119.80
2	REAR BUMPER SIDE RETAINER	NECESSARY	98.60	98.60
1	REAR BUMPER SIDE MOULDING	MISSING	89.10	89.10
1	REAR BUMPER CENTRE MOULDING	NECESSARY	112.35	112.35
1	BOOT LID	DENTED	1,227.00	1,227.00
1	BOOT LID BADGE - C 180	NECESSARY	53.20	53.20
1	BOOT LID BADGE - KOMPRESSOR	NECESSARY	65.20	65.20
1	BOOT LID LOGO	NECESSARY	56.40	56.40
1	REAR END PANEL	TO REPAIR SEE LABOUR	646.65	-
1	TAIL LAMP	CRACKED	351.20	351.20
1	REAR FENDER	TO REPAIR SEE LABOUR	972.15	-
1	REAR FENDER AIR GRILLE	DEFORMED	189.10	189.10
1	EXHAUST TAIL PIPE	DENTED	1,383.30	1,383.30
1	EXHAUST HEAT SHIELD	DEFORMED	89.20	89.20
1	EXHAUST MOUNTING	NECESSARY	52.00	52.00
1	BONNET	DENTED	1,147.00	1,147.00
1	BONNET LOCK UPPER	JAMMED	49.80	49.80
1	BONNET LOCK LOWER	JAMMED	58.20	58.20
1	FRONT BUMPER COVER	DEFORMED	1,179.00	1,179.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	322.00	-
1	FRONT BUMPER ABSORBER	NOT NECESSARY	132.40	-
2	FRONT BUMPER GARNISH MOULDING	NECESSARY	150.16	150.16
1	FRONT LICENCE PLATE GARNISH	CUT	98.00	98.00
1	HEADLAMP PANEL	TO REPAIR SEE LABOUR	226.00	-
1	RADIATOR SUPPORT PANEL	TO REPAIR SEE LABOUR	116.00	-
1	RADIATOR GRILLE	CRACKED	639.70	639.70



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RADIATOR GRILLE SUPPORT	NECESSARY	8.68	8.68
1	HEADLAMP	CRACKED	1,022.25	1,022.25
	LESS 10% DISCOUNT		-	-1,012.00
			12,535.24	9,108.04
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER SENSOR (SN)	DAMAGED	360.00	320.00
1	FRONT NUMBER PLATE (SN)	DENTED	50.00	30.00
1	SUNDRIES (CLIPS, BOLTS & ETC) (SN)	NECESSARY	120.00	50.00
			530.00	400.00
	<u>LABOUR</u>			
	TO REMOVE AND REPLACED REAR DAMAGED PARTS INCLUDING STRAIGHTENING AND REPOSITIONING REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL, REAR FENDER, HEADLAMP PANEL AND RADIATOR SUPPORT PANEL.		2,880.00	600.00
	TO REMOVE / REFIT INTERIOR FITTINGS TO FACILITATE REPAIR.		150.00	60.00
	TO REMOVE AND REPLACE FRONT DAMAGED PARTS INCLUDING STRAIGHTENING AND REPOSITIONING REPLACEMENT.		1,440.00	600.00
	TO CARRY OUT ANTI RUST TREATMENT ON THE AFFECTED PANELS.		180.00	40.00
	TO SUPPLY PAINT MATERIALS AND EXPANDABLE ITEMS. TO RESPRAY REAR AFFECTED PANELS (BOOT LID, REAR END PANEL, REAR FENDER & ETC.)		1,400.00	800.00
	TO SUPPLY PAINT MATERIALS AND EXPANDABLE ITEMS. TO RESPRAY FRONT AFFECTED PANELS (BONNET, FRONT BUMPER & ETC.)		1,300.00	500.00
	TO CHECK ELECTRICAL WIRING SYSTEM OF THE FRONT AND REAR SECTION FOR PROPER FUNCTIONS.		100.00	50.00
	INSTALL REAR BUMPER SENSOR AND CHECK FOR PROPER FUNCTIONS.		80.00	30.00
	TO REMOVE AND REPLACE EXHAUST SYSTEM. TO REALIGN EXHAUST SYSTEM.		120.00	60.00
	TO REMOVE AND REFIT REAR WINDSCREEN TO FACILITATE REPAIR.	NOT NECESSARY	150.00	-
	CARRY OUT DIAGNOSTIC TEST AND RESET MEMORY TO SPECIFICATIONS. FOCUS.		360.00	200.00

Report Ref No. CS3/AIG17007286/Sgbs2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PROVIDE TOWING SERVICE.		150.00	120.00
			8,310.00	3,060.00
GRAND TOTAL			21,375.24	12,568.04
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				10,000.00

Report Ref No. CS3/AIG17007286/Sgbs2-1

YEANG WAI KEEN

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.