


SMRT Accident Vehicle Repair Estimates

ALG

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5667M
Ref. No : TAX/11/17/2155
Reg. Date : 11/05/2012
Vehicle Type : TAXI
Make : CHEVROLET EPICA 2.0 VCDI
Model : EPICA-2.0
Name of Driver : LER THIAN HAI
Type of Accident : SIDE SWIPE
Date / Time of Accident : 24/11/2017 06:50:00 PM
Accident Reported Date / Time : 25/11/2017 12:00:00 AM
Surveyor is Required? : No
Survey by :
Vehicle is Towed Back? : Yes
Towed Back Date/Time : 24/11/2017
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024093289
Special Instruction to ARC, if any :
TOWED \$40
Prepared Date : 25/11/2017 11:25:34 AM



Sebastian.
27/11/2017.
- Lump Sum Repair.
- Question Mark Item
Photo.
- Photo After Repair.

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : KL1LA69RJBB126968

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	676.00	0.00
Total Spray Painting Charges	756.00	0.00
Total Material Charges	2,154.12	2,198.08
Other Charges	660.00	0.00
TOTAL	4,246.12	0.00
Lum Sum Total	4,250.00	0.00
No. of Repair Days	4.00	0.00
Prepared / Adjusted By		3 days
Arc / Surveyor Sign Off Date	27/11/2017 09:00:04 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 27/11/2017 09:00:04 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH REAR PORTION	676.00	0.00 400
Total Labour	676.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR FENDER LH	378.00	0.00 200
TO REPSRAY REAR BUMPER	378.00	0.00 200
Total Spray Painting & Panel Beating	756.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	0.00 ✓
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 30
TO REMOVE / REFIT SEAT	120.00	0.00 60
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	0.00 110
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	660.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
96632799	LEFT	6504637	FENDER LH REAR	1	1,191.00	10.00	1,071.90	Replace	Replace ✓	No
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace ✓ NEC	No
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace ✓ NEC	No
96632652	REAR	6504619	MOLDING WINDSCREEN REAR	1	45.00	10.00	40.50	Replace	Replace ✓ NEC	No
	COMMON		SEALANT W/SCREEN	2	37.00	0.00	74.00	Replace	Replace ✓ NEC	No
93745100	REAR	6504569	BUMPER RR	1	1,238.00	10.00	1,114.20	Replace	Replace R	No
	REAR		BRACKET RR BUMPER SIDE LH	1	49.00	10.00	44.10	Replace	Replace ?	No
96851763	REAR	6504563	LAMP RR COMBINATION LH	1	415.00	10.00	373.50	Replace	Replace ✓ SCR	No
TOTAL MATERIALS							2,747.60	2,747.60		
TOTAL MATERIALS(Discounted)							2,154.12	2,198.08		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									