

ASS. REC. BY:

REF: CS/FCI 17022737 / Krb^{N2}

Special Instruction:

Surveyor

Kenneth

ASSIGNMENT (Office)

CW'S

From (Person):

Joanne Yung

of

FCI

Date/Time: 29/11/17 @ 4:29pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YN 9787J

Insured:

SHA 16674

at Workshop m/s

K-Kim Hin Auto

Tel:

6452 7018

of

160 Sin Ming Drive # 02-20

Policy No:

Claim No:

D17011024MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 27/11/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

5:33pm @ 29/11/17

Person Contacted:

Shuman

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

YN 9787J - X

SHA 16674 - CS/FCI 17007759 / R1gh3n2 - D.O.A: 13/04/2017

Revert Ann email.

REF: FCL

ASSIGNMENT

From: _____ Date: 01.12.2017

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: YN 9787J

at Workshop m/s: K Kim Hin

of: 160 Sin Ming Dr #03-20

Insured: _____

Policy No: _____


Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

12pm - 1pm

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 07 days Res.: Yes or No

Lum Sum: 1. B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: YN 9787J Yr Regn: 10 15

Type: M.Car / M.Cycle / Bus / Van / Truck / Taxi / Prime Mover /

Truck / Trailer or

Make: Isuzu XBU710R 4009

Colour: White A/C Insured / Std / NI / NA

Sp. Reading: 189833 T/Radio: Insured / Std / NI / NA

Eng No: _____

C/No: JH1HUCS3H00K014701

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modj: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 700R16x8
R: — (N)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: 7 mm

L/Bal: 7 mm

D.O.A: 27/11/17

Rear

R/Bal: 22 mm

L/Bal: 22 mm

D.O.I: 11/12/17

Survey held at: _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

4/12 File pass to Catherine

Confirm \$11370.45, 7 days
Red: 81966.40, 141.

✓ 9/6/18

RECEIVED 13 APR 2018

Date/Time File Pass to? ☐ : Preli. Report1) typist ☒ : Final Report

Date/Time File Return to?

2)

Report Format :

TPLump Sum / I.B.I. : \$ 11370.45Days Of Repair: 7Resurvey No. of Trip: 2

Add Fee:

☐ Site Insp \$

☐ Interview \$

☐ Tech. Insp \$

☐ Weekend \$

Survey Fee:

Transportation

) \$ + RS \$

) Photos

) Others

TOTAL

3x15.451704.4550504.5034399



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17022737/Krb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 29-11-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 1667U	Veh. Inspected	YN 9787J
Policy No.		Coverage (\$)	0.00
Claim No.	D17011024MFSH	Excess (\$)	0.00
Assign From	CWS (JOANNE YONG)	Assign Date	29/11/2017

2. Vehicle Particulars & Condition

Make & Model		C.C	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	27/11/2017	Inspection Date	
Survey held at	160 SIN MING DRIVE # 02-20,575722		
Repairer	K KIM HIN AUTOMOTIVE PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17011024MFSH

Our Ref: CS/PCN7022737/Krb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. YN 9787J

Please be informed that we had conducted the inspection of the above mentioned vehicle on 01/12/2017 at the premises of M/s K KIM HIM AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 13,336.85</u>
Revised Estimate Amount	: <u>S\$ 11,370.45</u>
"Check" Items Amount	: <u>S\$</u>
Market Value	: <u>S\$ -</u>
LTA Reimbursement Value	: <u>S\$ -</u>
Nett Value	: <u>S\$ -</u>

Description of Damage:

The vehicle sustained damages
at front n/s portion.



Yours faithfully
KENNETH
Automotive Assessor

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	28-11-2017	Our Ref No. D17011024MFSH
Accident Date	27-11-2017	Claim Type. Third Party
Insured Vehicle	SHA1667U	Third Party Vehicle. YN9787J
Survey Location	160 Sin Ming Drive #02-20SIN MING AUTOCITY	
Contact Person.	SHUMAN	
Contact No.	64527018/ 0	Fax No. 64583895
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	K. KIM HIN AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/231186)



PRI Documents



Close X

PRI Header Details

Claim No	D17011024MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & K. KIM HIN
Workshop Name	K. KIM HIN AUTO PTE LTD (Contact Person : SHUMAN)	Survey Location & Contact Details	160 Sin Ming Drive #02-20SIN MING AUTOCITY Mobile: 0 , Phone: 64527018 , Fax: 64583895 EmailId: ADMIN1@KKIMHIN.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA1667U	TP Vehicle No	YN9787J
PRI Recieved Date	28-11-2017 08:26:17 PM	Surveyor Appointed Date	29-11-2017 04:28:29 PM	Surveyor Accept Date	29-11-2017 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	29-11-2017	Upload Survey Report *:	Choose File
------------------------------------	--	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
----------------	----------------------	-------------------------------------

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	5743N
Vehicle Details	
Vehicle No.	YN9787J
Vehicle to be Exported	No
Intended De-registration Date	27 Nov 2017
Vehicle Make	HINO
Vehicle Model	HINO XZU710R-HKFMS3
Primary Colour	White
Manufacturing Year	2015
Engine No.	N04CUS24372
Chassis No.	JHHUCS3H00K014701
Maximum Power Output	-
Open Market Value	\$29,058.00
Original Registration Date	21 Oct 2015
First Registration Date	21 Oct 2015
Transfer Count	0
Actual ARF Paid	\$1,453.00
Intended PARF Rebate Details	
PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00
Intended COE Rebate Details	
COE Expiry Date	20 Oct 2025
COE Category	C - Goods Vehicle & Bus
COE Period(Years)	10
PQP Paid	\$4,855.00
COE Rebate Amount	\$3,833.00
Total Rebate Amount	\$3,833.00

The information contained herein is correct as at 27 Nov 2017

OK

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,

Sin Ming AutoCity, Singapore 575722

Tel: 6452 7018 Fax: 6458 3895

Email: service@kkinhin.com.sg

No. : 29331

Vehicle Insured : SHA 1667 U

Accident Date : 27-Nov-2017

Date : 29-Nov-2017

Our Ref : 170861 (FIRST) / SHUMAN

PAGE : 1

YU LI CONSTRUCTION PTE LTD
Singapore

Not Authored
1. B.1
Revised By pcam 7 days

ESTIMATED COST OF REPAIR FOR HINO XZU710R-HKFMS3 4009CC (2015) YN9787J

1 pc	front bumper	B ₁	773.85	✓
1 pc	n/s front bumper bracket	B ₁	342.90	✓
1 pc	n/s front bumper foglamp and bracket	M/S	350.35	✓
1 pc	n/s headlamp assy and lower garnish	CM	1,217.60	✓
1 pc	front grille		755.70	7/
1 pc	front grille logo		108.15	7/
1 pc	front panel (outer)	B ₁	898.20	✓
1 pc	front panel (inner)		1,470.00	7x
1 pc	front panel "HINO" sticker	M ₁	66.45	✓
1 pc	front panel "300" sticker	M ₁	66.45	✓
1 pc	n/s front corner panel	B ₁	647.86	7
1 pc	n/s front door	B ₁	1,980.00	✓
1 pc	n/s front door lower hinge	B ₁	135.00	✓
1 pc	n/s front door "616" sticker	M ₁	66.95	✓
1 pc	n/s front door "EURO 5" emblem	M ₁	78.15	✓
1 pc	n/s front door step garnish	CM	265.00	✓
1 pc	aircon condenser	TTIPu	1,560.00	✓
1 pc	aircon condenser bracket		310.00	7
1 pc	aircon fan assy	CM/T ₂	480.00	✓
1 pc	aircon liquid pipe		235.00	7
			11,807.61	
		Less 10% :	-1,180.76	
			10,626.85	
1 pc	front panel company sticker	M ₁	180.00	sn 1065n
1 pc	n/s front door company sticker	M ₁	180.00	sn 1265n

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications are allowed
- Supplemental items must be surveyed and is subject to approval from Insurance Company

Acknowledgement:

Signature:

Date:

Con't Page 2 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : SHA 1667 U
Our Ref : 170861

Page : 2
No. : 29331

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

700
900.00

To remove door's fittings

80.00 60

To putty and respray on affected
portions.

1,200.00 1000

To remove aircon condenser, pipes
and driers. Vaccum and recharge gas

120.00 100

To focus headlamps. To check front
wiring and lighting operation.

50.00 20

Total : S\$13,336.85
=====

Singapore Dollars Thirteen Thousand Three Hundred
and Thirty Six and Cents Eighty Five Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

No. : 29331

Vehicle Insured : SHA 1667 U
Accident Date : 27-Nov-2017

Date : 29-Nov-2017

Our Ref : 170861 (FIRST) / SHUMAN

PAGE : 1

YU LI CONSTRUCTION PTE LTD
Singapore

Not Authorised
1. B1
Refused By person 7 days

ESTIMATED COST OF REPAIR FOR HINO XZU710R-HKFMS3 4009CC (2015) YN9787J

1 pc front bumper	B1 773.85	✓
1 pc n/s front bumper bracket	B1 342.90	✓
1 pc n/s front bumper foglamp and bracket	M/S 350.35	✓
1 pc n/s headlamp assy and lower garnish	CM 1,217.60	✓
1 pc front grille	M/S 755.70	✓
1 pc front grille logo	M 108.15	✓
1 pc front panel (outer)	B1 898.20	✓
1 pc front panel (inner)	R 1,470.00	XX
1 pc front panel "HINO" sticker	M 66.45	✓
1 pc front panel "300" sticker	M 66.45	✓
1 pc n/s front corner panel	M/S CM 647.86	✓
1 pc n/s front door	B1 1,980.00	✓
1 pc n/s front door lower hinge	B1 135.00	✓
1 pc n/s front door "616" sticker	M 66.95	✓
1 pc n/s front door "EURO 5" emblem	M 78.15	✓
1 pc n/s front door step garnish	CM 265.00	✓
1 pc aircon condenser	TTIP 1,560.00	✓
1 pc aircon condenser bracket	B1 310.00	✓
1 pc aircon fan assy	CM/T2 480.00	✓
1 pc aircon liquid pipe	L 235.00	XX
	11,807.61	
	Less 10% : -1,180.76	
	10,626.85	

1 pc front panel company sticker
1 pc n/s front door company sticker

M 180.00 sn 10012
M 180.00 sn 12012

Supplementary Item

1pc n/s Front step garnish bracket 68.30
1pc n/s Fog Lamp Cover 78.20
1pc n/s Fog Lamp Bracket 51.40

Con't Page 2 ...

金興(龔)汽車私人有限公司160 Sin Ming Drive, #02-18/19/20/21,
Sin Ming AutoCity, Singapore 575722

Tel: 6452 7018 Fax: 6458 3895

Email: service@kkimhin.com.sg

Vehicle Insured : SHA 1667 U
Our Ref : 170861Page : 2
No. : 29331To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.900.00 *For*

To remove door's fittings

80.00 *601*To putty and respray on affected
portions.1,200.00 *1000*To remove aircon condenser, pipes
and driers. Vacuum and recharge gas120.00 *1001*To focus headlamps. To check front
wiring and lighting operation.50.00 *201*Total : S\$13,336.85Singapore Dollars Thirteen Thousand Three Hundred
and Thirty Six and Cents Eighty Five Only*13514.96*

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

*10102.61 s/parts
+ 197.90 supp**10300.51
- 10%**9270.45 s/parts
220.00 SW
+ 1880.00 Labour**11370.45 ✓ ok*

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Vehicle Insured : SHA 1667U
Accident Date : 27-Nov-2017

Date : 07-Dec-2017

Our Ref : 170861 (FIRST) / SIMON

YU LI CONSTRUCTION PTE LTD
Singapore

SUPPLEMENTARY ITEMS FOR HINO XZU710R-HKFMS3 YN 9787J

1 pc	n/s Front Step Garnish Bracket	0.7	\$	68.30	✓
1 pc	n/s Front Fog Lamp Cover	nd	\$	78.20	✓
1 pc	n/s Front Fog Lamp Bracket	By	\$	51.40	✓

				\$ 197.90	
				Less 10%: - \$ 19.79	

Total:				\$ 178.11	

Note: Amount quoted above is subjected to prevailing GST at time of tax invoice.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17022737/Krbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 23-04-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 1667U	Veh. Inspected	YN 9787J	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17011024MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	29/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	ISUZU XZU710R	c.c	4009	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JHHUCS3H00K014701	Colour	WHITE	
Odometer	189833	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	700 R16X8	FIRESTONE	7 mm	
L/H Front Tyre	700 R16X8	FIRESTONE	7 mm	
R/H Rear Tyre	700 R16X8 (D)	FIRESTONE	2/2 mm	
L/H Rear Tyre	700 R16X8 (D)	FIRESTONE	2/2 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/11/2017	Inspection Date	01/12/2017	
Survey held at	160 SIN MING DRIVE # 02-20,575722			
Repairer	K KIM HIN AUTOMOTIVE PTE LTD			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 9787J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	BENT	773.85	773.85
1	N/S FRONT BUMPER BRACKET	BENT	342.90	342.90
1	N/S FRONT BUMPER FOGLAMP AND BRACKET	MISSING	350.35	350.35
1	N/S HEADLAMP ASSY AND LOWER GARNISH	CRACKED	1,217.60	1,217.60
1	FRONT GRILLE	MTG CRACKED	755.70	755.70
1	FRONT GRILLE LOGO	NECESSARY	108.15	108.15
1	FRONT PANEL (OUTER)	BENT	898.20	898.20
1	FRONT PANEL (INNER)	TO REPAIR SEE LABOUR	1,470.00	-
1	FRONT PANEL "HINO" STICKER	NECESSARY	66.45	66.45
1	FRONT PANEL "300" STICKER	NECESSARY	66.45	66.45
1	N/S FRONT CORNER PANEL	MTG CRACKED	647.86	647.86
1	N/S FRONT DOOR	BENT	1,980.00	1,980.00
1	N/S FRONT DOOR LOWER HINGE	BENT	135.00	135.00
1	N/S FRONT DOOR "616" STICKER	NECESSARY	66.95	66.95
1	N/S FRONT DOOR "EURO 5" EMBLEM	NECESSARY	78.15	78.15
1	N/S FRONT DOOR STEP GARNISH	CRACKED	265.00	265.00
1	AIRCON CONDENSER	TWISTED / PUNCTURE	1,560.00	1,560.00
1	AIRCON CONDENSER BRACKET	BENT	310.00	310.00
1	AIRCON FAN ASSY	CRACKED / JAMMED	480.00	480.00
1	AIRCON LIQUID PIPE	SERVICEABLE	235.00	-
1	N/S FRONT STEP GARNISH BRACKET (ADDITIONAL)	DISTORTED	68.30	68.30
1	N/S FRONT FOG LAMP COVER (ADDITIONAL)	DENTED	78.20	78.20
1	N/S FRONT FOG LAMP BRACKET (ADDITIONAL)	BENT	51.40	51.40
	LESS 10% DISCOUNT		-1,200.55	-1,030.06
			10,804.96	9,270.45
SPECIAL NETT ITEMS				
1	FRONT PANEL COMPANY STICKER (SN)	NECESSARY	180.00	100.00

Report Ref No. CS/FCI17022737/Krbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	N/S FRONT DOOR COMPANY STICKER (SN) <u>LABOUR</u> TO REMOVE,CUT OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW AFFECTED PARTS.INCLUSIVE OF THE REPAIR OF FRONT PANEL (INNER). TO REMOVE DOOR'S FITTINGS. TO PUTTY AND RESPRAY ON AFFECTED PORTIONS. TO REMOVE AIRCON CONDENSER,PIPES AND DRIERS.VACCUM AND RECHARGE GAS. TO FOCUS HEADLAMPS.TO CHECK FRONT WIRING AND LIGHTING OPERATION.	NECESSARY	180.00	120.00
			360.00	220.00
			900.00	700.00
			80.00	60.00
			1,200.00	1,000.00
			120.00	100.00
			50.00	20.00
			2,350.00	1,880.00
GRAND TOTAL			13,514.96	11,370.45
RECOMMENDED COST OF REPAIRS				11,370.45

Report Ref No. CS/FCI17022737/Krbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.