



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Kindly Help to arrange
Surveyor to Survey this
Vehicle Thanks

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLK MND BUILDING
SINGAPORE 069110
Registration No : SLN3249P
Chassis No : JHMGK3850HX200455
Model : JAZZ 1.3LXR CVT 17YM
Owner's Name : HEAP SENG GROUP PTE. LTD.
Ins Policy No. :
Date of Accident : 24/11/2017

Document No. : SQT17004796 Page 1
Date : 24. Nov 2017
Customer No. : WZE011
Svc Advisor : LIM CHOU SIONG
Engine No : L13B11020305
Date | Time : 24. Nov 2017 12:34:22 PM
Surveyor Name :
Survey Date :

Authorisation Date: Clients hence notify
the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during resurvey
- To sign and seal to confirmation

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO): OWNER: HEAP SENG GROUP PTE. LTD. OWNER INSURER: TOKIO MARINE INSURANCE SINGAPORE L ACC DATE: 24/11/2017 SURVEYED BY: DATE: REF NO: TP INSURER: EQ INSURANCE COMPANY LTD TP VEH: SGF3353Y						
73127-TY0-000	RUBBER CWINDSHIELD DAMPER	1	11.20	25	8.40	0.59	8.99
73214-T5A-013	RUBBERWINDSHIELD DAMPER	2	6.20	25	9.30	0.65	9.95
73226-SZW-000	DAMPERSTD 5X5	1	8.30	25	6.22	0.44	6.66
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
68100-TAR-U10ZZ	TAILGATE COMP	1	716.30	25	537.22	37.61	574.83
74440-T5A-003	WEATHERSTRIPTAILGATE	1	92.30	25	69.22	4.85	74.07
74801-T5A-013	LOCK ASSYTAILGATE	1	173.20	25	129.90	9.09	138.99
74813-T5A-003	STRIKER ASSYTAILGATE	1	24.70	25	18.52	1.30	19.82
74830-T5A-000	CABLETAILGATE OPENER	1	24.60	25	18.45	1.29	19.74
84440-T5A-J02ZA	LINING ASSYTAILGATE LOWER	1	97.00	25	72.75	5.09	77.84
84441-T5A-003ZB	POCKETTAILGATE LINING PULL	1	4.90	25	3.67	0.26	3.93
75722-T5L-T01	EMBLEMRR.	1	10.30	25	7.72	0.54	8.26
33500-T5A-J02	TAILLIGHT ASSYR.	1	212.50	25	159.37	11.16	170.53
33550-T5A-J02	TAILLIGHT ASSYL	1	212.50	25	159.37	11.16	170.53
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.15	48.15
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
04715-T5A-000ZZ	FACERR.BUMPER	1	492.70	25	369.52	25.87	395.39
71502-T5A-000	GARNISHR.RR.BUMPER	1	6.30	25	4.72	0.33	5.05
71507-T5A-000	GARNISHL.RR.BUMPER	1	6.30	25	4.72	0.33	5.05
71593-T5A-000	SPACERR.RR.BUMPER	1	11.50	25	8.62	0.60	9.22



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLK MND BUILDING
SINGAPORE 069110
Registration No : SLN3249P
Chassis No : JHMGK3850HX200455
Model : JAZZ 1.3LXR CVT 17YM
Owner's Name : HEAP SENG GROUP PTE. LTD.
Ins Policy No :
Date of Accident : 24/11/2017

Document No. : SQT17004796 Page 2
Date : 24. Nov 2017
Customer No. : WZE011
Svc Advisor : LIM CHOU SIONG
Engine No : L13B11020305
Date | Time : 24. Nov 2017 12:34:22 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
71598-T5A-000	SPACERL.RR.BUMPER	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIPBUMPER	5	2.00	25	7.50	0.53	8.03
66100-TAR-T00ZZ	PANEL COMPRR.	1	314.10	25	235.57	16.49	252.06
84640-T5A-003ZA	LINING ASSYRR.PANEL	1	60.80	25	45.60	3.19	48.79
Sum Item					2309.98	161.72	2,471.70
BOSUN	SUNDRIES	1	30.00	10	30.00	2.10	32.10
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	80.00	✓	80.00	5.60	85.60
BOBC	BODY UNDERSIDE COATING (N)	1	100.00	?	100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	130.00	✓	130.00	9.10	139.10
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00	180 ?	250.00	17.50	267.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	300.00	✓	300.00	21.00	321.00
BOMISC1	REMOVE, INSTALL & RESET REAR VIEW CAMERA.(N)	1	350.00	✓	350.00	24.50	374.50
BMI02D	REMOVE & INSTALL REAR COMPARTMENT LININGS, RR1	1	350.00	✓	350.00	24.50	374.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	380.00	✓	380.00	26.60	406.60
BKRP02M	CUT OFF & RENEW RR PANELREPAIR RR FLOOR PANEL,	1	2700.00	1120-1960	2700.00	189.00	2889.00
BP06R	SPRAY PAINTING ON TAILGATE, RR BUMPER, RR PANEL,	1	2900.00	1350	2900.00	203.00	3103.00
BOJSE	BODY JOINT SEALANT.	1	80.00	?	80.00	5.60	85.60
Sum Labor					7650.00	535.50	8,185.50

Survey By

Date & Time

Excess

Status

Signature

Total Amount 9,959.98 697.22 10,657.20

Total (Inclusive of GST) 10,657.20

Printed on 28/11/2017 8:28:08 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)