



Think One Autocare Pte Ltd

18 Defu Ave 2 Singapore 539522

Tel: 6844 3300 Fax: 6842 4988

ROC : 201322501G

ESTIMATE

GGB7669P TOYOTA HIACE 3.0DX DIESEL TURBO MT/2WD LGV

Page No. : 1 of 1

No	Description of Parts	Condition	Estimate By Workshop	Adjusted (\$)
<u>PARTS DESCRIPTION</u>				
1	FRONT BUMPER ASSY / Cut		\$ 1,886.00	/
1	FRONT BUMPER BRACKET X		\$ 168.00	
1	FRONT BUMPER REINFORCEMENT X 4 NV		\$ 288.00	
1	FRONT LEFT HEADLAMP / SCR		\$ 1,375.00	/
2	HEADLAMP BRACKET X 4 NV		\$ 168.00	
2	FRONT LEFT DOOR HINGES X 4 NV		\$ 220.00	
1	FRONT LEFT DOOR STEP GARNISH / Cut		\$ 268.00	/
1	FRONT LEFT FRONT DOOR X Repair.			
<u>SPECIAL NETT ITEMS</u>				
18	FRONT BUMPER CLIPS / MCL		\$ 60.00	/
<u>LABOUR</u>				
1	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN AFFECTED AREA & REPLACE ACCIDENT DAMAGE PARTS		\$ 850.00	400
2	TO PUTTY & SPRAY PAINTING REAR PORTION		\$ 800.00	250
3	LABOUR FOR DISMANTLE & INSTALL FRONT BUMPER		\$ 80.00	X NV
4	LABOUR FOR DISMANTLE & INSTALL HEADLAMP		\$ 80.00	30
				680
3 Days . Lump Sum Repair After repair photos. Guo Qiang - 82880282 Guo Qiang@lkk auto. com 04/12/17				
			\$4,500.00	
RECPMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature
Date: