

SMRT Accident Vehicle Repair Estimates



Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SG5579C
Ref. No : BUS/11/17/5039
Reg. Date : 28/11/2017
Vehicle Type : DOUBLE DECK
Make : VOLVO
Model : VOLVO
Name of Driver : Mohd Hafizie Bin Yahya
Type of Accident : OTHERS
Date / Time of Accident : 27/11/2017 10:25:00 PM
Accident Reported Date / Time : 27/11/2017 12:00:00 AM
Surveyor is Required? : Yes
Survey by : AIG
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No :
Special Instruction to ARC,if any :

SG5579C - FRONT LEFT PORTION (EDGE)

SLF5372U (TP) - INSURED WITH AIG

Prepared Date : 28/11/2017 10:45:54 AM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : Mileage : 0
Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	1,325.00	795.00
Total Spray Painting Charges :	616.00	528.00
Total Material Charges :	1,149.28	1,149.28
Other Charges :	0.00	0.00
TOTAL :	3,090.28	2,472.28
Lum Sum Total :	0.00	0.00
No. of Repair Days :	4.00	3.00
Prepared / Adjusted By :		
Arc / Surveyor Sign Off Date :	28/11/2017 02:31:39 PM	28/11/2017 02:55:24 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 28/11/2017 11:45:07 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	1,325.00	795.00
Total Labour	1,325.00	795.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	616.00	528.00
Total Spray Painting & Panel Beating	616.00	528.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
ATP-03155			N/S CORNER BUMPER CL2	1	947.85	10.00	853.06	Replace	Replace ✓ CRK	No
ATP-02961			LOWER FRONT DOME CL2	1	6,325.88	100.00	0.00	Repair	Repair R	No
ATP-02806			N/S CORNER DEFLECTOR	1	329.13	10.00	296.22	Replace	Replace ✓ CRK	No
ATP-02812			FRT N/S LIGHT BEZEL CL2	1	290.03	100.00	0.00	Repair	Repair R	No
TOTAL MATERIALS							1,149.28	1,149.28		
TOTAL MATERIALS(Discounted)							1,149.28	1,149.28		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									