

TRANS-CAB AUTO SERVICES PTE LTD

AAD1711-321

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB7588U - AXA

Not Authored
11 Sep @ 3300h

Vehicle No.:

SHB7588U - JHOW

Chassis No.:

KL1LA69RJBB092924

Vehicle Make:

CHEVROLET

Vehicle Model:

CHEVROLET EPICA 2.0

Date of Accident :

29.11.2017

Third Party Insurer :

AXA

PART**LIST**

1	1	Front Bumper	\$	<i>Br 121</i> 1,202.00 ✓
2	1	Front Bumper Reinforcement	\$	<i>R</i> 295.25 X
3	1	Front Bumper Lower Absorber	\$	<i>Sn</i> 180.00 X
4	1	Front Bumper Fog Lamp Outer Cover LH	\$	<i>Sn</i> 32.40 X
5	1	Front Bumper Lower Grille	\$	<i>Sn</i> 78.00 X
6	1	Front Bumper Lower Stiffener	\$	<i>R</i> 134.37 X
7	1	Front Bumper Retainer LH	\$	<i>Sn</i> 102.00 X
8	1	Front Headlamp LH	\$	<i>Sn</i> 816.00 X
9	1	Front Fender LH	\$	<i>R</i> 837.60 ✓
10	1	Front Fender Liner LH	\$	<i>D.1</i> 47.00 ✓
11	1	Resonator (B/S Fender LH) AIR BOX	\$	<i>Sn</i> 134.67 X
12	1	Resonator Hose	\$	<i>Sn</i> 37.00 X
13	1	Radiator Grille (Grille A-Rad)	\$	<i>Sn</i> 367.00 X
14	1	Bonnet	\$	<i>R</i> 1,250.00 X
15	1	Bonnet Moulding	\$	<i>Sn</i> 161.97 X
16	1	Front Shock Absorber Assy LH	\$	<i>Sn</i> 216.17 X
17	1	Front Lower Arm LH	\$	<i>Sn</i> 283.00 X
18	1	Front Knuckle Arm LH	\$	<i>Sn</i> 230.00 X
19	1	Side Rocker Panel Garnish LH	\$	<i>R</i> 236.40 X
20	1	Front Door LH	\$	<i>R</i> 1,133.00 X
21	1	Front Side View Mirror LH	\$	<i>Net/Br</i> 939.00 ✓

TOTAL	\$	8,712.83
10%	\$	871.28
	\$	7,841.55

Special Nett

1	1 Set Front Bumper Fastener Clip	\$	<i>Br</i> 30.00 ✓
2	1 Set Front licence plate with holder	\$	<i>na</i> 192.00 X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1711-321**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB7588U - AXA

3	1 Set Radiator Grille Top Cover Clip	\$	<i>nn</i>	10.00	X
4	1 Set Radiator Grille clip	\$	<i>nn</i>	35.00	X
5	1 Set Front Fender Liner Clip	\$	<i>nn</i>	30.00	X
6	1 Door Sticker "Trans-cab"	\$	<i>nn</i>	80.00	<i>6000</i>
7	1 Front Tyre LH	\$	<i>nn</i>	360.00	X
8	1 Front Wheel Rim LH	\$	<i>nn</i>	254.00	X
9	1 Front Wheel Rim Hub Cap LH	\$	<i>nn</i>	166.30	X

TOTAL	\$	1,157.30
TOTAL PARTS	\$	8,998.85

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$ 2,800.00 *500*

To Rust-Proofing Of The Affected Areas.

\$ 220.00 *300*

Putty and Spray Painting Of The Affected
Portion.

\$ 2,700.00 *700*

To Check Electrical Lighting Concerned.

\$ 170.00 *150*

To dismantle and refit front end suspension,
undercarriage parts, final checking and testing.

\$ *nn* 380.00 X

To check steering geometry and computer wheel
alignment

\$ 220.00 *600*

To transfer of tire, rim and on wheel balancing.

\$ *nn* 170.00 X

Towing fees

\$ *nn* 120.00 X

TOTAL	\$	6,780.00
Over All Total	\$	15,778.85

REPAIR DAYS *10 DAYS*
4 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before
- To display (stamped part(s) during resurvey
- Part given are subject to confirmation
- No repair modification(s) is allowed
- Supply of part(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: