

ASS. REC. BY:

REF: CS/MSG17022851/Dvb

Special Instruction:

Surveyor:
Merimen

Bryen

ASSIGNMENT (Office)

From (Person):

Lionel Tan

of

MSG

Date/Time:

11/12/17 @ 11:00am

Estimated Cost:

Bill to:

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJB1418T

Insured:

SJE 5371B

at Workshop m/s

Teamwork Garage

Tel:

6844 2475

of

53 Ubi Ave / #01-24, 108934

Policy No:

P27444762DMA

Claim No:

538376

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/11/2017

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time:

11:07am @ 11/12/17

Person Contacted:

Chris

Vehicle

☒ IN ☐ OUT

Date/Time	Action/Instruction
	(✓) Estimate
	SJB1418T-NA/MSG17022469/24-D.O.A: 23/11/2017
	SJE5371B-NA/MSG17022469/24-D.O.A: 23/11/2017
23/11/18	Send preli revised by merimen

DATE/TIME

REF:

2027

COE NOV 2017

ASSIGNMENT

From _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 85B 1418 T Yr Regn: Dec 2007
 Type: M.Ca / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: Volvo XC90 cc 2521

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 70097 T/Radio: Insured / Std / NI / NA

Eng/No: B5254T4194102

Ci/No: YV2CZ595781433602

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size F: 235/60R18

R: — 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Yokohama

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 23/11/2017 D.O.I. 01/12/2017

Survey held at Technic Park Ubi

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

03/05/18 M31G 8JE 5371 B
 Jumper 215 74501 - with 5 days of repair. (Red 12,856, 637)

RECEIVED 03 MAY 2018

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 5

1)

☐ : Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

Survey Fee:

2) 3/5 - typist

Add Fee: ☐ Site Insp (\$

Transportation:

Report Format: merimen

Lump Sum / I.B.I: (\$ 7450/2)

☐ Interview (\$

) Photos

☐ Tech. Invs (\$

) Other:

☐ Weekend (\$

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Alt Assigned	Adj Not	Adj Submitted	Ins Auth'd	Status
Main	24 Nov 2017		01 Dec 2017 11:00 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured: **TAN SIEW HOCK CALVIN**, ID: S1596099Z, Tel: +6597453039, Email: NOEMAIL

Main Claimant: **LAU MARY**, ID: S7210405F

Vehicle Reg. No.: **SJB1418T** Date of Loss: 23/11/2017 17:00 - :59

Claim Type: **TP / 538376** Policy/Cover Note No.: P27494762DMA (Comprehensive)
Coverage: 29/04/2017 - 28/04/2018

Vehicle Reg. No. (Insured): **SJE5371B** Policy No. (Claimant):
Excess:

Repairer: **Teamwork Garage Pte Ltd (HQ)** 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475

Handling Insurer: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: +65 6827 7888 ... [Handled by **Lionel Tan Tian Pei** - 6643 1307]

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... **[Imm.Advice due 02/12/2017]**

Driver/Custodian (Insured): **TAN SIEW HOCK CALVIN (54 / Male)**, NRIC: S1596099Z, Tel: +6597453039

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan Tian Pei

Date: 23 Apr 2018

Preliminary Advice

Insured Vehicle No	: SJE5371B		
TP Vehicle No	: SJB1418T	Accident Date	: 23/11/2017
Make	: VOLVO XC90	Assignment Date	: 01/12/2017
Date of Inspection	: 01/12/2017	Est. Duration of Repair	: 5.00
Inspection At	: TEAMWORK GARAGE PTE LTD (HQ) 53 UBI AVE 1 #01-24, PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,306.00
Revised Amount	:S\$	9,313.47
Check Items (Estimated)	:S\$	0.00
Total	:S\$	9,313.47

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

MSME17155867 / SNE Motor Pte Ltd - Kaki Bukit
ENTRY DATE & TIME: 24/11/2017 17:12

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 24/11/2017 17:12
Date Of Accident 23/11/2017 17:30
Exact Location Of Accident BUKIT TIMAH RD TOWARDS NEWTON.
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJB1418T
Insured/Policyholder
Name Of Registered Owner LAU MARY
NRIC No S7210405F
Email Address MARYL@SINGNET.COM.SG
Mobile Phone No (LOCAL) +65-96303212
Alternative Phone No OFFICE-96320330

Vehicle Particulars

Manufacturer VOLVO
Model XC90
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number S17MTPV01000838
Cover Note Number

Driver

Name of Driver LAU MARY
NRIC No S7210405F
Date Of Birth 24/03/1972
Occupation INDOOR
Date Of Driving Pass 21/10/2010
Driving Experience 7 YEARS AND 1 MONTH
Gender FEMALE
Mobile Number (LOCAL) +65-96303212
Fax Number
Contact Number OFFICE-96320330
Email Address MARYL@SINGNET.COM.SG

Address 9E BARKER ROAD
 Postcode 307421
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 3

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I WAS TRAVELLING ALONG BUKIT TIMAH ROAD TOWARDS NEWTON AT THE MIDDLE LANE. A VEHICLE IN FRONT OF ME SLOW DOWN AND STOPPED, I ALSO SLOWED DOWN MY CAR AND CAME TO A STOP WITHOUT ANY CONTACT AND A SAFE DISTANCE WITH THE FRONT VEHICLE. ALL OF A SUDDEN, I FELT AN IMPACT FROM THE REAR PORTION OF MY CAR. I GOT OFF MY CAR AND FIND THAT VEHICLE B SJE5371B HAD HIT ONTO MY CAR REAR PORTION.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJE5371B
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Name of Driver TAN SIEW HOCK CLAVIN
 NRIC/Passport Number S1596099Z
 Contact Number 97453039
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number
 Email Address

DETAILS OF INJURED PERSON 1

Name	LAU MARY
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SJB1418T
Were seat belts worn?	
Was injured conveyed to hospital by ambulance?	
Address	
Postcode	

DETAILS OF INJURED PERSON 2

Name	ISABELLA FISKE HARRISON
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SJB1418T
Were seat belts worn?	
Was injured conveyed to hospital by ambulance?	
Address	
Postcode	

Accident Sketch Plan Pg. 1

SKETCH PLAN

Bukit Timah Road Newton



A: 3881481

B: 3853712

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along Bukit Timah Road Newton at the middle lane. A vehicle in front of me slowed down and stopped. I also slowed down my car and came to a stop. Without my consent and a safe distance with the front vehicle. But at a sudden, I felt an impact from the rear portion of my car. I got off my car and found that vehicle B's SJE 53712 had hit onto my car rear portion.

DECLARATION

I/We declare that foregoing particulars are true in every respect.

Policeholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre/Personnel's Signature
Name:
NRIC/PIN No.:

Teamwork

Accident Sketch Plan Pg. 1



SOMPO

Sompo Insurance Singapore Pte. Ltd.

50 Market Place, #05-01/02 Singapore Land Tower, Singapore 048922
Tel: 6511 0500 / Fax: 6512 3362 | Website: www.sompo.com.sg
Co. Reg. No. 193054000 | GST Reg. No. S101040000

Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1950
ROAD TRANSPORT ACT, 1967 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1950 (MALAYSIA)

Cert No./Policy No. : D17MTPV01000638
 Insured : LAU MARY
 Motor Car (Registration No.) : SJB1418T
 Cover : Comprehensive - ExcelDrive Gold Plan
 Policy Commencement Date : 09 JANUARY 2017 00:00
 Policy Expiry Date : 06 JANUARY 2018 23:59
 Maximum Liability (Section I) : Market value at time of loss
 Excess* : \$1200 - Section I
 (Waived up to \$51,000 Standard Excess each claim at ExcelDrive Workshops for first two claims per policy year)
 Voluntary Excess* : N/A
 Windscreen Excess* : N/A
 Loss of Use : Per Policy Schedule
 * Subject to GST wherever applicable

Persons or Classes of Persons entitled to drive*

1. The Insured.
2. Any other person who is driving on the Insured's order or with his permission.
3. In the event of the death of the Insured,
 - a. any member of the Insured's family, or a paid driver who has been driving the Motor Car during the life of the Insured and permission to drive had not been withdrawn prior to the death of the Insured; and
 - b. any other person who has been given permission to drive the Motor Car prior to the death and such permission had not been withdrawn by the Insured.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Car or has been so permitted and is not disqualified by order of a Court of Law or by means of any enactment or regulation to that effect from driving the Motor Car. And provided further that the Motor Car is registered under the Road Traffic Act (Chapter 276) and its registration under the Road Traffic Act (Chapter 276) has not been cancelled at the time of the accident, loss or damage.

Limitations As To Use

Use only for social, domestic and pleasure purpose and for the Insured's business. The Policy does not cover use for hire or reward, racing, pace-making, speed testing, reliability trial, the carriage of goods other than samples in connection with any trade or business or use for any purposes in connection with the Motor Trade.

ExcelDrive Workshops and Accident Reporting

It is a condition precedent to liability that the Insured shall call at the Company's Accident Reporting Center with the Motor Car within 24 hours of the accident or by the next working day thereafter.

All accident repairs to the Motor Car must be carried out at ExcelDrive Workshops; otherwise the claim is not payable under the Policy. For ExcelDrive Prestige Plan, accident repairs to the Motor Car can be carried out at any workshop other than ExcelDrive Workshops.

For the list of Accident Reporting Centres and ExcelDrive Workshops, please visit our website at www.sompo.com.sg or call our Emergency Hotline: (65) 6226 3323.

I/WE HEREBY CERTIFY that the policy to which this Certificate refers is issued in accordance with (1) the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1967 (Malaysia) and (2) the Policy Terms, conditions and exclusions of the Motor Car Policy ref MTP/28

Sompo Insurance Singapore Pte. Ltd.

Authorized Signatory

Date/Time of Issue : 29 DECEMBER 2016 13:52

IMPORTANT NOTICE

- Keep the Certificate in your Motor Car.
- Under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189), it shall be unlawful for any person to use or permit to permit any other person to use a motor vehicle without a valid policy of insurance under the Act.
- On the sale of the Motor Car or if for any reason the Insurance is terminated during its currency, the Insured must surrender the Certificate of Insurance and the Policy to the Insurance company. If the Certificate of Insurance has been lost or destroyed, a statutory declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).
- This Policy will automatically void once the Motor Car has been sold to another person. This Policy is not transferable to the new owner of the Motor Car.

Intermediary Code & Name : 11N03304 & HAN TEE TOON (MR.) CI Code: 22A J6DLPL4_RPDQHS/W

MSIG Insurance (Singapore) Pte Ltd
4 Shenton Way #21-01
SGX Centre 2
Singapore 068807

Vehicle number	SJB1418T
Make / Model	VOLVO/XC90
Chassis number	YV1CZ595781433620
Accident date	23 Novemembr 2017
Reference	1711-54

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	TAILGATE LOWER Dent	2144.10
2	TAILGATE LOWER HINGE Svc	2750.00 ✓
2	TAILGATE LOWER LOCK Svc	297.96 X
1	TAILGATE LOWER STRIKER Svc	668.04 X
1	TAILGATE LOWER INNER TRIM Svc	260.30 X
1	EMBLEM - XC90 Nec	1880.00 X
1	EMBLEM - 2.5 T Nec	113.70 ✓
1	TAILGATE LOWER GARNISH MS	94.80 ✓
2	LOWER TAILLAMP o/s broken M/S NH	1060.44 X
1	REAR BUMPER COVER Dent	298.10 893.52 ✓
2	REAR BUMPER INNER BRACKET NH	1469.10 1872.24 ✓
1	REAR BUMPER Dent	237.12 X
2	REAR BUMPER BRACKET NH	1195.43 1827.70 ✓
2	REAR BUMPER RETAINER Svc	118.56 X
1	REAR BUMPER INNER GUIDE broken	98.80 X
1	REAR BUMPER LOWER SKID PLATE Cut	421.56 ✓
1	REAR BUMPER SPONGE torn	456.69 ✓
1	TOW COVER Cut	402.00 516.72 ✓
1	END PANEL Dent	100.40 ✓
1	END PANEL INNER GARNISH NH	1055.10 1649.10 ✓
4	PDC SENSOR 2pc damaged 2pc NH	1757.64 X
1	REAR WEATHERSTRIP Nec	427.00 854.00 ✓
		147.80 310.70 ✓
	8326.08	18239.99
	7493.47	Less 10 %
		1823.99
		Subtotal
		16416.00
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
Balance B/F		#REF!
1 SET	REAR BUMPER CLIP Nec	60.00 301-
1	REAR NUMBER PLATE NH	70.00 NH
1	JOINT SEALANT Nec	150.00 401-
		701-
		Subtotal
		280.00
	Balance C/F	#REF!
S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
	Balance B/F	#REF!
1	CHECK REAR LIGHTNING , WIRING SYSTEM	60.00 301-
2	REMOVE AND REFIT REAR LING, TRIM AND GARNISH	200.00 801-
3	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 401-

4	REMOVE AND STRAIGHTEN REAR EXHAUST	150.00	NH
5	DIAGNOIS CHECK AND CLEAR FAULT CODE	500.00	NH
6	TRANSFER PARTS, ATTACHMENT FROM OLD LOWER TAILGATE	200.00	60/-
7	PANEL BEATING ON AFFECTED AREAS	1200.00	800/-
8	SPRAY PAINTING ON AFFECTED AREAS	1000.00	700/-
9	APPLY ANTI RUST ON AFFECTED AREAS	150.00	40/-
Subtotal		3610.00	
Grand total		#REF!	
		9313.47	
		L/S 7450/-	

01/12/2017 E 1400h

Not Antenna

L/S 5 days

1 yr

2 KIC Auto

Check part prices.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Nov 2017		01 Dec 2017 11:00 Edit Adj Rpt	S\$7,450.00 Edit Estimates	S\$7,450.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TAN SIEW HOCK CALVIN, ID: S1596099Z, Tel: +6597453039, Email: NOEMAIL								
Main Claimant:	LAU MARY, ID: S7210405F								
Vehicle Reg. No.:	SJB1418T	Date of Loss:	23/11/2017 17:00 - :59 [118 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 538376	Policy/Cover Note No.:	P27494762DMA (Comprehensive) Coverage: 29/04/2017 - 28/04/2018						
Vehicle Reg. No. (Insured):	SJE5371B	Policy No. (Claimant):							
		Excess:							
Repairer:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 31/12/2017]								
Driver/Custodian (Insured):	TAN SIEW HOCK CALVIN (54 / Male), NRIC: S1596099Z, Tel: +6597453039								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJB1418T (538376)**
[SJE5371B]
TP
LAU MARY
Nov 23 2017 5:00PM
[TAN SIEW HOCK CALVIN]
Teamwork Garage Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
View
[View in Browser](#)

Assessment Reports				1 per page	☒
No	Finalized On		Thumbnail	Print	
1	01/12/17 10:36	MSIG Insurance (Singapore) Pte. Ltd. (HQ) Accident Statement From: SC - Reg. No: SJE5371B, Claimant: TAN SIEW HOCK CALVIN	 Load HTM		
No	Finalized On		Thumbnail	Print	
1	23/04/18 10:48	LKK Auto Consultants Pte Ltd (HQ) Adjuster Immediate Advice	 Load HTM		
Photos/Images				3 per page	☒
No	Relabel/Reorder		Thumbnail	Print	
1	20/04/18 18:15	LKK Auto Consultants Pte Ltd (HQ) Rear View Left	 Load JPG	☒	
2	20/04/18 18:15	Rear View Right	 Load JPG	☒	
3	20/04/18 18:15	General View	 Load JPG	☒	
4	20/04/18 18:15	General View	 Load JPG	☒	
5	20/04/18 18:15	General View	 Load JPG	☒	
6	20/04/18 18:15	General View	 Load JPG	☒	
7	20/04/18 18:15	General View	 Load JPG	☒	
8	20/04/18 18:15	General View	 Load JPG	☒	
9	20/04/18 18:15	General View	 Load JPG	☒	
10	20/04/18 18:15	General View	 Load JPG	☒	
11	20/04/18 18:15	General View	 Load JPG	☒	
12	20/04/18 18:15	General View	 Load JPG	☒	
13	20/04/18 18:15	General View	 Load JPG	☒	
14	20/04/18 18:15	General View	 Load JPG	☒	
15	20/04/18 18:16	General View	 Load JPG	☒	
16	20/04/18 18:16	General View	 Load JPG	☒	
17	20/04/18 18:16	General View	 Load JPG	☒	
18	20/04/18 18:16	General View	 Load JPG	☒	
19	20/04/18 18:16	General View	 Load JPG	☒	
20	20/04/18 18:16	General View	 Load JPG	☒	
21	20/04/18 18:16	General View	 Load JPG	☒	
22	20/04/18 18:16	General View	 Load JPG	☒	
23	20/04/18 18:16	Odometer Reading	 Load JPG	☒	
24	20/04/18 18:16	Chassis Number	 Load JPG	☒	
25	20/04/18 18:16	Reinspection Photo	 Load JPG	☒	
26	20/04/18 18:16	Reinspection Photo	 Load JPG	☒	
27	20/04/18 18:16	Reinspection Photo	 Load JPG	☒	
28	20/04/18 18:16	Reinspection Photo	 Load JPG	☒	
29	20/04/18 18:16	Reinspection Photo	 Load JPG	☒	
30	20/04/18 18:16	Reinspection Photo	 Load JPG	☒	
31	20/04/18 18:16	Reinspection Photo	 Load JPG	☒	
32	20/04/18 18:16	Reinspection Photo	 Load JPG		

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				☒
33	20/04/18 18:16	Reinspection Photo	 Load JPG	☒
34	20/04/18 18:16	Reinspection Photo	 Load JPG	☒
35	20/04/18 18:16	Reinspection Photo	 Load JPG	☒
36	20/04/18 18:16	Reinspection Photo	 Load JPG	☒
37	20/04/18 18:16	Reinspection Photo	 Load JPG	☒
38	20/04/18 18:16	Reinspection Photo	 Load JPG	☒
39	20/04/18 18:16	Reinspection Photo	 Load JPG	☒
40	20/04/18 18:16	Reinspection Photo	 Load JPG	☒
41	20/04/18 18:16	Reinspection Photo	 Load JPG	☒
42	20/04/18 18:16	Reinspection Photo	 Load JPG	☒
43	20/04/18 18:16	Reinspection Photo	 Load JPG	☒
44	20/04/18 18:16	Reinspection Photo	 Load JPG	☒
45	20/04/18 18:16	Reinspection Photo	 Load JPG	☒
46	20/04/18 18:16	Reinspection Photo	 Load JPG	☒
47	20/04/18 18:16	Reinspection Photo	 Load JPG	☒
48	20/04/18 18:16	Reinspection Photo	 Load JPG	☒
49	20/04/18 18:16	Reinspection Photo	 Load JPG	☒
50	20/04/18 18:16	Reinspection Photo	 Load JPG	☒
51	20/04/18 18:16	Reinspection Photo	 Load JPG	☒
52	20/04/18 18:16	Reinspection Photo	 Load JPG	☒
53	20/04/18 18:16	Reinspection Photo	 Load JPG	☒
54	20/04/18 18:16	Reinspection Photo	 Load JPG	☒
55	20/04/18 18:16	Reinspection Photo	 Load JPG	☒
56	20/04/18 18:16	Reinspection Photo	 Load JPG	☒
57	20/04/18 18:16	Reinspection Photo	 Load JPG	☒
58	20/04/18 18:16	Reinspection Photo	 Load JPG	☒
59	20/04/18 18:16	Reinspection Photo	 Load JPG	☒
60	20/04/18 18:16	Reinspection Photo	 Load JPG	☒
61	20/04/18 18:16	Reinspection Photo	 Load JPG	☒
62	20/04/18 18:16	Reinspection Photo	 Load JPG	☒
63	20/04/18 18:16	Reinspection Photo	 Load JPG	☒
64	20/04/18 18:16	Reinspection Photo	 Load JPG	☒
65	20/04/18 18:16	Finishing Photo	 Load JPG	☒
66	20/04/18 18:16	Finishing Photo	 Load JPG	☒
67	20/04/18 18:16	Finishing Photo	 Load JPG	☒
68	20/04/18 18:16	Finishing Photo	 Load JPG	☒
69	20/04/18 18:16	Finishing Photo	 Load JPG	☒
70	20/04/18 18:16	Finishing Photo	 Load JPG	☒
71	20/04/18 18:16	Finishing Photo	 Load JPG	☒
72	20/04/18 18:16	Finishing Photo	 Load JPG	☒
73	20/04/18 18:16	Finishing Photo	 Load JPG	☒
74	20/04/18 18:16	Finishing Photo	 Load JPG	☒
75	20/04/18 18:16	Finishing Photo	 Load JPG	☒
76	20/04/18 18:16	Finishing Photo	 Load JPG	☒
77	20/04/18 18:16	Finishing Photo	 Load JPG	☒
78	20/04/18 18:16	Finishing Photo	 Load JPG	☒
79	20/04/18 18:16	Finishing Photo	 Load JPG	☒
80	20/04/18 18:16	Finishing Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	01/12/17 10:36	SJB1418T E-FILE, CERT OF INS, DL & IC From: SC - Reg. No: SJE5371B, Claimant: TAN SIEW HOCK CALVIN	 Load PDF	
2	01/12/17 10:41	PRI from Teamwork Garage	 Load PDF	
3	01/12/17 11:00	Survey Agree on SJE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17022851/DVBQ2

Date: 10/05/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: P27494762DMA

Claimant Vehicle No : SJB1418T

Insured Vehicle No : SJE5371B

Date of Loss: 23/11/2017

Nature of Claim: TP

Claim No: 538376

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJB1418T

Make & Model: VOLVO XC90, 2.5 T ABS AIRBAG (A)

Engine No: B5254T4194102

Reg. Date: 31/12/2007 (Man. Year: 2007)

Chassis No: YV1CZ595781433602

Colour: Grey

Odometer: 70097 km

Engine Capacity: 2521 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/60R18

Rear Tyre Size: 235/60R18

Front Left Side: Yokohama 5 mm

Rear Left Side: Yokohama 5 mm

Front Right Side: Yokohama 5 mm

Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,695.99	7,563.47	9,132.52	54.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,610.00	1,750.00	1,860.00	51.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,305.99	9,313.47	10,992.52	54.13
Approved Total (Overridden) (S\$)		7,450.00		
(S\$)	20,305.99	7,450.00	12,855.99	63.31
+ GST 7.00/7.00% (S\$)	1,421.42	521.50	899.92	63.31
Nett Amount (S\$)	21,727.41	7,971.50	13,755.91	63.31

INSPECTION

Date of Assignment: 01/12/2017

Date Inspected: 01/12/2017 Inspected At:

Teamwork Garage Pte Ltd (HQ)
53 Ubi Ave 1 #01-24, Paya Ubi Industrial
Park
Singapore 408934

Estimated Period of Repair: 5.0 days

Adjuster: BRYAN TANI**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 May 2018)
Parts:	M1-SUV	VOLVO XC90 2.5 T ABS AIRBAG (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJB1418T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE LOWER	Dented	2,750.00 FL	*2,144.10 FL
2	2		*TAILGATE LOWER HINGE	Serviceable	297.96 FL	*- FL
3	2		*TAILGATE LOWER LOCK	Serviceable	668.04 FL	*- FL
4	1		*TAILGATE LOWER STRIKER	Serviceable	260.30 FL	*- FL
5	1		*TAILGATE LOWER INNER TRIM	Serviceable	1,880.00 FL	*- FL
6	1		*EMBLEM -XC90	Necessary	113.70 FL	*113.70 FL
7	1		*EMBLEM -2.5T	Necessary	94.80 FL	*94.80 FL
8	1		*TAILGATE LOWER GARNISH	No such part	1,060.44 FL	*- FL
9	1		*LOWER TAILLAMP	O/S Broken / N/S Not Necessary	893.52 FL	*298.10 FL
10	2		*REAR BUMPER COVER	Dented (1 PCS ONLY)	1,872.24 FL	*1,469.10 FL
11	2		*REAR BUMPER INNER BRACKET	Not Necessary	237.12 FL	*- FL
12	1		*REAR BUMPER	Dented	1,827.70 FL	*1,195.83 FL
13	2		*REAR BUMPER BRACKET	Not Necessary	118.56 FL	*- FL
14	2		*REAR BUMPER RETAINER	Serviceable	98.80 FL	*- FL
15	1		*REAR BUMPER INNER GUIDE	Broken	421.56 FL	*421.56 FL
16	1		*REAR BUMPER LOWER SKID PLATE	Cut	456.69 FL	*456.69 FL
17	1		*REAR BUMPER SPONGE	Torn	516.72 FL	*402.00 FL
18	1		*TOW COVER	Cut	100.40 FL	*100.40 FL
19	1		*END PANEL	Dented	1,649.10 FL	*1,055.00 FL
20	1		*END PANEL INNER GARNISH	Not Necessary	1,757.64 FL	*- FL
21	2		*PDC SENSOR	2PCDeformed /2PCSNOTNECESSARY	854.00 FL	*427.00 FL
22	1		*REAR WEATHERSTRIP	Necessary	310.70 FL	*147.80 FL
23	1		*SET REAR BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
24	1		*REAR NUMBER PLATE	Not Necessary	70.00 FS	*- FS
25	1		*JOINT SEALANT	Necessary	150.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,519.99	8,396.08
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,824.00	832.61
Total Parts (\$\$)	16,695.99	7,563.47

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK REAR LIGHTING ,WIRING SYSTEM	New	60.00	30.00
2	REMOVE AND REFIT REAR LING ,TRIM AND GARNISH	New	200.00	80.00
3	REMOVE AND RENEW REAR REVERSE SENSOR	New	150.00	40.00
4	REMOVE AND STRAIGHTEN REAR EXHAUST	New	150.00	0.00
5	DIAGNOIS CHECK AND CLEAR FAULT CODE	New	500.00	0.00
6	TRANSFER PARTS ,ATTACHMENT FROM OLD LOWER TAILGATE	New	200.00	60.00
7	PANEL BEATING ON AFFECTED AREAS	New	1,200.00	800.00
8	SPRAY PAINTING ON AFFECTED AREAS	New	1,000.00	700.00
9	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	40.00
Gross Labour Cost (S\$)			3,610.00	1,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >