

22/03/2002

ASS. REC. BY:

REF: CS/ms617022921/Uv62

Special Instruction:

Survivor: Marais

ASSIGNMENT (Office)

Merimen

From (Person):

Christina Wang

of

Meru

Date/Time:

04-12-2017 10:05am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

XD 2935J

Insured:

XD 5857G

at Workshop m/s

Mah Lian Motor

Tel:

6282 3336

of

No. 38 Dafu Lane 9

Policy No:

A28711255MKC

Claim No:

538389

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

24.11.2017

CA / REV / REP. / REV 24 HRS WP

05.12.2017

H.O.D. Endorsement:

Date/Time:

04.12.2017 10:39am

Person Contacted:

Wan Ruo

Vehicle: IN OUT

Date/Time

Action/Instruction

(✓)

Estimate

Estimate not yet done, request merimen.

XD 2935J

CS/TML13053004 / mlyidi

R20A 1203B

XD 5857G - X

5/12/17

Informed Christina pending workshop by merimen

11/1/18

Send preli revised by merimen

MS16

Page: 9 of 08

Date: 5/12/17

Vehicle: XD2935J

Make: Mah Hian Motor

Model: No 38 Defu June 9

Engine: 12882

Color: White / Red

Seating: 6

Engine: 6

Chassis: FV51JJA00322

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: 18 Rim / STD A/Rim or

Tyre Size: R 10.00 R20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / RIR / SUMI

LTOYO / YOKO or 10.00 R20

Front: 5/5 5/5

Rear: 5/5 5/5

Surveyed at: 5/12/17

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Roodtop or

The U/C / Chassis frame / Body Structure affected due to collision

Policy Condition: The veh had commenced its repair at the time of inspection.

Balance Market Value: 30

QAC Accident Report: Consistent? Yes or No

GIA / PP / Seen: Consistent? Yes or No


Est. Repairs: 12 days

Sum Sum: 20

QA / REV / REP. / 24 HRS 'wp'

Date: 9/2018

Person Contacted:



8/1/18 Confirmed 23.000 with AH Yecl.
(Red 23, 256.28, 5010)

RECEIVED 14 JUL 2017

Preli. Report: ☐

Final Report: ☐

Days Of Repair: 12

Resurvey No. of Trip: 2

Survey Fee: 150

11/1- typst

Add Fee: ☐

merimen 23,000/2

160

Survey Department Check List (Case Handler)

Reference No.: CS MSG 17022922 UWB

Policy Type: OD/ TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer: (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 11/11/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17022922/Uvb

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 04-12-2017



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 5857G	Veh. Inspected	XD 2935J
Policy No.	A28711255MKC	Coverage (\$)	0.00
Claim No.	538389	Excess (\$)	0.00
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	04/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	24/11/2017	Inspection Date	05/12/2017
Survey held at	MAH LIAN MOTOR VEHICLE REPAIRER 38 DEFU LANE 9 SINGAPORE 539278		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Nov 2017		04 Dec 2017 10:05 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	T. T. CHUA CONSTRUCTION PTE LTD, Co. Reg. No.: 198901247D								
Main Claimant:	LIAN HENG HUAT TRADING & TRANSPORT, Co. Reg. No.: 33397600B								
Vehicle Reg. No.:	XD2935J	Date of Loss:	24/11/2017 17:00 - :59						
Claim Type:	TP / 538389	Policy/Cover Note No.:	A28711255MKC (Comprehensive) Coverage: 18/04/2017 - 17/04/2018						
Vehicle Reg. No. (Insured):	XD5857G	Policy No. (Claimant):							
Repairer:	Mah Lian Motor Vehicle Repairer (HQ) NO. 38 DEFU LANE 9, 539278 Defu Lane - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 05/12/2017]								
Driver/Custodian (Insured):	ZHU KONGZHAN (), NRIC: G7544337X, Tel: +6586182836								
Adj Asg. Remarks:	CLIENT CHOOSE MARCUS. PLS CALL MR GOH / MS SI HUI @62823336 BEFORE GO DOWN SURVEY.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 11 Jan 2018

Preliminary Advice

Insured Vehicle No	: XD5857G	Accident Date	: 24/11/2017
TP Vehicle No	: XD2935J	Assignment Date	: 04/12/2017
Make	: MITSUBISHI FV51JJD4RDEA	Est. Duration of Repair	: 12.00
Date of Inspection	: 05/12/2017		
Inspection At	: MAH LIAN MOTOR VEHICLE REPAIRER (HQ) NO. 38 DEFU LANE 9 SINGAPORE 539278		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	46,256.28
Revised Amount	:S\$	29,232.37
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00
Lump Sum Repair	:S\$	23,000.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

View Sent Message

This mail is associated with :

***XD2935J (538389)**
[XD5857G]

TP
LIAN HENG HUAT TRADING & TRANSPORT
Nov 24 2017 5:00PM
[T. T. CHUA CONSTRUCTIOON PTE LTD]
Mah Lian Motor Vehicle Repairer

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **05/12/2017 14:25 PM**.
To MSIG_CWSF1
Subject TP SURVEY XD 2935J

Dear Christina,

Please be informed that we have inspected the vehicle XD 2935J on 5/12/2017.

We are pending estimate from repairer.

Best Regards,
Veron Chen

DOCUMENTS SUMMARY

There are no documents.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Business
Owner ID	7600B

Vehicle Details

Vehicle No.	XD2935J
Vehicle to be Exported	No
Intended De-registration Date	05 Dec 2017
Vehicle Make	MITSUBISHI
Vehicle Model	FV51JJD4RDEA
Primary Colour	White
Manufacturing Year	2008
Engine No.	6M70419677
Chassis No.	FV51JJA00322
Maximum Power Output	-
Open Market Value	\$86,257.00
Original Registration Date	09 Sep 2008
First Registration Date	09 Sep 2008
Transfer Count	0
Actual ARF Paid	\$4,313.00

Intended PARF Rebate Details

PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00

Intended COE Rebate Details

COE Expiry Date	08 Sep 2018
COE Category	C - Goods Vehicle & Bus
COE Period(Years)	10
QP Paid	\$12,989.00
COE Rebate Amount	\$984.00
Total Rebate Amount	\$984.00

The information contained herein is correct as at 05 Dec 2017

OK

Cheap Car Insurance Renewal

Is your car insurance expiring soon?

Receive best quotations from multiple insurers in as little as 2 hours.

Username / Email Add
 password

[Sign Up New Account](#)
[Forgot Password](#)

Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

New 5 Year Coe Renewal 2008 Toyota Altis 1.6A



\$2500 Downpayment Monthly
 From \$638 Onwards. Lowest
 3.88% P.A @ GV Cars Financing.
 GV Credit Pte Ltd - StarAd

PRIME MOTOR & LEASING

RENTING OR PURCHASING YOUR FAVORITE CAR OR VAN
 With over 50 units of vehicles
 to choose from, ranging from
 all European to Japanese Models

Browse by Category

Sort by Date Posted 20 results/page

1 vehicles

mitsubishi fv51

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	mitsubishi fv51		Any	Any	2008	Any	Any	Any	Available



**Mitsubishi Fuso FV51J (COE
 till 09/2022)**
Fuel Type: Diesel
New 5 Yr COE. New Paintwork. Vehicle In Great Condition!

Convince Auto

Posted: 01-Dec-2017 Tags: 2008 Mitsubishi Fuso, 2008 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso, Fuso,
 Used Mitsubishi

Save this search criteria, to get email alerts whenever a match is found.

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
--	------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used mitsubishi fv51, mitsubishi fv51 Singapore, used mitsubishi fv51 Singapore, used mitsubishi fv51, used vehicles Singapore or even buy used mitsubishi fv51 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, massage services, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

© 2004-2017 sgCarMart. All rights reserved.

- Terms of Service
- Privacy Policy
- Personal Data Protection Statement

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/11/2017 12:02
Date Of Accident	24/11/2017 17:10
Exact Location Of Accident	BUKIT BATOK HUA TIONG SITE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	XD2935J
Insured/Policyholder	
Name Of Registered Owner	LIAN HENG HUAT TRADING & TRANSPORT
Co Reg No	33397600B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90689660
Alternative Phone No	OFFICE-90689660

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	FV51JJD4RDEA-12.9 D (M)
Exact Purpose for which vehicle was being used at time of accident	WORKS
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	QBE INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	
Cover Note Number	

Driver

Name of Driver	YANG BO
Passport No/FIN	G5320438X
Date Of Birth	04/11/1979
Occupation	OUTDOOR
Date Of Driving Pass	22/11/2013
Driving Experience	4 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90689660
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
(b) all insurer(s) who have insured vehicle(s) involved in the accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


我 與 車 房 均 已 閱 覽 此 報 告

Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



A: XD2935J

B: XD5857G

BUKIT BATOK
(HUA TONG SITE)

Sketch Plan #3 Pg. 1

QBE Insurance (Singapore) Pte Ltd

A member of the worldwide QBE Insurance Group - Unique Entity No. 198401363C

1 Raffles Quay, #28-10 South Tower, Singapore 048583
Tel: 65-6224 6633 Fax: 65-6533 3270
GST Registration No.: M200644018
www.qbe.com.sg



Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULE, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate No. 8-V0015903-MVA

Account Name LCH LOCKTON PTE. LTD

MCI Type MZ301

- 1 Index Mark and Registration Number of Vehicle or Chassis No: XD2935J
- 2 Name of Policyholder LIAN HENG HUAT TRADING & TRANSPORT
- 3 Effective date of Commencement of Insurance for the purpose of the Regulations 09/09/2017
- 4 Date of Expiry 08/09/2018
- 5 Person or Classes of Person entitled to drive*

(1) Whilst the vehicle is being used in connection with the Policyholder's business:-

(a) Any person provided he is in the Policyholder's employ and is driving on their order or with their permission.

(2) Whilst the vehicle is being used for social, domestic or pleasure purposes:-

(a) Any person who is driving on the Policyholder's order or with their permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from the driving the Motor Vehicle

And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage

- 6 Limitations as to use*

Use in connection with the Policyholder's business.

Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business.

Use for social, domestic and pleasure purposes.

The Policy does not cover:-

(1) Use for racing, pace-making, reliability trial or speed testing.

(2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.



(3) Use for the carriage of passengers for hire or reward.

QBE Insurance (Singapore) Pte Ltd

A handwritten signature in black ink, appearing to be "R. P. P.", written over a horizontal line.

Authorized Signature

Date of Issue: 07/09/2017




Accident Photo



Accident Photo



Scene Photo



of Originals that can
be used in the Document

Witness Work Permit



Heavy
vehicles



Heavy
vehicles

WORK PERMIT

Employment of Foreign Manpower Act (Number 59)
Republic of Singapore

2 13

Employer
HUA TONG CONTRACTOR PTE LTD

Sector CONSTRUCTION

Name
RAHMAT MUSTAFA

Occupation
CONSTRUCTION WORKER

MAH LIAN MOTOR VEHICLE REPAIRER

No.38 Defu Lane 9 Singapore 539278
 TEL: 62823336 FAX: 62893336 Email: mahlian@singnet.com.sg
 GST:M90362564P RCB NO:201327339E

not allowed
Make
5/12/17
2/s 23.000
12 day

M/S : QBE Insurance (Singapore) Pte Ltd
 1 Raffles Quay, #29-10 South Tower,
 Singapore 048583

TEL: 6224 6633 FAX: 6533 3270

ATTN: Motor Claim Department

Your Ref No: LIAN HENG HUAT

Claim Type: Third Party

Accident Date: 24/11/2017

Estimate No: ES1700144
 Date: 05 Dec 2017
 Policy No: 8-V0015903-MVA
 Veh Reg No: XD2935J
 Make/Model: MITSUBISHI FV51J
 Chassis No: FV51JJA00322
 Engine No: 6M70419677
 Reg. Date:

Estimate Repair Cost to Vehicle No :XD2935J

Description	U/Price	Quantity	List Price	Amount
			SG	SG
List Price				
1 Front Panel <i>3.500</i>	2,961.90	1 PC	2,961.90	—
2 "Fuso" Emblem <i>new</i>	195.95	1 PC	195.95	—
3 Upper Grille <i>27</i>	400.98	1 PC	400.98	q
4 Lower Grille <i>27</i>	534.60	1 PC	534.60	q
5 "Mit" Logo <i>new</i>	50.40	1 PC	50.40	—
6 Front Panel Hinge LH/RH <i>one</i>	52.66	2 PC	105.32	✓
7 Front Panel Handle LH/RH <i>one 015</i>	111.44	2 PC	222.88	1 pc
8 Wiper Arm <i>2/s 2nd</i>	140.58	3 PC	421.74	2 pc 281.16
9 Wiper Blade <i>2/s 2nd</i>	66.74	3 PC	200.22	2 pc 133.48
10 Wiper Link <i>2nd 1/s</i>	415.80	3 PC	1,247.40	2 pc 831.60
11 Wiper Motor Assy <i>shipped 1/s</i>	794.00	1 PC	794.00	—
12 Wiper Panel <i>3.500</i>	447.05	1 PC	447.05	—
13 Front Panel Lock Assy LH/RH <i>015 1/s</i>	15.08	2 PC	30.16	1 pc
14 Front Corner Panel LH <i>one</i>	1,098.23	1 PC	1,098.23	—
15 Front Door Assy <i>3 pc 975.12</i>	7,360.20	1 PC	7,360.20	—
16 Front Fender RH <i>2 pc 5542.31</i>	1,212.84	1 PC	1,212.84	—
17 Front Fender Step Garnish RH <i>1 pc</i>	387.77	1 PC	387.77	X
18 Cabin Rear Corner Panel <i>3.500</i>	1,792.76	1 PC	1,792.76	—
19 Cabin Rear Corner Panel Step Garnish RH <i>7.5</i>	650.00	1 PC	650.00	—
20 Front Mirror Stay RH <i>3.500</i>	643.41	1 PC	643.41	—
21 Front Mirror Stay Lower Bracket Garnish RH <i>4.5</i>	37.20	1 PC	37.20	—
22 Front Windscreen Glass <i>3.500 1882.10</i>	2,213.37	1 PC	2,213.37	—
23 Front Windscreen Glass Rubber Seal <i>7.5</i>	664.48	1 PC	664.48	50% 332.24
24 Front Door Pillar <i>3.500 1855.10</i>	2,389.64	1 PC	2,389.64	—
25 Front Door Pillar Inner Panel <i>3.500</i>	895.78	1 PC	895.78	—
26 Front Door Pillar Inner Garnish <i>7.5</i>	280.72	1 PC	280.72	—
27 Speedometer Assy <i>1 pc</i>	5,424.27	1 PC	5,424.27	X
28 Speedometer Garnish <i>one</i>	346.37	1 PC	346.37	—
29 Center Console Dashboard <i>7.5</i>	1,786.72	1 PC	1,786.72	—
30 Dashboard Crossmember <i>3 pc</i>	1,598.72	1 PC	1,598.72	—
31 Steering Wheel Assy <i>1 pc</i>	693.33	1 PC	693.33	X
32 Steering Wheel Shaft Assy <i>1 pc</i>	2,361.00	1 PC	2,361.00	X
33 Aircon Brower Assy <i>3.500 1740.00</i>	1,614.00	1 PC	1,614.00	—
34 Aircon Cooling Assy <i>3.500 1728.12</i>	2,736.32	1 PC	2,736.32	—
35 Aircon Evaporator Assy <i>3.500</i>	1,485.99	1 PC	1,485.99	—
36 Aircon Suction Pipe <i>1 pc</i>	285.72	1 PC	285.72	X
37 Aircon Discharge Hose <i>1 pc</i>	256.37	1 PC	256.37	X
38 Aircon Outle Hose Assy <i>1 pc</i>	180.00	1 SET	180.00	X
39 Gear Console Box Assy <i>new</i>	428.30	1 PC	428.30	—

MAH LIAN MOTOR VEHICLE REPAIRER

No.38 Defu Lane 9 Singapore 539278
 TEL: 62823336 FAX: 62893336 Email: mahlian@singnet.com.sg
 GST:M90362564P RCB NO:201327339E

M/S : QBE Insurance (Singapore) Pte Ltd
 1 Raffles Quay, #29-10 South Tower,
 Singapore 048583

TEL: 6224 6633 FAX: 6533 3270
 ATTN: Motor Claim Department
 Your Ref No: LIAN HENG HUAT
 Claim Type: Third Party
 Accident Date: 24/11/2017

Estimate No: ES1700144
 Date: 05 Dec 2017
 Policy No: 8-V0015903-MVA
 Veh Reg No: XD2935J
 Make/Model: MITSUBISHI FV51J
 Chassis No: FV51JJA00322
 Engine No: 6M70419677
 Reg. Date:

Estimate Repair Cost to Vehicle No :XD2935J

Description	U/Price	Quantity	List Price	Amount
40 Dashboard Assy	1,654.57	1 PC	1,654.57	SS
41 Front Inner Panel	1,955.74	1 PC	1,955.74	SS
42 Front Inner Instrument Panel	695.23	1 PC	695.23	SS
			50,741.65	
		Less 25%	12,685.41	38,056.28
Net Price				
43 IU Bracket	30.00	1 PC	30.00	30.00
Labour				
44 To remove & refit front windscreen glass ,IU bracket .	150.00	1 JOB	150.00	120
45 To remove & refit front door RH ,realightment ,transfer parts .	120.00	1 JOB	120.00	60
46 To remove & refit dashboad assy .	380.00	1 JOB	380.00	250
47 To remove & refit aircon system ,brower ,evaporator ,cooling coil ,discharge hose ,suction hose ,outle hose ,etc.	320.00	1 JOB	320.00	150
48 To remove & refit steering wheel , steering shaft .	100.00	1 JOB	100.00	
49 To remove & refit wiper arm ,blade ,motor ,link .	100.00	1 JOB	100.00	
50 To remove & refit garnish ,wiring ,parts ,etc ,to carry out repair work .	280.00	1 JOB	280.00	
51 Labour charge to cut ,weld ,dismantle ,remove & refit all above parts .	3,900.00	1 JOB	3,900.00	
52 To spray & painting at accident area .	2,300.00	1 JOB	2,300.00	1100
53 To rush proofing at accident area .	280.00	1 JOB	280.00	100
54 To vacuum & top up aircon gas .	60.00	1 JOB	60.00	X
55 Towing charge .	180.00	1 TRIP	180.00	150
			8,170.00	8,170.00

Total SS 46,256.28

Add GST @ 7% 3,237.94

Total Amount Payable SS 49,494.22

TOTAL: SINGAPORE DOLLAR FORTY NINE THOUSAND FOUR HUNDRED NINETY FOUR AND CENTS TWENTY TWO ONLY

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For MAH LIAN MOTOR VEHICLE REPAIRER

AUTHORISED SIGNATURE

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Nov 2017		04 Dec 2017 10:05 Edit Adj Rpt	S\$23,000.00 Edit Estimates	S\$23,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS			[Created by Insurer]
Insured:	T. T. CHUA CONSTRUCTION PTE LTD, Co. Reg. No.: 198901247D		
Main Claimant:	LIAN HENG HUAT TRADING & TRANSPORT, Co. Reg. No.: 33397600B		
Vehicle Reg. No.:	XD2935J	Date of Loss:	24/11/2017 17:00 - :59
Claim Type:	TP / 538389	Policy/Cover Note No.:	A28711255MKC (Comprehensive) Coverage: 18/04/2017 - 17/04/2018
Vehicle Reg. No. (Insured):	XD5857G	Policy No. (Claimant):	
		Excess:	
Repairer:	Mah Lian Motor Vehicle Repairer (HQ) NO. 38 DEFU LANE 9, 539278 Defu Lane - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 03/01/2018]		
Driver/Custodian (Insured):	ZHU KONGZHAN (), NRIC: G7544337X, Tel: +6586182836		
Adj Asg. Remarks:	CLIENT CHOOSE MARCUS. PLS CALL MR GOH / MS SI HUI @62823336 BEFORE GO DOWN SURVEY.		

ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			

ALL ASSOCIATED TASKS ☐										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

***XD2935J (538389)**

[XD5857G]

TP

LIAN HENG HUAT TRADING & TRANSPORT

Nov 24 2017 5:00PM

[T. T. CHUA CONSTRUCTION PTE LTD]

Mah Lian Motor Vehicle Repairer

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#)

Assessment Reports				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	04/12/17 10:04	Accident Statement From: SC - Reg. No: XD5857G, Claimant: T. T. CHUA CONSTRUCTION PTE LTD	1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/01/18 10:30	Adjuster Immediate Advice	1	Load HTM	

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/12/17 13:47	General View	1	Load JPG	☒
2	05/12/17 13:47	General View	1	Load JPG	☒
3	05/12/17 13:47	General View	1	Load JPG	☒
4	05/12/17 13:47	General View	1	Load JPG	☒
5	05/12/17 13:47	General View	1	Load JPG	☒
6	05/12/17 13:47	General View	1	Load JPG	☒
7	05/12/17 13:47	General View	1	Load JPG	☒
8	05/12/17 13:47	General View	1	Load JPG	☒
9	05/12/17 13:47	General View	1	Load JPG	☒
10	05/12/17 13:47	General View	1	Load JPG	☒
11	05/12/17 13:47	General View	1	Load JPG	☒
12	05/12/17 13:47	General View	1	Load JPG	☒
13	05/12/17 13:47	General View	1	Load JPG	☒
14	05/12/17 13:47	General View	1	Load JPG	☒
15	05/12/17 13:47	General View	1	Load JPG	☒
16	05/12/17 13:47	General View	1	Load JPG	☒
17	05/12/17 13:47	General View	1	Load JPG	☒
18	05/12/17 13:47	General View	1	Load JPG	☒
19	05/12/17 13:47	General View	1	Load JPG	☒
20	05/12/17 13:47	General View	1	Load JPG	☒
21	05/12/17 13:47	General View	1	Load JPG	☒
22	05/12/17 13:47	General View	1	Load JPG	☒
23	05/12/17 13:47	General View	1	Load JPG	☒
24	05/12/17 13:47	General View	1	Load JPG	☒
25	05/12/17 13:47	General View	1	Load JPG	☒
26	05/12/17 13:47	General View	1	Load JPG	☒
27	05/12/17 13:47	General View	1	Load JPG	☒
28	05/12/17 13:47	General View	1	Load JPG	☒
29	05/12/17 13:47	General View	2	Load JPG	☒
30	05/12/17 13:47	General View	1	Load JPG	

					☒
31	05/12/17 13:47	General View	1	Load JPG	☒
32	05/12/17 13:47	General View	1	Load JPG	☒
33	05/12/17 13:47	General View	1	Load JPG	☒
34	05/12/17 13:47	General View	1	Load JPG	☒
35	05/12/17 13:47	General View	1	Load JPG	☒
36	05/12/17 13:47	General View	1	Load JPG	☒
37	05/12/17 13:47	General View	1	Load JPG	☒
38	05/12/17 13:47	General View	1	Load JPG	☒
39	05/12/17 13:47	General View	1	Load JPG	☒
40	05/12/17 13:47	General View	1	Load JPG	☒
41	05/12/17 13:47	General View	1	Load JPG	☒
42	05/12/17 13:47	General View	1	Load JPG	☒
43	05/12/17 13:47	General View	1	Load JPG	☒
44	05/12/17 13:47	General View	1	Load JPG	☒
45	05/12/17 13:47	General View	1	Load JPG	☒
46	05/12/17 13:47	General View	1	Load JPG	☒
47	05/12/17 13:47	General View	1	Load JPG	☒
48	05/12/17 13:47	General View	1	Load JPG	☒
49	05/12/17 13:47	General View	1	Load JPG	☒
50	05/12/17 13:47	General View	1	Load JPG	☒
51	05/12/17 13:47	General View	1	Load JPG	☒
52	05/12/17 13:47	General View	1	Load JPG	☒
53	05/12/17 13:47	General View	1	Load JPG	☒
54	05/12/17 13:47	General View	1	Load JPG	☒
55	05/12/17 13:47	General View	1	Load JPG	☒
56	05/12/17 13:47	General View	1	Load JPG	☒
57	05/12/17 13:47	General View	1	Load JPG	☒
58	05/12/17 13:47	General View	1	Load JPG	☒
59	05/12/17 13:47	General View	1	Load JPG	☒
60	05/12/17 13:47	General View	1	Load JPG	☒
61	05/12/17 13:47	General View	1	Load JPG	☒
62	05/12/17 13:47	General View	1	Load JPG	☒
63	05/12/17 13:47	General View	1	Load JPG	☒
64	05/12/17 13:47	General View	1	Load JPG	☒
65	05/12/17 13:47	General View	1	Load JPG	☒
66	05/12/17 13:47	General View	1	Load JPG	☒
67	05/12/17 13:47	General View	1	Load JPG	☒
68	05/12/17 13:47	General View	1	Load JPG	☒
69	05/12/17 13:47	General View	1	Load JPG	☒
70	05/12/17 13:47	General View	1	Load JPG	☒
71	05/12/17 13:47	General View	1	Load JPG	☒
72	05/12/17 13:47	General View	1	Load JPG	☒
73	05/12/17 13:47	General View	1	Load JPG	☒
74	05/12/17 13:47	General View	1	Load JPG	☒
75	05/12/17 13:47	General View	1	Load JPG	☒
76	05/12/17 13:47	General View	1	Load JPG	☒
77	05/12/17 13:47	Chassis Number	1	Load JPG	☒
78	05/12/17 13:47	General View	1	Load JPG	☒
79	05/12/17 13:47	General View	1	Load JPG	☒

80	05/12/17 13:47	General View	1	Load JPG	☒
81	05/12/17 13:47	General View	1	Load JPG	☒
82	05/12/17 13:47	General View	1	Load JPG	☒
83	05/12/17 13:47	General View	1	Load JPG	☒
84	05/12/17 13:47	General View	1	Load JPG	☒
85	05/12/17 13:47	General View	1	Load JPG	☒
86	05/12/17 13:47	General View	1	Load JPG	☒
87	05/12/17 13:47	General View	1	Load JPG	☒
88	05/12/17 13:47	General View	1	Load JPG	☒
89	05/12/17 13:47	General View	1	Load JPG	☒
90	05/12/17 13:47	General View	1	Load JPG	☒
91	05/12/17 13:47	General View	1	Load JPG	☒
92	05/12/17 13:47	General View	1	Load JPG	☒
93	05/12/17 13:47	General View	1	Load JPG	☒
94	05/12/17 13:47	General View	1	Load JPG	☒
95	05/12/17 13:47	General View	1	Load JPG	☒
96	11/12/17 13:54	Reinspection Photo	1	Load JPG	☒
97	11/12/17 13:54	Reinspection Photo	1	Load JPG	☒
98	11/12/17 13:54	Reinspection Photo	1	Load JPG	☒
99	11/12/17 13:54	Reinspection Photo	1	Load JPG	☒
100	11/12/17 13:54	Reinspection Photo	1	Load JPG	☒
101	11/12/17 13:54	Reinspection Photo	1	Load JPG	☒
102	11/12/17 13:54	Reinspection Photo	1	Load JPG	☒
103	11/12/17 13:54	Reinspection Photo	1	Load JPG	☒
104	11/12/17 13:54	Reinspection Photo	1	Load JPG	☒
105	11/12/17 13:54	Reinspection Photo	1	Load JPG	☒
106	11/12/17 13:54	Reinspection Photo	1	Load JPG	☒
107	11/12/17 13:54	Reinspection Photo	1	Load JPG	☒
108	11/12/17 13:54	Reinspection Photo	1	Load JPG	☒
109	11/12/17 13:54	Reinspection Photo	1	Load JPG	☒
110	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
111	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
112	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
113	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
114	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
115	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
116	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
117	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
118	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
119	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
120	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
121	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
122	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
123	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
124	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
125	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
126	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
127	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
128	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
129	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒

130	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
131	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
132	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
133	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
134	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
135	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
136	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
137	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
138	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
139	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
140	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
141	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
142	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
143	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
144	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
145	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
146	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
147	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
148	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
149	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
150	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
151	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
152	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
153	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
154	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
155	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
156	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
157	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
158	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
159	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
160	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
161	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
162	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
163	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
164	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
165	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
166	11/12/17 13:55	Reinspection Photo	1	Load JPG	☒
167	08/01/18 08:24	Reinspection Photo	1	Load JPG	☒
168	08/01/18 08:24	Reinspection Photo	1	Load JPG	☒
169	08/01/18 08:24	Reinspection Photo	1	Load JPG	☒
170	08/01/18 08:24	Reinspection Photo	1	Load JPG	☒
Documentation					1 per page ☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	04/12/17 10:01	TPD XD2935J GIA REPORT.	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST				Reset	Save	Print
There are no document checklists configured.						

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^
v

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG17022922/UVBE2**Date:** 12/01/2018**REFERENCE**

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A28711255MKC

Claimant Vehicle No : XD2935J

Insured Vehicle No : XD5857G

Date of Loss: 24/11/2017

Nature of Claim: TP

Claim No: 538389

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: XD2935J

Make & Model: MITSUBISHI FV51JJD4RDEA, 12.9 D (M)

Engine No: 6M70419677

Reg. Date: 09/09/2008 (Man. Year: 2008)

Chassis No: FV51JJA00322

Colour: Red/White

Odometer: 0 km

Engine Capacity: 12882 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 10.00 R20

Rear Tyre Size: 10.00 R20 (D)

Front Left Side: Sailun 5 mm

Rear Left Side: Sailun 5/5 mm

Front Right Side: Sailun 5 mm

Rear Right Side: Sailun 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	38,086.24	24,302.37	13,783.87	36.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,170.00	4,930.00	3,240.00	39.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	46,256.24	29,232.37	17,023.87	36.80
Approved Total (Overridden) (S\$)		23,000.00		
(S\$)	46,256.24	23,000.00	23,256.24	50.28
+ GST 7.00/7.00% (S\$)	3,237.94	1,610.00	1,627.94	50.28
Nett Amount (S\$)	49,494.18	24,610.00	24,884.18	50.28

INSPECTION

Date of Assignment: 04/12/2017

Date Inspected: 05/12/2017 Inspected At:

Mah Lian Motor Vehicle Repairer (HQ)
NO. 38 DEFU LANE 9
Singapore 539278

Estimated Period of Repair: 12.0 days

Adjuster: MARCUS CHUA

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 12 Jan 2018)	
Parts:	N/A	mitsubishi FV51JJD4RDEA 12.9 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD2935J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PANEL	Badly Dented	2,961.90 FL	*2,961.90 FL
2	1		*FUSO EMBLEM	Necessary	195.95 FL	*195.95 FL
3	1		*UPPER GRILLE	Not Necessary	400.98 FL	*- FL
4	1		*LOWER GRILLE	Not Necessary	534.60 FL	*- FL
5	1		*MIT LOGO	Necessary	50.40 FL	*50.40 FL
6	2		*FRONT PANEL HINGE LH / RH	Cracked	105.32 FL	*105.32 FL
7	1		*FRONT PANEL HANDLE LH / RH	O/S Cracked	222.88 FL	*111.44 FL
8	1		*WIPER ARM (3 PCS)	Bent-2pcs only	421.74 FL	*281.16 FL
9	1		*WIPER BLADE (3 PCS)	Bent-2pcs only	200.22 FL	*133.48 FL
10	1		*WIPER LINK (3 PCS)	Bent / Jammed-2pcs only	1,247.40 FL	*831.60 FL
11	1		*WIPER MOTOR ASSY	Shorted / Jammed	794.00 FL	*794.00 FL
12	1		*WIPER PANEL	Badly Dented	447.05 FL	*447.05 FL
13	1		*FRONT PANEL LOCK ASSY LH / RH	O/S Twisted	30.16 FL	*15.08 FL
14	1		*FRONT CORNER PANEL LH	Cracked	1,098.23 FL	*975.12 FL
15	1		*FRONT DOOR ASSY	Buckled	7,360.20 FL	*5,542.31 FL
16	1		*FRONT FENDER RH	Deformed / Cracked	1,212.84 FL	*1,212.84 FL
17	1		*FRONT FENDER STEP GARNISH RH	Not Necessary	387.77 FL	*- FL
18	1		*CABIN REAR CORNER PANEL	Badly Dented	1,792.76 FL	*1,792.76 FL
19	1		*CABIN REAR CORNER PANEL STEP GARNISH RH	Distorted	650.00 FL	*650.00 FL
20	1		*FRONT MIRROR STAY RH	Broken	643.41 FL	*643.41 FL
21	1		*FRONT MIRROR STAY LOWER BRACKET GARNISH RH	Missing	37.20 FL	*37.20 FL
22	1		*FRONT WINDSCREEN GLASS	Broken	2,213.37 FL	*1,882.10 FL
23	1		*FRONT WINDSCREEN GLASS RUBBER SEAL (50%)	Torn	498.36 FS	*332.24 FS
24	1		*FRONT DOOR PILLAR	Badly Dented	2,389.64 FL	*1,855.10 FL
25	1		*FRONT DOOR PILLAR INNER PANEL	Badly Dented	895.78 FL	*895.78 FL
26	1		*FRONT DOOR PILLAR INNER GARNISH	Distorted	280.72 FL	*280.72 FL
27	1		*SPEEDOMETER ASSY	Not Necessary	5,424.27 FL	*- FL
28	1		*SPEEDOMETER GARNISH	Cracked	346.37 FL	*346.37 FL
29	1		*CENTER CONSOLE DASHBOARD	Distorted	1,786.72 FL	*1,786.72 FL
30	1		*DASHBOARD CROSSMEMBER	Bent	1,598.72 FL	*1,598.72 FL
31	1		*STEERING WHEEL ASSY	Not Necessary	693.33 FL	*- FL
32	1		*STEERING WHEEL SHAFT ASSY	Not Necessary	2,361.00 FL	*- FL
33	1		*AIRCON BLOWER ASSY	Broken	1,614.00 FL	*1,210.00 FL
34	1		*AIRCON COOLING ASSY	Broken	2,736.32 FL	*1,728.12 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
35	1		*AIRCON EVAPORATOR ASSY	Broken	1,485.99 FL	*1,485.99 FL
36	1		*AIRCON SUCTION PIPE	Not Necessary	285.72 FL	*- FL
37	1		*AIRCON DISCHARGE HOSE	Not Necessary	256.37 FL	*- FL
38	1		*SET AIRCON OUTLE HOSE ASSY	Not Necessary	180.00 FL	*- FL
39	1		*GEAR CONSOLE BOX ASSY	Cracked	428.30 FL	*428.30 FL
40	1		*DASHBOARD ASSY	Distorted	1,654.57 FL	*1,654.57 FL
41	1		*FRONT INNER PANEL	Repair	1,955.74 FL	*- FL
42	1		*FRONT INNER INSTRUMENT PANEL	Repair	695.23 FL	*- FL
43	1		*IU BRACKET	Necessary	30.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 50,605.53 32,285.75

- List Item Discount on L Items 25.00/25.00% (S\$) 12,519.29 7,983.38

Total Parts (S\$) 38,086.24 24,302.37

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT FRONT WINDSCREEN GLASS, IU BRACKET	New	150.00	120.00
2	TO REMOVE & REFIT FRONT DOOR RH, REALIGHTMENT, TRANSFER PARTS	New	120.00	60.00
3	TO REMOVE & REFIT DASHBOARD ASSY	New	380.00	250.00
4	TO REMOVE & REFIT AIRCON SYSTEM, BROWER, EVAPORATOR, COOLING COIL, DISCHARGE HOSE, SUCTION HOSE, OUTLE HOSE, ETC	New	320.00	150.00
5	TO REMOVE & REFIT STEERING WHEEL, STEERING SHAFT }	New	100.00	3,000.00
6	TO REMOVE & REFIT WIPER ARM, BLADE, MOTOR LINK }	New	100.00	0.00
7	TO REMOVE & REFIT GARNISH, WIRING, PARTS, ETC, TO CARRY OUT REPAIR WORK }	New	280.00	0.00
8	LABOUR CHARGE TO CUT, WELD, DISMANTLE, REMOVE & REFIT ALL ABOVE PARTS }	New	3,900.00	0.00
9	TO SPRAY & PAINTING AT ACCIDENT AREA	New	2,300.00	1,100.00
10	TO RUSH PROOFING AT ACCIDENT AREA	New	280.00	100.00
11	TO VACUUM & TOP UP AIRCON GAS	New	60.00	0.00
12	TOWING CHARGE	New	180.00	150.00
Gross Labour Cost (S\$)			8,170.00	4,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >