

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17022924/SVBE2
Date: 04/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: P27598557DMV
Claimant Vehicle No : SFU8238Y **Insured Vehicle No :** SKH2444S
Date of Loss: 27/11/2017 Nature of Claim: TP Claim No: 538493

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFU8238Y**
Make & Model: MINI COOPER, 1.5 (A) Engine No: 53569006B38A15A
Reg. Date: 12/12/2014 (Man. Year: 2014) Chassis No: WMWXS52040T825313
Colour: Orange Odometer: 25848 km
Engine Capacity: 1499 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/45 R17 Rear Tyre Size: 205/45 R17
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,441.32	1,241.30	1,200.02	49.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,930.00	4,990.00	940.00	15.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,371.32	6,231.30	2,140.02	25.56
+ GST 7.00/7.00% (S\$)	585.99	436.19	149.80	25.56
Nett Amount (S\$)	8,957.31	6,667.49	2,289.82	25.56

INSPECTION

Date of Assignment: 04/12/2017
Date Inspected: 05/12/2017 Inspected At: Trans Eurokars Pte Ltd (Sungei Kadut)
12 Sungei Kadut Ave
Singapore 729648
Estimated Period of Repair: 5.0 days

Adjuster: Sebastian Yeang Wai Keen**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Apr 2018)

Parts: 144 MINI COOPER 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: LKK Auto Consultants Pte Ltd/SFU8238Y/04/04/2018 16:58

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	772.86 F	-
2	1		*REAR BUMPER SENSOR HOLDER RH	Necessary	48.78 F	*48.78 F
3	1		*REAR BUMPER SENSOR HOLDER LH	Necessary	48.78 F	*48.78 F
4	1		*REAR BUMPER SPOILER	Not Necessary	254.64 F	*- F
5	4		*REAR BUMPER BLIND RIVET	Necessary	13.92 F	*13.92 F
6	1		*REAR WHEEL ARCH LH	Cut	95.28 F	*95.28 F
7	1		*REAR BUMPER FOGLAMP CHROME	Not Necessary	92.10 F	*- F
8	1		*SPORT RIM	Cut	960.78 F	*960.78 F
9	1		*SPORT RIM CAP	Not Necessary	30.42 F	*- F
10	4		*REAR SENSOR GASKET	Necessary	23.76 F	*23.76 F
11	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					2,441.32	1,241.30

LKK Auto Consultants Pte Ltd/SFU8238Y/04/04/2018 16:58. Not valid without Reference section.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER. TO REPAIR REAR FENDER LH AND ALL AREAS AFFECTED BY THE ACCIDENT	New	2,100.00	1,680.00
2	TO RESPRAY REAR BUMPER AND REAR FENDER LH	New	1,800.00	1,600.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION	New	250.00	150.00
4	TO MOUNT 1 PC SPORT RIM AND CONDUCT WHEEL BALANCING	New	120.00	120.00
5	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT	New	560.00	560.00
6	TO TRANSFER THE REVERSE SENSORS	New	500.00	420.00
7	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	180.00
8	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	280.00
Gross Labour Cost (S\$)			5,930.00	4,990.00

LKK Auto Consultants Pte Ltd/SFU8238Y/04/04/2018 16:58. Not valid without Reference section.

< END OF ESTIMATES >