

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PART	ACTION (LABOUR)	COMMENT
	1		WIRE CHECKING.	20	0	0	Reviewing	
	2		REMOVE & REFIX AIRCON AND GAS.	100	0	0	Reviewing	
	3		LABOUR CHARGE.	600	0	0	Reviewing	
	4		SPRAY PAINTING.	500	0	0	Reviewing	

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPRJ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
	11	1			FRT BUMPER TOW COVER			Serviceable	0				0
	12	1			FRT BUMPER LOWER GRILLE			Cracked	0				0
	13	1			FRT BUMPER REINFORCEMENT			Bent	0				0
	14	1			FRT BUMPER INNER SPONGE			Cracked	0				0
	15	2			FRT BUMPER BEAM (BELOW HEADLAMP)			Cracked	0				0
	16	1			FRT FOG LAMP RH			Cracked	0				0
	17	1			FRT FOG LAMP GANISH RH			Deformed	0				0
	18	1			FRT HEADLAMP RH			Cracked	0				0
	19	1			HEADLAMP SUPPORT PANEL			Damaged	0				0
	20	1			HEADLAMP PANEL RH			Bent	0				0
	21	1			AIRCON CONDENSER			Bent	0				0
	22	1			RADIATOR			Cracked	0				0
	23	1			RADIATOR FAN COWLING			Serviceable	0				0
	24	1			RADIATOR FAN MOTOR			Serviceable	0				0
	25	1			AIR DUCT FRONT			Serviceable	0				0

Detailed Assessment

Inspection Date *

12/04/2017



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

205/55R16

Rear Tyre Size

205/55R16

FNOL INFORMATI... 9A GUAN SOON AVE, 489583, Singapore

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI... Personal Correspondence

POST SURVEY INF...

CATEGORY Gender

FNOL INFORMATI... Female

POST SURVEY INF...

CATEGORY Marital status

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Identification #

FNOL INFORMATI... S8921549H

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT ... VOLKSWAGEN

ASSESSMENT INFO...
VOLKSWAGEN

CATEGORY Model

POLICY INFORMAT ... GOLF 1.4 TSI

ASSESSMENT INFO...
NEW GOLF 1.4 AT 5K13G5

CATEGORY Type

POLICY INFORMAT ...
ASSESSMENT INFO...
▼

CATEGORY Type of Paint

POLICY INFORMAT ...
ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT ... WWWZZ1KZCW106450

CATEGORY Date of Birth

FNOL INFORMATI... June 20, 1989

POST SURVEY INF...
mm/dd/yyyy 

CATEGORY Age

FNOL INFORMATI... 29

POST SURVEY INF ...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF ...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...
▼

CATEGORY Driving Experience

Accelerated survey
and authorize

Claim Handler

ANG Yvonne
6568804461
yvonne.ang@axa.com.sg

Additional Instructions

NIL excess

Messages
Assessment
Invoices
Metrics
History
Notes
Documents
Add

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
User Portal	2/9/18 12:51 PM	1385	1385	Approved	Share	Clone
ANG Yvonne	12/4/17 11:22 AM			Open	Share	Clone

Accelerated survey
and authorize

Claim Handler

ANG Yvonne
6568804461
yvonne.ang@axa.com.sg

Additional Instructions

Messages Invoices History Documents

Assessment Metrics Notes

NIL excess

Document Type

Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Accident Statement	Reports & Statement		Merimen	
PART INVOICES.pdf	Invoice	Spare Part / Accessories Supplier	LOW Garnet	May 17, 2018
SKD 2454J SUPPLEMENTARY EST.pdf	Forms / Claim Documents	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (OD)	January 15, 2018