

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 456 9830 • FAX: ~~455 3986~~
Business Regn No : 269436/00J

*Not authorized
L1Lyn @ 3000
Resurvey After Repair
5 days*

01, December 2017

Ecics Limited
7 Temasek Boulevard
#10-01 Suntec Tower One
S 038987

Att: Motor claim dept-3rd party claim
Claiming against your insured vehicle No: SJG1402L
Accident involving vehicle No: SJK7311E/SJG1402L
DOA: 30112017 AT Slip Rd From PIE To Lor 1 Toa Payoh

Dear officer incharge
Re: Estimate cost of repair for vehicle No: SJK7311E
To supply—

Description	Qty	Amount
Lid	1	593.00 N ✓
Lid lock	1	64.00 N X
Lid-GLX emblem	1	28.00 N ✓
Lid-Lancer emblem	1	32.00 N ✓
Lid-Mit loo	1	44.00 N ✓
Rear bumper	1	697.00 N ✓
Rear bumper retainer @50 N	2	100.00 N ✓
End panel	1	495.00 N ✓
End panel top garnish	1	156.00 N X
Taillamp, Rh	1	421.00 N ✓
	Parts	2,630.00
	Parts less 10%	263.00
		2,367.00

Reverse sensor

CM 220.00 200.00

To remove damaged parts and attachemnts.

750.00 650.00

Repair/reshape spare tyre panel, rear fender, Rh and dented areas.

Renew/align all parts into position.

To spray paint.

900.00 800.00

4,017.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: