

22/03/2002

ASS. REC. BY:

REF:

CS/FWD17022970/Gmbz

Special Instruction:

SURVEYOR:

GID

ASSIGNMENT (Office)

From (Person):

Clara Li

of

FWD

Date/Time:

04.12.2017 2:09pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKT 4214M

Insured:

at Workshop m/s

Kan Took Sing Motor

Tel:

6747 9560

of

No. 61 Defu Lane 12

Policy No:

PNPV 2017 - 00004409

Claim No:

1201700008458

Sum Insured:

Excess:

\$ 1000.00

Make of Veh:

(Client's Record)

D.O.A.

01.12.2017

CA / REV / REP. / REV 24 HRS

05.12.2017

H.O.D. Endorsement:

Date/Time:

04.12.2017 4:30pm

Person Contacted:

Team

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKT 4214M - X

6/12/17

Sent poli through merimen

7/12/17

Authorise repair & inform reporter.

Xcel

RCR FWD

Vehicle Details

Page: Date: 5/12/17

Estimated Cost:

☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To inspect vehicle No: SKT 4214 M
at Workshop/ins: Kan Fook Sing Motor
of: No. 61 Defu Lane 12

Insured:

Policy No:

Claims No:

Sum Insured: Excess: \$1,000.00

Clients Receipt:

Make of Veh:

Policy Condition:

Remark: The veh had commenced its repair at the time of inspection.

Ball on Market Value: \$79k

ADAC Accident Report: Consistent?: Yes or No

GIA / RR Seen: Consistent?: Yes or No

Est. Repairs: 9 days Rest: Yes or No

Lum Surp: 3 Vals: Yes or No

CA: ☒ REV ☐ REP. / 24 HRS

Date: Person Contacted:

Vehicle IN / OUT

Date Time Action Instruction

Page: 08 Jun 2015

Type: ☒ B ☐ C ☐ D ☐ E ☐ F ☐ G ☐ H ☐ I ☐ J ☐ K ☐ L ☐ M ☐ N ☐ O ☐ P ☐ Q ☐ R ☐ S ☐ T ☐ U ☐ V ☐ W ☐ X ☐ Y ☐ Z

Track / Trailer or

Make: Toyota corolla ATi's 1598

Colour: Grey

So Reading: -

Eng No:

C No: MRO53REH104533951

Gen. Cond: ☒ Good ☐ Fair ☐ Poor ☐ Burnt

Steering: ☒ In ☐ Jammed ☐ Leaked ☐ Burnt or

Brake: ☒ In ☐ Jammed ☐ Leaked ☐ Burnt or

Mod: ☒ Nil ☐ S Rim ☐ STD A Rim or

Tyre Size: R: 205/55 R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI

TOYO / YOKO or

Front

Rear

R Bal: 6 mm

L Bal: 6 mm

D.O.A: 05-12-17

Survey held at: W/S 12 pm

Des. of Damages: ☒ Front ☐ Rear ☐ O/S ☐ N/S ☐ U/O ☐ Rooftop or

The U/O Chassis frame Body Structure affected due to collision

confirm \$16,562.00, 9 days
Red: \$1723, 9% POR checked.

[Signature]
12/04/18

RECEIVED 12 APR 2018

One Time Fee Paid: ☐ Prelim. Report

typst

☒ Final Report

Days Of Repair: 9

Resurvey No. of Trip: 2

Survey Fee:

See Time Fee Return:

Transport:

Add Fee: ☐ Site Visit \$

☐ Parking \$

☐ Test \$

☐ Other \$

Report Fee Paid:

00

Amount: 16562.00

250

RECEIVED 12 APR 2018



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FWD SINGAPORE PTE LTD		Ref : CS/FWD17022970/Grb		
6 TEMASEK BOULEVARD #18-01 SUNTEC TOWER 4SINGAPORE 038986		Date : 04-12-2017		
		Code : FWD		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected		SKT 4214M
Policy No. PNPV2017-00004409		Coverage (\$)		0.00
Claim No. 1201700008458		Excess (\$)		1,000.00
Assign From MERIMEN (CLARA LI)		Assign Date		04/12/2017
2. Vehicle Particulars & Condition				
Make & Model		c.c		0
Engine No. HIDDEN		Year of Reg.		
Chassis No.		Colour		
Odometer -		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date 01/12/2017		Inspection Date 04/12/2017		
Survey held at		KAN FOOK SING MOTOR WORKSHOP 61 DEFU LANE 12 SINGAPORE 539147		
5a. Remarks				
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Li Zi Rong

Date: 06 Dec 2017

Preliminary Advice

Vehicle No	: SKT4214M	Accident Date	: 01/12/2017
Make	: TOYOTA COROLLA ALTIS	Policy No.	: PNPV2017-00004409
Assignment Date	: 04/12/2017	Excess	: S\$1,000.00
Date of Inspection	: 05/12/2017	Est. Duration of Repair	: 9.00
Inspection At	: KAN FOOK SING MOTOR WORKSHOP (DEFU) NO. 61 DEFU LANE 12 SINGAPORE 539147		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,518.00
Revised Amount	:S\$	10,918.00
Check Items (Estimated)	:S\$	1,170.00
Total	:S\$	12,088.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	79,000.00
COE / PARF Rebate	:S\$	61,660.00
Salvage Value	:S\$	
Margin for Repair	:S\$	17,340.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Print Received Message

This mail is associated with :

SKT4214M (1201700008458)

OD

Dec 1 2017 5:00PM

[CHONG SHU HUI, EILEEN (ZHONG SHUHUI)]

Kan Fook Sing Motor Workshop

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 06/12/2017 18:04 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$12088.00) - SKT4214M - Claim Handler: Clara Li Zi Rong

Approved:12088.00.

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Thursday, December 07, 2017 3:18 PM
To: 'mttan@kanfs.net'
Cc: SUR
Subject: SKT 4214M FWD OD DOA : 01.12.2017

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SKT 4214M (excess \$1,000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Li Zi Rong

Date: 12 Apr 2018

Preliminary Advice

Vehicle No	: SKT4214M	Accident Date	: 01/12/2017
Make	: TOYOTA COROLLA ALTIS	Policy No.	: PNPV2017-00004409
Assignment Date	: 04/12/2017	Excess	: S\$1,000.00
Date of Inspection	: 05/12/2017	Est. Duration of Repair	: 9.00
Inspection At	: KAN FOOK SING MOTOR WORKSHOP (DEFU) NO. 61 DEFU LANE 12 SINGAPORE 539147		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,285.00	(Include Supplementary \$4,767.00)
Revised Amount	:S\$	16,562.00	(Include Supplementary + check item)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	16,562.00	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	79,000.00
COE / PARF Rebate	:S\$	61,660.00
Salvage Value	:S\$	
Margin for Repair	:S\$	17,340.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	7460H

Vehicle Details

Vehicle No.	SKT4214M
Vehicle to be Exported	No
Intended De-registration Date	06 Dec 2017
Vehicle Make	TOYOTA
Vehicle Model	TOYOTA COROLLA ALTIS 1.6L CVT
Primary Colour	Grey
Manufacturing Year	2015
Engine No.	1ZRX514076
Chassis No.	MR053REH104533951
Maximum Power Output	90.0 kW (120 bhp)
Open Market Value	\$19,589.00
Original Registration Date	08 Jun 2015
First Registration Date	08 Jun 2015
Transfer Count	0
Actual ARF Paid	\$14,589.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	07 Jun 2025
PARF Rebate Amount	\$10,941.00

Intended COE Rebate Details

COE Expiry Date	07 Jun 2025
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$67,601.00
COE Rebate Amount	\$50,719.00
Total Rebate Amount	\$61,660.00

The information contained herein is correct as at 06 Dec 2017

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/12/2017 12:16
Date Of Accident	01/12/2017 17:50
Exact Location Of Accident	ALONG MCE TOWARDS KPE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKT4214M
Insured/Policyholder	
Name Of Registered Owner	CHONG SHU HUI, EILEEN (ZHONG SHUHUI)
NRIC No	S7907460H
Email Address	NICHOLDIMUS@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-98223461
Alternative Phone No	OTHERS-98223461

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 L CVT (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2017-00004409
Cover Note Number	08/06/2017 TO 07/06/2018

Driver

Name of Driver	CHONG SHU HUI, EILEEN (ZHONG SHUHUI)
NRIC No	S7907460H
Date Of Birth	16/03/1979
Occupation	INDOOR
Date Of Driving Pass	20/05/1999
Driving Experience	18 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98223461
Fax Number	
Contact Number	OTHERS-98223461
EMail Address	NICHOLDIMUS@HOTMAIL.COM

Address	APT BLK 113 COMPASSVALE BOW #16-07 (S) 544814
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

refer with attach.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLB3660Y
Vehicle Make/Model/Colour	MERCEDES BENZ
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLF4072S
Vehicle Make/Model/Colour	HONA VEZEL

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SHD4496K

Vehicle Make/Model/Colour TAXI

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number UNKNOWN

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 2 December 2017
12:41

Driver's Signature


Date & Time: 2 December 2017
12:41

Reporting Centre Personnel's Signature

Name:
NRIC/FIN No:



SKETCH PLAN



A: SKT 421HM

B: SLB 3660Y

C: SLF 4072S

D: SHD 4496K

E: UNKNOWN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along MCE (East-bound, before Fort Road exit), keeping at a speed limit of about 70km/h, a distance of 2.5 car lengths behind SLB 3660Y. Suddenly I heard a tyre screeching sound and saw ^{SLB 3660Y's} ~~the~~ brake lights come on. I immediately slammed my brakes but still did not manage to stop in time. Everyone alighted from their cars and I saw 3 other cars in front of mine. - the first was a Comfort taxi SHD 4496K, second was SLF 4072S, third was SLB 3660Y. my vehicle was the last car in the collision. According to the other drivers, there was a car before the taxi who was the culprit to the collision but the car had sped off.

DECLARATION


I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 2 December 2017
12:41

Driver's Signature
(If driver is not the policyholder)
Date & Time: 2 December 2017
12:41

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

insurer's nric & license



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7907460H



NAME
CHONG SHU HUI, EILEEN
(ZHONG SHUHUI)



姓 名 慈

RACE
CHINESE

DATE OF BIRTH
16-03-1979

COUNTRY OF BIRTH
SINGAPORE

SEX
F



certificate of insurance



CERTIFICATE OF INSURANCE

Please call +65-6322-2072 for FWD Emergency Assistance
if Your Car breaks down or is involved in an accident.
All accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

POLICY NUMBER: PNPV2017-00004409 (Comprehensive - Classic Plan)

Car plate number: SKT4214M

Your name (As the policyholder): Chong Shu Hui, Eileen

Coverage start date: 08/06/2017

Coverage end date: 07/06/2018

Covered geographical area: Singapore, West Malaysia and Southern Thailand

Who is insured to drive:

(a) You; and

(b) Anyone with a valid driving license who You give permission to drive Your Car.

Important things to know:

Your Policy comprises this Certificate of Insurance, the Contract, the Car Insurance Summary and any Endorsements attached by Us. These documents should be read together as one. You must make sure that any person You give permission to drive Your Car understands Your duties under this Policy and complies with its conditions.

Your Policy is only valid if Your Car is being used for non-commercial activities in accordance with Your contract.

Finance company: DBS Bank Ltd

We confirm that this Policy complies with the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).

Issued on: 30/05/2017

Abhishek Bhatia
Chief Executive Officer
FWD Singapore Pte Ltd

Please immediately inform us at +65-6820-8888
or email us at contact.sg@fwd.com if any details
in this Certificate of Insurance need to be changed.



簡福星噴漆工廠
KAN FOOK SING MOTOR WORKSHOP
 Tel: (65) 6747 9560 6858 2126 6858 4311
 Fax: (65) 6748 1006 6261 8428
 E-mail: kants@pacific.net.sg Website: www.carparts.com.sg

INSURER: **FWD Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	PNPV2017-00004409	Date of Loss:	01/12/2017
Vehicle Reg. No.:	SKT4214M	Driveable?	
Driver Age/Info:	38 / FEMALE	Party At Fault:	UNKNOWN
TP Injury	NO	Third Party	YES
Involved?		Involved?	
Insured/Claimant:	CHONG SHU HUI, EILEEN (ZHONG SHUHUI)	Contact No:	+6598223461
Driver:	CHONG SHU HUI, EILEEN (ZHONG SHUHUI)		

Make/Model:	TOYOTA COROLLA ALTIS, 1.6 L CVT (A)	Vehicle Reg. Date:	07/06/2015
Vehicle Colour:	METALLIC BLUE		
Engine No:	1ZR514076	Chassis No:	MR053REH104533951
Odometer:	0 KM		

Paint Type:

Total Loss? **NO**

Est. Duration of Repair (day) 10

Description of Accident/Loss REFER WITH ATTACH.

Present Location: KAN FOOK SING MOTOR WORKSHOP (DEFU)

COST OF CLAIMS	Amount
Parts	10,010.00
Miscellaneous Items	218.00
Labour	2,090.00
Paintwork Labour	1,200.00
Towing	0.00
Calculated Gross Total (S\$)	13,518.00
- Excess (S\$)	1,000.00
(S\$)	12,518.00
+ GST 7.00% (S\$)	876.26
Nett Amount (S\$)	13,394.26

This claim is handled by: TAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 04 Dec 2017)
Parts: 143 **TOYOTA COROLLA ALTIS 1.6 L CVT (A)** (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Kan Fook Sing Motor Workshop/SKT4214M/04/12/2017 12:29
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT WINDSCREEN GLASS / CPA	0.00	0.00	*400.00 F 380
2	1		*FRONT WINDSCREEN MOULDING / MC	0.00	0.00	*40.00 F 40
3	1		*STEERING AIR BAG / Act	0.00	0.00	*850.00 F 850
4	1		*STEERING AIR BAG WIRE / Act	0.00	0.00	*170.00 F 170
5	1		*DASHBOARD / CPA	0.00	0.00	*650.00 F 650
6	1		*DASHBOARD AIR BAG / Act	0.00	0.00	*1,150.00 F 1150
7	1		*SEAT BELT RH / Act	0.00	0.00	*280.00 F 280
8	1		*SEAT BELT LH / Act	0.00	0.00	*280.00 F 280
9	1		*AIR BAG ECU / Act	0.00	0.00	*280.00 F 280
10	1		*AIR BAG IMPACT SENSOR RH / Act	0.00	0.00	*145.00 F 145
11	1		*AIR BAG IMPACT SENSOR LH / Act	0.00	0.00	*145.00 F 145
12	1		*FRONT BONNET / MC	0.00	0.00	*270.00 F 270
13	1		*FRONT BONNET LOCK / BT	0.00	0.00	*60.00 F 60
14	1		*FRONT BONNET HINGE RH / BT	0.00	0.00	*30.00 F 30
15	1		*FRONT BONNET HINGE LH / BT	0.00	0.00	*30.00 F 30
16	1		*FRONT BONNET INSULATOR / MC	0.00	0.00	*95.00 F 95
17	10		*FRONT BONNET INSULATOR CLIP / MC	0.00	0.00	*15.00 F 15
18	1		*FRONT SUPPORT PANEL / BT	0.00	0.00	*220.00 F 220
19	1		*FRONT BRACE PANEL / CPA	0.00	0.00	*40.00 F 40
20	1		*FRONT GRILLE / CPA	0.00	0.00	*150.00 F 150
21	1		*FRONT GRILLE TOP GARNISH / MC	0.00	0.00	*35.00 F 35
22	6		*FRONT GRILLE TOP GARNISH CLIP / MC	0.00	0.00	*9.00 F 9
23	1		*FRONT GRILLE TOP RUBBER / MC	0.00	0.00	*15.00 F 15
24	1		*FRONT HEADLAMP RH / CPA	0.00	0.00	*650.00 F 650
25	1		*FRONT HEADLAMP LH / CPA	0.00	0.00	*650.00 F 650
26	1		*FRONT HEADLAMP CHROME RH / MC	0.00	0.00	*60.00 F 60
27	1		*FRONT HEADLAMP CHROME LH / MC	0.00	0.00	*60.00 F 60
28	1		*FRONT FENDER LH / MC	0.00	0.00	*190.00 F 190
29	1		*FRONT FENDER SHIELD LH / MC	0.00	0.00	*55.00 F 55
30	10		*FRONT FENDER SHIELD CLIP / MC	0.00	0.00	*15.00 F 15
31	1		*FRONT FENDER VVTI EMBLEM RH / MC	0.00	0.00	*18.00 F 18
32	1		*FRONT FENDER VVTI EMBLEM LH / MC	0.00	0.00	*18.00 F 18
33	1		*FRONT BUMPER / CPA	0.00	0.00	*190.00 F 190
34	1		*FRONT BUMPER REINFORCEMENT / BT	0.00	0.00	*110.00 F 110
35	1		*FRONT BUMPER FOAM / MC	0.00	0.00	*35.00 F 35
36	1		*FRONT BUMPER SIDE RETAINER RH / MC	0.00	0.00	*35.00 F 35
37	1		*FRONT BUMPER SIDE RETAINER LH / MC	0.00	0.00	*35.00 F 35
38	1		*FRONT BUMPER CENTRE GRILLE / MC	0.00	0.00	*50.00 F 50
39	10		*FRONT BUMPER CLIP / MC	0.00	0.00	*15.00 F 15
40	1		*FRONT CHASSIS FRAME BRACKET RH / NN	0.00	0.00	*35.00 F x
41	1		*FRONT CHASSIS FRAME BRACKET LH / NN	0.00	0.00	*35.00 F x
42	1		*AIR CON CONDENSER / BT	0.00	0.00	*380.00 F 380
43	1		*AIR CON LIQUID PIPE / NN	0.00	0.00	*40.00 F x
44	1		*RADIATOR / BT	0.00	0.00	*380.00 F 380

Kan Fook Sing Motor Workshop/SKT4214M/04/12/2017 12:29. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
45	1		*RADIATOR TOP GARNISH <i>7/ CRA</i>	0.00	0.00	*40.00 F
46	1		*RADIATOR FAN COWLING <i>CRA</i>	0.00	0.00	*90.00 F
47	1		*RADIATOR FAN BLADE <i>7/ CRA</i>	0.00	0.00	*55.00 F
48	1		*RADIATOR FAN MOTOR <i>7/ NW</i>	0.00	0.00	*180.00 F
49	1		*RADIATOR TOP BRACKET RH <i>BT</i>	0.00	0.00	*25.00 F
50	1		*RAIDATOR TOP BRACKET LH <i>BT</i>	0.00	0.00	*25.00 F
51	1		*RAIDATOR TOP HOSE <i>P/ Cut</i>	0.00	0.00	*25.00 F
52	1		*SPARE TANK <i>7/ R2</i>	0.00	0.00	*55.00 F
53	1		*FUSE BOX TOP <i>7/ R2</i>	0.00	0.00	*40.00 F
54	1		*FUSES BOX LOWER <i>7/ CRA</i>	0.00	0.00	*35.00 F
55	1		*FUSES BOX CENTRE <i>7/ BT</i>	0.00	0.00	*60.00 F
56	1		*BATTERY TOP BRAK CET <i>BT</i>	0.00	0.00	*25.00 F
57	1		*BATTERY COVER <i>P/ R2</i>	0.00	0.00	*35.00 F
58	1		*BATTERY TRAY <i>7/ R2</i>	0.00	0.00	*40.00 F
59	1		*MANIFOLD INTAKE <i>7/ CRA</i>	0.00	0.00	*220.00 F
60	1		*RESONATOR BOX <i>7/ CRA</i>	0.00	0.00	*50.00 F
61	1		*RESONATOR HOSE <i>7/ CRA</i>	0.00	0.00	*65.00 F
62	1		*AIR CLEANER BOX ASSY <i>7/ CRA</i>	0.00	0.00	*260.00 F
63	1		*ENGIEN TOP COVER <i>7/ Cut</i>	0.00	0.00	*85.00 F
64	1		*ENGINE MOUNTING LH <i>7/ NW</i>	0.00	0.00	*95.00 F
65	1		*ENGINE MOUNTING FR <i>7/ NW</i>	0.00	0.00	*90.00 F

F=Franchise part.

Total Parts (S\$)

10,010.00

Kan Fook Sing Motor Workshop/SKT4214M/04/12/2017 12:29. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	BATTERY / <i>CRA</i>	138.00
2	1	ERP STICKER / <i>MC</i>	10.00
3	1	FRONT NUMBER PLATE / <i>BT</i>	30.00
4	1	FRONT WINDSCREEN GUM / <i>MC</i>	40.00
Sub Total (\$\$)			218.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	SPRAYPAINTING CHARGES	New	1,200.00 <i>600</i>
Labour Items			
2	TO CHECK WIRING SYSTEM	New	50.00 <i>20</i>
3	TO REMOVE/REFIT FRONT WINDSCREEN GLASS	New	100.00 <i>80</i>
4	TO REMOVE/REFIT/REFILL AIR CON GAS	New	80.00 <i>50</i>
5	TO REMOVE/REFIT ENGINE MOUNTINGS	New	80.00 <i>80</i>
6	TO REMOVE/REFIT DASHBOARD	New	280.00 <i>200</i>
7	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	1,500.00 <i>800</i>
Gross Labour Cost (\$\$)			3,290.00

Kan Fook Sing Motor Workshop/SKT4214M/04/12/2017 12:29. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Excess \$1000
 Not Authorized.
 put by pet.
 before paint photos.
 Gino Qiang - 82880282
 9 Days.

[Signature]
 7/2/17.

UKK Auto Consultants hence notify**the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Dec 2017)
 Parts: 143 TOYOTA COROLLA ALTIS 1.6 L CVT (A) (Catalogue: Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Kan Fook Sing Motor Workshop/SKT4214M/04/12/2017 12:29
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT WINDSCREEN GLASS / CPA	0.00	0.00	*400.00 F
2	1		*FRONT WINDSCREEN MOULDING / MC	0.00	0.00	*40.00 F
3	1		*STEERING AIR BAG / Act	0.00	0.00	*850.00 F
4	1		*STEERING AIR BAG WIRE / Act	0.00	0.00	*170.00 F
5	1		*DASHBOARD / CPA	0.00	0.00	*650.00 F
6	1		*DASHBOARD AIR BAG / Act	0.00	0.00	*1,150.00 F
7	1		*SEAT BELT RH / Act	0.00	0.00	*280.00 F
8	1		*SEAT BELT LH / Act	0.00	0.00	*280.00 F
9	1		*AIR BAG ECU / Act	0.00	0.00	*280.00 F
10	1		*AIR BAG IMPACT SENSOR RH / Act	0.00	0.00	*145.00 F
11	1		*AIR BAG IMPACT SENSOR LH / Act	0.00	0.00	*145.00 F
12	1		*FRONT BONNET / MC	0.00	0.00	*270.00 F
13	1		*FRONT BONNET LOCK / BT	0.00	0.00	*60.00 F
14	1		*FRONT BONNET HINGE RH / BT	0.00	0.00	*30.00 F
15	1		*FRONT BONNET HINGE LH / BT	0.00	0.00	*30.00 F
16	1		*FRONT BONNET INSULATOR / MC	0.00	0.00	*95.00 F
17	10		*FRONT BONNET INSULATOR CLIP / MC	0.00	0.00	*15.00 F
18	1		*FRONT SUPPORT PANEL / MC	0.00	0.00	*220.00 F
19	1		*FRONT BRACE PANEL / BT	0.00	0.00	*40.00 F
20	1		*FRONT GRILLE / CPA	0.00	0.00	*150.00 F
21	1		*FRONT GRILLE TOP GARNISH / MC	0.00	0.00	*35.00 F
22	6		*FRONT GRILLE TOP GARNISH CLIP / MC	0.00	0.00	*9.00 F
23	1		*FRONT GRILLE TOP RUBBER / MC	0.00	0.00	*15.00 F
24	1		*FRONT HEADLAMP RH / CPA	0.00	0.00	*650.00 F
25	1		*FRONT HEADLAMP LH / CPA	0.00	0.00	*650.00 F
26	1		*FRONT HEADLAMP CHROME RH / MC	0.00	0.00	*60.00 F
27	1		*FRONT HEADLAMP CHROME LH / MC	0.00	0.00	*60.00 F
28	1		*FRONT FENDER LH / MC	0.00	0.00	*190.00 F
29	1		*FRONT FENDER SHIELD LH / MC	0.00	0.00	*55.00 F
30	10		*FRONT FENDER SHIELD CLIP / MC	0.00	0.00	*15.00 F
31	1		*FRONT FENDER VVTI EMBLEM RH / MC	0.00	0.00	*18.00 F
32	1		*FRONT FENDER VVTI EMBLEM LH / MC	0.00	0.00	*18.00 F
33	1		*FRONT BUMPER / CPA	0.00	0.00	*190.00 F
34	1		*FRONT BUMPER REINFORCEMENT / BT	0.00	0.00	*110.00 F
35	1		*FRONT BUMPER FOAM / MC	0.00	0.00	*35.00 F
36	1		*FRONT BUMPER SIDE RETAINER RH / MC	0.00	0.00	*35.00 F
37	1		*FRONT BUMPER SIDE RETAINER LH / MC	0.00	0.00	*35.00 F
38	1		*FRONT BUMPER CENTRE GRILLE / MC	0.00	0.00	*50.00 F
39	10		*FRONT BUMPER CLIP / MC	0.00	0.00	*15.00 F
40	1		*FRONT CHASSIS FRAME BRACKET RH / ?	0.00	0.00	*35.00 F
41	1		*FRONT CHASSIS FRAME BRACKET LH / ?	0.00	0.00	*35.00 F
42	1		*AIR CON CONDENSER / BT	0.00	0.00	*380.00 F
43	1		*AIR CON LIQUID PIPE / ?	0.00	0.00	*40.00 F
44	1		*RADIATOR / BT	0.00	0.00	*380.00 F

Kan Fook Sing Motor Workshop/SKT4214M/04/12/2017 12:29. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
45	1		*RADIATOR TOP GARNISH <i>2 - CFA</i>	0.00	0.00	*40.00 F
46	1		*RADIATOR FAN COWLING <i>1 - CFA</i>	0.00	0.00	*90.00 F
47	1		*RADIATOR FAN BLADE <i>8 - CFA</i>	0.00	0.00	*55.00 F
48	1		*RADIATOR FAN MOTOR <i>2 - NW</i>	0.00	0.00	*180.00 F
49	1		*RADIATOR TOP BRACKET RH <i>= BT</i>	0.00	0.00	*25.00 F
50	1		*RAIDATOR TOP BRACKET LH <i>= BT</i>	0.00	0.00	*25.00 F
51	1		*RAIDATOR TOP HOSE <i>?</i>	0.00	0.00	*25.00 F
52	1		*SPARE TANK <i>2 - CFA</i>	0.00	0.00	*55.00 F
53	1		*FUSE BOX TOP <i>8 - R</i>	0.00	0.00	*40.00 F
54	1		*FUSES BOX LOWER <i>8 - R</i>	0.00	0.00	*35.00 F
55	1		*FUSES BOX CENTRE <i>8 - R</i>	0.00	0.00	*60.00 F
56	1		*BATTERY TOP BRAK CET <i>BT</i>	0.00	0.00	*25.00 F
57	1		*BATTERY COVER <i>2 - CFA</i>	0.00	0.00	*35.00 F
58	1		*BATTERY TRAY <i>2 - CFA</i>	0.00	0.00	*40.00 F
59	1		*MANIFOLD INTAKE <i>2 - CFA</i>	0.00	0.00	*220.00 F
60	1		*RESONATOR BOX <i>= CFA</i>	0.00	0.00	*50.00 F
61	1		*RESONATOR HOSE <i>= CFA</i>	0.00	0.00	*65.00 F
62	1		*AIR CLEANER BOX ASSY <i>CFA</i>	0.00	0.00	*260.00 F
63	1		*ENGIEN TOP COVER <i>Cat</i>	0.00	0.00	*85.00 F
64	1		*ENGINE MOUNTING LH <i>?</i>	0.00	0.00	*95.00 F
65	1		*ENGINE MOUNTING FR <i>?</i>	0.00	0.00	*90.00 F

F=Franchise part.

Total Parts (S\$) 10,010.00

Kan Fook Sing Motor Workshop/SKT4214M/04/12/2017 12:29. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Kan. G. P.
12/12/17

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	BATTERY / CRA	138.00
2	1	ERP STICKER / MCL	10.00
3	1	FRONT NUMBER PLATE / BT	30.00
4	1	FRONT WINDSCREEN GUM / MCL	40.00
Sub Total (S\$)			218.00

Estimates on Labour

No	Particulars	Lab.Type	Amount	
Paintwork Labour				
1	SPRAYPAINTING CHARGES	New	1,200.00	900
Labour Items				
2	TO CHECK WIRING SYSTEM	New	50.00	2
3	TO REMOVE/REFIT FRONT WINDSCREEN GLASS	New	100.00	80
4	TO REMOVE/REFIT/REFILL AIR CON GAS	New	80.00	60
5	TO REMOVE/REFIT ENGINE MOUNTINGS	New	80.00	?
6	TO REMOVE/REFIT DASHBOARD	New	280.00	200
7	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	1,500.00	800
Gross Labour Cost (S\$)			3,290.00	1100

Kan Fook Sing Motor Workshop/SKT4214M/04/12/2017 12:29. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Excess \$1000
Not Authorised.
part by part.
before paint photos.
Gino Qiang - 82880282
9 Days.

LIK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SKT4214M

Supplementary

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Mar 2018)
 Parts: 143 TOYOTA COROLLA ALTIS 1.6 L CVT (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Kan Fook Sing Motor Workshop/SKT4214M/09/03/2018 11:50
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER SIDE CLIP COVER / <i>ABC</i>	0.00	0.00	*4.00 F
2	1		Δ *ENGINE ECU / <i>DM</i>	0.00	0.00	*3,750.00 F
3	1		*FUSE BOX OUTER BRACKET / <i>DT</i>	0.00	0.00	*25.00 F
4	1		*FRONT GRILLE EMBLEM / <i>ABC</i>	0.00	0.00	*25.00 F
5	1		Δ *THROTTLE BODY / <i>DM</i>	0.00	0.00	*650.00 F
6	1		Δ *FRONT BUMPER FOG LAMP LH / <i>CRA</i>	0.00	0.00	*105.00 F
7	1		Δ *DASHBOARD AIRBAG WIRE LH / <i>DM</i>	0.00	0.00	*25.00 F
8	1		Δ *A/C RELAY / <i>DM</i>	0.00	0.00	*150.00 F
9	1		*RADIATOR BYPASS HOSE / <i>Cut</i>	0.00	0.00	*33.00 F

F=Franchise part.

Total Parts (S\$) 4,767.00

Kan Fook Sing Motor Workshop/SKT4214M/09/03/2018 11:50. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Kan Fook Sing Motor Workshop/SKT4214M/09/03/2018 11:50. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Dec 2017)
 Parts: 143 TOYOTA COROLLA ALTIS 1.6 L CVT (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Kan Fook Sing Motor Workshop/SKT4214M/04/12/2017 12:29
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT WINDSCREEN GLASS / CFA	0.00	0.00	*400.00 F	360
2	1		*FRONT WINDSCREEN MOULDING / ACC	0.00	0.00	*40.00 F	—
3	1		*STEERING AIR BAG — Act	0.00	0.00	*850.00 F	—
4	1		*STEERING AIR BAG WIRE — Act	0.00	0.00	*170.00 F	—
5	1		*DASHBOARD — CFA	0.00	0.00	*650.00 F	—
6	1		*DASHBOARD AIR BAG — Act	0.00	0.00	*1,150.00 F	—
7	1		*SEAT BELT RH — Act	0.00	0.00	*280.00 F	—
8	1		*SEAT BELT LH — Act	0.00	0.00	*280.00 F	—
9	1		*AIR BAG ECU — Act	0.00	0.00	*280.00 F	—
10	1		*AIR BAG IMPACT SENSOR RH — Act	0.00	0.00	*145.00 F	—
11	1		*AIR BAG IMPACT SENSOR LH — Act	0.00	0.00	*145.00 F	—
12	1		*FRONT BONNET — Acc	0.00	0.00	*270.00 F	—
13	1		*FRONT BONNET LOCK — BT	0.00	0.00	*60.00 F	—
14	1		*FRONT BONNET HINGE RH — BT	0.00	0.00	*30.00 F	—
15	1		*FRONT BONNET HINGE LH — BT	0.00	0.00	*30.00 F	—
16	1		*FRONT BONNET INSULATOR — Acc	0.00	0.00	*95.00 F	—
17	10		*FRONT BONNET INSULATOR CLIP — Acc	0.00	0.00	*15.00 F	—
18	1		*FRONT SUPPORT PANEL — Acc	0.00	0.00	*220.00 F	—
19	1		*FRONT BRACE PANEL — Acc	0.00	0.00	*40.00 F	—
20	1		*FRONT GRILLE — CFA	0.00	0.00	*150.00 F	—
21	1		*FRONT GRILLE TOP GARNISH — Acc	0.00	0.00	*35.00 F	—
22	6		*FRONT GRILLE TOP GARNISH CLIP — Acc	0.00	0.00	*9.00 F	—
23	1		*FRONT GRILLE TOP RUBBER — Acc	0.00	0.00	*15.00 F	—
24	1		*FRONT HEADLAMP RH — Acc	0.00	0.00	*650.00 F	—
25	1		*FRONT HEADLAMP LH — Acc	0.00	0.00	*650.00 F	—
26	1		*FRONT HEADLAMP CHROME RH — Acc	0.00	0.00	*60.00 F	—
27	1		*FRONT HEADLAMP CHROME LH — Acc	0.00	0.00	*60.00 F	—
28	1		*FRONT FENDER LH — Acc	0.00	0.00	*190.00 F	—
29	1		*FRONT FENDER SHIELD LH — Acc	0.00	0.00	*55.00 F	—
30	10		*FRONT FENDER SHIELD CLIP — Acc	0.00	0.00	*15.00 F	—
31	1		*FRONT FENDER VVTI EMBLEM RH — Acc	0.00	0.00	*18.00 F	—
32	1		*FRONT FENDER VVTI EMBLEM LH — Acc	0.00	0.00	*18.00 F	—
33	1		*FRONT BUMPER — CFA	0.00	0.00	*190.00 F	—
34	1		*FRONT BUMPER REINFORCEMENT — BT	0.00	0.00	*110.00 F	—
35	1		*FRONT BUMPER FOAM — Acc	0.00	0.00	*35.00 F	—
36	1		*FRONT BUMPER SIDE RETAINER RH — Acc	0.00	0.00	*35.00 F	—
37	1		*FRONT BUMPER SIDE RETAINER LH — Acc	0.00	0.00	*35.00 F	—
38	1		*FRONT BUMPER CENTRE GRILLE — Acc	0.00	0.00	*50.00 F	—
39	10		*FRONT BUMPER CLIP — Acc	0.00	0.00	*15.00 F	1 Z
40	1		*FRONT CHASSIS FRAME BRACKET RH — ?	0.00	0.00	*35.00 F	—
41	1		*FRONT CHASSIS FRAME BRACKET LH — ?	0.00	0.00	*35.00 F	—
42	1		*AIR CON CONDENSER — BT	0.00	0.00	*380.00 F	1 2 5
43	1		*AIR CON LIQUID PIPE — ?	0.00	0.00	*40.00 F	—
44	1		*RADIATOR — BT	0.00	0.00	*380.00 F	1 3 0

Kan Fook Sing Motor Workshop/SKT4214M/04/12/2017 12:29. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
45	1		*RADIATOR TOP GARNISH <i>CR</i>	0.00	0.00	*40.00 F —
46	1		*RADIATOR FAN COWLING <i>CR</i>	0.00	0.00	*90.00 F —
47	1		*RADIATOR FAN BLADE <i>CR</i>	0.00	0.00	*55.00 F —
48	1		*RADIATOR FAN MOTOR <i>NW</i>	0.00	0.00	*180.00 F —
49	1		*RADIATOR TOP BRACKET RH <i>BT</i>	0.00	0.00	*25.00 F —
50	1		*RAIDATOR TOP BRACKET LH <i>BT</i>	0.00	0.00	*25.00 F —
51	1		*RAIDATOR TOP HOSE <i>?</i>	0.00	0.00	*55.00 F —
52	1		*SPARE TANK <i>?</i>	0.00	0.00	*40.00 F —
53	1		*FUSE BOX TOP <i>?</i>	0.00	0.00	*35.00 F —
54	1		*FUSES BOX LOWER <i>?</i>	0.00	0.00	*60.00 F —
55	1		*FUSES BOX CENTRE <i>?</i>	0.00	0.00	*25.00 F —
56	1		*BATTERY TOP BRACKET <i>BT</i>	0.00	0.00	*35.00 F —
57	1		*BATTERY COVER <i>?</i>	0.00	0.00	*40.00 F —
58	1		*BATTERY TRAY <i>?</i>	0.00	0.00	*220.00 F —
59	1		*MANIFOLD INTAKE <i>CR</i>	0.00	0.00	*50.00 F —
60	1		*RESONATOR BOX <i>CR</i>	0.00	0.00	*65.00 F —
61	1		*RESONATOR HOSE <i>?</i>	0.00	0.00	*260.00 F —
62	1		*AIR CLEANER BOX ASSY <i>CR</i>	0.00	0.00	*85.00 F 75
63	1		*ENGIN TOP COVER <i>CR</i>	0.00	0.00	*95.00 F
64	1		*ENGINE MOUNTING LH <i>?</i>	0.00	0.00	*80.00 F
65	1		*ENGINE MOUNTING FR <i>?</i>	0.00	0.00	
F=Franchise part.						
Total Parts (S\$)						10,010.00 <i>9177</i>

Kan Fook Sing Motor Workshop/SKT4214M/04/12/2017 12:29. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Can. Qrp.
12/12/17

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	BATTERY / CRA	138.00
2	1	ERP STICKER / MLC	10.00
3	1	FRONT NUMBER PLATE / BT	30.00
4	1	FRONT WINDSCREEN GUM / MLC	40.00
Sub Total (S\$)			218.00

Estimates on Labour

No	Particulars	Lab.Type	Amount	
<u>Paintwork Labour</u>				
1	SPRAYPAINTING CHARGES	New	1,200.00	900
<u>Labour Items</u>				
2	TO CHECK WIRING SYSTEM	New	50.00	75 2
3	TO REMOVE/REFIT FRONT WINDSCREEN GLASS	New	100.00	80
4	TO REMOVE/REFIT/REFILL AIR CON GAS	New	80.00	60
5	TO REMOVE/REFIT ENGINE MOUNTINGS	New	80.00	?
6	TO REMOVE/REFIT DASHBOARD	New	280.00	200
7	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	1,500.00	800
Gross Labour Cost (S\$)			3,290.00	1100

Kan Fook Sing Motor Workshop/SKT4214M/04/12/2017 12:29. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Excess \$1000
Not Authorized.
part by part.
before paint photos.
Gue Qi ang - 82880282
9 Days.

LIK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by: Repairer
Signature:
Date:

SKT4214M

Supplementary

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Mar 2018)
 Parts: 143 TOYOTA COROLLA ALTIS 1.6 L CVT (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Kan Fook Sing Motor Workshop/SKT4214M/09/03/2018 11:50
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER SIDE CLIP COVER / <i>AGC</i>	0.00	0.00	*4.00 F
2	1	10,11	*ENGINE ECU / <i>DM</i>	0.00	0.00	*3,750.00 F
3	1	37,38	*FUSE BOX OUTER BRACKET / <i>DM</i>	0.00	0.00	*25.00 F
4	1		*FRONT GRILLE EMBLEM / <i>AGC</i>	0.00	0.00	*25.00 F
5	1	7,8	*THROTTLE BODY / <i>DM</i>	0.00	0.00	*650.00 F
6	1		*FRONT BUMPER FOG LAMP LH / <i>CRA</i>	0.00	0.00	*105.00 F
7	1	18	*DASHBOARD AIRBAG WIRE LH / <i>DM</i>	0.00	0.00	*25.00 F
8	1	42	*A/C RELAY / <i>DM</i>	0.00	0.00	*150.00 F
9	1	34	*RADIATOR BYPASS HOSE / <i>Cut</i>	0.00	0.00	*33.00 F
Total Parts (S\$)						4,767.00

F=Franchise part.

Kan Fook Sing Motor Workshop/SKT4214M/09/03/2018 11:50. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Kan Fook Sing Motor Workshop/SKT4214M/09/03/2018 11:50. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Engine ECU - NO 10,11,37,38

Throttle body - NO 7,8

Dash board - 18

AC Relay - 42, 43, 44

Radiator bypass - 34

簡福星摩多工廠
KAN TOOK SING MOTOR WORKSHOP
61 DEFU LANE 12
SINGAPORE 539147
TEL: 67479560, 68582126, 68584361
FAX: 67481006, 62818428

FWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4
SINGAPORE 038986
VEHICLE NO. : SKT4214M
ACCIDENT DATE : 01-12-2017 17:50
THIRD PARTY REF. : SLB3660Y

INVOICE NO : TEST
DATE : 12-01-2018

ATTN: FWD SINGAPORE PTE LTD

INVOICE COST OF REPAIRS TO VEHICLE SKT4214M TOYOTA COROLLA ALTIS-1.6 L CVT (A)

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	FRONT WINDSCREEN GLASS	380.00
1	FRONT WINDSCREEN MOULDING	40.00
1	STEERING AIR BAG	850.00
1	STEERING AIR BAG WIRE	170.00
1	DASHBOARD	650.00
1	DASHBOARD AIR BAG	1150.00
2	SEAT BELT@\$280.00	560.00
1	AIR BAG ECU	280.00
2	AIR BAG IMPACT SENSOR@\$145.00	290.00
1	FRONT BONNET	270.00
1	FRONT BONNET LOCK	60.00
2	FRONT BONNET HINGE @\$30.00	60.00
1	FRONT BONNET INSULATOR	95.00
10	FRONT BONNET INSULATOR CLIP @\$1.50	15.00
1	FRONT SUPPORT PANEL	220.00
1	FRONT BRACE PANEL	40.00
1	FRONT GRILLE	150.00
1	FRONT GRILLE TOP GARNISH	35.00
6	FRONT GRILLE TOP GARNISH CLIP @\$1.50	9.00
1	FRONT GRILLE TOP RUBBER	15.00
2	FRONT HEADLAMP @\$650.00	1300.00
2	FRONT HEADLAMP CHROME @\$60.00	120.00
1	FRONT FENDER LH	190.00
1	FRONT FENDER SHIELD LH	55.00
10	FRONT FENDER SHIELD CLIP @\$1.50	15.00

閩福星摩哆工廠
 TAN FOOK SING MOTOR WORKSHOP
 61 DEFU LANE 12
 SINGAPORE 539147
 TEL: 67479560, 68582126, 68584361
 FAX: 67481006, 62818428

VEHICLE NO. : SKT4214M
 ACCIDENT DATE : 01-12-2017 17:50
 THIRD PARTY REF. : SLB3660Y

<u>QTY</u>	<u>PARTS DESCRIPTION</u>	<u>AMOUNT (SG\$)</u>
2	FRONT FENDER VVTI EMBLEM@\$18.00	36.00
1	FRONT BUMPER	190.00
1	FRONT BUMPER REINFORCEMENT	110.00
1	FRONT BUMPER FOAM	35.00
2	FRONT BUMPER SIDE RETAINER @\$35.00	70.00
1	FRONT BUMPER CENTRE GRILLE	50.00
8	FRONT BUMPER CLIP @\$1.50	12.00
1	AIR CON CONDENSER	125.00
1	RADIATOR	130.00
1	RADIATOR TOP GARNISH	40.00
1	RADIATOR FAN COWLING	90.00
1	RADIATOR FAN BLADE	55.00
1	RADIATOR FAN MOTOR	180.00
2	RADIATOR TOP BRACKET@\$25.00	50.00
1	RADIATOR TOP HOSE	25.00
1	SPARE TANK	55.00
1	FUSES BOX TOP LH	40.00
1	FUSES BOX LOWER LH	35.00
1	FUSES BOX CENTRE LH	60.00
1	BATTERY TOP BRACKET	25.00
1	BATTERY COVER	35.00
1	BATTERY TRAY	40.00
1	MAINFOLD INTAKE	220.00
1	RESONATOR BOX	50.00
1	RESONATOR HOSE	65.00

簡福星嘢咗工廠
KAN TOOK SING MOTOR WORKSHOP
61 DEFU LANE 12
SINGAPORE 539147
TEL: 67479560, 68582126, 68584361
FAX: 67481006, 62818428

VEHICLE NO. : SKT4214M
ACCIDENT DATE : 01-12-2017 17:50
THIRD PARTY REF. : SLB3660Y

<u>QTY</u>	<u>PARTS DESCRIPTION</u>	<u>AMOUNT (SG\$)</u>
1	AIR CLEANER BOX ASSY	260.00
1	ENGINE TOP COVER	75.00
1	FUSE BOX OUTER BRACKET	25.00
1	FRONT GRILLE EMBLEM	25.00
1	THROTTLE BODY	650.00
1	FRONT BUMPER FOGLAMP LH	105.00
1	DASHBOARD AIRBAG WIRE LH	25.00
1	A/C RELAY	150.00
2	RADIATOR BYPASS HOSES	33.00
1	FRONT BUMPER SIDE CLIP COVER	4.00
1	ENGINE ECU	3750.00
		13,944.00
ADD 0 %		
TOTAL (A)		13,944.00

SPECIAL NETT ITEMS

1	FRONT NUMBER PLATE	30.00
1	FRONT WINDSCREEN GUM	40.00
1	ERP STICKER	10.00
1	BATTERY	138.00
TOTAL (C)		218.00

LABOUR CHARGES

1	TO CHECK WIRING SYSTEM	20.00
1	TO REMOVE/REFIT FRONT WINDSCREEN GLASS	100.00
1	TO REMOVE/REFIT/REFILL AIR CON GAS	80.00

簡福星摩多工廠
 KIN FOOK SING MOTOR WORKSHOP
 61 DEFU LANE 12
 SINGAPORE 539147
 TEL: 67479560, 68582126, 68584361
 FAX: 67481006, 62818428

VEHICLE NO. : SKT4214M
 ACCIDENT DATE : 01-12-2017 17:50
 THIRD PARTY REF. : SLB3660Y

<u>QTY</u>	<u>PARTS DESCRIPTION</u>	<u>AMOUNT (SG\$)</u>
1	TO REMOVE/REFIT DASHBOARD	200.00
1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FI- TTING NEW PARTS	1100.00
1	SPRAYPAINTING CHARGES	900.00

TOTAL (D)	2,400.00
TOTAL REPAIR COST :	16,562.00
G S T % :	1,089.34
EXCESS AMOUNT :	1,000.00
INVOICE AMOUNT :	16,651.34



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: KAN FOOK SENG MOTOR WORKSHOP

61 DEFU LANE 12

SINGAPORE 539147

NO: DLI9197043

PAGE: 1

DATE: 12/12/2017

A/C CODE: LDKF239

TERMS: CR

Handwritten signature


VEH NO

SKT4214M

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1 T53301-02310	BONNET	DB1J17*	1	270.00	270.00
2 3510-02670	BONNET LOCK -02671	DU1B86	1	60.00	60.00
3 T53420-02360	BONNET HINGE LH	DU1AD33-0	1	30.00	30.00
4 T53201-02370	SUPPORT PANEL	DB1E4	1	220.00	220.00
5 T53208-02210	BRACE PANEL	DU1E33-2	1	40.00	40.00
6 T53100-02760	GRILLE	DB2H	1	150.00	150.00
7 T81130-02F51	H/LAMP RH	DB1H3	1	650.00	650.00
8 T53181-02070	HEADLAMP CVR RH	DU1H21	1	60.00	60.00
9 T53802-02220	FENDER FR LH	DB1D33	1	190.00	190.00
10 T52119-0Z955	FR BUMPER	DB2G	1	190.00	190.00
11 T52131-02190	BUMPER REINF FR	DB1E33L	1	110.00	110.00
12 T52611-02310	FR BUMPER SPONG	DB1E49	1	35.00	35.00
13 T52116-02270	BUMPER RETAINER FR LH	DU1AD44-1	1	35.00	35.00
14 T52161-0K040	CLIP	DU1AD10-10	1	1.50	1.50
15 T16711-0T101	FAN SHROUD	DBAA1S	1	90.00	90.00
16 T16361-0D201	FAN BLADE	DU1AB20-7	1	55.00	55.00
17 T16363-0T140	FAN MOTOR	DU1Q16	1	180.00	180.00
18 T17120-0T090	INTAKE MANIFOLD	DBCC1S	1	220.00	220.00
19 T17751-0T150	INLET AIR CLEANER	DU1G20-1	1	65.00	65.00
20 T17700-0T110	AIR CLEANER ASSY	DB2K9	1	260.00	260.00
21 T52115-02270	BUMPER RETAINER FR RH	DDS	1	35.00	35.00
22 T17893-0T080	RESONATOR	DDS	1	50.00	50.00
23 T53410-02360	BONNET HINGE RH	DDS	1	30.00	30.00

Print / LIM / 12/12/2017 3:03:32 PM

Cont'd





合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R


TAX INVOICE

M/S: KAN FOOK SING MOTOR WORKSHOP

NO: DLI9197043

PAGE 2

TOTAL QUANTITY:	23	TOTAL	SIN 3,026.50
		ADD GST @ 7%	211.86
		GRAND TOTAL	<u>SIN 3,238.36</u>




Print / LIM / 12/12/2017 3:03:32 PM

SALESMAN: LIM

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE





特立機器貿易 MEGA POWER ENGINEERING & TRADING

Head Office: No. 39 Genting Road Singapore 349485 Tel: 6842 3389 Fax: 6842 3373
Blk 5025, Ang Mo Kio Ind. Park 2 #01-55/57 Singapore 569528 Tel: 6482 3389 Fax: 6481 1187
No. 13 Kaki Bukit Road 4 #01-27 Bartley Biz Centre Singapore 417807 Tel: 6385 3389 Fax: 6385 3329
No. 5 Soon Lee Street #01-26 Pioneer Point Singapore 627607 Tel: 6252 3389 Fax: 6275 3389
No. 21 Toh Guan Road East #01-33 Toh Guan Centre Singapore 608609 Tel: 6766 3389 Fax: 6316 2464
Email: mega1989@singnet.com.sg Business Reg. No: 408691/00-W



TAX INVOICE
GST Reg#: MB-8002998-3
INVOICE# : X611258
INV DATE: 13/12/2017

Bill To: KA008

Ship To: GA1

KAN FOOK SING MOTOR WORKSHOP
61 DEFU LANE 12

KAN FOOK SING MOTOR WORKSHOP
61 DEFU LN 12
LUNCH TIME :12.30PM-2PM
*MUST KEYIN VEH.NO *

S(539147)
TEL: 85048993 FAX: 67481006
Attn : AH TAN

Dept:LOCAL User:GC02 S/O#: S624256 Cr.Term:60 DAYS P/O#: MR053REH104533951

S/No	Bin Code	WH	QTY U/M	U/Price	Amount
1	G1-D3-5 TOY ALTIS ORG FAN TRANSISTOR - SKT 4214M	G1 # 89257-12010	1.00 PCS	150.00	150.00

Note: Goods sold are not returnable.
All Brand New compressor sold are without warranty

Total Amount	(SGD)	150.00
Add 7% GST	(SGD)	10.50
Net Amount	(SGD)	160.50

Goods received in good order By

Goods delivered By

Prepared By

Computer Generated
No Signature required
Print on:13/12/2017-15:09:18



特立機器貿易 MEGA POWER ENGINEERING & TRADING

Head Office: No. 39 Genting Road Singapore 349485 Tel: 6842 3389 Fax: 6842 3373
Blk 5025, Ang Mo Kio Ind. Park 2 #01-55/57 Singapore 569528 Tel: 6482 3389 Fax: 6481 1187
No. 13 Kaki Bukit Road 4 #01-27 Bartley Biz Centre Singapore 417807 Tel: 6385 3389 Fax: 6385 3329
No. 5 Soon Lee Street #01-26 Pioneer Point Singapore 627607 Tel: 6252 3389 Fax: 6275 3389
No. 21 Toh Guan Road East #01-33 Toh Guan Centre Singapore 608609 Tel: 6766 3389 Fax: 6316 2464
Email: mega1989@singnet.com.sg Business Reg. No: 408691/00-W



TAX INVOICE

GST Reg#: M8-8002998-3

INVOICE#: X610769

INV DATE: 12/12/2017

Bill To: KA008

Ship To: GAI

KAN FOOK SING MOTOR WORKSHOP
61 DEFU LANE 12

KAN FOOK SING MOTOR WORKSHOP
61 DEFU LN 12

S(539147)

TEL: 85048993 FAX: 67481006

Attn: AH TAN

LUNCH TIME :12.30PM-2PM

*MUST KEYIN VEH.NO *

Dept:LOCAL User:G002 S/O#: S623780 Cr.Term:60 DAYS P/O#: MR053REHL04533951

S/N	Bin Code	WH	QTY U/M	U/Price	Amount
1	2C1502	G1	1.00 PCS	125.00	125.00
	TOY ALTIS 1.6 CVT ND COND W/DESI# 1331 				
	-				
	SKT 4214M				

Note: Goods sold are not returnable.
All Brand New compressor sold are without warranty

Total Amount	(SGD)	125.00
Add 7% GST	(SGD)	8.75
Net Amount	(SGD)	133.75

Goods received in good order By

Goods delivered By

Prepared By

Computer Generated
No Signature required
Print on:12/12/2017-14:27:19



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: KAN FOOK SING MOTOR WORKSHOP

61 DEFU LANE 12

SINGAPORE 539147

NO: DLI9197048

PAGE: 1

DATE: 12/12/2017

A/C CODE: LDKF239

TERMS: CR

VEH NO: SKT4214M




Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1 T82741-12120	RELAY BLOCK	DU1G22-7	1	60.00	60.00
2 6712-0D150	FAN SHROUD	DU1AB33-1	1	40.00	40.00
3 T82662-02390	RELAY CVR	DDS	1	40.00	40.00
TOTAL QUANTITY:			3	TOTAL	SIN 140.00
				ADD GST @ 7%	9.80
				GRAND TOTAL	SIN 149.80

Reprint 2 / LIM / 12/12/2017 3:13:42 PM

SALESMAN LIM

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE





合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: KAN FOOK SING MOTOR WORKSHOP

61 DEFULANE 12

SINGAPORE 539147

NO: DLI9197088

PAGE: 1


DATE: 13/12/2017

A/C CODE: LDKF239

TERMS: CR

4214

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1 T82663-12140	RELAY CVR LWR	DU1A144	1	35.00	35.00
2 T16261-0T111	HOSE.WATER BY-PASS	DDS	1	15.00	15.00
3 16264-0T071	HOSE.WATER BY-PASS NO 2	DDS	1	18.00	18.00
TOTAL QUANTITY			3	TOTAL	SIN 68.00
				ADD GST @ 7%	4.76
				GRAND TOTAL	<u>SIN 72.76</u>




Reprint 2 / LIM / 13/12/2017 12:31:32 PM

SALESMAN: LIM

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE





合興汽車零件私人有限公司 HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: KAN FOOK SING MOTOR WORKSHOP

61 DEFU LANE 12

SINGAPORE 539147

NO: DL9197100

PAGE: 1

DATE: 13/12/2017

A/C CODE: LDKF239

TERMS: CR

VEH NO: SKT4214M

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
Our D/O No: DDO9020931					
1 45130-02710-C0	STEERING AIRBAG	DD2G6	1	850.00 -	850.00
2 T55302-02660-C0	DASHBOARD	DB3AA	1	650.00 -	650.00
3 T73960-02210	FR AIRBAG LH	DD2G2	1	1,150.00 -	1,150.00
4 T73210-02610-C0	SEATBELT RH	DD2G7	1	280.00 -	280.00
5 T73220-02560-C0	SEATBELT LH	DD3A8	1	280.00 -	280.00
6 T89173-19475	AIRBAG SENSOR RHLH	DUIAF4	2	145.00 -	290.00
7 T84306-06190	CABLE	DD1AS5-5	1	170.00 -	170.00
8 T74404-02550	BATTERY CLAMP	DUID40-3	1	25.00 -	25.00
9 T74431-02280	BATT TRAY	DDS	1	40.00 -	40.00
TOTAL QUANTITY:			10	TOTAL	SIN 3,735.00
				ADD GST @ 7%	261.45
				GRAND TOTAL	<u>SIN 3,996.45</u>

Reprint: 1 / LIM / 13/12/2017 3:10:29 PM

SALESMAN: LIM

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE



... Specialist in automotive spare parts (parallel import models)

GST Registration No.: 200807224Z

Customer Name & Address:

KAN FOOK SING MOTOR WORKSHOP
 61 DEFU LANE 12
 SINGAPORE 539147
 ***skt4214m t/altis

INVOICE No.: A 11225

DATE: 14/12/2017

TERMS: 30 DAYS

S/No.	DESCRIPTION	QUANTITY	UNIT PRICE	AMOUNT
1	RESERVE TANK	1	\$ 55.00	\$ 55.00
2	HOSE, RAD	1	\$ 25.00	\$ 25.00
3	RAD BRKT	2	\$ 25.00	\$ 50.00
4	GRILL RUBBER	1	\$ 15.00	\$ 15.00
5	H/LAMP LH	1	\$ 650.00	\$ 650.00
6	ECU, AIRBAG	1	\$ 280.00	\$ 280.00
7	BRACKET, FUSE BOX	1	\$ 25.00	\$ 25.00
Singapore Dollars			TOTAL	\$ 1,100.00
			GST 7%	\$ 77.00
			DEPOSIT	\$ -
			BALANCE	\$ 1,177.00

Goods Sold are not exchangeable and returnable.

All cheques should be crossed "A/C PAYEE" and made payable to LION'S AUTO TRADING PTE LTD.

for LION'S AUTO TRADING PTE LTD

Customer's Signature and Stamp

Authorised Signature



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: KAN FOOK SING MOTOR WORKSHOP

61 DEFU LANE 12

SINGAPORE 539147

NO: DLI9197120

PAGE: 1

DATE: 14/12/2017

A/C CODE: LDKF239

TERMS: CR

VEH NO: SKT4214M


Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1 T82140-02420	WIRE AIRBAG LH	DD1A34-3	1	25.00	25.00
TOTAL QUANTITY:			1	TOTAL	SIN 25.00
				ADD GST @ 7%	1.75
				GRAND TOTAL	<u>SIN 26.75</u>

Print / LIM / 14/12/2017 10:19:58 AM

SALESMAN: LIM

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE



GOODS RECEIVED BY





力善汽車零件私人有限公司 LESUN AUTO PARTS PTE LTD

BLK 3018 UBI ROAD 1 #02-117 SINGAPORE 408710

TEL: 6846 8655 FAX: 6748 3092

A/C TEL: 6291 1886 FAX: 6291 7717

EMAIL: lesun@singnet.com.sg

Co. Reg. No.: 200516381H GST Reg. No.: 200516381H

TAX INVOICE

M/S: KAN FOOK SING MOTOR WORKSHOP

61 DEFULANE 12 (S) 539147

NO: LLI0203068

DATE: 18/12/2017


A/C CODE: LLDKFS7

TERMS: CR

SKJ 4214 m

PAGE:1

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1	LT90467-05090-B1	FRT BUMPER SIDE CLIP R/L IF-5D	2	1.50	3.00
2	LT90467-05090-B1	FRT BUMPER SIDE CLIP R/L LL1	1	1.50	1.50
TOTAL QUANTITY:			3	TOTAL	SIN 4.50
				ADD GST @ 7%	0.32
				GRAND TOTAL	SIN 4.82



Print / EDDIE / 18/12/2017 4:01:17 PM

SALESMAN: EDDIE

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

E. & O. E.

GOODS RECEIVED BY





合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: KAN FOOK SING MOTOR WORKSHOP

61 DEFULANE 12

SINGAPORE 539147

T/ALTIS

NO: DLI9197248

PAGE: 1

DATE: 18/12/2017

A/C CODE: LDKF239

TERMS: CR

VEH NO: SKT4214M


Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
11212-37010	COVER CYLINDER	DU1AC39-4	1	75.00	75.00
TOTAL QUANTITY:			1	TOTAL	SIN 75.00
				ADD GST @ 7%	5.25
				GRAND TOTAL	SIN 80.25

Print / LCC / 18/12/2017 12:11:25 PM

SALESMAN: LCC

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE



Ec&Odey
PARTS

GOODS RECEIVED BY

18

18

18

18/12/2017

18/12/2017

... Specialist in automotive spare parts (parallel import models)

GST Registration No.: 200807224Z

Customer Name & Address:

KAN FOOK SING MOTOR WORKSHOP
 61 DEFU LANE 12
 SINGAPORE 539147
 ***skt4214m t/altis

INVOICE No.: A 11226

DATE: 18/12/2017

TERMS: 30 DAYS

S/No.	DESCRIPTION	QUANTITY	UNIT PRICE	AMOUNT
1	VVTI EMBLEM	2	\$ 18.00	\$ 36.00
2	CVR BATTERY	1	\$ 35.00	\$ 35.00
3	CLIP	6	\$ 1.50	\$ 9.00
4	CLIPS	10	\$ 1.50	\$ 15.00
5	CLIP	10	\$ 1.50	\$ 15.00
6	FENDER INNER SHIELD FRT L	1	\$ 55.00	\$ 55.00
Singapore Dollars			TOTAL	\$ 165.00
			GST 7%	\$ 11.55
			DEPOSIT	\$ -
			BALANCE	\$ 176.55

Goods Sold are not exchangeable and returnable.

All cheques should be crossed "A/C PAYEE" and made payable to LION'S AUTO TRADING PTE LTD.

for LION'S AUTO TRADING PTE LTD

Customer's Signature and Stamp

Authorised Signature



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: KAN FOOK SING MOTOR WORKSHOP

61 DEFU LANE 12

SINGAPORE 539147

T/ALTIS

NO: DL19197236

PAGE: 1


DATE: 18/12/2017

A/C CODE: LDKF239

TERMS: CR

VEH NO: SKJ4214M

Part No	Description	Location	Qty	Unit Price	Amount
				<u>SIN</u>	<u>SIN</u>
1 T81220-47010	FOGLAMP ASSY LH	DBAA9	1	105.00	105.00
TOTAL QUANTITY:			1	TOTAL	SIN 105.00
				ADD GST @ 7%	7.35
				GRAND TOTAL	<u><u>SIN 112.35</u></u>






Print / LCC / 18/12/2017 11:13:04 AM

SALESMAN: LCC

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE





合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403
TOYOTA / LEXUS / MITSUBISHI / FORD / WINDSCREEN / CHEVROLET /
DAIHATSU / KIA / SUZUKI / HONDA
TEL: 6291 2827 FAX: 6296 4390
A/C: 6291 1888 FAX: 6291 7717
Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: KAN FOOK SING MOTOR WORKSHOP

61 DEFULANE 12

SINGAPORE 539147
T/ALTIS

NO: DLI9197225

PAGE: 1

DATE: 18/12/2017

A/C CODE: LDKF239

TERMS: CR

VEH NO: SKJ4214M




Part No	Description	Location	Qty	Unit Price	Amount
				<u>SIN</u>	<u>SIN</u>
1 T53341-02290	BONNET INSULATOR	DB2K2	1	95.00	95.00
2 T75311-02190	GRILLE LOGO	DUIAS3-62	1	25.00	25.00
3 T53141-02110	RAD CVR	DUIE8	1	35.00	35.00
4 T53112-02630	FR LWR GRILLE	DUIF14-5	1	50.00	50.00
5 T53879-58010	RETAINER FR FENDER	DUIA105	1	4.00	4.00
6 T22030-37050	THROTTLE BODY	DUIAD9	1	650.00	650.00
7 T47749-58010	CLIP	DUIAD10-6	1	1.50	1.50
8 T52161-16010	CLIP	DUIAD11-3	3	1.50	4.50
TOTAL QUANTITY:			10	TOTAL	SIN 865.00
				ADD GST @ 7%	60.55
				GRAND TOTAL	<u>SIN 925.55</u>

Reprint:2 / LCC / 18/12/2017 5:33:15 PM

SALESMAN: LCC

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE



GOODS RECEIVED BY





合興汽車玻璃私人有限公司

HE XING AUTO GLASS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403
CAR WINDSCREEN DIV. No 26 CUFF RD. S 209736
TEL : 6298 3113 FAX : 6298 3002
A/C : 6291 1886 FAX : 6291 7717
Co. Reg. No: 200310936C GST Reg. No: 20-0310936-C

TAX INVOICE

M/S : KAN FOOK SING MOTOR WORKSHOP


61 DEFU LANE 12 (S) 539147

TOYOTA COROLLA ALTIS (SKT 4214)

NO: GLI8129208
DATE: 18/12/2017
A/C CODE: LDKF239
TERMS: CR
P/O NO: SKT 4214

PAGE:1

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
WT56101-02967	W/S GLASS FRT	CC1A	1	380.00 —	380.00
2 T75531-02220	W/S MLDG FRT	CC1A	1	40.00 —	40.00
			2	TOTAL	SIN 420.00
				ADD GST @ 7%	29.40
				GRAND TOTAL	<u>SIN 449.40</u>



Reprint:1 / SENG / 18/12/2017 10:16:35 AM

SALESMAN: SENG

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

Back Glass

Door Glass

E. & O. E.

GOODS RECEIVED BY Side Glass



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: KAN FOOK SING MOTOR WORKSHOP

61 DEFU LANE 12

SINGAPORE 539147

NO: DLI9197121

PAGE: 1


DATE: 14/12/2017

A/C CODE: LDKF239

TERMS: CR

VEH NO: SKT4214M

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1 53182-02070	HEADLAMP CVR LH	DUIF27-1	1 /	60.00	60.00
TOTAL QUANTITY			1	TOTAL	SIN 60.00
				ADD GST @ 7%	4.20
				GRAND TOTAL	<u>SIN 64.20</u>




Print 'LIM' / 14/12/2017 10:22:55 AM

SALESMAN: LIM


This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE



Ec&Ord1st
PARTS

GOODS RECEIVED BY



CHOP SONG HUAT
1 Kaki Bukit Avenue 6, #01-104, Auto Bay @ Kaki Bukit, Singapore 417883
Tel: (65) 6747 4366 Fax: (65) 6747 7560
No. 1, Syed Alwi Road #01-03, Song Lin Building, Singapore 207628
Tel: (65) 6294 3698 Fax: (65) 6297 0448
Reg. No. 040495/00X

No. 102555

Date 12/12/81

Reg. No. 040452001

KAN FOLK SONG

M. SKT

421 U M

Specialize In All Types of Motor Vehicle's Radiator.

[illegible]

貨物出門恕不退換。
Goods sold are not returnable.

E. & O. E.

共銀
TOTAL

... Specialist in automotive spare parts (parallel import models)

GST Registration No.: 200807224Z

Customer Name & Address:

KAN FOOK SING MOTOR WORKSHOP
61 DEFU LANE 12
SINGAPORE 539147
***skt4214m t/altis

INVOICE No.: A 11227

DATE: 26/2/2018

TERMS: 30 DAYS

S/No.	DESCRIPTION	QUANTITY	UNIT PRICE	AMOUNT
1	ECU ENGINE	1	\$ 3,750.00	\$ 3,750.00
Singapore Dollars			TOTAL	\$ 3,750.00
			GST 7%	\$ 262.50
			DEPOSIT	\$ -
			BALANCE	\$ 4,012.50

Goods Sold are not exchangeable and returnable.

All cheques should be crossed "A/C PAYEE" and made payable to LION'S AUTO TRADING PTE LTD.

for LION'S AUTO TRADING PTE LTD

Customer's Signature and Stamp

Authorised Signature

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Dec 2017 Sendback Est	04 Dec 2017 12:29 S\$13,518.00	04 Dec 2017 14:09 Edit Adj Rpt	S\$16,562.00 Edit Estimates	S\$16,562.00 View Rpt		Pending for Survey Report Cancel Case
Supp #1	09 Mar 2018 11:47	09 Mar 2018 11:50 S\$4,767.00	09 Mar 2018 11:50			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	CHONG SHU HUI, EILEEN (ZHONG SHUHUI) , ID: S7907460H, Tel: +6598223461, Email: nicholdimus@hotmail.com		
Vehicle Reg. No.:	SKT4214M	Date of Loss:	01/12/2017 17:00 - :59 [29 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 1201700008458	Policy/Cover Note No.:	PNPV2017-00004409 (Comprehensive)
		Excess:	S\$1,000.00
Repairer:	Kan Fook Sing Motor Workshop (Defu) No. 61 Defu Lane 12, 539147 Defu Lane - Tel: 67479560		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 13/12/2017]		
Driver/Custodian:	CHONG SHU HUI, EILEEN (ZHONG SHUHUI) (38 / Female), NRIC: S7907460H, Tel: +6598223461		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- FWD_SG (12/04/2018): Alert - Adj Mandate Approved (S\$16562.00) - SKT4214M - Claim Handler: Clara Li Z...
- FWD_SG (06/12/2017): Alert - Adj Mandate Approved (S\$12088.00) - SKT4214M - Claim Handler: Clara Li Z...

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SKT4214M (1201700008458)
OD
Dec 1 2017 5:00PM
[CHONG SHU HUI, EILEEN (ZHONG SHUHUI)]
Kan Fook Sing Motor Workshop

Upload Documents		Upload Photos	Compose New Letter	View View in Browser v	
Assessment Reports				1 per page v	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)		Thumbnail	Print
1	04/12/17 12:29	Repairer Estimates		Load HTM	☐
2	09/03/18 11:50	Repairer Estimates Suppl. #1		Load HTM	☐
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	06/12/17 17:55	Adjuster Immediate Advice		Load HTM	☐
2	12/04/18 12:16	Adjuster Immediate Advice		Load HTM	☐
Photos/Images				3 per page v	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)		Thumbnail	Print
1	04/12/17 10:37	Accident Photo		Load JPG	☒
2	04/12/17 10:37	Accident Photo		Load JPG	☒
3	04/12/17 10:37	Accident Photo		Load JPG	☒
4	04/12/17 10:37	Accident Photo		Load JPG	☒
5	04/12/17 10:37	Accident Photo		Load JPG	☒
6	04/12/17 10:37	Accident Photo		Load JPG	☒
7	04/12/17 10:37	Accident Photo		Load JPG	☒
8	04/12/17 10:37	Accident Photo		Load JPG	☒
9	04/12/17 10:37	Accident Photo		Load JPG	☒
10	04/12/17 10:37	Accident Photo		Load JPG	☒
11	04/12/17 10:37	Accident Photo		Load JPG	☒
12	04/12/17 10:37	Accident Photo		Load JPG	☒
13	04/12/17 10:37	Accident Photo		Load JPG	☒
14	04/12/17 10:37	Accident Photo		Load JPG	☒
15	04/12/17 10:37	Accident Photo		Load JPG	☒
16	04/12/17 10:37	Accident Photo		Load JPG	☒
17	04/12/17 10:37	Accident Photo		Load JPG	☒
18	04/12/17 10:37	Accident Photo		Load JPG	☒
19	04/12/17 10:37	Accident Photo		Load JPG	☒
20	04/12/17 10:37	Accident Photo		Load JPG	☒
21	04/12/17 10:37	Accident Photo		Load JPG	☒
22	04/12/17 10:37	Accident Photo		Load JPG	☒
23	04/12/17 10:37	Accident Photo		Load JPG	☒
24	04/12/17 10:37	Accident Photo		Load JPG	☒
25	04/12/17 10:37	Accident Photo		Load JPG	☒
26	04/12/17 10:37	Accident Photo		Load JPG	☒
27	04/12/17 10:37	Accident Photo		Load JPG	☒
28	04/12/17 10:37	Accident Photo		Load JPG	☒
29	04/12/17 10:37	Accident Photo		Load JPG	☒
30	04/12/17 10:37	Accident Photo		Load JPG	☒
31	04/12/17 10:37	Accident Photo		Load JPG	☒
32	04/12/17 10:37	Accident Photo		Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
33	04/12/17 10:37	Accident Photo	 Load JPG	☒
34	04/12/17 10:37	Accident Photo	 Load JPG	☒
35	04/12/17 10:37	Accident Photo	 Load JPG	☒
36	04/12/17 10:37	Accident Photo	 Load JPG	☒
37	04/12/17 10:37	Accident Photo	 Load JPG	☒
38	04/12/17 10:37	Accident Photo	 Load JPG	☒
39	04/12/17 10:37	Accident Photo	 Load JPG	☒
40	04/12/17 10:37	Accident Photo	 Load JPG	☒
41	04/12/17 10:37	Accident Photo	 Load JPG	☒
42	04/12/17 10:37	Accident Photo	 Load JPG	☒
43	04/12/17 10:37	Accident Photo	 Load JPG	☒
44	04/12/17 10:37	Accident Photo	 Load JPG	☒
45	04/12/17 10:37	Accident Photo	 Load JPG	☒
46	04/12/17 10:37	Accident Photo	 Load JPG	☒
47	04/12/17 10:37	Accident Photo	 Load JPG	☒
48	04/12/17 10:37	Accident Photo	 Load JPG	☒
49	04/12/17 10:37	TYRE	 Load JPG	☒
50	04/12/17 10:37	TYRE BRAND	 Load JPG	☒
51	04/12/17 10:37	TYRE SIZE	 Load JPG	☒
52	04/12/17 10:37	TYRE TREAD	 Load JPG	☒
53	04/12/17 10:37	Chassis Number	 Load JPG	☒
54	04/12/17 10:37	Accident Photo	 Load JPG	☒
55	04/12/17 10:37	Accident Photo	 Load JPG	☒
56	04/12/17 10:37	Accident Photo	 Load JPG	☒
57	04/12/17 10:37	Accident Photo	 Load JPG	☒
58	04/12/17 10:37	Accident Photo	 Load JPG	☒
59	04/12/17 10:37	Accident Photo	 Load JPG	☒
60	04/12/17 10:37	Accident Photo	 Load JPG	☒
61	04/12/17 10:37	Accident Photo	 Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/04/18 12:18	General View	 Load JPG	☒
2	12/04/18 12:18	General View	 Load JPG	☒
3	12/04/18 12:18	General View	 Load JPG	☒
4	12/04/18 12:18	General View	 Load JPG	☒
5	12/04/18 12:18	General View	 Load JPG	☒
6	12/04/18 12:18	General View	 Load JPG	☒
7	12/04/18 12:18	General View	 Load JPG	☒
8	12/04/18 12:18	General View	 Load JPG	☒
9	12/04/18 12:18	General View	 Load JPG	☒
10	12/04/18 12:18	General View	 Load JPG	☒
11	12/04/18 12:18	General View	 Load JPG	☒
12	12/04/18 12:18	General View	 Load JPG	☒
13	12/04/18 12:18	General View	 Load JPG	☒
14	12/04/18 12:18	General View	 Load JPG	☒
15	12/04/18 12:18	General View	 Load JPG	☒
16	12/04/18 12:18	General View	 Load JPG	☒
17	12/04/18 12:18	General View	 Load JPG	☒
18	12/04/18 12:18	General View	 Load JPG	☒
19	12/04/18 12:18	General View	 Load JPG	☒
20	12/04/18 12:18	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
21	12/04/18 12:18	General View	 Load JPG	☒
22	12/04/18 12:18	General View	 Load JPG	☒
23	12/04/18 12:18	General View	 Load JPG	☒
24	12/04/18 12:18	General View	 Load JPG	☒
25	12/04/18 12:18	General View	 Load JPG	☒
26	12/04/18 12:18	General View	 Load JPG	☒
27	12/04/18 12:18	General View	 Load JPG	☒
28	12/04/18 12:18	General View	 Load JPG	☒
29	12/04/18 12:18	General View	 Load JPG	☒
30	12/04/18 12:18	General View	 Load JPG	☒
31	12/04/18 12:18	General View	 Load JPG	☒
32	12/04/18 12:18	General View	 Load JPG	☒
33	12/04/18 12:18	General View	 Load JPG	☒
34	12/04/18 12:18	General View	 Load JPG	☒
35	12/04/18 12:18	General View	 Load JPG	☒
36	12/04/18 12:18	General View	 Load JPG	☒
37	12/04/18 12:18	General View	 Load JPG	☒
38	12/04/18 12:18	General View	 Load JPG	☒
39	12/04/18 12:18	General View	 Load JPG	☒
40	12/04/18 12:18	General View	 Load JPG	☒
41	12/04/18 12:18	General View	 Load JPG	☒
42	12/04/18 12:18	General View	 Load JPG	☒
43	12/04/18 12:18	General View	 Load JPG	☒
44	12/04/18 12:18	General View	 Load JPG	☒
45	12/04/18 12:18	General View	 Load JPG	☒
46	12/04/18 12:18	General View	 Load JPG	☒
47	12/04/18 12:18	General View	 Load JPG	☒
48	12/04/18 12:18	General View	 Load JPG	☒
49	12/04/18 12:18	General View	 Load JPG	☒
50	12/04/18 12:18	General View	 Load JPG	☒
51	12/04/18 12:18	General View	 Load JPG	☒
52	12/04/18 12:18	General View	 Load JPG	☒
53	12/04/18 12:18	General View	 Load JPG	☒
54	12/04/18 12:18	General View	 Load JPG	☒
55	12/04/18 12:18	General View	 Load JPG	☒
56	12/04/18 12:18	General View	 Load JPG	☒
57	12/04/18 12:18	General View	 Load JPG	☒
58	12/04/18 12:18	General View	 Load JPG	☒
59	12/04/18 12:18	General View	 Load JPG	☒
60	12/04/18 12:18	General View	 Load JPG	☒
61	12/04/18 12:18	General View	 Load JPG	☒
62	12/04/18 12:18	General View	 Load JPG	☒
63	12/04/18 12:19	Reinspection Photo	 Load JPG	☒
64	12/04/18 12:19	Reinspection Photo	 Load JPG	☒
65	12/04/18 12:19	Reinspection Photo	 Load JPG	☒
66	12/04/18 12:19	Reinspection Photo	 Load JPG	☒
67	12/04/18 12:19	Reinspection Photo	 Load JPG	☒
68	12/04/18 12:19	Reinspection Photo	 Load JPG	☒
69	12/04/18 12:19	Reinspection Photo	 Load JPG	☒
70	12/04/18 12:19	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
71	12/04/18 12:19	Reinspection Photo	 Load JPG	☒
72	12/04/18 12:19	Reinspection Photo	 Load JPG	☒
73	12/04/18 12:19	Reinspection Photo	 Load JPG	☒
74	12/04/18 12:19	Reinspection Photo	 Load JPG	☒
75	12/04/18 12:19	Reinspection Photo	 Load JPG	☒
76	12/04/18 12:19	Reinspection Photo	 Load JPG	☒
77	12/04/18 12:19	Reinspection Photo	 Load JPG	☒
78	12/04/18 12:19	Reinspection Photo	 Load JPG	☒
79	12/04/18 12:19	Reinspection Photo	 Load JPG	☒
80	12/04/18 12:19	Reinspection Photo	 Load JPG	☒
81	12/04/18 12:19	Reinspection Photo	 Load JPG	☒
82	12/04/18 12:19	Reinspection Photo	 Load JPG	☒
83	12/04/18 12:19	Reinspection Photo	 Load JPG	☒
84	12/04/18 12:19	Reinspection Photo	 Load JPG	☒
85	12/04/18 12:19	Reinspection Photo	 Load JPG	☒
86	12/04/18 12:19	Reinspection Photo	 Load JPG	☒
87	12/04/18 12:19	Reinspection Photo	 Load JPG	☒
88	12/04/18 12:19	Reinspection Photo	 Load JPG	☒
89	12/04/18 12:19	Reinspection Photo	 Load JPG	☒
90	12/04/18 12:19	Reinspection Photo	 Load JPG	☒
91	12/04/18 12:19	Reinspection Photo	 Load JPG	☒
92	12/04/18 12:19	Reinspection Photo	 Load JPG	☒
93	12/04/18 12:19	Reinspection Photo	 Load JPG	☒
94	12/04/18 12:19	Reinspection Photo	 Load JPG	☒
95	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
96	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
97	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
98	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
99	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
100	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
101	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
102	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
103	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
104	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
105	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
106	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
107	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
108	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
109	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
110	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
111	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
112	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
113	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
114	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
115	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
116	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
117	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
118	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
119	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
120	12/04/18 12:20	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
121	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
122	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
123	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
124	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
125	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
126	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
127	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
128	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
129	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
130	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
131	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
132	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
133	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
134	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
135	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
136	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
137	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
138	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
139	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
140	12/04/18 12:20	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	04/12/17 10:29	E-filed GIA report	 Load PDF	
2	13/04/18 09:24	Repairer's Bill	 Load PDF	
3	13/04/18 09:24	Signed DV	 Load PDF	
4	13/04/18 09:24	Survey Questionnaire	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/04/18 12:25	SKT 4214M SUPPLEMENTARY	 Load PDF	
2	12/04/18 12:36	SKT 4214M ESTIMATE	 Load PDF	
3	18/04/18 12:47	Parts Invoice	 Load PDF	
4	18/04/18 12:47	Workshop Invoice	 Load PDF	

Linked Accident Report Documents

Video			View	View In Browser
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	05/12/17 16:49	Video - Accident	 Load MP4	
2	05/12/17 16:53	Video - Accident	 Load MP4	
3	05/12/17 16:54	Video - Accident	 Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	02/12/17 14:26	Accident Statement	 Load HTM	
2	05/12/17 17:00	Addendum Sheet	 Load TIFF	
3	05/12/17 17:01	Accident Statement Addm. #1	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	02/12/17 12:55	Accident Photo	 Load JPG	☒
2	02/12/17 12:55	Accident Photo	 Load JPG	☒
3	02/12/17 12:55	Accident Photo	 Load JPG	☒
4	02/12/17 12:55	Accident Photo	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
5	02/12/17 12:55	Accident Photo	 Load JPG	☒
6	02/12/17 12:55	Accident Photo	 Load JPG	☒
7	02/12/17 12:55	Accident Photo	 Load JPG	☒
8	02/12/17 12:55	Accident Photo	 Load JPG	☒
9	02/12/17 12:55	Accident Photo	 Load JPG	☒
10	02/12/17 12:55	Accident Photo	 Load JPG	☒
11	02/12/17 12:55	Accident Photo	 Load JPG	☒
12	02/12/17 12:55	Accident Photo	 Load JPG	☒
13	02/12/17 12:55	Accident Photo	 Load JPG	☒
14	02/12/17 12:55	Accident Photo	 Load JPG	☒
15	02/12/17 12:55	Accident Photo	 Load JPG	☒
16	02/12/17 12:55	Accident Photo	 Load JPG	☒
17	02/12/17 12:55	Accident Photo	 Load JPG	☒
18	02/12/17 12:55	Accident Photo	 Load JPG	☒
19	02/12/17 12:55	Accident Photo	 Load JPG	☒
20	02/12/17 12:55	Accident Photo	 Load JPG	☒
21	02/12/17 12:55	Accident Photo	 Load JPG	☒
22	02/12/17 12:55	Accident Photo	 Load JPG	☒
23	02/12/17 12:55	Accident Photo	 Load JPG	☒
24	02/12/17 12:55	Accident Photo	 Load JPG	☒
25	02/12/17 12:55	Accident Photo	 Load JPG	☒
26	02/12/17 12:55	Accident Photo	 Load JPG	☒
27	02/12/17 12:55	Accident Photo	 Load JPG	☒
28	02/12/17 12:55	Accident Photo	 Load JPG	☒
29	02/12/17 12:55	Accident Photo	 Load JPG	☒
30	02/12/17 12:55	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	02/12/17 14:25	Accident Sketch Plan	 Load TIF	
2	02/12/17 14:25	Accident Sketch Plan	 Load TIF	
3	02/12/17 14:25	insurer's nric & license	 Load TIF	
4	02/12/17 14:25	certificate of insurance	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower 4
Singapore 038986

Our File No: CS/FWD17022970/GRBE2

Date: 18/04/2018

REFERENCE

Insured/Claimant: CHONG SHU HUI, EILEEN (ZHONG SHUHUI)

Policy No: PNPV2017-00004409

Date of Loss: 01/12/2017

Nature of Claim:

OD

Claim No:

1201700008458

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKT4214M

Make & Model: TOYOTA COROLLA ALTIS, 1.6 L CVT (A)

Engine No: 1ZR514076

Reg. Date: 08/06/2015 (Man. Year: 2015)

Chassis No: MR053REH104533951

Colour: Grey

Odometer: 0 km

Engine Capacity: 1598 cc

Market Value/New Car Price: S\$79,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,777.00	13,944.00	833.00	5.64
Miscellaneous Items	218.00	218.00	0.00	0.00
Labour	2,090.00	1,500.00	590.00	28.23
Paintwork Labour	1,200.00	900.00	300.00	25.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,285.00	16,562.00	1,723.00	9.42
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	17,285.00	15,562.00	1,723.00	9.97
+ GST 7.00/7.00% (S\$)	1,209.95	1,089.34	120.61	9.97
Nett Amount (S\$)	18,494.95	16,651.34	1,843.61	9.97

INSPECTION

Date of Assignment: 04/12/2017 Present Location:

Kan Fook Sing Motor Workshop (Defu)

Date Inspected: 05/12/2017 Inspected At:

No. 61 Defu Lane 12

Singapore 539147

Estimated Period of Repair: 9.0 days

Adjuster: XING GUO QIANG

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 18 Apr 2018)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 L CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKT4214M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN GLASS	Cracked	400.00 F	*380.00 F
2	1		*FRONT WINDSCREEN MOULDING	Necessary	40.00 F	*40.00 F
3	1		*STEERING AIR BAG	Activated	850.00 F	*850.00 F
4	1		*STEERING AIR BAG WIRE	Activated	170.00 F	*170.00 F
5	1		*DASHBOARD	Cracked	650.00 F	*650.00 F
6	1		*DASHBOARD AIR BAG	Activated	1,150.00 F	*1,150.00 F
7	1		*SEAT BELT RH	Activated	280.00 F	*280.00 F
8	1		*SEAT BELT LH	Activated	280.00 F	*280.00 F
9	1		*AIR BAG ECU	Activated	280.00 F	*280.00 F
10	1		*AIR BAG IMPACT SENSOR RH	Activated	145.00 F	*145.00 F
11	1		*AIR BAG IMPACT SENSOR LH	Activated	145.00 F	*145.00 F
12	1		*FRONT BONNET	Buckled	270.00 F	*270.00 F
13	1		*FRONT BONNET LOCK	Bent	60.00 F	*60.00 F
14	1		*FRONT BONNET HINGE RH	Bent	30.00 F	*30.00 F
15	1		*FRONT BONNET HINGE LH	Bent	30.00 F	*30.00 F
16	1		*FRONT BONNET INSULATOR	Deformed	95.00 F	*95.00 F
17	10		*FRONT BONNET INSULATOR CLIP	Necessary	15.00 F	*15.00 F
18	1		*FRONT SUPPORT PANEL	Buckled	220.00 F	*220.00 F
19	1		*FRONT BRACE PANEL	Bent	40.00 F	*40.00 F
20	1		*FRONT GRILLE	Cracked	150.00 F	*150.00 F
21	1		*FRONT GRILLE TOP GARNISH	Deformed	35.00 F	*35.00 F
22	6		*FRONT GRILLE TOP GARNISH CLIP	Necessary	9.00 F	*9.00 F
23	1		*FRONT GRILLE TOP RUBBER	Deformed	15.00 F	*15.00 F
24	1		*FRONT HEADLAMP RH	Cracked	650.00 F	*650.00 F
25	1		*FRONT HEADLAMP LH	Distorted	650.00 F	*650.00 F
26	1		*FRONT HEADLAMP CHROME RH	Necessary	60.00 F	*60.00 F
27	1		*FRONT HEADLAMP CHROME LH	Necessary	60.00 F	*60.00 F
28	1		*FRONT FENDER LH	Buckled	190.00 F	*190.00 F
29	1		*FRONT FENDER SHIELD LH	Deformed	55.00 F	*55.00 F
30	10		*FRONT FENDER SHIELD CLIP	Necessary	15.00 F	*15.00 F
31	1		*FRONT FENDER VVTI EMBLEM RH	Necessary	18.00 F	*18.00 F
32	1		*FRONT FENDER VVTI EMBLEM LH	Necessary	18.00 F	*18.00 F
33	1		*FRONT BUMPER	Cracked	190.00 F	*190.00 F
34	1		*FRONT BUMPER REINFORCEMENT	Bent	110.00 F	*110.00 F
35	1		*FRONT BUMPER FOAM	Deformed	35.00 F	*35.00 F
36	1		*FRONT BUMPER SIDE RETAINER RH	Necessary	35.00 F	*35.00 F
37	1		*FRONT BUMPER SIDE RETAINER LH	Necessary	35.00 F	*35.00 F
38	1		*FRONT BUMPER CENTRE GRILLE	Deformed	50.00 F	*50.00 F
39	10		*FRONT BUMPER CLIP	Necessary	15.00 F	*12.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*FRONT CHASSIS FRAME BRACKET RH	Not Necessary	35.00 F	*- F
41	1		*FRONT CHASSIS FRAME BRACKET LH	Not Necessary	35.00 F	*- F
42	1		*AIR CON CONDENSER	Bent	380.00 F	*125.00 F
43	1		*AIR CON LIQUID PIPE	Not Necessary	40.00 F	*- F
44	1		*RADIATOR	Bent	380.00 F	*130.00 F
45	1		*RADIATOR TOP GARNISH	Cracked	40.00 F	*40.00 F
46	1		*RADIATOR FAN COWLING	Cracked	90.00 F	*90.00 F
47	1		*RADIATOR FAN BLADE	Cracked	55.00 F	*55.00 F
48	1		*RADIATOR FAN MOTOR	Not Working	180.00 F	*180.00 F
49	1		*RADIATOR TOP BRACKET RH	Bent	25.00 F	*25.00 F
50	1		*RAIDATOR TOP BRACKET LH	Bent	25.00 F	*25.00 F
51	1		*RAIDATOR TOP HOSE	Cut	25.00 F	*25.00 F
52	1		*SPARE TANK	Deformed	55.00 F	*55.00 F
53	1		*FUSE BOX TOP	Cracked	40.00 F	*40.00 F
54	1		*FUSES BOX LOWER	Cracked	35.00 F	*35.00 F
55	1		*FUSES BOX CENTRE	Cracked	60.00 F	*60.00 F
56	1		*BATTERY TOP BRAK CET	Bent	25.00 F	*25.00 F
57	1		*BATTERY COVER	Deformed	35.00 F	*35.00 F
58	1		*BATTERY TRAY	Deformed	40.00 F	*40.00 F
59	1		*MANIFOLD INTAKE	Cracked	220.00 F	*220.00 F
60	1		*RESONATOR BOX	Cracked	50.00 F	*50.00 F
61	1		*RESONATOR HOSE	Cracked	65.00 F	*65.00 F
62	1		*AIR CLEANER BOX ASSY	Cracked	260.00 F	*260.00 F
63	1		*ENGIEN TOP COVER	Cut	85.00 F	*75.00 F
64	1		*ENGINE MOUNTING LH	Not Necessary	95.00 F	*- F
65	1		*ENGINE MOUNTING FR	Not Necessary	90.00 F	*- F
Supplementary #1						
66	1		*FRONT BUMPER SIDE CLIP COVER	Necessary	4.00 F	*4.00 F
67	1		*ENGINE ECU	Damaged	3,750.00 F	*3,750.00 F
68	1		*FUSE BOX OUTER BRACKET	Bent	25.00 F	*25.00 F
69	1		*FRONT GRILLE EMBLEM	Necessary	25.00 F	*25.00 F
70	1		*THROTTLE BODY	Damaged	650.00 F	*650.00 F
71	1		*FRONT BUMPER FOG LAMP LH	Cracked	105.00 F	*105.00 F
72	1		*DASHBOARD AIRBAG WIRE LH	Damaged	25.00 F	*25.00 F
73	1		*A/C RELAY	Damaged	150.00 F	*150.00 F
74	1		*RADIATOR BYPASS HOSE	Cut	33.00 F	*33.00 F
F=Franchise part.						
Total Parts (S\$)					14,777.00	13,944.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	BATTERY (CRACKED)	138.00	138.00
2	1	ERP STICKER (NECESSARY)	10.00	10.00
3	1	FRONT NUMBER PLATE (BENT)	30.00	30.00
4	1	FRONT WINDSCREEN GUM (NECESSARY)	40.00	40.00
Sub Total (\$\$)			218.00	218.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	SPRAYPAINTING CHARGES	New	1,200.00	900.00
Labour Items				
2	TO CHECK WIRING SYSTEM	New	50.00	20.00
3	TO REMOVE/REFIT FRONT WINDSCREEN GLASS	New	100.00	100.00
4	TO REMOVE/REFIT/REFILL AIR CON GAS	New	80.00	80.00
5	TO REMOVE/REFIT ENGINE MOUNTINGS	New	80.00	0.00
6	TO REMOVE/REFIT DASHBOARD	New	280.00	200.00
7	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	1,500.00	1,100.00
Gross Labour Cost (\$\$)			3,290.00	2,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >