




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
M NEDUMARAN & CO*		Ref : CS/LAW17023016/T1vbe2		
No. 11 SIN MING ROAD #B2-09 (UNIT 2), THOMSON V TWO SINGAPORE 575629		Date : 28-12-2017		
		Code : L134		
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	SJU 2932T	Veh. Inspected	PC 2009H	
Policy No.	PCS.CCC.2017.213930.TM	Coverage (\$)	0.00	
Claim No.	MN/IG/E2/1611043	Excess (\$)	0.00	
Assign From	IGENE LIM	Assign Date	30/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE HIROOF	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	JTFST22P600017012	Colour	WHITE	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	YOKOHAMA	5 mm	
L/H Front Tyre	195 R15	YOKOHAMA	5 mm	
R/H Rear Tyre	195 R15	YOKOHAMA	5 mm	
L/H Rear Tyre	195 R15	YOKOHAMA	5 mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	27/06/2016	Inspection Date	06/12/2017	
Survey held at	38 WOODLANDS IND PARK E1 #05-13			
Repairer	EMERSON AUTOMOTIVE SERVICES PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		