

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
DIRECT ASIA INSURANCE (S) PL			Ref : CC6/DAI17023026/Upa3s2		
88 SOUTH BRIDGE ROAD SINGAPORE 058716			Date: 03-05-2018 Code: DAI		
1. Policy Particulars :- THIRD PARTY CLAIM					
1.	Insured Veh.	SJS 9447S	ı	MCN 3065	
	Policy No.	333 9447 3	Veh. Inspected Coverage (\$)	0.00	
	Claim No.	74069	Excess (\$)	0.00	
	Assign From	74003	Assign Date	05/12/2017	
0	Assign From	Vahiala Bautia		03/12/2017	
2.	Mala O Madal		culars & Condition	1495	
	Make & Model	TOYOTA AVANZA (A)	C.C	2014	
	Engine No. Chassis No.	MHKM1CB3M0K009697	Year of Reg.	WHITE	
		101471		IN ORDER	
	Odometer Brakes	IN ORDER	Steering Modification	SPORTS RIM	
		GOOD	Modification	SPURTS KIIVI	
3. Conditions of Tyres					
	R/H Front Tyre	Size 195/60R15	Make MICHELIN	Balance 6 mm	
	L/H Front Tyre	195/60R15	MICHELIN	6 mm	
	R/H Rear Tyre	195/60R15	MICHELIN	6 mm	
		195/60R15	MICHELIN	6 mm	
4.	L/H Rear Tyre			O IIIIII	
4.	Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. THE CHASSIS FRAME AFFECTED DUE TO COLLISION.				
	DAMAGES SEE DETAILS.				
5.	5. General Information				
	Accident Date	03/12/2017	Inspection Date	05/12/2017	
	Survey held at	FASTECH AUTO PTE LTD			
		1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 15 Working Days				