

ASS. REC. BY:

REF: CS/ATC170 J3055 /A46n2 Special Instruction:

Surveyor: Adrian ASSIGNMENT (Office)From (Person): Ashley Chan of ALH Date/Time: 05/12/2017 11:32am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GX 7620E Insured: SLQ 16Zat Workshop m/s Liang Hee motor Tel: 9752 7252of Blk 1 Kaki Bukit Ave 6 # 01-62Policy No: 2100385123 Claim No: 481904380257

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 01-12-2017
(Client's Record)

CA / REV / REP. / REV 24 HRS Wp H.O.D. Endorsement: _____

Date/Time: 05-12-2017 1:03pm Person Contacted: David Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>GX 7620E - CTS / INC09/020514 / TJI</u> Duf: 080309
	<u>SLQ 16Z - X</u>
	<u>lump sum \$4100 (Red: 22/1.2/135%)</u>

REF: ALH

ASSIGNMENT

From: Date: 05.12.2017

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GX 7620E

at Workshop m/s: Liang Hee

of:

Insured:

Policy No.:

Claims No.:

Sum Insured: Excess:

(Client's Record)

Make of Veh.:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle IN / OUT

Veh No: GX7620E. Yr Regn: 2004 Sept

Type: M.Car / M.Cycle / Bus / Van / Loon / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Cabstar. cc 3153

Colour: ~~Lotus~~ Silver A/C. Insured / Std / NI / NA

Sp. Reading: 459687 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JN1SF4F2320852824

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195R15C BS.

R: 155R12C -Yoko

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 06 mm R/Bal: 06 mm

L/Bal: 06 mm L/Bal: 06 mm

D.O.A. D.O.I. 05/12/17.

Survey held at: Liang Hee.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP ALG.

O/E Enquiry: 08/09/19.

RECEIVED 11 JAN 2018

Date/Time, File Pass to?

11/1 Typist

Date/Time, File Return to?

3

Report Format:

Lump Sum / I.B.I: \$

TP 400/-

☐ : Preli. Report☒ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee

Transportation

8 - RS 81

Photos

Others

Add Fee:

☐ Site Insp: (\$☐ Interview: (\$☐ Tech. Invs: (\$☐ Weekend: (\$250
20

270



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CS/AIG17023055/Atb		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 05-12-2017		
Code : AIG				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLQ 16Z	Veh. Inspected	GX 7620E	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	ASHLEY CHAN	Assign Date	05/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	01/12/2017	Inspection Date	05/12/2017	
Survey held at	LIANG HEE MOTOR WORKSHOP 1 KAKI BUKIT AVE 6 #01-62 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

- Pre repair inspection request - GX7620E VS SLQ16Z (OI) DOA: 01/12/2017

From: Chan, Yoke Shi
To: assignments, Admin A
Cc: Tan, Lily (AIG), Fong, Andy-SY, Kaur, Baljit, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang
Sent: Tuesday, 5 December, 2017 11:32:46 AM
Attachments:  FaxC97E.TIF

Hi,

Please refer to the enclosed request from JusEquity Law Corporation.

Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.
Kindly assist to assign Adrian Ling as Single Joint Expert as requested.

Thank you.

Regards,

Yoke Shi @ Ashley

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)
Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 | Ext 1012102

yokeshi.chan@aig.com www.aig.com

From: Sim Teo Koon [mailto:tk_sim@juseq.com.sg]
Sent: Tuesday, December 05, 2017 11:06 AM
To: Chan, Yoke Shi
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLQ16Z AND GX7620E ON 01/12/2017

Dear Sir,

We refer to your email.

Our client is agreeable to appoint Adrian Ling (LKK Auto Consultants Pte Ltd) as a single joint expert.

Please be informed that our client's motor vehicle is available for pre-repair inspection at the under-stated Workshop:-

Liang Hee Motor Workshop
1 Kaki Bukit Ave 6 #01-62
Singapore 417883
Tel : 9752 7252 (David) / 6747-4416. Fax : 6747-2935

Regards,

Sim Teo Koon
JusEquity Law Corporation
171 Chin Swee Road #02-06, CES Centre
Singapore 169877
Tel: 6506 6488 / 6536 9339
Fax: 6536 5368
E-mail: tk_sim@juseq.com.sg

This message (and all its attachments) is intended only for the use of the individual or entity to whom it is addressed and is privileged and confidential. If you are not the intended recipient, please notify us immediately by return electronic mail, delete this message and you should not disseminate, distribute or copy any information contained herein.

From: Chan, Yoke Shi [<mailto:yokeshi.chan@aig.com>]

Sent: Tuesday, December 5, 2017 7:47 AM

To: juseq@singnet.com.sg

Cc: Tan, Lily (AIG) <Lily.Tan@aig.com>; Fong, Andy-SY <Andy-SY.Fong@aig.com>; Kaur, Baljit <Baljit.Kaur@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Md Ishak, Mohd Imran <Imran.Ishak@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>

Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLQ16Z AND GX7620E ON 01/12/2017

Without Prejudice

Your Reference : JEQ/170941/1217/L.HEE (ZUL)

Our Reference : SLQ16Z

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
Lim Kok Chong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Ricky Teng	RT Appraisal Pte Ltd
Elson Teng	RT Appraisal Pte Ltd
Michael Cheong	RT Appraisal Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon Han Xin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Henry Ng	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Steven Foong	LKK Auto Consultants Pte Ltd
Wei Jie	LKK Auto Consultants Pte Ltd
Ma Chin Fook	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Yoke Shi @ Ashley

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia

Tel +6 03 2719 6000 | Ext 1012102

yokeshi.chan@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	3223G
Vehicle Details	
Vehicle No.	GX7620E
Vehicle to be Exported	Yes
Intended De-registration Date	05 Dec 2017
Vehicle Make	NISSAN
Vehicle Model	CABSTAR
Primary Colour	Gold
Manufacturing Year	2004
Engine No.	QD32195293
Chassis No.	JN15F4F23Z0852824
Maximum Power Output	-
Open Market Value	\$20,418.00
Original Registration Date	09 Sep 2004
First Registration Date	09 Sep 2004
Transfer Count	2
Actual ARF Paid	\$1,021.00
Intended PARF Rebate Details	
PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00
Intended COE Rebate Details	
COE Expiry Date	08 Sep 2019
COE Category	C - Goods Vehicle & Bus
COE Period(Years)	5
PQP Paid	\$23,901.00
COE Rebate Amount	\$8,405.00
Total Rebate Amount	\$8,405.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 05 Dec 2017

OK

TPAIG

Dense

GX7620E

Nissan Cabstar

JNISF4F2320852824.

Rear Number Plate	Best	30(SN)	
Rear Number Plate Bracket	Best	75.20 (N)	
Taillamp x 02	Curled	225 x 2 = 450(N)	
Taillamp Panel x 02	RH Best	68 x 2 = 136 - 68.	
Reverse Sensor	Dented	280(SN) 200(SN)	
Stopper x 02	1 piece at	20 x 2 = 40(SN)	20(SN)
Stopper Bracket x 02	RH Best	155.6 x 2 = 311.20	155.60
Rear Cross member	Best	377.30	
Spare Tyre Lock Regulator	Dented	187.30(N)	
Rear LH Door	Dented	1600(SN) 1100(SN)	
70km/h Sticker	n	15(SN)	
Rear RH Door	Dented	1600(SN) 1100(SN)	
Rear RH Door Lock Bar	n n	450(SN)	+ 405 SN
Rear RH Door Lock Bar Catch.	n n	120(SN)	+ 712.5
Rear Door Lower Panel.	Dented	468.30	+ 641.25
			1292.30
			904.96

List 1069.20
 Less 30%: 748.44

Nett: 712.5
 Less 10%: 641.25

SN: 2465

G x 7620E.

Panel Beating

Spray Painting.

Wiring.

To undersell.

To remove reverse sensor.

~~1000~~ 600
~~1000~~ 600
~~50~~ 30

150 +

~~100.~~ 50

1280

total: 5134.69
4/5: 4.11K.
05 Days

8440.30

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG17023055/ATBN2

Date: 15/01/2018

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100385123
Claimant Vehicle No :	GX7620E	Insured Vehicle No :	SLQ16Z
Date of Loss:	01/12/2017	Nature of Claim:	TP
		Claim No:	4819043802SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GX7620E	Engine No:	QD32195293
Make & Model:	NISSAN CABSTAR, 3.2 D (M)	Chassis No:	JN1SF4F23Z0852824
Reg. Date:	09/09/2004 (Man. Year: 2004)	Odometer:	459687 km
Colour:	Silver		
Engine Capacity:	3153 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15C	Rear Tyre Size:	155R12C
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,140.30	3,854.69	2,285.61	37.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	1,280.00	1,020.00	44.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,440.30	5,134.69	3,305.61	39.16
Approved Total (Overridden) (\$\$)		4,100.00		
Nett Amount (\$\$)	8,440.30	4,100.00	4,340.30	51.42

INSPECTION

Date of Assignment:	05/12/2017	
Date Inspected:	05/12/2017	Inspected At:
		Liang Hee Motor Workshop (HQ) 1 KAKI BUKIT AVE 6 #01-62, AUTOBAY @ KAKI BUKIT Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILLAMP PANEL	O/s Bent	136.00 F	*68.00 FL
2	1		*STOPPER BRACKET	O/s Bent	311.20 F	*155.60 FL
3	1		*REAR CROSS MEMBER	Bent	377.30 F	*377.30 FL
4	1		*REAR DOOR LOWER PANEL	Dented	468.30 F	*468.30 FL
5	1		*REAR NUMBER PLATE BRACKET	Bent	75.20 F	*75.20 FN
6	2		*TAILLAMP	Cracked	450.00 F	*450.00 FN
7	1		*SPARE TYRE LOCK REGULATOR	Damaged	187.30 F	*187.30 FN
8	1		*REAR NUMBER PLATE	Bent	30.00 FS	*30.00 FS
9	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
10	2		*STOPPER	Cut (1 Pc only)	40.00 FS	*20.00 FS
11	1		*REAR LH DOOR	Dented	1,600.00 FS	*1,100.00 FS
12	1		*70KM/H STICKER	Necessary	15.00 FS	*15.00 FS
13	1		*REAR RH DOOR	Dented	1,600.00 FS	*1,100.00 FS
14	1		*REAR RH DOOR LOCK BAR	Not Necessary	450.00 FS	*- FS
15	1		*REAR RH DOOR LOCK BAR CATCH	Not Necessary	120.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc, N=NettItemDisc.

Sub Total (\$\$)	6,140.30	4,246.70
- List Item Discount on L Items 0.00/30.00% (\$\$)	0.00	320.76
- Nett Item Discount on N Items 0.00/10.00% (\$\$)	0.00	71.25
Total Parts (\$\$)	6,140.30	3,854.69

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,000.00	600.00
2	SPRAY PAINTING	New	1,000.00	600.00
3	WIRING	New	50.00	30.00
4	TO UNDERSEAL	New	150.00	-
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
Gross Labour Cost (\$\$)			2,300.00	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >