15/5/20	010		1 00 4 11	CS1702	076,6	1 66752	LKK: IDAC:	
INS.	CASE OWNER:		CC \ /I					
		mprus	11.55%-36%	ASSIGNM	. 3/ 1/		4112	17
Surv	veyor:	West Committee	DOI:	- 3		Date / Time :		
			29.		3	Registered in Merir	men:	
Pre	-assign / CCU / FTE	200	01.00.2					
		sym	86666		Claim No.	*		
Insu	red Vehicle No. :	111	. Tell.	500		in in	CARDINY:	7101
Nan	ne of Insured :	HOO FEW		20	Policy No.	: N. h		140
	ared Tel No.		HP: 0167	14766	Make / Model	: VOV	SWADEN	
-		S	D.O.A: 7		Place of Accide	01 An -	TWOS ITE	
Exc	ess Sec II :S\$				Place of Accide	ne.		
Is d	river the owner?	(YES / NO)	Nature of Accid	lent :				
If N	O, Driver Name / Ag	A PARA A PARA	-0 m			T: YES NO ; TP		S/NO
	Driver Tel No.:	n66668	69 (V/L: YI	ES/NO)	Insured Liability	y: %	Final? Yes/No	
52	V 88714	. cho	57060 _		c7m 81	66P	- SLN 65	19R
7.0	O P D	700	7777			-	Maria and	
N INS	SRS:	INSR	S:		INSRS:		INSRS:	4
WS		WSP:			WSP:	1	WSP: V	powin
Tel		H Tel:	lles.	H	Tel: Liability:	D D	Liability:	411
- 1	bility:	Liabil	350		RMKS:		RMKS:	(P
RM	IKS:	RMK	.5:		KHRS.	W. W. P. C.		-
- Date	/Time							me i naco
2	NA 921	1 borrap - 10	9.7	m 8600p	-4	STAGE Non-Reporting ltr (1		TE / PIC
Vol	IVI					Non-Reporting ltr (2		
¥	MALV					Non-Reporting ltr (F		
						Notification ltr (if no	on-pickup):	
3	118 + 2.80 CAU	AD OID CONFIRM	THE ACLIDENT		OF IN HARM C.C	and the second second	EMAIL OB/1/18	
		WAS THE 2900	VAM. INTORN	- W	of Gasse	After call ltr to OI:		Tourist
	Sen	UE AND AMPR	E ABOUT NO	D 1354L,		Documentation Ch		Typist
						Notification ltr (if no	on-pickup)	-
						After call ltr to OI:	. –	
Ť						Authorisation To Ac	X:	
D. P.						Release Voucher:		-
ini:		1 0			1	Final Repair Bill:		-
		RECE	VEU18	JAN 2018]		Car Rental Invoice:		
						Towing Invoice		
						LTA / GIA :		-
						Medical Bill:	_	- -
						PIR:		- -
						Mandate/Reject In	istruction:	7
						LOD	non Econor	-
	The same of the sa	AD TO LOD. A		- 15-1		Payment Breakdo		
RELIMIN	ARY ADVICE Date	/Time: [V[]	YY Sen	t By:		Post-Repair Photo	38:	1 -
						Others:	_	
INALIZA'		e/Time: 8/12/17	The second secon	nfirm with: UNDA		Confirm by: CVC	Email Call	
epair Cost:		3,101.50 (4 days) Red		7 %	m u[] c :		
INAL SET	TLEMENT Date	e/Time: 12 - 18	Confirm with	Annual Control of the	0	Email Cal		
nai Liabili		100	ed / Assessed) BO		8	II NO or B 28, A	SS. LIE. U/*	775
epair Cost:	A STATE OF THE PARTY OF THE PAR	5,340.03	200 200 200	4 VEH ((010 340	- Amin	1 3 5 3	11
oss of Rent		- (days)			7 01	IN I CO	1
.o.s of Use	AND THE RESERVE TO THE PARTY OF	360.00 (\$ 60	x (days)			1	18/1/10	U
oss of Inco	The second secon	- (\$	x days)	Triple and a seed				
OR only [LOR + LOU	LOR + LOI	[Tick only one]				
HA/LTA Se	The second secon	00-4				1) Claim status N	Normal/Reject/Priva	te Settle
Medical:	SS	-		m	. \	Report Format	No. of the Control of	
Disburseme	nt: SS	-	(e.j	z. Tow/ Independen	()	Survey fee:	⇒ 450	
Legg Cost	SS		Global Sum			3) Survey ree.		
The second second		3,702.03						

Confirm with: LINDA

Name 2:

Name 3:

Name 1: ABWIM STEVICE PTE 270

Date/Time: 13/18

SS 3,702.03

SS

FINAL PAYMENT

Payce 3: (Strike if N.A.)

Payee 1:

Email

Call



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile CC4/ICS17023076/Ueb3 Ref: ECICS LTD 7 TEMASEK BOULEVARD Date: 05-12-2017 #10-01 SUNTEC TOWER ONE SINGAPORE 038987 Code: ICS Policy Particulars :- THIRD PARTY CLAIM 1. SLN 6519R SJM 8666P Veh. Inspected Insured Veh. 0.00 Coverage (\$) Policy No. 0.00 Excess (\$) Claim No. 05/12/2017 Assign Date Assign From Vehicle Particulars & Condition 2. 0 Make & Model C.C HIDDEN Year of Reg. Engine No. Colour Chassis No. Steering Odometer Modification Brakes General Conditions of Tyre's 3. Make Balance Size mm R/H Front Tyre mm L/H Front Tyre mm R/H Rear Tyre mm L/H Rear Tyre Description of Dama jes 4. **General Information** 5. 08/12/2017 Inspection Date 30/11/2017 **Accident Date** ABWIN SERVICE PTE LTD Survey held at No. 8 KAKI BUKIT AVENUE 4 #07-48 PREMIER@KAKI BUKIT GATE 2 SINGAPORE 415875 Remarks 5a.

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.

B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Please arrange to survey vehicle at 8 KAKI BUKIT AVENUE 4 - GATE 2 #07-48 PREMIER @ KAKI BUKIT SINGAPORE 415875

OS/14/7 @ 1230Hrs In ABWIN

WWW 5 SWW LINDA LIAO
ABWIN SERVICE PTE LTD
DID: 67139417
Fax: 67139415
HP: 97519596



Date

: 01/12/2017

TP Vehicle No. To

: SJM-8666-P : ECICS LIMITED

Attn

: Motor Claim Department

Owner

: ANMANI GENERAL CONSTRUCTION PTE LTD

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Certificate No. Vehicle No.

: 200813721M

: SLN-6519-R

Make & Model : HONDA VEZEL 1.5X A

HP: 97519596

11 \$250.00 2

Accident Date: 30/11/2017

216.52 B 3121.52

ESTIMATED REPAIR COST DETAILS

TAILGATE WEATHERSTRIP

E211IVI	ATED REPAIR COST DETAILS	longon	, syou for	
QTY	DESCRIPTION	Hong.	REPAIR AMOUNT	SURVEYOR APP.
List Iter		9/12/12		
1	TAILGATE ' EMBLEM V-1) .	1. 11	, le \$35.00	
1	TAILGATE		B. J.D \$953.60	
1	TAILGATE TOP GARNISH		11 \$720.00	α
1	TAILGATE LAMP RH		17 \$250.00	4
1	TAILGATE LAMP LH		11 \$250.00	

at .	TALEGATE WEATHERS IN	25-27/1000	360013 - 0000000
1	TAILGATE INNER TRIMBOARD	11	\$250.00
10	TAILGATE INNER TRIMBOARD CLIPS	1-	\$50.00
1	REAR WINDSCREEN MOULDING	su	\$150.00
		Permanence e	4050 00 1

1	REAR FENDER RH	17 \$950.00 X
1	REAR FENDER LH	17 \$1,250.00 X
1	REAR FENDER INNER SHIELD RH	11 \$285.00 ×

1	REAR FENDER INNER SHIELD LH	11	\$285.00
1	TAILLAMP RH	11	\$580.60
1	TAILLAMP LH	100	\$580.60

1	SPARE TYRE PANEL	1 1,530.00
1	SPARE TYRE PANEL INSULATOR	11 \$485.00 X

1	SPARE TYRE COMPARTMENT COVER & TYRE BOARD	11 \$260.90 0
10	SPARE TYRE INSULATOR CLIPS	11 \$260.90 X
		1 caon on X

10	SPARE TYRE INSULATOR CLIPS	\$50.00
1	REAR END PANEL	1 \$480.60 X
1	REAR END PANEL BRACKET RH	11 \$65.00 4
1	REAR END PANEL BRACKET LH	12 \$65.00
1	REAR BUMPER	De \$762.70
4.0	DEAD BUILDED CLIDS	144 \$50.00

1	KEAK BUMPEK	100 00000
10	REAR BUMPER CLIPS	lu \$50.00
1	REAR BUMPER RETAINER RH	11 \$45.00 Q
1	REAR BUMEPR RETAINER LH	11 \$45.00 Q

1	REAR BUMEPK RETAINER LH	11	343.00
1	REAR BUMPER REFLECTOR RH	11	\$185.40
1	REAR BUMPER REFLECTOR LH	11	\$185.40 X \$185.40 X

11 \$156.00 EXHAUST HEAT SHIELD

1951.3



LINDA LIAO

: 01/12/2017

TP Vehicle No. : SJM-8666-P

To

: ECICS LIMITED

Attn

Date

: Motor Claim Department

ABWIN SERVICE PTE LTD

DID: 67139417 Fax: 67139415

HP: 97519596

Owner

: ANMANI GENERAL CONSTRUCTION PTE LTD

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Certificate No. : 200813721M

Vehicle No.

: SLN-6519-R

Make & Model : HONDA VEZEL 1.5X A

Accident Date: 30/11/2017

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT SURVEYOR AF	
	Sub Total	\$11,205.80	
	Discount 25% on Parts	(\$2,801.45)	
		\$8,404.35	
Special	Nett		
1	REAR REVERSE CAMERA	17, \$480.00	
1	REAR REVERSE SENSOR	Short \$350.00 2005. N	
1	REAR NUMBER PLATE & CASEING	11 \$45.00 √	
	Sub Total	\$875.00	

& Misc TO STAIGHTEN AND PANEL BEAT ACCIDENT /	AREAS	\$1,500.00 4	00
TO SPRAY PAINT ON AFFECTED AREAS		\$1,500.00	00
TO APPLY TUFF KOTE		\$60.00	
TO TRANSFER ALL REAR TAILGATE FITTING		\$250.00 6	
TO REMOVE & INSTALL REAR WINDSCREEN		\$150.00 / 2	
TO CHECK ALL NECCESSARY WIRINGS		\$150.00 2	2
TO CONDUCT INTERIOR TRIMBOARD		\$150.00 6	2
TO INSTALL REVERSE CAMERA AND CHECK FUNCTIONALITY		\$250.00	2
TO INSTALL REVERSE SENSOR & CHECK FUN	CTIONALITY	\$250.00	
Sub Total		\$4,260.00	
	Sub Total	\$13,539.35	

\$13,539.35 Sub Total \$947.75 **GST 7%** \$14,487.10 Total

13652.30



SUPPLEMENTARY

LINDA LIAO

ABWIN SERVICE PTE LTD

: 11/12/2017

DID: 67139417

TP Vehicle No. : SJM-8666-P To

: ECICS LIMITED

Fax: 67139415

Attn

: Motor Claim Department

HP: 97519596

Owner

: ANMANI GENERAL CONSTRUCTION PTE LTD

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Certificate No. : 200813721M

Accident Date: 30/11/2017

Vehicle No.

: SLN-6519-R

Make & Model : HONDA VEZEL 1.5X A

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION		REPAIR AMOUNT	SURVEYOR APP.
List Ite	<u>m</u>			8.
1	SMART BUZZER ASSY		CM \$150.6	0
	Sub Total		\$150.6	0
	Discount 25% on Parts		(\$37.65	5)
			\$112.9	5
		Sub Total	\$112.9	5
		GST 7%	\$7.9	1
		Total	\$120.8	6

1681.52

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref:

To Be Advised

Date:

11.12.2017

Our ref:

CC4/ICS17023076/Ueb3

The Motor Claims Department M/s ECICS LIMITED

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLN6519R

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on <u>08.12.2017</u> at the premises of M/s <u>Abwin Service Pte Ltd</u> and have the following to report:-

Workshop Estimate Amount	: S\$	13,539.35
Revised Estimate Amount	: S\$	2,903.48
"Check" Items Amount	: S\$	412.50
Market Value	: S\$	
LTA Reimbursement Value	: S\$	
Nett Value	: S\$	

Description of Damage:

The vehicle sustained damages at the

Rear Portion

rear from

Comments/Present Status:

Damages Consistent

Estimated normal period for repairs:

4 days

Yours faithfully,

MARCUS CHUA

Licensed Appraiser

· Please arrange to survey vehicle at 8 KAKI BUKIT AVENUE 4 - GATE 2 #07-48 PREMIER @ KAKI BUKIT SINGAPORE 415875

OSM17@ 1230HIS 加 ABWIN 論 LINDA LIAO ABWIN SERVICE PTE LTD DID: 67120417



Fax: 67139415 HP: 97519596

To

TP Vehicle No. : SJM-8666-P : ECICS LIMITED

: 01/12/2017

Attn

Date

: Motor Claim Department

Owner

: ANMANI GENERAL CONSTRUCTION PTE LTD

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Certificate No. : 200813721M Vehicle No.

: SLN-6519-R

Make & Model : HONDA VEZEL 1.5X A

Not All Accident Date: 30/1:

Accident Date: 30/11/2017

ESTIMATED REPAIR COST DETAILS

TAILGATE	ESTIMA	TED REPAIR COST DETAILS 700	ware selon family	20 EW)
1 TAILGATE EMBLEM VE 2	QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
1 TAILGATE 1 TAILGATE 1 TAILGATE TOP GARNISH 1 TAILGATE LAMP RH 1 TAILGATE LAMP RH 1 TAILGATE LAMP RH 1 TAILGATE LAMP LH 1 TAILGATE WEATHERSTRIP 250.00 2 SECO.00 2 SECO.00 3 SECO.00 3 SECO.00 3 SECO.00 4 SECO.00 6 SECO.00 7 SECO.00 7 SECO.00 7 SECO.00 8 SECO.00 9 SECO.00 7 SECO.00 7 SECO.00 8 SECO.00 9 SECO.00 7 SECO.00 9 SE	List Item	, 12/.2	1, 2	8
1 TAILGATE TOP GARNISH 1 TAILGATE LAMP RH 1 TAILGATE LAMP RH 1 TAILGATE LAMP RH 1 TAILGATE LAMP LH 2 \$250.00 X 1 TAILGATE LAMP LH 2 \$250.00 X 2 \$250.00 X 2 \$250.00 X 2 \$250.00 X 3 \$250.00 X 3 \$250.00 X 4 \$250.00 X 2 \$250.00 X 3 \$250.00 X 4 \$250.00 X 5 \$250.00 X 5 \$250.00 X 6 \$250.0	1	TAILGATE EMBLEM VE LE		
1 TAILGATE LAMP RH 1 TAILGATE LAMP LH 2 \$250.00 X 1 TAILGATE LAMP LH 2 \$250.00 X 2 \$250.00 X 2 \$250.00 X 3 \$250.00 X 4 \$250.00 X 5 \$250.00	1	TAILGATE	5, 1 3 \$953.60	_
1 TAILGATE LAMP LH 1 TAILGATE WEATHERSTRIP 2525.00 2	1	TAILGATE TOP GARNISH	11 \$720.00	X
1 TAILGATE WEATHERSTRIP 1 TAILGATE INNER TRIMBOARD 2 \$250.00? 1 TAILGATE INNER TRIMBOARD CLIPS 550.00? 1 REAR WINDSCREEN MOULDING 1 REAR FENDER RH 1 REAR FENDER LH 1 REAR FENDER INNER SHIELD RH 1 REAR FENDER INNER SHIELD LH 1 TAILLAMP RH 1 TAILLAMP LH 1 SPARE TYRE PANEL 1 SPARE TYRE PANEL 1 SPARE TYRE PANEL SPARE TYRE BOARD 1 SPARE TYRE INSULATOR 1 SPARE TYRE INSULATOR SPARE TYRE BOARD 1 REAR END PANEL BRACKET LH 1 REAR END PANEL BRACKET LH 1 REAR BUMPER RETAINER LH 1 REAR BUMPER RETAINER LH 1 REAR BUMPER RETAINER LH 1 REAR BUMPER REFLECTOR RH 1 REAR BUMPER REFLECTOR LH	1	TAILGATE LAMP RH	17 \$250.00	*
1 TAILGATE INNER TRIMBOARD 10 TAILGATE INNER TRIMBOARD CLIPS 11 REAR WINDSCREEN MOULDING 12 REAR WINDSCREEN MOULDING 13 REAR FENDER RH 14 \$950.00 15 REAR FENDER LH 16 \$285.00 16 REAR FENDER INNER SHIELD RH 17 \$1,250.00 17 \$285.00 18 REAR FENDER INNER SHIELD LH 19 \$285.00 19 \$285.00 10 \$1,250.00 11 TAILLAMP RH 10 \$580.60 11 SPARE TYRE PANEL 11 SPARE TYRE PANEL INSULATOR 11 SPARE TYRE PANEL INSULATOR 12 SPARE TYRE COMPARTMENT COVER & TYRE BOARD 10 SPARE TYRE INSULATOR CLIPS 11 REAR END PANEL BRACKET LH 12 REAR END PANEL BRACKET LH 13 REAR END PANEL BRACKET LH 14 REAR BUMPER 15 \$762.70 16 SPARE TYRE CLIPS 17 \$65.00 18 REAR BUMPER CLIPS 19 \$762.70 10 REAR BUMPER REFLIECTOR RH 11 REAR BUMPER REFLECTOR RH 12 REAR BUMPER REFLECTOR LH 14 \$45.00 15 SPARE TYRE STAINER LH 16 \$45.00 17 \$150.00 18 \$150.00 19 \$150.00 19 \$150.00 10 \$150.00 10 \$150.00 10 \$150.00 11 \$150.00 11 \$150.00 12 \$150.00 13 \$150.00 14 \$150.00 15 \$150.00 16 \$150.00 17 \$150.00 17 \$150.00 18 \$150.00 19 \$150.00 10 \$150.00 10 \$150.00 10 \$150.00 11 \$150.00 11 \$150.00 12 \$150.00 13 \$150.00 14 \$150.00 15 \$150.00 16 \$150.00 17 \$150.00 17 \$150.00 18 \$150.00 19 \$150.00	1	TAILGATE LAMP LH	11 \$250.00	X
10 TAILGATE INNER TRIMBOARD CLIPS 1 REAR WINDSCREEN MOULDING 1 REAR FENDER RH 1 REAR FENDER RH 1 REAR FENDER LH 1 REAR FENDER LH 1 REAR FENDER INNER SHIELD RH 1 REAR FENDER INNER SHIELD LH 1 TAILLAMP RH 1 SPARE TYRE PANEL 1 SPARE TYRE PANEL 1 SPARE TYRE PANEL INSULATOR 1 SPARE TYRE COMPARTMENT COVER & TYRE BOARD 10 SPARE TYRE INSULATOR CLIPS 11 REAR END PANEL 11 REAR END PANEL BRACKET RH 12 REAR END PANEL BRACKET LH 13 REAR BUMPER 14 S45.00 15 S762.70 16 REAR BUMPER RETAINER RH 17 S45.00 18 S45.00 19 S762.70 10 REAR BUMPER RETAINER LH 11 REAR BUMPER REFLECTOR RH 12 S45.00 13 S45.00 14 S45.00 15 S762.70 16 S15.40 17 S15.40 18 S15.40	1	TAILGATE WEATHERSTRIP	\$250.00	?
1 REAR WINDSCREEN MOULDING 1 REAR FENDER RH 1 REAR FENDER RH 2 \$950.00 2 \$1,250.00 3 \$285.00 4 \$285.00 4 \$285.00 5 \$285.00 7 \$	1	TAILGATE INNER TRIMBOARD	\$250.00	7.
1 REAR FENDER RH 1 REAR FENDER LH 1 REAR FENDER INNER SHIELD RH 1 REAR FENDER INNER SHIELD RH 1 REAR FENDER INNER SHIELD LH 1 TAILLAMP RH 1 TAILLAMP LH 2 SPARE TYRE PANEL 1 SPARE TYRE PANEL INSULATOR 2 SPARE TYRE COMPARTMENT COVER & TYRE BOARD 2 SPARE TYRE INSULATOR CLIPS 3 REAR END PANEL 4 REAR END PANEL BRACKET RH 5 REAR END PANEL BRACKET LH 5 REAR BUMPER 1 REAR BUMPER RETAINER RH 1 REAR BUMPER RETAINER RH 1 REAR BUMPER RETAINER LH 1 REAR BUMPER RETAINER LH 1 REAR BUMPER REFLECTOR RH 1 REAR BUMPER REFLECTOR LH 1 REAR BUMPER REFLECTOR LH 1 SAS.00 2 SAS.0	10	TAILGATE INNER TRIMBOARD CLIPS	\$50.00	?
1 REAR FENDER LH 1 REAR FENDER INNER SHIELD RH 1 REAR FENDER INNER SHIELD LH 1 S285.00 1 TAILLAMP RH 1 TAILLAMP RH 1 SPARE TYRE PANEL 1 SPARE TYRE PANEL INSULATOR 1 SPARE TYRE COMPARTMENT COVER & TYRE BOARD 1 SPARE TYRE INSULATOR CLIPS 1 REAR END PANEL 1 REAR END PANEL 1 REAR END PANEL BRACKET RH 1 REAR BUMPER 1 REAR BUMPER CLIPS 1 REAR BUMPER RETAINER RH 1 REAR BUMPER RETAINER LH 1 REAR BUMPER REFLECTOR RH 1 REAR BUMPER REFLECTOR LH 1 REAR BUMPER REFLECTOR LH 1 REAR BUMPER REFLECTOR LH 1 S185.40	1	REAR WINDSCREEN MOULDING	\$150.00	
1 REAR FENDER INNER SHIELD RH 1 REAR FENDER INNER SHIELD LH 2 \$285.00 2	1	REAR FENDER RH	A-1 \$950.00	α
1 REAR FENDER INNER SHIELD LH 1 TAILLAMP RH 1 TAILLAMP RH 1 SPARE TYRE PANEL 1 SPARE TYRE PANEL 1 SPARE TYRE PANEL 1 SPARE TYRE PANEL INSULATOR 1 SPARE TYRE COMPARTMENT COVER & TYRE BOARD 1 SPARE TYRE INSULATOR CLIPS 1 REAR END PANEL 1 REAR END PANEL BRACKET RH 1 REAR BUMPER 1 REAR BUMPER CLIPS 1 REAR BUMPER RETAINER RH 1 REAR BUMPER RETAINER RH 1 REAR BUMPER RETAINER LH 1 REAR BUMPER REFLECTOR RH 1 REAR BUMPER REFLECTOR LH 1 REAR BUMPER REFLECTOR LH 1 REAR BUMPER REFLECTOR LH 1 S185.40	1	REAR FENDER LH	11 \$1,250.00	X
1 TAILLAMP RH 1 TAILLAMP LH 1 SPARE TYRE PANEL 1 SPARE TYRE PANEL 1 SPARE TYRE PANEL INSULATOR 1 SPARE TYRE COMPARTMENT COVER & TYRE BOARD 1 SPARE TYRE INSULATOR CLIPS 1 REAR END PANEL 1 REAR END PANEL BRACKET RH 1 REAR END PANEL BRACKET LH 1 REAR BUMPER 1 REAR BUMPER RETAINER RH 1 REAR BUMPER RETAINER RH 1 REAR BUMPER RETAINER LH 1 REAR BUMPER REFLECTOR RH 1 REAR BUMPER REFLECTOR LH 1 REAR BUMPER REFLECTOR LH 1 SSS.40	1	REAR FENDER INNER SHIELD RH	A1 \$285.00	Ø
1 TAILLAMP LH 1 SPARE TYRE PANEL 1 SPARE TYRE PANEL 1 SPARE TYRE PANEL INSULATOR 1 SPARE TYRE COMPARTMENT COVER & TYRE BOARD 10 SPARE TYRE INSULATOR CLIPS 1 REAR END PANEL 1 REAR END PANEL BRACKET RH 1 REAR END PANEL BRACKET LH 1 REAR BUMPER 1 REAR BUMPER 1 REAR BUMPER CLIPS 1 REAR BUMPER RETAINER RH 1 REAR BUMPER RETAINER RH 1 REAR BUMPER REFLECTOR RH 1 REAR BUMPER REFLECTOR LH 1 REAR BUMPER REFLECTOR LH 1 S185.40	1	REAR FENDER INNER SHIELD LH	11 \$285.00	X
1 SPARE TYRE PANEL 1 SPARE TYRE PANEL INSULATOR 1 SPARE TYRE COMPARTMENT COVER & TYRE BOARD 10 SPARE TYRE INSULATOR CLIPS 1 REAR END PANEL 1 REAR END PANEL 1 REAR END PANEL BRACKET RH 1 REAR BUMPER 10 REAR BUMPER 10 REAR BUMPER CLIPS 11 REAR BUMPER RETAINER RH 11 \$45.00 12 REAR BUMPER RETAINER RH 12 \$45.00 13 REAR BUMPER RETAINER LH 14 \$45.00 15 REAR BUMPER REFLECTOR RH 16 REAR BUMPER REFLECTOR LH 17 \$1,530.00 1 \$1,530.00 1 \$1,530.00 1 \$260.90 1 \$50.00 1 \$50.00 1 \$65.00 1 \$65.00 1 \$762.70 1 \$185.40 1 \$185.40	1	TAILLAMP RH	1, \$580.60	3
1 SPARE TYRE PANEL INSULATOR 1 SPARE TYRE COMPARTMENT COVER & TYRE BOARD 10 SPARE TYRE INSULATOR CLIPS 1 REAR END PANEL 1 REAR END PANEL 1 REAR END PANEL BRACKET RH 1 REAR END PANEL BRACKET LH 1 REAR BUMPER 10 REAR BUMPER CLIPS 1 REAR BUMPER RETAINER RH 1 REAR BUMPER RETAINER RH 1 REAR BUMPER RETAINER LH 1 REAR BUMPER REFLECTOR RH 1 REAR BUMPER REFLECTOR LH 1 S185.40	1	TAILLAMP LH	1 \$580.60	^
1 SPARE TYRE COMPARTMENT COVER & TYRE BOARD 10 SPARE TYRE INSULATOR CLIPS 1 REAR END PANEL 1 REAR END PANEL 1 REAR END PANEL BRACKET RH 1 REAR BUMPER 10 REAR BUMPER CLIPS 1 REAR BUMPER RETAINER RH 1 REAR BUMPER RETAINER LH 1 REAR BUMPER REFLECTOR RH 1 REAR BUMPER REFLECTOR LH 1 REAR BUMPER REFLECTOR LH 1 S185.40	1	SPARE TYRE PANEL	A \(\$1,530.00 \)	X
10 SPARE TYRE INSULATOR CLIPS 1 REAR END PANEL 1 REAR END PANEL 1 REAR END PANEL BRACKET RH 1 \$65.00 1 REAR BUMPER 1 REAR BUMPER 10 REAR BUMPER CLIPS 1 REAR BUMPER RETAINER RH 1 REAR BUMPER RETAINER LH 1 REAR BUMPER REFLECTOR RH 1 REAR BUMPER REFLECTOR LH 1 REAR BUMPER REFLECTOR LH 1 \$185.40	1	SPARE TYRE PANEL INSULATOR	1 ↑ \$485.00	X
1 REAR END PANEL 1 REAR END PANEL BRACKET RH 1 REAR END PANEL BRACKET LH 1 REAR BUMPER 1 REAR BUMPER CLIPS 1 REAR BUMPER RETAINER RH 1 REAR BUMPER RETAINER LH 1 REAR BUMPER REFLECTOR RH 1 REAR BUMPER REFLECTOR LH 2 \$480.60 1 \$480.60 1 \$65.00 1 \$762.70 1 \$50.00 1 REAR BUMPER RETAINER RH 1 \$45.00 1 \$185.40 1 \$185.40	1	SPARE TYRE COMPARTMENT COVER & TYRE BO	OARD 11 \$260.90	d.
1 REAR END PANEL BRACKET RH 1 REAR END PANEL BRACKET LH 1 REAR BUMPER 10 REAR BUMPER CLIPS 1 REAR BUMPER RETAINER RH 1 REAR BUMPER RETAINER LH 1 REAR BUMPER REFLECTOR RH 1 REAR BUMPER REFLECTOR LH 1 S185.40	10	SPARE TYRE INSULATOR CLIPS		
1 REAR BUMPER CLIPS 1 REAR BUMPER CLIPS 1 REAR BUMPER RETAINER RH 1 REAR BUMPER RETAINER LH 1 REAR BUMPER REFLECTOR RH 1 REAR BUMPER REFLECTOR LH 2 \$65.00 2 \$762.70 3 \$50.00 4 \$45.00 6 \$45.00 7 \$45.00 7 \$185.40 7 \$185.40	1	REAR END PANEL	1 \$480.60	X
1 REAR BUMPER CLIPS 10 REAR BUMPER CLIPS 1 REAR BUMPER RETAINER RH 1 REAR BUMEPR RETAINER LH 1 REAR BUMPER REFLECTOR RH 1 REAR BUMPER REFLECTOR LH 2 \$762.70 2 \$50.00 4 \$45.00 6 \$45.00 7 \$185.40 7 \$185.40	1	REAR END PANEL BRACKET RH	N. N. S.	No.
10 REAR BUMPER CLIPS 1 REAR BUMPER RETAINER RH 1 REAR BUMPER RETAINER LH 1 REAR BUMPER REFLECTOR RH 1 REAR BUMPER REFLECTOR LH 1 REAR BUMPER REFLECTOR LH 1 \$185.40	1	REAR END PANEL BRACKET LH	1 \$65.00	4
1 REAR BUMPER RETAINER RH 1 REAR BUMPER RETAINER LH 1 REAR BUMPER REFLECTOR RH 1 REAR BUMPER REFLECTOR LH 1 \$185.40	1	REAR BUMPER	De \$762.70	
1 REAR BUMPER RETAINER LH 1 REAR BUMPER REFLECTOR RH 1 REAR BUMPER REFLECTOR LH 2 \$185.40	10	REAR BUMPER CLIPS	le \$50.00	
1 REAR BUMPER REFLECTOR RH 1 REAR BUMPER REFLECTOR LH 2 \$185.40	1	REAR BUMPER RETAINER RH	11 \$45.00	a
1 REAR BUMPER REFLECTOR LH	1	REAR BUMEPR RETAINER LH	11 \$45.00	9
T REAR BOWER REFERENCE	1	REAR BUMPER REFLECTOR RH	in agreement and a second and a	À
1 EXHAUST HEAT SHIELD \$156.00	1	REAR BUMPER REFLECTOR LH	A SECONDARY OF A SECONDARY	٧,
	1	EXHAUST HEAT SHIELD	11 \$156.00	α



LINDA LIAO

ABWIN SERVICE PTE LTD

DID: 67139417 Fax: 67139415

HP: 97519596

: 01/12/2017 TP Vehicle No. : SJM-8666-P : ECICS LIMITED

To Attn

Date

: Motor Claim Department

Owner

: ANMANI GENERAL CONSTRUCTION PTE LTD

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Certificate No. : 200813721M

Vehicle No.

: SLN-6519-R

Make & Model : HONDA VEZEL 1.5X A

Accident Date: 30/11/2017

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
	Sub Total	\$11,205.80	
	Discount 25% on Parts	(\$2,801.45)	
		\$8,404.35	
Special	Nett		/
1	REAR REVERSE CAMERA	1 7 \$480.00	X ,
1	REAR REVERSE SENSOR	Shud \$350.00	2005. N
1	REAR NUMBER PLATE & CASEING	AA \$45.00	X
	Sub Total	\$875.00	

TO STAIGHTEN AND PANEL BEAT ACCIDENT AREAS	\$1,500.00	400
TO SPRAY PAINT ON AFFECTED AREAS	\$1,500.00	500
TO APPLY TUFF KOTE	\$60.00	30
TO TRANSFER ALL REAR TAILGATE FITTING	\$250.00	60
TO REMOVE & INSTALL REAR WINDSCREEN	\$150.00	120
TO CHECK ALL NECCESSARY WIRINGS	\$150.00	20
TO CONDUCT INTERIOR TRIMBOARD	\$150.00	60
TO INSTALL REVERSE CAMERA AND CHECK FUNCTIONALITY	\$250.00	مكر
TO INSTALL REVERSE SENSOR & CHECK FUNCTIONALITY	\$250.00	
Sub Total	\$4,260.00	

\$13,539.35 **Sub Total** \$947.75 **GST 7%** \$14,487.10 Total

LKK Auto Consultants hence notify the Repairer of the following:

- To re ... very beforelatter spray painting
- To display damaged puritis) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature: Date:

Page 2 of 2

ABWIN SERVICE PTE LTD, 8 KAKI BUKIT AVENUE 4 - GATE 2, #07-48 PREMIER @ KAKI BUKIT, SINGAPORE 415875

Nivitha (LKK Auto)

From:

ECICS Claims <claims@ecics.com.sg>

Sent:

Monday, 4 December, 2017 5:08 PM

To: Cc:

Linda Liao; 'assignments'

Subject:

Ivan Teo; ECICS Claims RE: SLN6519R Against SJM8666P Accident on 30/11/2017

Attachments:

SAS2317907.pdf; Estimation.pdf

Without Prejudice

901am@ 5/12/17

Dear Linda

Vehicle Not In person @ Linda

Thank you for your email. We will assign LKK for PRI.

Aside to LKK

Please assist and arrange PRI.

Thank you.

Regards, Janice Goh Claims Division DID: +65 6303 0182 FAX: +65 6338 9267

ECICS Limited

7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: Linda Liao [mailto:lindaliao@abwin.com.sg]

Sent: Monday, 4 December, 2017 5:05 PM

To: ECICS Claims Cc: Ivan Teo

Subject: RE: SLN6519R Against SJM8666P Accident on 30/11/2017

Dear Janice

Please appoint LKK.

Thank you Regards

ABWIN

Abwin Service Pte Ltd No. 8 Kaki Bukit Avenue 4 #07-48 Premier@Kaki Bukit Gate 2 Singapore 415875

Linda Liao

Motor Claim Executive

DID +65 6713 9417 HP:9751 9596

T +65 6713 9400 | F +65 6713 9415

Website | Facebook | LinkedIn

Looking to start a new business soon? Find out how we can provide you with a complete vehicle ownership solution and much more!

Click here to view our listing >>



From: ECICS Claims [mailto:claims@ecics.com.sg]

Sent: Monday, 4 December, 2017 5:01 PM

To: Linda Liao < lindaliao@abwin.com.sg>; ECICS Claims < claims@ecics.com.sg>

Cc: Ivan Teo < ivanteo@abwin.com.sg>

Subject: RE: SLN6519R Against SJM8666P Accident on 30/11/2017

Without prejudice

Dear Linda

Thank you for your email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client's workshop. We propose to use one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:

- 1. LKK
- 2. JP knight
- 3. Formteam
- Appraisal Associates
- Autoprobe
- 6. Raleigh
- 7. In-House Surveyor

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Thank you.

Regards, Janice Goh Claims Division DID: +65 6303 0182 FAX: +65 6338 9267

ECICS Limited

7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sq directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: Linda Liao [mailto:lindaliao@abwin.com.sg]
Sent: Friday, 1 December, 2017 11:39 AM

To: ECICS Claims

Cc: Ivan Teo
Subject: Re: SLN6519R Against SJM8666P Accident on 30/11/2017

Dear Motor Claim Dept

Please arrange survey before repair as soon as possible.

Thank you Regards

ABWIN

Abwin Service Pte Ltd No. 8 Kaki Bukit Avenue 4 #07-48 Premier@Kaki Bukit Gate 2 Singapore 415875

Linda Liao Motor Claim Executive DID +65 6713 9417 HP:9751 9596 T +65 6713 9400 | F +65 6713 9415

Website | Facebook | LinkedIn

Looking to start a new business soon? Find out how we can provide you with a complete vehicle ownership solution and much more!

Click here to view our listing >>





This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

Shu Pei (LKKAuto)

From:

Janice Goh Siew Geok (ECICS, Claims) < Janice_Goh@ecics.com.sg>

Sent:

Wednesday, 27 December, 2017 9:13 AM

To:

Shu Pei (LKKAuto); ECICS Claims; motorsurvey

Cc:

Phoebe Jay Xie (ECICS, Claims); Lionel Chua Kok Keong (ECICS, Claims); Carrie Tan Chi

Hui (ECICS, Claims); Admin A; Asher Sng (LKKAuto)

Subject:

RE: SLN6519R Against SJM8666P Accident on 30/11/2017 ****LKK

REF:CC4/ICS17023076/Ueb3

Attachments:

SJM8666P.PDF

Dear Shu Pei

As requested, please see attachment. Thank you.

Regards, Janice Goh Claims Division D!D: +65 6303 0182 FAX: +65 6338 9267

ECICS Limited

7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sq directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: Shu Pei (LKKAuto) [mailto:shupei@lkkauto.com]

Sent: Wednesday, 27 December, 2017 9:08 AM

To: ECICS Claims; motorsu:vey

Cc: Janice Goh Siew Geok (ECICS, Claims); Phoebe Jay Xie (ECICS, Claims); Lionel Chua Kok Keong (ECICS, Claims);

Carrie Tan Chi Hui (ECICS, Claims); Admin A; Asher Sng (LKKAuto)

Subject: RE: SLN6519R Against SJM8666P Accident on 30/11/2017 ****LKK REF:CC4/ICS17023076/Ueb3

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Thank you.

"Wishes you a Merry Christmas & Happy New Year 2018"

Best Regards,

Shu Pei | Admin

Phone: 6366-0055 | email: shupei@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto)

Sent: Monday, 11 December, 2017 7:30 PM

To: ECICS Claims < claims@ecics.com.sg>; 'motorsurvey' < motorsurvey@ecics.com.sg>

Cc: Janice Goh Siew Geok (ECICS, Claims) < Janice Goh@ecics.com.sg >; Phoebe Jay Xie (ECICS, Claims)

<PhoebeJay Xie@ecics.com.sg>; Lionel Chua Kok Keong (ECICS, Claims) < Lionel Chua@ecics.com.sg>; Carrie Tan Chi

Hui (ECICS, Claims) < Carrie Tan@ecics.com.sg>; Admin A < admin-a@lkkauto.com>; Asher Sng (LKKAuto)

<AsherSng@lkkauto.com>

Subject: RE: SLN6519R Against SJM8666P Accident on 30/11/2017 **** LKK REF:CC4/ICS17023076/Ueb3

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SLN 6519R at M/s Abwin Service Pte Ltd.

Enclosed for your perusal is:

TP estimated cost of repair

Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge Asher and she can be contacted at DID: 6841 6051.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupei@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Tuesday, 5 December, 2017 9:25 AM

To: 'ECICS Claims' < claims@ecics.com.sg>; assignments < assignments@lickauto.com>

Cc: 'Janice Goh Siew Geok (ECICS, Claims)' < Janice Goh@ecics.com.sg>; Admin A < admin-a@lkkauto.com>

Subject: RE: SLN6519R Against SJM8666P Accident on 30/11/2017

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Ptc Ltd

Phone: 6841-1972 | email: <u>assignments@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ECICS Claims [mailto:claims@ecics.com.sg]

Sent: Monday, 4 December, 2017 5:08 PM

To: Linda Liao; 'assignments' Cc: Ivan Teo; ECICS Claims

Subject: RE: SLN6519R Against SJM8666P Accident on 30/11/2017

Without Prejudice

Dear Linda

Thank you for your email. We will assign LKK for PRI.

Aside to LKK

Please assist and arrange PRI.

Thank you.

Regards, Janice Goh Claims Division DID: +65 6303 0182 FAX: +65 6338 9267

ECICS Limited

7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sq directly.

**Please bear with us should we take longer to response as we are currently experiencing a high volume of claims.

Thank you for your kind patience and understanding.**

From: Linda Liao [mailto:lindaliao@abwin.com.sq]

Sent: Monday, 4 December, 2017 5:05 PM

To: ECICS Claims Cc: Ivan Teo

Subject: RE: SLN6519R Against SJM8666P Accident on 30/11/2017

Dear Janice

Please appoint LKK.

Thank you Regards

ABWIN Abwin Service Pte Ltd
No. 8 Kaki Bukit Avenue 4

#07-48 Premier@Kaki Bukit Gate 2 Singapore 415875

Linda Liao

Motor Claim Executive

DID +65 6713 9417 HP:9751 9596 T +65 6713 9400 | F +65 6713 9415

Website | Facebook | LinkedIn

Looking to start a new business soon? Find out how we can provide you with a complete vehicle ownership solution and much more!

Click here to view our listing >>



From: ECICS Claims [mailto:claims@ecics.com.sg] Sent: Monday, 4 December, 2017 5:01 PM

To: Linda Liao < lindaliao@abwin.com.sg>; ECICS Claims < claims@ecics.com.sg>

Cc: Ivan Teo < ivanteo@abwin.com.sg>

Subject: RE: SLN6519R Against SJM8666P Accident on 30/11/2017

Without prejudice

Dear Linda

Thank you for your email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client's workshop. We propose to use one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:

- 1. LKK
- JP knight
- Formteam
- Appraisal Associates
- Autoprobe
- Raleigh
- 7. In-House Surveyor

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Thank you.

Regards, Janice Goh Claims Division DID: +65 6303 0182 FAX: +65 6338 9267 **ECICS Limited**

7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

**Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding. **

From: Linda Liao [mailto:lindaliao@abwin.com.sg]

Sent: Friday, 1 December, 2017 11:39 AM

To: ECICS Claims Cc: Ivan Teo

Subject: Re: SLN6519R Against SJM8666P Accident on 30/11/2017

Dear Motor Claim Dept

Please arrange survey before repair as soon as possible.

Thank you Regards

ABWIN掘

Abwin Service Pte Ltd No. 8 Kaki Bukit Avenue 4 #07-48 Premier@Kaki Bukit Gate 2 Singapore 415875

Linda Liao

Motor Claim Executive

DID +65 6713 9417 HP:9751 9596 T +65 6713 9400 | F +65 6713 9415

Website | Facebook | LinkedIn

Looking to start a new business soon? Find out how we can provide you with a complete vehicle ownership solution and much more!

Click here to view our listing >>



×	×	X
---	---	---

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

To : M/s ECICS LTD

Date: 24/01/2018

THIRD PARTY DIRECT SETTLEMENT

	SJM 8666P	(Insd Veh)	Your Ref. No.: MPC17A00047101
Vehicle No.	SLN 6519R	(TP Veh)	Our Ref. No. : CC4/ICS17023076/Ueb3s2
Date of Accident	30/11/2017		

Liability		100%	
Final Repair Cost	: \$	3,340.03	
Loss of Use	: \$	360.00	6 days
Rental (If any)	: \$		days
Others:	: \$	2.00	
	: \$		
		3,702.03	
Final Settlement Sum	: \$	3,702.03	
Remarks	2		

1)	ABWIN SERVICE PTE LTD	: \$	3,702.03
512	APP to Property Tourist Country of the Country of t	: \$	

NUR SHAQILAH LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Into	ernationale Des Experts En Autom		
ECICS LTD		Ref : CC4/ICS17023076/Ueb3s2		
7 TEMASEK BOULEV #10-01 SUNTEC TOW SINGAPORE 038987		Date: 24-01-2018 Code: ICS		
1.	Policy Partic	ulars :- THIRD PARTY CLAI	M	
Insured Veh.	SJM 8666P	Veh. Inspected	SLN 6519R	
Policy No.	MPC17A00047101	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	04/12/2017	
2.	Vehicle	Particulars & Condition		
Make & Model	HONDA VEZEL (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	RU11211569	Colour	BLUE	
Odometer	18197	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3.	С	Conditions of Tyres		
	Size	Make	Balance	
R/H Front Tyre	215/60R16	DUNLOP	6 mm	
L/H Front Tyre	215/60R16	DUNLOP	6 mm	
R/H Rear Tyre	215/60R16	DUNLOP	6 mm	
L/H Rear Tyre	215/60R16	DUNLOP	6 mm	
4.	Des	cription of Damages		
THE VEHICLE S	USTAINED DAMAGES AT T	HE REAR PORTION.		
DAMAGES SEE	DETAILS.			
5.	G	eneral Information		
Accident Date	30/11/2017	Inspection Date	08/12/2017	
Survey held at	ABWIN SERVICE PTE LT	TD		
	No. 8 KAKI BUKIT AVEN #07-48 PREMIER@KAKI SINGAPORE 415875			
5a.		Remarks		
A)THE INSPECT B)IN ACCORDA	ION WAS CONDUCTED ON	I A"WITHOUT PREJUDICE" BA ONS, WE HAVE NOT AUTHORI	SIS. SED REPAIRS.	
5b.		timate Days of Repair		

ESTIMATED NORMAL PERIOD FOR REPAIR:

4 Working Days



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 6519R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE EMBLEM VEZEL	NECESSARY	35.00	35.00
1	TAILGATE	BADLY DENTED	953.60	953.60
	TAILGATE TOP GARNISH	NOT NECESSARY	720.00	-
1	TAILGATE LAMP RH	NOT NECESSARY	250.00	-
1	TAILGATE LAMP LH	NOT NECESSARY	250.00	-
1	TAILGATE WEATHERSTRIP	NOT NECESSARY	250.00	-
-1	TAILGATE INNER TRIMBOARD	NOT NECESSARY	250.00	-
10	TAILGATE INNER TRIMBOARD CLIPS	NOT NECESSARY	50.00	-
1	REAR WINDSCREEN MOULDING	NECESSARY	150.00	150.00
1	REAR FENDER RH	NOT NECESSARY	950.00	-
1	REAR FENDER LH	NOT NECESSARY	1,250.00	-
1	REAR FENDER INNER SHIELD RH	NOT NECESSARY	285.00	-
1	REAR FENDER INNER SHIELD LH	NOT NECESSARY	285.00	-
1	TAILLAMP RH	NOT NECESSARY	580.60	-
1	TAILLAMP LH	NOT NECESSARY	580.60	-
1	SPARE TYRE PANEL	NOT NECESSARY	1,530.00	-
1	SPARE TYRE PANEL INSULATOR	NOT NECESSARY	485.00	-
1	SPARE TYRE COMPARTMENT COVER & TYRE BOARD	NOT NECESSARY	260.90	-
10	SPARE TYRE INSULATOR CLIPS	NOT NECESSARY	50.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	480.60	
1	REAR END PANEL BRACKET RH	NOT NECESSARY	65.00	
1	REAR END PANEL BRACKET LH	NOT NECESSARY	65.00	
1	REAR BUMPER	DEFORMED	762.70	762.70
10	REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR BUMPER RETAINER RH	NOT NECESSARY	45.00	
1	REAR BUMPER RETAINER LH	NOT NECESSARY	45.00	
1	REAR BUMPER REFLECTOR RH	NOT NECESSARY	185.40	
1	REAR BUMPER REFLECTOR LH	NOT NECESSARY	185.40)
1	EXHAUST HEAT SHIELD	NOT NECESSARY	156.00	
3	SMART BUZZER ASSY (ADDITIONAL)	CRACKED	150.60	150.60

Report Ref No. CC4/ICS17023076/Ueb3s2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LESS 25% DISCOUNT		-2,839.10	
	LESS 20% DISCOUNT		-	-420.38
			8,517.30	1,681.52
	SPECIAL NETT ITEMS			
1	REAR REVERSE CAMERA (SN)	NOT NECESSARY	480.00	
	REAR REVERSE SENSOR (SN)	SHORTED	350.00	200.00
	REAR NUMBER PLATE & CASING (SN)	NOT NECESSARY	45.00	
8			875.00	200.00
	LABOUR			
	TO STRAIGHTEN AND PANEL BEAT ACCIDENT PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		1,500.00	400.00
	TO SPRAY PAINT ON AFFECTED AREAS.		1,500.00	500.00
	TO APPLY TUFF KOTE.		60.00	30.00
	TO TRANSFER ALL REAR TAILGATE FITTING.		250.00	60.00
	TO REMOVE & INSTALL REAR WINDSCREEN.		150.00	120.00
	TO CHECK ALL NECESSARY WIRINGS.		150.00	20.00
	TO CONDUCT INTERIOR TRIMBOARD.		150.00	60.00
	TO INSTALL REVERSE CAMERA AND CHECK FUNCTIONALITY. }		250.00	50.00
	TO INSTALL REVERSE SENSOR & CHECK FUNCTIONALITY. }		250.00	
	(8)		4,260.00	1,240.00
	GRAND TOTAL		13,652.30	3,121.52
	RECOMMENDED COST OF REPAIRS			3,121.52

Report Ref No. CC4/ICS17023076/Ueb3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.