

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883

Tel: 6747 6106 (6 Lines) Fax: 6744 2368

Email: service@smemotor.com.sg Website: www.smemotor.com.sg

Co. & GST Reg. No: 201119451E

INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	17/MSIG/OD-569 (12)
Policy No:	A28817353QMX	Date of Loss:	01/12/2017
Vehicle Reg. No.:	SKA7625R	Driveable?	
Driver Age/Info:	46 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CHEW MEI FONG	Contact No:	+6597269611
Driver:	CHEW MEI FONG		

Make/Model:	BMW 523i, 2.5 (A)	Vehicle Reg. Date:	31/03/2011
Vehicle Colour:	SILVER	Chassis No:	WBAFP32040C865439
Engine No:	10697716N52B25AF		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair 14 (day)			

Not Authorised p/p
Make
Take photo before party
Excess \$600
6 day

Description of Accident/Loss	FRONT VEHICLE SUDDENLY STOP. I CANNOT STOP IN TIME AND HIT VEHICLE B REAR PORTION.
Remarks:	VEHICLE IN.
Present Location:	SME MOTOR PTE LTD (KAKI BUKIT)

COST OF CLAIMS

	Amount
Parts	13,853.40
Miscellaneous Items	65.00
Labour	1,630.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (\$\$)	15,548.40
- Excess (\$\$)	600.00
Signature:	(\$\$) 14,948.40
Date:	(\$\$) 1,046.39
+ GST 7.00% (\$\$)	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer


Signature:

Date:

Nett Amount (S\$) 15,994.79

This claim is handled by: PEI YING

Generated using **Merimen e-Claims Internet Estimation & Adjusting System**



REPAIR DETAILS**Reference****Part Source:** MRM-SG

Version: 1.0 (Last Synchronised: 04 Dec 2017)

Parts: 143

BMW 523i 2.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: SME Motor Pte Ltd/SKA7625R/04/12/2017 12:03**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRT BONNET <i>Buc</i>	0.00	0.00	*1,560.00 F	—
2	2		*FRT BONNET LOCK CATCH TOP (SIDES) <i>2uf/7w1</i>	0.00	0.00	*160.00 F	—
3	1		*FRT BONNET LOCK CATCH TOP (CENTER) <i>7w1</i>	0.00	0.00	*50.00 F	—
4	2		*FRT BONNET LOCK LOWER (SIDES) <i>7w1</i>	0.00	0.00	*390.00 F	—
5	1		*FRT BONNET LOCK CABLE	0.00	0.00	*26.00 F	?
6	2		*FRT GRILLE <i>310</i>	0.00	0.00	*230.00 F	—
7	1		*FRT BUMPER <i>D.S</i>	0.00	0.00	*1,050.00 F	—
8	2		*FRT BUMPER RETAINER <i>0/5 Buc</i>	0.00	0.00	*36.00 F	— <i>12c</i>
9	1		*FRT BUMPER CENTER LOGO <i>ru</i>	0.00	0.00	*95.00 F	—
10	10		*FRT BUMPER CLIP <i>ru</i>	0.00	0.00	*20.00 F	—
11	1		*FRT BUMPER TOP RUBBER SEAL <i>7w1</i>	0.00	0.00	*35.00 F	—
12	1		*FRT BUMPER TOWING COVER <i>7w1</i>	0.00	0.00	*32.00 F	—
13	2		*FRT BUMPER PARKING SENSOR <i>shod</i>	0.00	0.00	*330.00 F	—
14	2		*FRT BUMPER PARKING SENSOR SEAL <i>ru</i>	0.00	0.00	*10.00 F	—
15	1		*FRT BUMPER LOWER GRILLE CENTER	0.00	0.00	*60.00 F	?
16	2		*FRT BUMPER LOWER GRILLE SIDES <i>0/5 7w1</i>	0.00	0.00	*130.00 F	— <i>12c</i>
17	1		*FRT BUMPER INNER SPONGE <i>Cne</i>	0.00	0.00	*40.00 F	—
18	1		*FRT BUMPER REINFORCEMENT <i>DD</i>	0.00	0.00	*495.00 F	—
19	1		*FRT BUMPER PARKING SENSOR WIRE	0.00	0.00	*120.00 F	?
20	2		*HEADLAMP <i>0/5 310</i>	0.00	0.00	*3,160.00 F	— <i>12c RH</i>
21	1		*RH HEADLAMP NOOZLE	0.00	0.00	*150.00 F	?
22	1		*HEADLAMP NOOZLE HOSE	0.00	0.00	*60.00 F	?
23	1		*RH HEADLAMP NOOZLE COVER <i>7w1</i>	0.00	0.00	*50.00 F	—
24	1		*AIR BUFFER <i>D.S</i>	0.00	0.00	*240.00 F	—
25	1		*CENTER TOP PANEL (OUTER) <i>Buc</i>	0.00	0.00	*165.00 F	—
26	2		*HEADLAMP PANEL	0.00	0.00	*270.00 F	?
27	2		*HEADLAMP PANEL TOP GARNISH <i>0/5 7w1</i>	0.00	0.00	*60.00 F	— <i>12c</i>
28	1		*CENTER TOP PANEL (INNER)	0.00	0.00	*90.00 F	?
29	1		*AIRCON CONDENSER	0.00	0.00	*700.00 F	?
30	1		*RADIATOR	0.00	0.00	*680.00 F	?
31	1		*RADIATOR FAN ASSY	0.00	0.00	*850.00 F	?
32	2		*FRT BUMPER INNER GARNISH <i>D.S</i>	0.00	0.00	*100.00 F	—
33	1		*FRT BUMPER FOG LAMP RH <i>Cne</i>	0.00	0.00	*185.00 F	—
34	1		*FRT RH FENDER <i>DD/310</i>	0.00	0.00	*620.00 F	—
35	1		*FRT RH FENDER INNER COWLING (FRT) <i>11</i>	0.00	0.00	*120.00 F	—
36	10		*INNER COWLING CLIP <i>11</i>	0.00	0.00	*25.00 F	—
37	2		*FRT FENDER INNER TOP GARNISH	0.00	0.00	*140.00 F	?
38	12		*FRT FENDER INNER TOP GARNISH CLIP	0.00	0.00	*60.00 F	?

F=Franchise part.

Sub Total (S\$) **12,594.00**
+ Margin on L,N Items 10.00% (S\$) **1,259.40**

SME Motor Pte Ltd/SKA7625R/04/12/2017 12:03. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
Total Parts (S\$)						13,853.40

SME Motor Pte Ltd/SKA7625R/04/12/2017 12:03. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars		Amount
Miscellaneous Items				
1	1	NUMBER PLATE	35	40.00 ✓
2	1	RADIATOR COOLANT	100	25.00 ✓
Sub Total (S\$)				65.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	WIRE CHECKING	New	30.00 ✓
2	REMOVE & REFIX AIRCON AND GAS	New	100.00 ✓
3	LABOUR CHARGE	New	700.00 600
4	SPRAY PAINTING	New	800.00 700
Gross Labour Cost (S\$)			1,630.00

SME Motor Pte Ltd/SKA7625R/04/12/2017 12:03. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >