

15/5/2018

INS. CASE OWNER:

Clara Li

CC 4 / FWD170

23104, 6 ea352

LKK:

IDAC:

Surveyor:

XG12

DOI:

ASSIGNMENT

5/12/17

Date / Time:

5/12/17

Registered in Merimen:

5/12/17

Pre-assign / CCU / FTE



Insured Vehicle No.:

SCT 4214M

Name of Insured:

Chong Shu Hai, Eileen (Zhong Shu Hai)

Insured Tel No.:

HP: 98223461

Excess Sec II :SS

D.O.A: 01-12-17

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

1701700008458

Policy No.:

PNPV2017-00004409

Make / Model:

Toyota Altis

Place of Accident:

MCT > KPE

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

%

Final ? Yes / No

SUB 3660Y



INSRS:

WSP:

Tel:

Liability:

RMKS:

Kam Fook Sing?



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

14/12
A2WSUB 3660Y. X;
SCT 4214M, CC/FWD 17022970/16; DOA 1/12/17

18/12/17

Email WSP Liability Create.

7.5.18

FILE PASS TO TYPIST TO TYPE REPORT.

RECEIVED 3 JUL 2018

RECEIVED 04 JUL 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

21.2.17

Sent By:

A2W

FINALIZATION

Date/Time: 7.5.18

Confirm with: TAN

Confirm by: XG12

Repair Cost:

PIP

SS31,940.60

(13 days)

Reduction:

31

%

Email

Call

FINAL SETTLEMENT

Date/Time: 2.7.18

Confirm with: PAT

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

28

If NO or B 28, Ass. Lia: 100%

Repair Cost:

WIKSI

SS33,748.44

5VEN CC OI LABI

Loss of Rental (LOR): WIKSI

SS 1,936.00

(18 days)

x 100

Loss of Use (LOU):

SS

(\$

x

days)

Loss of Income (LOI):

SS

(\$

x

days)

LOR only

☒

LOU only

☐

LOR + LOU

☐

LOR + LOI

☐

[Tick only one]

GIA/LTA Search

SS

-

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

Total:

SS35,674.44

Global Sum SS:

FINAL PAYMENT

Date/Time: 2.7.18

Confirm with: PAT

Email

Call

Payee 1:

SS35,674.44

Name 1:

KAM FOOK SING MOTOR WORKSHOP

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT
4/7/18

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

+500



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FWD SINGAPORE PTE LTD			Ref : CC4/FWD17023104/Gea3	
6 TEMASEK BOULEVARD #18-01 SUNTEC TOWER 4SINGAPORE 038986			Date : 05-12-2017	
			Code : FWD	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKT 4214M	Veh. Inspected	SLB 3660Y	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	05/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	01/12/2017	Inspection Date	05/12/2017	
Survey held at	KAN FOOK SING MOTOR WORKSHOP 61 DEFU LANE 12 SINGAPORE 539147			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12 Singapore 539147
Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
E-mail: ryan@kanfs.net/ patricia@kanfs.net
Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
Tel: (65) 6481 5150 Fax: (65) 6481 8683

FWD SINGAPORE PTE LTD

DATE : 05-12-2017

6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4
SINGAPORE 038986
VEHICLE NO. : SLB3660Y

ACCIDENT DATE : 01-12-2017 17:53

THIRD PARTY REF. : SKT4214M

ATTN: FWD SINGAPORE PTE LTD

ESTIMATE COST OF REPAIR TO VEHICLE SLB3660Y MERCEDES BENZ GLA 180

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	REAR BOOT COVER - Bul	1767.00✓
2	1	REAR BOOT RUBBER 3X {NN	202.00
3	1	REAR LAMP 2X	650.00
4	1	REAR BUMPER - Re	1570.00✓
5	1	REAR BUMPER TOP GARNISH 2✓ MC.	148.00✓
6	5	REAR BUMPER TOP GARNISH CLIP@\$9.00 2✓ MC.	45.00✓
7	1	REAR BUMPER TOW COVER - mis	0.00 55.00✓
8	1	REAR BUMPER REINFORCEMENT - BT	545.00✓
9	2	REAR BUMPER SIDE RETAINER@\$20.00 - MC	40.00✓
10	1	REAR BUMPER SIDE GARNISH RH - Re	29.00✓
11	1	REAR BUMPER LOWER GARNISH RH - mis	92.00✓
12	4	REAR BUMPER SENSOR@\$185.00 2X {NN	740.00
13	4	REAR BUMPER SENSOR RING@\$12.00 2X {NN	48.00
14	1	REAR BUMPER LOWER - Re	663.00✓
15	1	REAR BUMPER LOWER COVER - Re	525.00✓
16	2	REAR BUMPER LOWER GARNISH BRACKET@\$90.00 2✓ MIS	180.00✓
17	1	REAR UNDERCOVER - Re	740.00✓
18	1	REAR EXHAUST MUFFLER 2✓ BT	1111.00✓
19	1	REAR EXHAUST HEAT SHIELD CENTRE 2✓ Bul	0.00 26.00
20	2	REAR EXHAUST HEAT SHIELD SIDE@\$ 2X NN	0.00
21	2	REAR EXHAUST CHROME PIPE@\$256.00 X ✓ BT	512.00✓
22	2	REAR EXHAUST MOUNTING@\$38.00 2✓ BT	76.00✓
23	1	FRONT BONNET - BT	1398.00✓
24	1	FRONT BONNET SEAL - Twi	34.00✓
25	1	FRONT BONNET STAND X NN.	22.00



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

VEHICLE NO. : SLB3660Y

ACCIDENT DATE : 01-12-2017 17:53

THIRD PARTY REF. : SKT4214M

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
26	1	FRONT BONNET LOCK TOP <i>RX LNN</i>	45.00
27	1	FRONT BONNET LOCK LOWER <i>RX</i>	113.00
28	2	FRONT BONNET HINGES@\$82.00 <i>DT</i>	164.00 ✓
29	2	FRONT BONNET ACTUATOR@\$175.00 <i>RX DM</i>	350.00 ✓
30	2	FRONT BONNET STOPPER@\$19.00 <i>Cut</i>	38.00 ✓
31	1	FRONT BONNET LOCK SWITCH <i>RX NN</i>	122.00
32	1	FRONT GRILLE BASE <i>CRA</i>	285.00 ✓
33	1	FRONT GRILLE EMBLEM <i>MC</i>	255.00 ✓
34	1	FRONT GRILLE CHROME <i>Cut</i>	145.00 ✓
35	4	FRONT GRILLE CHROME FIN@\$63.00 <i>Cut</i>	252.00 ✓
36	2	FRONT HEADLAMP@\$2360.00 <i>LH RX NN 2360 ✓</i>	4720.00 <i>IPC 2360 ✓</i>
37	1	FRONT HEADLAMP BLUB <i>RX</i>	477.00
38	1	FRONT HEADLAMP HID UNIT <i>RX LNN</i>	765.00
39	1	FRONT SUPPORT PANEL <i>BT</i>	608.00 ✓
40	2	FRONT SUPPORT SIDE BRACKET@\$38.00 <i>RX NN</i>	76.00 <i>24.00 X</i>
41	1	FRONT FENDER RH <i>MC</i>	705.00 ✓
42	1	FRONT FENDER SHIELD RH <i>RX BT</i>	170.00 ✓
43	10	FRONT FENDER SHIELD CLIP@\$9.00 <i>MC</i>	90.00 ✓
44	2	FRONT FENDER GARNISH@\$108.00 <i>MC 1pc</i>	327.00 <i>✓ 108.00</i>
45	8	FRONT FENDER GARNISH CLIP@\$9.00 <i>MC</i>	72.00 ✓
46	1	FRONT BUMPER <i>CRA</i>	1645.00 ✓
47	1	FRONT BUMPER FOAM <i>CRA</i>	130.00 ✓
48	1	FRONT BUMPER TOP FRAME <i>RX DE</i>	120.00 ✓
49	1	FRONT BUMPER REINFORCEMENT <i>BT</i>	305.00 ✓
50	2	FRONT BUMPER REINFORCEMENT BRACKET@\$110.00 <i>RX RH BT LH X NN</i>	220.00 <i>✓ 110.00</i>



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

VEHICLE NO. : SLB3660Y
ACCIDENT DATE : 01-12-2017 17:53
THIRD PARTY REF. : SKT4214M

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
51	2	FRONT BUMPER SIDE RETAINER@\$9.00 / MC	18.00✓
52	1	FRONT BUMPER TOW COVER / cut	67.00✓
53	4	FRONT BUMPER SENSOR@\$ - DM 1PC	0.00/85.00✓
54	2	FRONT BUMPER SENSOR RING@\$ - MC	0.00/24.00✓
55	1	FRONT BUMPER SENSOR WIRE 2 / MC	114.00✓
56	2	FRONT BUMPER WIPER NOZZLE @\$172.00 2X NN	344.00
57	1	FRONT BUMPER WIPER NOZZLE TUBE 2X	57.00✓
58	2	FRONT BUMPER WIPER NOZZLE COVER@\$52.00 < LH X NA RH - cut	104.00✓ 52.00
59	2	FRONT BUMPER WIPER COVER SPRING@\$20.00 < LH X NN RH - M's	40.00✓ 20.00
60	2	FRONT BUMPER FOGLAMP COVER@\$45.00 < LH X NN RH - M's	90.00✓ 45.00
61	1	FRONT BUMPER LOWER CENTRE 2X NN	550.00
62	2	FRONT BUMPER LOWER SIDE@\$280.00 2X NN	560.00
63	1	FRONT BUMPER EMBLEM - MC	60.00✓
64	10	FRONT BUMPER CLIP@\$9.00 - MC	90.00✓
65	1	FRONT BUMPER CENTRE GRILLE 2X NN	166.00
66	1	FRONT BUMPER LOWER COVER 2X	86.00
67	1	FRONT NUMBER PLATE GARNISH - ee	164.00✓
68	1	AIR CON CONDENSER 2X ✓ 85	1078.00✓
69	1	AIR CON LIQUID PIPE 2X	356.00
70	1	AIR CON SUCTION HOSE 2X NN	316.00
71	1	AIR CON DISCHARGE HOSE 2X	316.00
72	1	RADIATOR ASSY 2X ✓ 85	840.00✓
73	1	RADIATOR TOP HOSE 2X NN	55.00
74	1	RADIATOR LOWER HOSE 2X	85.00
75	2	RADIATOR TOP BRACKET@\$90.00 2X NN	180.00



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

VEHICLE NO. : SLB3660Y

ACCIDENT DATE : 01-12-2017 17:53

THIRD PARTY REF. : SKT4214M

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
76	2	RADIATOR TOP BUSH@\$12.00 <i>2x</i>	24.00
77	2	RADIATOR LOWER BRACKET@\$33.00 <i>2x</i>	66.00
78	1	RADIATOR FAN ASSY <i>1x</i>	428.00✓
79	1	RADIATOR SPARE TANK <i>1x</i>	155.00✓
80	1	SPARE TANK BREATHING PIPE <i>1x</i>	88.00✓
81	1	WASHER TANK <i>1x</i>	148.00
82	1	WASHER TANK MOTOR <i>1x</i>	88.00
83	2	RADIATOR SIDE GARNISH @\$16.00 <i>2x</i>	32.00 <i>1x 38.00</i>
84	1	RADIATOR LOWER GARNISH <i>1x</i>	57.00 <i>1x 38.00</i>
85	1	AIR CON DECEIVER <i>1x</i>	216.00
86	2	AIR CON SIDE GARNISH@\$137.00 <i>2x</i>	274.00 <i>2x 23.00</i>
87	1	INTERCOOLER <i>1x</i>	832.00
88	1	INTERCOOLER PIPE RH <i>1x</i>	190.00✓
89	1	INTERCOOLER PIPE LH <i>1x</i>	230.00✓
90	2	REAR BUMPER LOWER SIDE BRACKET LOWER@\$40.00 <i>2x</i>	80.00
91	1	REAR BUMPER SENSOR WIRE <i>1x</i>	90.00
92	1	FRONT BONNET STAND HOLDER <i>1x</i>	9.00
93	1	FRONT GRILLE BASE <i>1x</i>	71.00
94	2	FRONT HEADLAMP ADJUSTER CONTROL@\$277.00 <i>2x</i>	554.00✓ <i>1x 277.00</i>
95	1	ENGINE UNDERCOVER FRT <i>1x</i>	302.00
96	1	FRONT SUPPORT LOWER <i>1x</i>	395.00
97	1	FRONT SUPPORT LOWER BRACKET LONG@\$199.00 <i>1x</i>	395.00
98	2	FRONT SUPPORT LOWER BRACKET SHORT @\$145.00 <i>2x</i>	290.00
99	2	FRONT HEADLAMP LOWER BRACKET @\$67.00 <i>2x</i>	134.00
100	1	FRONT SUPPORT TOP PLASTIC <i>1x</i>	16.00



簡福星摩哆工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

VEHICLE NO. : SLB3660Y
ACCIDENT DATE : 01-12-2017 17:53
THIRD PARTY REF. : SKT4214M

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1011		FRONT BONNET LOCK COVER LOWER <i>Q ✓ mis</i>	<u>67.00</u> <i>70.00</i>
			34,303.00
<i>Suppl REFER TO FINAL REPORT.</i>			LESS 10 %
			<u>3,430.30</u>
			TOTAL (A)
			<u>30,872.70</u>

SPECIAL NETT ITEMS

1	1	REAR WINDSCREEN GUM <i>Q ✓ MCC</i>	40.00 ✓
2	1	FRONT NUMBER PLATE <i>- BT</i>	30.00 ✓
3	1	REAR NUMBER PLATE <i>X NN</i>	30.00
			TOTAL (C)
			<u>100.00</u>

LABOUR CHARGES

1	1	TO CHECK WIRING SYSTEM	100.00 ✓
2	1	TO REMOVE/REFIT/REFILL AIR CON GAS	80.00 ✓
3	1	TO REMOVE/REFIT EXHAUST SYSTEM	80.00 ✓
4	1	TO REMOVE/REFIT REAR FENDER INNER GARNISH AND ETC	120.00 <i>600 ✓</i>
5	1	TO REMOVE/REFIT REAR WINDSCREEN GLASS	100.00 ✓
6	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS (REAR)	1300.00 <i>400 500</i>
7	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS (FRONT)	1600.00 <i>800 1000</i>



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12 Singapore 539147
Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
E-mail: ryan@kanfs.net/ patricia@kanfs.net
Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
Tel: (65) 6481 5150 Fax: (65) 6481 8683

VEHICLE NO. : SLB3660Y
ACCIDENT DATE : 01-12-2017 17:53
THIRD PARTY REF. : SKT4214M

#	QTY	PARTS DESCRIPTION
8	1	SPRAYPAINTING CHARGES (FRONT & REAR)

AMOUNT (SG\$)

2000.00 (1200)

TOTAL (D)

5,380.00

ESTIMATE TOTAL

36,352.70

10 Days .

part by part

before paint photos.

Gino Qian - 82880282

05/12/17

37245.5

45821.20

LKK Auto Insurants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FWD SINGAPORE PTE LTD

6 TEMASEK BOULEVARD

#18-01 SUNTEC TOWER 4

SINGAPORE 038986

VEHICLE NO. : SLB3660Y

ACCIDENT DATE : 01-12-2017 17:53

THIRD PARTY REF. : SKT4214M

INVOICE NO : TEST

DATE : 26-02-2018

ATTN: FWD SINGAPORE PTE LTD

INVOICE COST OF REPAIRS TO VEHICLE SLB3660Y MERCEDES BENZ GLA 180

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	REAR BOOT COVER	1767.00
1	REAR BUMPER	1570.00
1	REAR BUMPER TOP CHROME	148.00
5	REAR BUMPER TOP GARNISH CLIP@\$9.00	45.00
1	REAR BUMPER TOW COVER	55.00
1	REAR BUMPER REINFORCEMENT	545.00
2	REAR BUMPER SIDE RETAINER@\$20.00	40.00
1	REAR BUMPER SIDE GARNISH RH	29.00
1	REAR BUMPER LOWER GARNISH RH	92.00
1	REAR BUMPER LOWER	663.00
1	REAR BUMPER LOWER COVER	525.00
2	REAR BUMPER LOWER GARNISH BRACKET@\$90.00	180.00
1	REAR UNDERCOVER	740.00
1	REAR EXHAUST MUFFLER	1111.00
1	REAR EXHAUST HEAT SHIELD CENTRE	126.00
2	REAR EXHAUST CHROME PIPE@\$256.00	512.00
2	REAR EXHAUST MOUNTING@\$38.00	76.00
1	FRONT BONNET	1398.00
1	FRONT BONNET SEAL	34.00
2	FRONT BONNET HINGES@\$82.00	164.00
2	FRONT BONNET ACTUATOR@\$175.00	350.00
2	FRONT BONNET STOPPER@\$19.00	38.00
1	FRONT GRILLE BASE	285.00
1	FRONT GRILLE EMBLEM	255.00
1	FRONT GRILLE CHROME	145.00

VEHICLE NO. : SLB3660Y
ACCIDENT DATE : 01-12-2017 17:53
THIRD PARTY REF. : SKT4214M

<u>QTY</u>	<u>PARTS DESCRIPTION</u>	<u>AMOUNT (SG\$)</u>
4	FRONT GRILLE CHROME FIN@\$63.00	252.00
1	FRONT HEADLAMP RH	2360.00
1	FRONT SUPPORT PANEL	608.00
1	FRONT FENDER RH	705.00
10	FRONT FENDER SHIELD CLIP@\$9.00	90.00
1	FRONT FENDER GARNISH RH	108.00
8	FRONT FENDER GARNISH CLIP@\$9.00	72.00
1	FRONT BUMPER	1645.00
1	FRONT BUMPER FOAM	130.00
1	FRONT BUMPER TOP FRAME	120.00
1	FRONT BUMPER REINFORCEMENT	305.00
1	FRONT BUMPER REINFORCEMENT BRACKET RH	110.00
2	FRONT BUMPER SIDE RETAINER@\$9.00	18.00
1	FRONT BUMPER TOW COVER	67.00
1	FRONT BUMPER SENSOR	185.00
2	FRONT BUMPER SENSOR RING @\$12.00	24.00
1	FRONT BUMPER SENSOR WIRE	114.00
1	FRONT BUMPER WIPER NOZZLE COVER RH	52.00
1	FRONT BUMPER WIPER COVER SPRING RH	20.00
1	FRONT BUMPER FOGLAMP COVER RH	45.00
1	FRONT BUMPER EMBLEM	60.00
10	FRONT BUMPER CLIP@\$9.00	90.00
1	AIR CON CONDENSER	1078.00
1	RADIATOR ASSY	840.00
1	RADIATOR FAN ASSY	428.00

VEHICLE NO. : SLB3660Y
 ACCIDENT DATE : 01-12-2017 17:53
 THIRD PARTY REF. : SKT4214M

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	RADIATOR SPARE TANK	155.00
1	SPARE TANK BREATHING PIPE	88.00
1	INTERCOOLER PIPE RH	190.00
1	INTERCOOLER PIPE LH	230.00
1	FRONT FENDER SHIELD RH	170.00
1	FRONT HEADLAMP ADJUSTOR CONTROL	277.00
40 (A)	RIVET @\$9.00 / <i>MCC</i>	360.00
1	FRONT BONNET LOCK COVER	70.00
1 (A)	AIR DUCT / <i>MIS</i>	105.00
1 (A)	ENGINE TOP COVER / <i>CRA</i>	365.00
1 (A)	FRONT SUPPORT SIDE BRACKET RH / <i>MCC</i>	24.00
1 (A)	TURBO ASSY / <i>DM</i>	6760.00
1 (A)	TURBO PIPE / <i>CRA</i>	95.00
1 (A)	INTAKE MANIFOLD PIPE / <i>4BT</i>	210.00
1 (A)	MANIFOLD JOINT PIPE	130.00
1 (A)	WATER PUMP / <i>OD</i>	650.00
1 (A)	WATER PUMP PIPE / <i>BT</i>	155.00
1	AIR CON SIDE GARNISH RH	22.00
1	RADITOR SIDE GARNISH TOP RH	38.00
1	RADIATOR SIDE GARNISH LOWER RH	38.00
1 (A)	ENGINE MOUNTING RH / <i>BT</i>	370.00
1	FRONT NUMBER PLATE GARNISH	164.00
2 (A)	ROOF MOULDING CLIP @\$12.00 / <i>MCC</i>	24.00
1 (A)	REAR BUMPER TOW COVER TRIM / <i>MIS</i>	15.00
1 (A)	REAR FENDER SIDE GARNISH RH / <i>MIS</i>	210.00

VEHICLE NO. : SLB3660Y
ACCIDENT DATE : 01-12-2017 17:53
THIRD PARTY REF. : SKT4214M

<u>QTY</u>	<u>PARTS DESCRIPTION</u>	<u>AMOUNT (SG\$)</u>
		31,334.00
	LESS 10 %	3,133.40
	TOTAL (A)	28,200.60

SPECIAL NETT ITEMS

1	REAR WINDSCREEN GUM	40.00
1	FRONT NUMBER PLATE	30.00
1	COOLANT (9) / <i>MC</i>	50.00
	TOTAL (C)	120.00

LABOUR CHARGES

1	TO CHECK WIRING SYSTEM, RE-PROGRAM/RESET MEMORY	100.00
1	TO REMOVE/REFIT/REFILL AIR CON GAS	80.00
1	TO REMOVE/REFIT EXHAUST SYSTEM	80.00
1	TO REMOVE/REFIT REAR FENDER INNER GARNISH AND ETC	60.00
1	TO REMOVE/REFIT REAR WINDSCREEN GLASS	100.00
1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS (REAR)	500.00
1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS (FRONT)	1100.00
1	SPRAYPAINTING CHARGES (FRONT & REAR)	1200.00

VEHICLE NO. : SLB3660Y
ACCIDENT DATE : 01-12-2017 17:53
THIRD PARTY REF. : SKT4214M

QTY PARTS DESCRIPTION

	<u>AMOUNT (SG\$)</u>
TOTAL (D)	3,220.00
TOTAL REPAIR COST :	31,540.60
G S T % :	2,207.84
INVOICE AMOUNT :	33,748.44

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Li Zi Rong

Date: 07 Dec 2017

Preliminary Advice

Insured Vehicle No	: SKT4214M	Accident Date	: 01/12/2017
TP Vehicle No	: SLB3660Y	Assignment Date	: 05/12/2017
Make	: MERCEDES-BENZ GLA180	Est. Duration of Repair	: 10 days
Date of Inspection	: 05/12/2017		
Inspection At	: Kan Fook Sing Motor Workshop (Defu) No. 61 Defu Lane 12 Singapore 539147		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages ...front and rear.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	36,352.70
Revised Amount	:S\$	16,442.00
Check Items (Estimated)	:S\$	16,608.90
Total	:S\$	33,050.90

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorized repairs.

1.00			2.00			3.00		
r	?	X	r	?	r	?	x	
1,767.00	202.00	512.00	164.00	45.00	18.00	114.00		
1,570.00	650.00	22.00	38.00	113.00	67.00	344.00		
545.00	148.00		285.00	350.00	52.00	57.00	52.00	
40.00	45.00		255.00	122.00	45.00	40.00	45.00	
29.00	740.00		145.00		60.00	550.00		
92.00	48.00		252.00		90.00	560.00		
663.00	180.00		2,360.00	2,360.00	164.00	166.00		
525.00	1,111.00		608.00	477.00		86.00		
740.00	76.00		705.00	765.00		1,078.00		
1,398.00			90.00	76.00		356.00		
34.00			327.00	170.00		316.00		
			72.00	120.00		316.00		
			1,645.00	220.00		840.00		
			130.00			55.00		
			305.00			85.00		
						180.00		
7,403.00	3,200.00	534.00	# 7,381.00	4,818.00	# 496.00	5,143.00	97.00	29,072.00

? X

24.00
66.00
428.00
155.00
88.00
148.00
88.00
32.00
57.00
216.00
274.00
832.00
190.00
230.00
80.00
90.00
9.00
554.00 71.00
302.00
395.00
395.00
290.00
134.00
16.00
67.00
5,160.00 71.00

parts

r	15,280.00	13,752.00
?	18,321.00	16,488.90
x	702.00	631.80
	34,303.00	30,872.70

13,752.00	16,488.90
30.00	40.00
20.00	80.00
80.00	
60.00	
100.00	
400.00	
800.00	
1,200.00	
<u>16,442.00</u>	<u>16,608.90</u>

PA

Fst: #36352.70

Revised #1644.00

check: #16608.90

✓ CH 13/14/14

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Monday, 18 December, 2017 11:49 AM
To: 'patricia@kanfs.net'
Cc: Vic (LKKAUTO)
Subject: RE: SKT 4214M & SLB3660Y & SLF 4072S & SHD 4496K on 01.12.2017 at MCE to KPE Our Ref: 1201700008458

WITHOUT PREJUDICE

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: patricia [<mailto:patricia@kanfs.net>]
Sent: Monday, 4 December, 2017 10:53 AM
To: Clara Li Zirong - SGUser
Subject: SKT 4214M & SLB3660Y & SLF 4072S & SHD 4496K on 01.12.2017 at MCE to KPE

Dear Mdm,

With reference to the above mentioned case, we are assisting SLB 3660Y to claim against SKT 4214M . please kindly advise liability.

Thank you

Patricia

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	05 Dec 2017 19:57	Clim Veh Model Changed	(204808) HONDA VEZEL 1.5 (A).	[A] HOW MEI KWAN
2	05 Dec 2017 19:57	Clim Created	Reg No: SLB3660Y. Acct Date: 2017/12/01. Claim Type: TP. Insurer: FWD Singapore Pte. Ltd. (HQ). Workshop: Kan Fook Sing Motor Workshop (Defu)	[A] HOW MEI KWAN
3	05 Dec 2017 19:57	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ); RR Region: FWD - Ext Auto Adj Assignment. Suggested Adj. : AJAX Inspection Services Pte Ltd.	[A] HOW MEI KWAN
4	05 Dec 2017 19:57	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/12/14	[A] HOW MEI KWAN
5	05 Dec 2017 19:57	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] HOW MEI KWAN
6	05 Dec 2017 19:58	Adj Adjuster Assigned	[None] -> MARCUS CHUA	[A] HOW MEI KWAN
7	06 Dec 2017 10:06	Clim Registration Modified	Pol No:->PNPV2017-00004409.	[I] Clara Li Zi Rong
8	06 Dec 2017 10:07	Clim Registration Modified	Excess: -> 1000.00.	[I] Clara Li Zi Rong
9	06 Dec 2017 10:15	Adj Adjuster Assigned	MARCUS CHUA -> XING GUO QIANG	[A] CATHERINE CHONG KAI LING
10	07 Dec 2017 15:10	Clim Veh Model Changed	(204808) -> (204229) MERCEDES-BENZ GLA180 1.6 (A).	[A] HOW MEI KWAN
11	13 Dec 2017 10:00	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2017/12/14	[A] HOW MEI KWAN
12	05 Jun 2018 15:27	Adj Rpt Initiated		[A] NUR SHAQILAH BTE ABDOL WAHAB
13	05 Jun 2018 15:27	Clim Dtl Modified	Driver Name: -> Chong Shu Hui, Eileen.	[A] NUR SHAQILAH BTE ABDOL WAHAB
14	05 Jun 2018 15:27	Clim Dtl Modified	JPJ Reg. Date: -> 2016/04/05.	[A] NUR SHAQILAH BTE ABDOL WAHAB
15	05 Jun 2018 15:27	Clim Details Notified		[A] NUR SHAQILAH BTE ABDOL WAHAB
16	08 Jun 2018 14:16	Adj Mandate Request	Cur.Req:35674.44:LIABILITY: 100% B:28 5VEH CC OI LAST QUANTUM: (a) COR w/G ST: \$33,748.44 + (b) LOR w/GST : \$1,926.00 (18days x \$100) Total: a+b+c = \$35,674.44 PLEASE REVERT WITH YOUR APPROVAL / MANDATE / INSTRUCTIONS, IF ANY.	[A] Asher Sng Rong Yi

Date From



Date To



Audit Type None

Go

ACTIVITY

[18/12/2017 11:48] Asher Sng Rong Yi:
100% B:28
5VEH C.C OI LAST

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1666312	13/12/2017 10:00	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLB3660Y		10.70

Print Received Message

This mail is associated with :

***SLB3660Y (1201700008458)**
[SKT4214M]

TP

TAY KIM HUAT

Dec 1 2017 5:00PM

[Chong Shu Hui, Eileen]

Kan Fook Sing Motor Workshop

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 22/06/2018 09:52 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$35674.44) - SLB3660Y - Claim Handler: Clara Li Zi Rong

Approved:35674.44.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Dec 2017 Edit Reg		05 Dec 2017 00:00 Edit Adj Rpt	S\$31,540.60 Edit Estimates	S\$31,540.60 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Chong Shu Hui, Eileen , ID: S7907460H		
Main Claimant:	TAY KIM HUAT , ID: S7724821H		
Vehicle Reg. No.:	SLB3660Y	Date of Loss:	01/12/2017 17:00 - :59 [19 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1201700008458	Policy/Cover Note No.:	PNPV2017-00004409 (Comprehensive)
Vehicle Reg. No. (Insured):	SKT4214M	Policy No. (Claimant):	GA097830/1
		Excess:	S\$1,000.00
Repairer:	Kan Fook Sing Motor Workshop (Defu) No. 61 Defu Lane 12, 539147 Defu Lane - Tel: 67479560		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 14/12/2017]		
Driver/Custodian (Insured):	Chong Shu Hui, Eileen (), NRIC: S7907460H		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- FWD_SG (22/06/2018): Alert - Adj Mandate Approved (S\$35674.44) - SLB3660Y - Claim Handler: Clara Li Z...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLB3660Y (1201700008458)

[SKT4214M]

TP

TAY KIM HUAT

Dec 1 2017 5:00PM

[Chong Shu Hui, Eileen]

Kan Fook Sing Motor Workshop

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Letters/Correspondences

1 per page ▼ ☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	Edit	

Assessment Reports

1 per page ▼ ☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/12/17 10:00	Adjuster Immediate Advice	Load HTM	

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/05/18 10:58	General View	Load JPG	☒
2	07/05/18 10:58	General View	Load JPG	☒
3	07/05/18 10:58	General View	Load JPG	☒
4	07/05/18 10:58	General View	Load JPG	☒
5	07/05/18 10:58	General View	Load JPG	☒
6	07/05/18 10:58	General View	Load JPG	☒
7	07/05/18 10:58	General View	Load JPG	☒
8	07/05/18 10:58	General View	Load JPG	☒
9	07/05/18 10:58	General View	Load JPG	☒
10	07/05/18 10:58	General View	Load JPG	☒
11	07/05/18 10:58	General View	Load JPG	☒
12	07/05/18 10:58	General View	Load JPG	☒
13	07/05/18 10:58	General View	Load JPG	☒
14	07/05/18 10:58	General View	Load JPG	☒
15	07/05/18 10:58	General View	Load JPG	☒
16	07/05/18 10:58	General View	Load JPG	☒
17	07/05/18 10:58	General View	Load JPG	☒
18	07/05/18 10:58	General View	Load JPG	☒
19	07/05/18 10:58	General View	Load JPG	☒
20	07/05/18 10:58	General View	Load JPG	☒
21	07/05/18 10:58	General View	Load JPG	☒
22	07/05/18 10:58	General View	Load JPG	☒
23	07/05/18 10:58	General View	Load JPG	☒
24	07/05/18 10:58	General View	Load JPG	☒
25	07/05/18 10:58	General View	Load JPG	☒
26	07/05/18 10:58	General View	Load JPG	☒
27	07/05/18 10:58	General View	Load JPG	☒
28	07/05/18 10:58	General View	Load JPG	☒

Letters/Correspondences					
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
29	07/05/18 10:58	General View		Load JPG	
30	07/05/18 10:58	General View		Load JPG	
31	07/05/18 10:58	General View		Load JPG	
32	07/05/18 10:58	General View		Load JPG	
33	07/05/18 10:58	General View		Load JPG	
34	07/05/18 10:58	General View		Load JPG	
35	07/05/18 10:58	General View		Load JPG	
36	07/05/18 10:58	General View		Load JPG	
37	07/05/18 10:58	General View		Load JPG	
38	07/05/18 10:58	General View		Load JPG	
39	07/05/18 10:58	General View		Load JPG	
40	07/05/18 10:58	General View		Load JPG	
41	07/05/18 10:58	General View		Load JPG	
42	07/05/18 10:58	General View		Load JPG	
43	07/05/18 10:58	General View		Load JPG	
44	07/05/18 10:58	General View		Load JPG	
45	07/05/18 10:58	General View		Load JPG	
46	07/05/18 10:58	General View		Load JPG	
47	07/05/18 10:58	General View		Load JPG	
48	07/05/18 10:58	General View		Load JPG	
49	07/05/18 10:58	General View		Load JPG	
50	07/05/18 10:58	General View		Load JPG	
51	07/05/18 10:58	General View		Load JPG	
52	07/05/18 10:58	General View		Load JPG	
53	07/05/18 10:58	General View		Load JPG	
54	07/05/18 10:58	General View		Load JPG	
55	07/05/18 10:58	General View		Load JPG	
56	07/05/18 10:58	General View		Load JPG	
57	07/05/18 10:58	General View		Load JPG	
58	07/05/18 10:58	General View		Load JPG	
59	07/05/18 10:58	General View		Load JPG	
60	07/05/18 10:58	General View		Load JPG	
61	07/05/18 10:58	General View		Load JPG	
62	07/05/18 10:58	General View		Load JPG	
63	07/05/18 10:58	General View		Load JPG	
64	07/05/18 10:58	General View		Load JPG	
65	07/05/18 10:58	General View		Load JPG	
66	07/05/18 10:58	General View		Load JPG	
67	07/05/18 10:58	General View		Load JPG	
68	07/05/18 10:58	General View		Load JPG	
69	07/05/18 10:58	General View		Load JPG	
70	07/05/18 10:58	General View		Load JPG	
71	07/05/18 10:58	General View		Load JPG	
72	07/05/18 10:58	General View		Load JPG	
73	07/05/18 10:58	Odometer Reading		Load JPG	
74	07/05/18 10:58	Chassis Number		Load JPG	
75	07/05/18 10:58	Reinspection Photo		Load JPG	
76	07/05/18 10:58	Reinspection Photo		Load JPG	

Letters/Correspondences				
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
77	07/05/18 10:58	Reinspection Photo		Load JPG ☒
78	07/05/18 10:58	Reinspection Photo		Load JPG ☒
79	07/05/18 10:58	Reinspection Photo		Load JPG ☒
80	07/05/18 10:58	Reinspection Photo		Load JPG ☒
81	07/05/18 10:58	Reinspection Photo		Load JPG ☒
82	07/05/18 10:58	Reinspection Photo		Load JPG ☒
83	07/05/18 10:58	Reinspection Photo		Load JPG ☒
84	07/05/18 10:58	Reinspection Photo		Load JPG ☒
85	07/05/18 10:58	Reinspection Photo		Load JPG ☒
86	07/05/18 10:58	Reinspection Photo		Load JPG ☒
87	07/05/18 10:58	Reinspection Photo		Load JPG ☒
88	07/05/18 10:58	Reinspection Photo		Load JPG ☒
89	07/05/18 10:58	Reinspection Photo		Load JPG ☒
90	07/05/18 10:58	Reinspection Photo		Load JPG ☒
91	07/05/18 10:58	Reinspection Photo		Load JPG ☒
92	07/05/18 10:58	Reinspection Photo		Load JPG ☒
93	07/05/18 10:58	Reinspection Photo		Load JPG ☒
94	07/05/18 10:58	Reinspection Photo		Load JPG ☒
95	07/05/18 10:58	Reinspection Photo		Load JPG ☒
96	07/05/18 10:58	Reinspection Photo		Load JPG ☒
97	07/05/18 10:58	Reinspection Photo		Load JPG ☒
98	07/05/18 10:58	Reinspection Photo		Load JPG ☒
99	07/05/18 10:58	Reinspection Photo		Load JPG ☒
100	07/05/18 10:58	Reinspection Photo		Load JPG ☒
101	07/05/18 10:58	Reinspection Photo		Load JPG ☒
102	07/05/18 10:58	Reinspection Photo		Load JPG ☒
103	07/05/18 10:58	Reinspection Photo		Load JPG ☒
104	07/05/18 10:58	Reinspection Photo		Load JPG ☒
105	07/05/18 10:58	Reinspection Photo		Load JPG ☒
106	07/05/18 10:58	Reinspection Photo		Load JPG ☒
107	07/05/18 10:58	Reinspection Photo		Load JPG ☒
108	07/05/18 10:58	Reinspection Photo		Load JPG ☒
109	07/05/18 10:58	Reinspection Photo		Load JPG ☒
110	07/05/18 10:58	Reinspection Photo		Load JPG ☒
111	07/05/18 10:58	Reinspection Photo		Load JPG ☒
112	07/05/18 10:58	Reinspection Photo		Load JPG ☒
113	07/05/18 10:58	Reinspection Photo		Load JPG ☒
114	07/05/18 10:58	Reinspection Photo		Load JPG ☒
115	07/05/18 10:58	Reinspection Photo		Load JPG ☒
116	07/05/18 10:58	Reinspection Photo		Load JPG ☒
117	07/05/18 10:58	Reinspection Photo		Load JPG ☒
118	07/05/18 10:58	Reinspection Photo		Load JPG ☒
119	07/05/18 10:58	Reinspection Photo		Load JPG ☒
120	07/05/18 10:58	Reinspection Photo		Load JPG ☒
121	07/05/18 10:58	Reinspection Photo		Load JPG ☒
122	07/05/18 10:58	Reinspection Photo		Load JPG ☒
123	07/05/18 10:58	Reinspection Photo		Load JPG ☒
124	07/05/18 10:58	Reinspection Photo		Load JPG ☒

Letters/Correspondences					
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
125	07/05/18 10:58	Reinspection Photo	1	Load JPG	✓
126	07/05/18 10:58	Reinspection Photo	1	Load JPG	✓
127	07/05/18 10:58	Reinspection Photo	1	Load JPG	✓
128	07/05/18 10:58	Reinspection Photo	1	Load JPG	✓
129	07/05/18 10:58	Reinspection Photo	1	Load JPG	✓
130	07/05/18 10:58	Reinspection Photo	1	Load JPG	✓
131	07/05/18 10:58	Reinspection Photo	1	Load JPG	✓
132	07/05/18 10:58	Reinspection Photo	1	Load JPG	✓
133	07/05/18 10:58	Reinspection Photo	1	Load JPG	✓
134	07/05/18 10:58	Reinspection Photo	1	Load JPG	✓
135	07/05/18 10:58	Reinspection Photo	1	Load JPG	✓
136	07/05/18 10:58	Reinspection Photo	1	Load JPG	✓
137	07/05/18 10:58	Reinspection Photo	1	Load JPG	✓
138	07/05/18 10:58	Reinspection Photo	1	Load JPG	✓
139	07/05/18 10:58	Reinspection Photo	1	Load JPG	✓
140	07/05/18 10:58	Reinspection Photo	1	Load JPG	✓
141	07/05/18 10:58	Reinspection Photo	1	Load JPG	✓
142	07/05/18 10:58	Reinspection Photo	1	Load JPG	✓
143	07/05/18 10:58	Reinspection Photo	1	Load JPG	✓
144	07/05/18 10:58	Reinspection Photo	1	Load JPG	✓
145	07/05/18 10:58	Reinspection Photo	1	Load JPG	✓
146	07/05/18 10:58	Reinspection Photo	1	Load JPG	✓
147	07/05/18 10:58	Reinspection Photo	1	Load JPG	✓
148	07/05/18 10:58	Reinspection Photo	1	Load JPG	✓
149	07/05/18 10:58	Reinspection Photo	1	Load JPG	✓
150	07/05/18 10:58	Reinspection Photo	1	Load JPG	✓
151	07/05/18 10:58	Reinspection Photo	1	Load JPG	✓
152	07/05/18 10:58	Reinspection Photo	1	Load JPG	✓
153	07/05/18 10:58	Reinspection Photo	1	Load JPG	✓
154	07/05/18 10:58	Reinspection Photo	1	Load JPG	✓
155	07/05/18 10:58	Reinspection Photo	1	Load JPG	✓
156	07/05/18 10:58	Reinspection Photo	1	Load JPG	✓
157	07/05/18 10:58	Reinspection Photo	1	Load JPG	✓
158	07/05/18 10:58	Reinspection Photo	1	Load JPG	✓
159	07/05/18 10:58	Reinspection Photo	1	Load JPG	✓
160	07/05/18 10:58	Reinspection Photo	1	Load JPG	✓
161	07/05/18 10:58	Reinspection Photo	1	Load JPG	✓
162	07/05/18 10:58	Reinspection Photo	1	Load JPG	✓
163	07/05/18 10:58	Reinspection Photo	1	Load JPG	✓
164	07/05/18 10:59	PHOTO BEFORE PAINT	1	Load JPG	✓
165	07/05/18 10:59	PHOTO BEFORE PAINT	1	Load JPG	✓
166	07/05/18 10:59	PHOTO BEFORE PAINT	1	Load JPG	✓
167	07/05/18 10:59	PHOTO BEFORE PAINT	1	Load JPG	✓
168	07/05/18 10:59	PHOTO BEFORE PAINT	1	Load JPG	✓
169	07/05/18 10:59	PHOTO BEFORE PAINT	1	Load JPG	✓
170	07/05/18 10:59	PHOTO BEFORE PAINT	1	Load JPG	✓
171	07/05/18 10:59	PHOTO BEFORE PAINT	1	Load JPG	✓

Letters/Correspondences				☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/12/17 19:58	EMAIL FROM FWD TO OI DD 05.12.2017	Load PDF	
2	05/12/17 19:58	ACKNOWLEDGEMENT EMAIL TO FWD DD 05.12.2017	Load PDF	
3	07/12/17 15:22	TP GIA REPORT	Load PDF	
4	07/12/17 20:22	TP ESTIMATE - MARKED	Load PDF	
5	08/06/18 14:12	WORKSHOP INVOICE	Load PDF	
6	08/06/18 14:12	RENTAL	Load PDF	
7	04/07/18 14:01	AUTHORISATION TO ACT	Load PDF	
8	04/07/18 14:01	LOD	Load PDF	
9	04/07/18 14:01	RELEASE VOUCHER	Load PDF	
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	13/12/17 10:15	OI GIA Report	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKT4214M (Insd veh)	Model:	MERCEDES-BENZ GLA180 1.6
	SLB3660Y (TP veh)		(A)
Date of Accident:	01/12/2017		

Global Sum Settlement	:	[]	Yes	[X]	No
Repair Estimate	:	\$		49,028.68	
Final Repair Cost	:	\$		33,748.44	
Loss of Use	:	\$			days at \$0.00 per day
Rental (if any)	:	\$		1,926.00	18 days
LTA / GIA Search Fee	:	\$			
Others:	:	\$			
	:	\$			
Final Settlement Sum	:	\$		35,674.44	
Is Third Party Workshop GIA Registered? [X] YES [] NO (Kindly indicate below)					
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____ (%)			
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: __28__			
BOLA Liability: _____ 100 _____ (%)		Assessed Liability (*): _____ 100 _____ (%)			
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.					
Remarks _____					

Payment Instruction: Payee's Breakdown			
1)	Kan Fook Sing Motor Workshop	:	\$ 35,674.44
2)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

04 Jul
2018

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD17023104/GEA3S2
Date: 04/07/2018

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2017-00004409
Claimant Vehicle No : SLB3660Y **Insured Vehicle No :** SKT4214M
 Date of Loss: 01/12/2017 Nature of Claim: TP Claim No: 1201700008458

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLB3660Y**
 Make & Model: MERCEDES-BENZ GLA180, 1.6 (A) Engine No: 27091030774756
 Reg. Date: 05/04/2016 (Man. Year: 2015) Chassis No: WDC1569422J175009
 Colour: Black Odometer: 28107 km
 Engine Capacity: 1595 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/45ZR19 Rear Tyre Size: 235/45ZR19
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	40,441.20	28,320.60	12,120.60	29.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,380.00	3,220.00	2,160.00	40.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	45,821.20	31,540.60	14,280.60	31.17
+ GST 7.00/7.00% (S\$)	3,207.48	2,207.84	999.64	31.17
Nett Amount (S\$)	49,028.68	33,748.44	15,280.24	31.17
+ Car Rental (18.0 x S\$100.00/day + 7.00% GST) (S\$)		1,926.00		
Nett Liability (S\$)		35,674.44		

INSPECTION

Date of Assignment: 05/12/2017
 Date Inspected: 05/12/2017 Inspected At: Kan Fook Sing Motor Workshop (Defu)
 No. 61 Defu Lane 12
 Singapore 539147
 Estimated Period of Repair: 13.0 days

Adjuster: XING GUO QIANG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Jul 2018)
Parts:	M1-SUV	MERCEDES-BENZ GLA180 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB3660Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BOOT COVER	Buckled	1,767.00 FL	*1,767.00 FL
2	1	*REAR BOOT RUBBER	Not Necessary	202.00 FL	*- FL
3	1	*REAR LAMP	Not Necessary	650.00 FL	*- FL
4	1	*REAR BUMPER	Deformed	1,570.00 FL	*1,570.00 FL
5	1	*REAR BUMPER TOP GARNISH	Necessary	148.00 FL	*148.00 FL
6	5	*REAR BUMPER TOP GARNISH CLIP	Necessary	45.00 FL	*45.00 FL
7	1	*REAR BUMPER TOW COVER	Missing	55.00 FL	*55.00 FL
8	1	*REAR BUMPER REINFORCEMENT	Bent	545.00 FL	*545.00 FL
9	2	*REAR BUMPER SIDE RETAINERS	Necessary	40.00 FL	*40.00 FL
10	1	*REAR BUMPER SIDE GARNISH RH	Deformed	29.00 FL	*29.00 FL
11	1	*REAR BUMPER LOWER GARNISH RH	Missing	92.00 FL	*92.00 FL
12	4	*REAR BUMPER SENSOR	Not Necessary	740.00 FL	*- FL
13	4	*REAR BUMPER SENSOR RING	Not Necessary	48.00 FL	*- FL
14	1	*REAR BUMPER LOWER	Deformed	663.00 FL	*663.00 FL
15	1	*REAR BUMPER LOWER COVER	Deformed	525.00 FL	*525.00 FL
16	2	*REAR BUMPER LOWER GARNISH BRACKET	Missing	180.00 FL	*180.00 FL
17	1	*REAR UNDERCOVER	Deformed	740.00 FL	*740.00 FL
18	1	*REAR EXHAUST MUFFLER	Bent	1,111.00 FL	*1,111.00 FL
19	1	*REAR EXHAUST HEAT SHIELD CENTRE	Buckled	126.00 FL	*126.00 FL
20	2	*REAR EXHAUST HEAT SHIELD SIDE (NPA)	Not Necessary	0.00 FL	*- FL
21	2	*REAR EXHAUST CHROME PIPE	Bent	512.00 FL	*512.00 FL
22	2	*REAR EXHAUST MOUNTING	Bent	76.00 FL	*76.00 FL
23	1	*FRONT BONNET	Bent	1,398.00 FL	*1,398.00 FL
24	1	*FRONT BONNET SEAL	Twisted	34.00 FL	*34.00 FL
25	1	*FRONT BONNET STAND	Not Necessary	22.00 FL	*- FL
26	1	*FRONT BONNET LOCK TOP	Not Necessary	45.00 FL	*- FL
27	1	*FRONT BONNET LOCK LOWER	Not Necessary	113.00 FL	*- FL
28	2	*FRONT BONNET HINGES	Bent	164.00 FL	*164.00 FL
29	2	*FRONT BONNET ACTUATOR	Damaged	350.00 FL	*350.00 FL
30	2	*FRONT BONNET STOPPER	Cut	38.00 FL	*38.00 FL
31	1	*FRONT BONNET LOCK SWITCH	Not Necessary	122.00 FL	*- FL
32	1	*FRONT GRILLE BASE	Cracked	285.00 FL	*285.00 FL
33	1	*FRONT GRILLE EMBLEM	Necessary	255.00 FL	*255.00 FL
34	1	*FRONT GRILLE CHROME	Cut	145.00 FL	*145.00 FL
35	4	*FRONT GRILLE CHROME FIN	Cut	252.00 FL	*252.00 FL
36	1	*FRONT HEADLAMP	N/s Not Necessary/O/s Cracked	4,720.00 FL	*2,360.00 FL
37	1	*FRONT HEADLAMP BLUB	Not Necessary	477.00 FL	*- FL
38	1	*FRONT HEADLAMP HID UNIT	Not Necessary	765.00 FL	*- FL
39	1	*FRONT SUPPORT PANEL	Bent	608.00 FL	*608.00 FL
40	2	*FRONT SUPPORT SIDE BRACKET	Not Necessary	76.00 FL	*- FL
41	1	*FRONT FENDER RH	Buckled	705.00 FL	*705.00 FL
42	1	*FRONT FENDER SHIELD RH	Bent	170.00 FL	*170.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
43	10	*FRONT FENDER SHIELD CLIPS	Necessary	90.00 FL	*90.00 FL
44	2	*FRONT FENDER GARNISH	Deformed 1pc Only	327.00 FL	*108.00 FL
45	8	*FRONT FENDER GARNISH CLIP	Necessary	72.00 FL	*72.00 FL
46	1	*FRONT BUMPER	Cracked	1,645.00 FL	*1,645.00 FL
47	1	*FRONT BUMPER FOAM	Cracked	130.00 FL	*130.00 FL
48	1	*FRONT BUMPER TOP FRAME	Deformed	120.00 FL	*120.00 FL
49	1	*FRONT BUMPER REINFORCEMENT	Bent	305.00 FL	*305.00 FL
50	1	*FRONT BUMPER REINFORCEMENT BRACKET	O/s Bent / N/s Not Necessary	220.00 FL	*110.00 FL
51	2	*FRONT BUMPER SIDE RETAINER	Necessary	18.00 FL	*18.00 FL
52	1	*FRONT BUMPER TOW COVER	Cut	67.00 FL	*67.00 FL
53	4	*FRONT BUMPER SENSOR	Damaged 1pc Only	740.00 FL	*185.00 FL
54	2	*FRONT BUMPER SENSOR RING	Necessary	24.00 FL	*24.00 FL
55	1	*FRONT BUMPER SENSOR WIRE	Necessary	114.00 FL	*114.00 FL
56	2	*FRONT BUMPER WIPER NOZZLE	Not Necessary	344.00 FL	*- FL
57	1	*FRONT BUMPER WIPER NOZZLE TUBE	Not Necessary	57.00 FL	*- FL
58	1	*FRONT BUMPER WIPER NOZZLE COVER	N/s Not Necessary / O/s Cut	104.00 FL	*52.00 FL
59	1	*FRONT BUMPER WIPER COVER SPRING	N/s Not Necessary/O/s Missing	40.00 FL	*20.00 FL
60	1	*FRONT BUMPER FOGLAMP COVER	N/s Not Necessary/O/s Missing	90.00 FL	*45.00 FL
61	1	*FRONT BUMPER LOWER CENTRE	Not Necessary	550.00 FL	*- FL
62	2	*FRONT BUMPER LOWER SIDE	Not Necessary	560.00 FL	*- FL
63	1	*FRONT BUMPER EMBLEM	Necessary	60.00 FL	*60.00 FL
64	10	*FRONT BUMPER CLIP	Necessary	90.00 FL	*90.00 FL
65	1	*FRONT BUMPER CENTRE GRILLE	Not Necessary	166.00 FL	*- FL
66	1	*FRONT BUMPER LOWER COVER	Not Necessary	86.00 FL	*- FL
67	1	*FRONT NUMBER PLATE GARNISH	Deformed	164.00 FL	*164.00 FL
68	1	*AIR CON CONDENSER	Bent	1,078.00 FL	*1,078.00 FL
69	1	*AIR CON LIQUID PIPE	Not Necessary	356.00 FL	*- FL
70	1	*AIR CON SUCTION HOSE	Not Necessary	316.00 FL	*- FL
71	1	*AIR CON DISCHARGE HOSE	Not Necessary	316.00 FL	*- FL
72	1	*RADIATOR ASSY	Bent	840.00 FL	*840.00 FL
73	1	*RADIATOR TOP HOSE	Not Necessary	55.00 FL	*- FL
74	1	*RADIATOR LOWER HOSE	Not Necessary	85.00 FL	*- FL
75	2	*RADIATOR TOP BRACKET	Not Necessary	180.00 FL	*- FL
76	2	*RADIATOR TOP BUSH	Not Necessary	24.00 FL	*- FL
77	2	*RADIATOR LOWER BRACKET	Not Necessary	66.00 FL	*- FL
78	1	*RADIATOR FAN ASSY	Cracked	428.00 FL	*428.00 FL
79	1	*RADIATOR SPARE TANK	Deformed	155.00 FL	*155.00 FL
80	1	*SPARE TANK BREATHING PIPE	Bent	88.00 FL	*88.00 FL
81	1	*WASHER TANK	Not Necessary	148.00 FL	*- FL
82	1	*WASHER TANK MOTOR	Not Necessary	88.00 FL	*- FL
83	1	*RADIATOR SIDE GARNISH	O/s Deformed/N/s Not Necessary	76.00 FL	*38.00 FL
84	1	*RADIATOR LOWER GARNISH	Cracked	57.00 FL	*38.00 FL
85	1	*AIR CON DECEIVER	Not Necessary	216.00 FL	*- FL
86	1	*AIR CON SIDE GARNISH	N/s Not Necessary/O/s Missing	274.00 FL	*22.00 FL
87	1	*INTERCOOLER	Not Necessary	832.00 FL	*- FL
88	1	*INTERCOOLER PIPE RH	Cracked	190.00 FL	*190.00 FL
89	1	*INTERCOOLER PIPE LH	Cracked	230.00 FL	*230.00 FL
90	2	*REAR BUMPER LOWER SIDE BRACKET LOWER	Not Necessary	80.00 FL	*- FL
91	1	*REAR BUMPER SENSOR WIRE	Not Necessary	90.00 FL	*- FL
92	1	*FRONT BONNET STAND HOLDER	Not Necessary	9.00 FL	*- FL
93	1	*FRONT GRILLE BASE	Repeated	71.00 FL	*- FL
94	1	*FRONT HEADLAMP ADJUSTER CONTROL	O/s Bent / N/s Not Necessary	554.00 FL	*277.00 FL
95	1	*ENGINE UNDERCOVER FRT	Not Necessary	302.00 FL	*- FL
96	1	*FRONT SUPPORT LOWER	Not Necessary	395.00 FL	*- FL
97	1	*FRONT SUPPORT LOWER BRACKET LONG	Not Necessary	395.00 FL	*- FL
98	2	*FRONT SUPPORT LOWER BRACKET SHORT	Not Necessary	290.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
99	2	*FRONT HEADLAMP LOWER BRACKET	Not Necessary	134.00 FL	*- FL
100	1	*FRONT SUPPORT TOP PLASTIC	Not Necessary	16.00 FL	*- FL
101	1	*REAR WINDSCREEN GUM	Necessary	40.00 FS	*40.00 FS
102	1	*FRONT NUMBER PLATE	Bent	30.00 FS	*30.00 FS
103	1	*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
104	1	*RIVET 40pcs	Necessary	360.00 FL	*360.00 FL
105	1	*AIR DUCT	Missing	105.00 FL	*105.00 FL
106	1	*ENGINE TOP COVER	Cracked	365.00 FL	*365.00 FL
107	1	*FRONT SUPPORT SIDE BRACKET RH	Necessary	24.00 FL	*24.00 FL
108	1	*TURBO ASSY	Damaged	6,760.00 FL	*6,760.00 FL
109	1	*TURBO PIPE	Cracked	95.00 FL	*95.00 FL
110	1	*INTAKE MANIFOLD PIPE	Bent	210.00 FL	*210.00 FL
111	1	*MANIFOLD JOINT PIPE	Bent	130.00 FL	*130.00 FL
112	1	*WATER PUMP	Dented	650.00 FL	*650.00 FL
113	1	*WATER PUMP PIPE	Bent	155.00 FL	*155.00 FL
114	1	*ENGINE MOUNTING RH	Bent	370.00 FL	*370.00 FL
115	1	*ROOF MOULDING CLIP	Necessary	24.00 FL	*24.00 FL
116	1	*REAR BUMPER TOW COVER TRIM	Missing	15.00 FL	*15.00 FL
117	1	*REAR FENDER SIDE GARNISH RH	Missing	210.00 FL	*210.00 FL
118	1	*COOLANT	Necessary	50.00 FS	*50.00 FS
119	1	*FRONT BONNET LOCK COVER LOWER	Missing	70.00 FL	*70.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	44,918.00	31,454.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	4,476.80	3,133.40
Total Parts (\$\$)	40,441.20	28,320.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING.	New	100.00	100.00
2	TO REMOVE / REFIT / REFILL AIR CON GAS.	New	80.00	80.00
3	TO REMOVE / REFIT EXHAUST SYSTEM.	New	80.00	80.00
4	TO REMOVE / REFIT REAR FENDER INNER GARNISH AND ETC.	New	120.00	60.00
5	TO REMOVE / REFIT REAR WINDSCREEN GLASS.	New	100.00	100.00
6	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS (REAR)	New	1,300.00	500.00
7	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS (FRONT)	New	1,600.00	1,100.00
8	SPRAY PAINTING CHARGES (FRONT & REAR)	New	2,000.00	1,200.00
Gross Labour Cost (S\$)			5,380.00	3,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >