

ASS. REC. BY:

REF: CS/FCI17023132/Krbnz

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

aws

From (Person):

Lurene Jaw

of

FCI

Date/Time:

5.56pm @ 6/12/17

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 5557S

Insured:

SHA 9150R

at Workshop m/s

Trans-Cab

Tel:

6287 6666

of

NO. 2 AMK Street 63

Policy No:

Claim No:

D17011148 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

30/11/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time:

8.26am @ 6/12/17

Person Contacted:

jiong haw

Vehicle IN/OUT

Date/Time

Action/Instruction

() Estimate

SHC 5557S - X

SHA 9150R - NSI INC13007785 / HJLn

D.O.A. : 25/04/2013

7/12/17

Sent preli through email



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17023132/Krb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 06-12-2017	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9150R	Veh. Inspected	SHC 5557S	
Policy No.		Coverage (\$)	0.00	
Claim No.	D17011148MFSH	Excess (\$)	0.00	
Assign From	CWS (LURENE JAW)	Assign Date	06/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	30/11/2017	Inspection Date	06/12/2017	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	04-12-2017	Our Ref No. D17011148MFSH
Accident Date	30-11-2017	Claim Type. Third Party
Insured Vehicle	SHA9150R	Third Party Vehicle. SHC5557S
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	JIONG HOW NG	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/231354)



PRI Documents



Close



PRI Header Details

Claim No	D17011148MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & TRANS-CA
Workshop Name	TRANS-CAB AUTO SERVICES PTE LTD (Contact Person : JIONG HOW NG)	Survey Location & Contact Details	NO. 2 ANG MO KIO STREET 63 Mobile: 0 , Phone: 62876666 , Fax: 62571330 EmailId: JIONGHOW.NG@TRANSCAB.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA9150R	TP Vehicle No	SHC5557S
PRI Recieved Date	04-12-2017 06:01:11 PM	Surveyor Appointed Date	05-12-2017 05:55:18 PM	Surveyor Accept Date	06-12-2017 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	06-12-2017	Upload Survey Report *:	Choose File
------------------------------------	--	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17011148MFSH

Our Ref: CS/FCI17023132/Krb

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 5557S

Please be informed that we had conducted the inspection of the above mentioned vehicle on 06/12/2017 at the premises of M/s TRANS-CAB AUTO SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ 29,177.40 .
Revised Estimate Amount	: S\$ 3,281.00 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:
The vehicle sustained damages
at the n/s front portion.



Yours faithfully

KENNETH
Automotive Assessor

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Thursday, December 07, 2017 3:54 PM
To: 'Claim Workflow System'; LURENEJAW@FIRST-INSURANCE.COM.SG
Cc: SUR
Subject: RE: SURVEY ASSESSMENT - D17011148MFSH/1
Attachments: SHC 5557S.pdf

Dear Lurene,

Enclosed preliminary revised for **SHC 5557S**

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, December 06, 2017 9:09 AM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17011148MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Tuesday, 5 December, 2017 5:55 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; LURENEJAW@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17011148MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Company
Owner ID	3878K

Vehicle Details

Vehicle No.	SHC5557S
Vehicle to be Exported	Yes
Intended De-registration Date	01 Dec 2017
Vehicle Make	RENAULT
Vehicle Model	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour	Red
Manufacturing Year	2014
Engine No.	M9R8839C001968
Chassis No.	VF1ABL15AUC279248
Maximum Power Output	127.0 kW (170 bhp)
Open Market Value	\$19,998.00
Original Registration Date	15 Sep 2014
First Registration Date	15 Sep 2014
Transfer Count	0
Actual ARF Paid	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	14 Sep 2022
PARF Rebate Amount	\$9,373.00

Intended COE Rebate Details

COE Expiry Date	14 Sep 2022
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	8
PQP Paid	\$50,704.00
COE Rebate Amount	\$30,334.00
Total Rebate Amount	\$39,707.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 01 Dec 2017

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5557S -**AAD1712-010***Not Authenticated
21 Sep @ 2600*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHC5557S - JHOW
VF1ABL15AUC279248
RENAULT
LATITUDE
30.11.2017
FCIL

PART**LIST**

1	1	BUMPER COVER FRT	\$	<i>Bu</i>	1,259.42	✓
2	1	BUMPER SPOILER FRT	\$	<i>Sm</i>	181.75	X
3	1	BUMPER FOG LAMP GRILLE LH	\$	<i>Sm</i>	207.22	✓
4	1	BUMPER RETAINER FRT LH	\$	<i>Di</i>	151.41	✓
5	1	BUMPER RETAINER FRT RH	\$	<i>Sm</i>	151.41	X
6	1	BUMPER SUPPORT FRT LH	\$	<i>Sm</i>	123.88	X
7	1	BUMPER SUPPORT FRT RH	\$	<i>Sm</i>	123.88	✓
8	1	BUMPER BEAM FRT	\$	<i>R</i>	914.08	
9	1	RADAIOR GRILLE	\$	<i>Sm</i>	1,707.78	
10	1	RADAIOR GRILLE BADGE 'RENAULT'	\$	<i>Sm</i>	225.36	
11	1	RADAIOR GRILLE FRAME	\$	<i>Sm</i>	1,353.75	
12	1	FRAME FULL SUPPORT PANEL	\$	<i>Sm</i>	615.90	
13	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i>	89.79	
14	1	AIR CLEANER LOWER	\$	<i>Sm</i>	352.64	
15	1	AIR CLEANER HOSE	\$	<i>Sm</i>	76.14	
16	1	LOWER ARM LH	\$	<i>Sm</i>	685.76	
17	1	KUNCKLE ARM LH	\$	<i>Sm</i>	846.98	
18	1	ABSORBER FRT LH	\$	<i>Sm</i>	360.54	
19	1	BONNET	\$	<i>R</i>	1,941.63	
20	1	HEADLAMP LH	\$	<i>Sm</i>	1,184.43	
21	1	HEADLAMP PANEL FRT LH	\$	<i>R</i>	152.15	
22	1	FENDER PANEL FRT LH	\$	<i>Bu</i>	783.83	✓
23	1	FENDER INSULATOR LH	\$	<i>Sm</i>	130.84	X
24	1	WHEEL HOUSING PANEL FRT LH	\$	<i>R</i>	4,682.09	X
25	1	WHEELARCH FRT LH	\$	<i>Sm</i>	278.84	X
26	1	DOOR MIRROR LH	\$	<i>Sm</i>	1,483.40	X
27	1	DOOR MIRROR GLASS LH	\$	<i>Sm</i>	148.20	X
28	1	DOOR MIRROR BACK COVER LH	\$	<i>Sm</i>	218.46	X
29	1	DOOR PANEL FRT LH	\$	<i>R</i>	2,844.66	X

Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s)
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL	\$	23,276.23
--------------	----	------------------

10%	\$	2,327.62
------------	----	-----------------

	\$	20,948.60
--	----	------------------

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-010**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5557S -**Specical Nett**

1	1SET	FRONT BUMPER CLIP	\$	66.00 ✓
2	1SET	WHEELARCH CLIP LH	\$	66.00 X
3	1	TOW COVER FRT	\$	14.50 X
4	1	CAP HUB LH FRT	\$	35.00 X
5	1	RIM LH FRT	\$	385.00 X
6	1	TYRE LH FRT	\$	330.00 X
7	1SET	BUMPER SUPPORT FRT CLIP LH	\$	9.80 X
8	1SET	BUMEPR RETAINER FRT CLIP LH	\$	12.50 X
9	1	DOOR STICKER "Trans-cab"	\$	80.00 60\$
10	1	DOOR STICKER "Classic"	\$	30.00 15\$

TOTAL	\$	1,028.80
TOTAL PARTS	\$	21,977.40

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,800.00 400

To Check Electrical Lighting Concerned.

\$ 170.00 15/

Putty and spray painting of the affected portion.

\$ 3,000.00 660

To check steering geometry and computer wheel alignment

\$ 220.00 60

Towing Fees

\$ 120.00 X

To transfer of tire, rim and on wheel balancing.

\$ 170.00 X

To rust-proofing of the affected areas.

\$ 170.00 30

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ 380.00 X

To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.

\$ 170.00 X

TOTAL	\$	7,200.00
Over All Total	\$	29,177.40

(PARTS BY PARTS) Repair Days**10 Days**

2 1/2 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17023132/Krbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 14-12-2017		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9150R	Veh. Inspected	SHC 5557S	
Policy No.	D-15072702MFSH	Coverage (\$)	0.00	
Claim No.	D17011148MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	06/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	VF1ABL15AUC279248	Colour	METALLIC WHITE / RED	
Odometer	331385	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	7 mm	
L/H Front Tyre	215/60 R16	GITI	7 mm	
R/H Rear Tyre	215/60 R16	LING LONG	6 mm	
L/H Rear Tyre	215/60 R16	LING LONG	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/11/2017	Inspection Date	06/12/2017	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2.500 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5557S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER FRT	BUCKLED	1,259.42	1,259.42
1	BUMPER SPOILER FRT	SERVICEABLE	181.75	-
1	BUMPER FOG LAMP GRILLE LH	SERVICEABLE	207.22	-
1	BUMPER RETAINER FRT LH	DISTORTED	151.41	151.41
1	BUMPER RETAINER FRT RH	SERVICEABLE	151.41	-
1	BUMPER SUPPORT FRT LH	SERVICEABLE	123.88	-
1	BUMPER SUPPORT FRT RH	SERVICEABLE	123.88	-
1	BUMPER BEAM FRT	TO REPAIR SEE LABOUR	914.08	-
1	RADIATOR GRILLE	SERVICEABLE	1,707.78	-
1	RADIATOR GRILLE BADGE "RENAULT"	SERVICEABLE	225.36	-
1	RADIATOR GRILLE FRAME	SERVICEABLE	1,353.75	-
1	FRAME FULL SUPPORT PANEL	SERVICEABLE	615.90	-
1	FRAME FULL SUPPORT BRACKET	TO REPAIR SEE LABOUR	89.79	-
1	AIR CLEANER LOWER	SERVICEABLE	352.64	-
1	AIR CLEANER HOSE	SERVICEABLE	76.14	-
1	LOWER ARM LH	SERVICEABLE	685.76	-
1	KNUCKLE ARM LH	SERVICEABLE	846.98	-
1	ABSORBER FRT LH	SERVICEABLE	360.54	-
1	BONNET	TO REPAIR SEE LABOUR	1,941.63	-
1	HEADLAMP LH	SERVICEABLE	1,184.43	-
1	HEADLAMP PANEL FRT LH	TO REPAIR SEE LABOUR	152.15	-
1	FENDER PANEL FRT LH	BENT	783.83	783.83
1	FENDER INSULATOR LH	SERVICEABLE	130.84	-
1	WHEEL HOUSING PANEL FRT LH	TO REPAIR SEE LABOUR	4,682.09	-
1	WHEELARCH FRT LH	SERVICEABLE	278.84	-
1	DOOR MIRROR LH	SERVICEABLE	1,483.40	-
1	DOOR MIRROR GLASS LH	SERVICEABLE	148.20	-

Report Ref No. CS/FC17023132/Krbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR MIRROR BACK COVER LH	SERVICEABLE	218.46	-
1	DOOR PANEL FRT LH	TO REPAIR SEE LABOUR	2,844.66	-
	LESS 10% DISCOUNT		-2,327.62	-219.47
			20,948.60	1,975.19
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET WHEELARCH CLIP LH (SN)	NOT NECESSARY	66.00	-
1	TOW COVER FRT (SN)	SERVICEABLE	14.50	-
1	CAP HUB LH FRT (SN)	SERVICEABLE	35.00	-
1	RIM LH FRT (SN)	SERVICEABLE	385.00	-
1	TYRE LH FRT (SN)	SERVICEABLE	330.00	-
1	SET BUMPER SUPPORT FRT CLIP LH (SN)	NOT NECESSARY	9.80	-
1	SET BUMPER RETAINER FRT CLIP LH (SN)	NOT NECESSARY	12.50	-
1	DOOR STICKER "TRANS-CAB" (SN)	NECESSARY	80.00	60.00
1	DOOR STICKER "CLASSIC" (SN)	NECESSARY	30.00	15.00
			1,028.80	141.00
	LABOUR			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION.REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER BEAM FRT,FRAME FULL SUPPORT BRACKET,BONNET,HEADLAMP PANEL FRT LH,WHEEL HOUSING PANEL FRT LH AND DOOR PANEL FRT LH.		2,800.00	400.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	15.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	660.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TOWING FEES.	NOT NECESSARY	120.00	-
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-

Report Ref No. CS/FCI17023132/Krbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
			7,200.00	1,165.00
GRAND TOTAL			29,177.40	3,281.19
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,600.00

Report Ref No. CS/FCI17023132/Krbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.