



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 313Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FACEFR.BUMPER (SN)	TO REPAIR SEE LABOUR	514.72	-
1	BEAM COMP,FR.BUMPER (SN)	NOT NECESSARY	218.85	-
14	CLIPBUMPER (SN)	NECESSARY-13PCS ONLY	21.00	19.50
1	SUNDRIES (SN)	NECESSARY	10.00	10.00
			764.57	29.50
<u>LABOUR</u>				
	INSPECT FR LIGHTING MECHANISMS & FOCUS.		100.00	100.00
	STRAIGHTEN ALIGN FR R BULKHEAD WHEELHOUSE & INCLUSIVE OF THE REPAIR OF FACEFR.BUMPER.		1,120.00	560.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (3P)		1,350.00	450.00
			2,570.00	1,110.00
GRAND TOTAL			3,334.57	1,139.50
RECOMMENDED COST OF REPAIRS				1,139.50

Report Ref No. CS/FCI17023137/Wqbe2

WILSON TEO CHENG MING

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.