

ASS. REC. BY:

REF: CS / FCI 17023139 / Kqb / 02

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

CWS

From (Person):

Joanna Yong

of

FCI

Date/Time: 9:51 am @ 6/12/17

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 94022

Insured:

SHD 6967 E

at Workshop m/s

Trans-Cab

Tel:

6287 6666

of

No. 2 AMK street # 63

Policy No:

0-15072701 MFSH

Claim No:

D17011190MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

1/12/2017

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time: 10am @ 6/12/17

Person Contacted:

Candy Kong

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SHD 94022 - CS / EGI 17010648 / Kqb 392

D.O.A. 31/05/17

SHD 6967 E - X

07/12/17 @ 5:04pm revised to Joanna Yong by email.

L/S \$ 9450, 14 days (Red \$ 17157.51, 64%)

L/S \$ 8500, 14 days (Red: 18107.51; 68%)

25/6

confirmed with Kenneth Hsueh to \$8500.00

REF. FCI

ASSIGNMENT

From: _____ Date: 6/12/17

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No. SHD 9402 Z

at Workshop m/s Trans-Cab

of No. 2 AMK Street 63

Insured _____

Policy No. _____

Claims No. _____

Sum Insured _____

Excess _____

(Client's Record)

Make of Veh. _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 14 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS up

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Van No. SHD 9402 Z Reg. 02 12

Type: M-Car / M-Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or _____

Make Chevrolet Epic 1991

Colour White / Red A/C Insured / Std / NI / NA

Sp. Reading 928901 T-Radio: Insured / Std / NI / NA

Eng. No. _____

C.No. K111A69RTBB 055864

Gen. Cond. Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Type Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Giti

Front

Rear

R.Bal. 5 mm

R.Bal. 4 mm

L.Bal. 5 mm

L.Bal. 4 mm

D.O.A. 1/12/17

D.O.L. 6/12/17

Survey held at: _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The n/s

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

7/12 15h pass to Customer

RECEIVED 20 JUN 2018

Date/Time File Pass to?

☐

Preli. Report

☐

Final Report

Date/Time File Return to?

S:

Add Fee:

☐

Site Insp. \$

☐

Interview \$

☐

Test \$

☐

Rep. end \$

Report Format: TP

Lump Sum / 1 Bt: 3

9450 8500/-

Days Of Repair: 14

Resurvey No. of Trip:

Survey Fee

Inspector

S-2013

OSR

20/6/18

16X15 = 240

170 + 240

50

22

482

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17023139/Kqb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 06-12-2017	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6967E	Veh. Inspected	SHD 9402Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	D17011190MFSH	Excess (\$)	0.00	
Assign From	CWS (JOANNE YONG)	Assign Date	06/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	01/12/2017	Inspection Date	06/12/2017	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17011190MFSH

Date: 07 December 2017

Our Ref: CS/FCI17023139/Kqb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 9402Z .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 06/12/2017 at the premises of M/s TRANS-CAB, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>26,607.51</u> .
Revised Estimate Amount	: S\$ <u>11,830.56</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the rear n/s portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	04-12-2017	Our Ref No. D17011190MFSH
Accident Date	01-12-2017	Claim Type. Third Party
Insured Vehicle	SHD6967E	Third Party Vehicle. SHD9402Z
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	CANDY KONG	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/231431)



PRI Documents



Close



PRI Header Details

Claim No	D17011190MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & TRANS-CA
Workshop Name	TRANS-CAB AUTO SERVICES PTE LTD (Contact Person : CANDY KONG)	Survey Location & Contact Details	NO. 2 ANG MO KIO STREET 63 Mobile: 0 , Phone: 62876666 , Fax: 62571330 EmailId: ZHEWEI.KEK@TRANSCAB.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD6967E	TP Vehicle No	SHD9402Z
PRI Recieved Date	05-12-2017 08:24:08 PM	Surveyor Appointed Date	06-12-2017 09:36:09 AM	Surveyor Accept Date	06-12-2017 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	06-12-2017	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 7 December, 2017 5:04 PM
To: 'Claim Workflow System'; assignments
Cc: JOANNEYONG@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17011190MFSH/1
Attachments: CSFCI17023139Kqb.pdf

Dear Joanne,

Enclosed herewith preliminary advice of SHD 9402Z.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 6 December, 2017 9:59 AM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: JOANNEYONG@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17011190MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Wednesday, 6 December, 2017 9:36 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; JOANNEYONG@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17011190MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Company
Owner ID	3878K

Vehicle Details

Vehicle No.	SHD9402Z
Vehicle to be Exported	Yes
Intended De-registration Date	04 Dec 2017
Vehicle Make	CHEVROLET
Vehicle Model	EPICA 2.0DSL AT ABS D/AB 2WD 4DR TURBO
Primary Colour	Red
Manufacturing Year	2011
Engine No.	Z20S1443987K
Chassis No.	KL1LA69RJBB065864
Maximum Power Output	110.0 kW (147 bhp)
Open Market Value	\$13,834.00
Original Registration Date	28 Feb 2012
First Registration Date	28 Feb 2012
Transfer Count	0
Actual ARF Paid	\$13,834.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	27 Feb 2020
PARF Rebate Amount	\$9,683.00

Intended COE Rebate Details

COE Expiry Date	27 Feb 2020
COE Category	A - Car (1600cc & below)
COE Period(Years)	8
QP Paid	\$40,232.00
COE Rebate Amount	\$11,228.00
Total Rebate Amount	\$20,911.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon

TRANS-CAB AUTO SERVICES PTE LTD

AAD1712-024

NO. 2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9402Z - FCIL

Not Authored
Proposed 1/1/2017 @ 85000

Vehicle No.:

SHD9402Z - FCIL

Chassis No.:

KL1LA69RJB065864

Vehicle Make:

CHEVROLET

Vehicle Model:

EPICA 2.0

Date of Accident :

01.12.2017

Third Party Insurer :

FCIL

PART**LIST**

1	1	Rear Bumper	\$	<i>Nil</i>	1,202.00	✓
2	1	Rear Bumper Beam	\$	<i>B</i>	239.94	✓
3	1	Rear Bumper Centre Absorber	\$	<i>Nil</i>	260.00	✓
4	1	Rear Bumper Side Retainer RH	\$	<i>CM</i>	68.76	✓
5	1	Rear Bumper Side Retainer LH	\$	<i>CM</i>	68.76	✓
6	1	Rear Bumper Reflectors RH	\$	<i>Nil</i>	119.74	✓
7	1	Rear Bumper Reflectors LH	\$	<i>Nil</i>	119.74	✓
8	1	Rear Bumper Tow Hook Cover	\$	<i>Nil</i>	93.00	✓
9	1	Rear Luggage Floor Panel	\$	<i>B</i>	973.00	X
10	1	Rear Luggage Floor Panel Insulator	\$	<i>Nil</i>	63.50	X
11	1	Rear Luggage Floor Panel Trim Board	\$	<i>Sn</i>	378.00	X
12	1	Rear End Panel Outer	\$	<i>B</i>	623.76	✓
13	1	Rear End Panel Inner Trim	\$	<i>Sn</i>	263.84	X
14	1	Bootlid	\$	<i>B</i>	973.00	✓
15	1	Bootlid inner trim board	\$	<i>Sn</i>	400.00	X
16	1	Bootlid Weatherstrip	\$	<i>172.14</i>	<i>CM</i> 344.28	<i>508.00</i>
17	1	Bootlid Lock - Top	\$	<i>Nil</i>	466.56	✓
18	1	Bootlid 'CHEVROLET' Badge	\$	<i>Nil</i>	120.62	✓
19	1	Bootlid Logo	\$	<i>Nil</i>	138.84	✓
20	1	Bootlid 'EPICA LT' Badge	\$	<i>Nil</i>	119.84	✓
21	1	Bootlid Reflector Centre	\$	<i>Sn</i>	217.97	X
22	1	Bootlid Reflector RH	\$	<i>Sn</i>	128.40	X
23	1	Bootlid Reflector LH	\$	<i>CM</i>	128.40	✓
24	1	Bootlid Hinge RH	\$	<i>R</i>	120.00	X
25	1	Bootlid Hinge LH	\$	<i>R</i>	120.00	X
26	1	Rear Tail Lamp RH	\$	<i>Sn</i>	479.30	X
27	1	Rear Tail Lamp Panel RH	\$	<i>R</i>	359.00	X
28	1	Rear Tail Lamp LH	\$	<i>M3, CM</i>	479.30	✓
29	1	Rear Tail Lamp Panel LH	\$	<i>B</i>	359.00	✓
30	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	<i>B</i>	1,110.00	✓

TRANS-CAB AUTO SERVICES PTE LTD

AAD1712-024

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9402Z - FCIL

31	1	Rear Fender RH	\$	R 1,145.00	X
32	1	Rear Fender Inner Trim RH	\$	Sn 418.44	X
33	1	Rear Fender Inner Cowling RH	\$	Sn 76.60	X
34	1	Rear Fender LH	\$	Bu 1,145.00	✓
35	1	Rear Fender Inner Trim LH	\$	Sn 418.44	X
36	1	Rear Fender Inner Cowling LH	\$	Tn 76.60	✓

TOTAL	\$	13,818.63
10%	\$	1,381.86
	\$	12,436.77

Specical Nett

1	1Set	Licence Plate With Holder	\$	Sn 60.00	X
2	1Set	Bootlid inner trim board Clip	\$	nn 40.00	X
3	1Set	Rear Bumper Parking Sensor	\$	Tn 300.00	✓
4	1Set	Rear Bumper Fastener Clip	\$	nc 44.00	✓
5	1Set	Rear Fender Inner Trim Clip LH	\$	nn 30.00	X
6	1Set	Rear Fender Inner Trim Clip RH	\$	nn 30.00	X
7	1Set	Rear Bumper End Dust Cover Clip	\$	nn 30.00	X
8	1	Rear Boot Sticker 'Trans-cab'	\$	nn 30.00	✓
9	1	Rear Boot Sticker '6555-3333'	\$	nn 30.00	✓
10	1	Rear Exhaust Mounting	\$	Sn 10.00	X
11	2	Rear Windscreen Sealant	\$	nn 80.00	40sn
12	1	Rear Windscreen Inner Sponge Seal	\$	nn 100.00	30sn
13	1	Spare Tyre	\$	Sn 180.00	X
14	1	Spare Wheel Rim	\$	Sn 126.74	X

TOTAL	\$	1,090.74
TOTAL PARTS	\$	13,527.51

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$ 5,400.00 1600

To Check Electrical Lighting Concerned.

\$ 170.00 200

Putty And Spray Painting Of The Affected
Portion.

\$ 5,600.00 10000

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-024**

NO. 2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9402Z - FCIL

To Rust-Proofing Of The Affected Areas.	\$	170.00	1200
To reinstall rear bumper parking sensor.	\$	170.00	600
To transfer of end panel fittings and conduct water seepage test.	\$	170.00	} 1000
To transfer of luggage floor panel fittings and conduct water seepage test.	\$	170.00	
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00	1200
To transfer of boot fittings and conduct water seepage test.	\$	170.00	600
Towing fees	\$	120.00	500
To transfer of Fender fittings, attachments and perform water seepage test.	\$	~ 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	~ 380.00	X
To check steering geometry and computer wheel alignment	\$	~ 220.00	X

	\$	13,080.00
TOTAL	\$	26,607.51

Repair Days~~20 Days~~

14 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17023139/Kqbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 25-06-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6967E	Veh. Inspected	SHD 9402Z	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17011190MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	06/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	CHEVROLET EPICA (A)	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	KL1LA69RJBB065864	Colour	WHITE / RED	
Odometer	928901	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	GITI	5 mm	
L/H Front Tyre	195/65 R15	GITI	5 mm	
R/H Rear Tyre	195/65 R15	GITI	4 mm	
L/H Rear Tyre	195/65 R15	GITI	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/12/2017	Inspection Date	06/12/2017	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9402Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	MISSING	1,202.00	1,202.00
1	REAR BUMPER BEAM	BENT	239.94	239.94
1	REAR BUMPER CENTRE ABSORBER	MISSING	260.00	260.00
1	REAR BUMPER SIDE RETAINER RH	CRACKED	68.76	68.76
1	REAR BUMPER SIDE RETAINER LH	CRACKED	68.76	68.76
1	REAR BUMPER REFLECTORS RH	MISSING	119.74	119.74
1	REAR BUMPER REFLECTORS LH	MISSING	119.74	119.74
1	REAR BUMPET TOW HOOK COVER	MISSING	93.00	93.00
1	REAR LUGGAGE FLOOR PANEL	BUCKLED	973.00	973.00
1	REAR LUGGAGE FLOOR PANEL INSULATOR	NECESSARY	63.50	63.50
1	REAR LUGGAGE FLOOR PANEL TRIM BOARD	SERVICEABLE	378.00	-
1	REAR END PANEL OUTER	BENT	623.76	623.76
1	REAR END PANEL INNER TRIM	SERVICEABLE	263.84	-
1	BOOTLID	BENT	973.00	973.00
1	BOOTLID INNER TRIM BOARD	SERVICEABLE	400.00	-
1	BOOTLID LOCK-TOP	DENTED	466.56	466.56
1	BOOTLID "CHEVROLET" BADGE	NECESSARY	120.62	120.62
1	BOOTLID LOGO	NECESSARY	138.84	138.84
1	BOOTLID "EPICA LT" BADGE	NECESSARY	119.84	119.84
1	BOOTLID REFLECTOR CENTRE	SERVICEABLE	217.97	-
1	BOOTLID REFLECTOR RH	SERVICEABLE	128.40	-
1	BOOTLID REFLECTOR LH	CRACKED	128.40	128.40
1	BOOTLID HINGE RH	TO REPAIR SEE LABOUR	120.00	-
1	BOOTLID HINGE LH	TO REPAIR SEE LABOUR	120.00	-
1	REAR TAIL LAMP RH	SERVICEABLE	479.30	-
1	REAR TAIL LAMP PANEL RH	TO REPAIR SEE LABOUR	359.00	-
1	REAR TAIL LAMP LH	MTG CRACKED	479.30	479.30
1	REAR TAIL LAMP PANEL LH	BENT	359.00	359.00
1	REAR EXHAUST BOX (MUFFLER A-EXH,RR)	BENT	1,110.00	1,110.00

Report Ref No. CS/FCI17023139/Kqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FENDER RH	TO REPAIR SEE LABOUR	1,145.00	-
1	REAR FENDER INNER TRIM RH	SERVICEABLE	418.44	-
1	REAR FENDER INNER COWLING RH	SERVICEABLE	76.60	-
1	REAR FENDER LH	BUCKLED	1,145.00	1,145.00
1	REAR FENDER INNER TRIM LH	SERVICEABLE	418.44	-
1	REAR FENDER INNER COWLING LH	TORN	76.60	76.60
	LESS 10% DISCOUNT		-1,347.43	-894.94
			12,126.92	8,054.42
1	BOOTLID WEATHERSTRIP (50%)(SN)	CUT	344.28	172.14
	LESS 10% DISCOUNT		-34.43	-
			309.85	172.14
SPECIAL NETT ITEMS				
1	SET LICENCE PLATE WITH HOLDER (SN)	SERVICEABLE	60.00	-
1	SET BOOTLID INNER TRIM BOARD CLIP (SN)	NOT NECESSARY	40.00	-
1	SET REAR BUMPER PARKING SENSOR (SN)	TORN	300.00	300.00
1	SET REAR BUMPER FASTENER CLIP (SN)	NECESSARY	44.00	44.00
1	SET REAR FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	30.00	-
1	SET REAR FENDER INNER TRIM CLIP RH (SN)	NOT NECESSARY	30.00	-
1	SET REAR BUMPER END DUST COVER CLIP (SN)	NOT NECESSARY	30.00	-
1	REAR BOOT STICKER "TRANS-CAB" (SN)	NECESSARY	30.00	30.00
1	REAR BOOT STICKER "6555-3333" (SN)	NECESSARY	30.00	30.00
1	REAR EXHAUST MOUNTING (SN)	SERVICEABLE	10.00	-
2	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	100.00	30.00
1	SPARE TYRE (SN)	SERVICEABLE	180.00	-
1	SPARE WHEEL RIM (SN)	SERVICEABLE	126.74	-
			1,090.74	474.00

Report Ref No. CS/FCI17023139/Kqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BOOTLID HINGE RH,BOOTLID HINGE LH,REAR TAIL LAMP PANEL RH AND REAR FENDER RH. TO CHECK ELECTRICAL LIGHTING CONCERNED.		5,400.00	1,600.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		170.00	20.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		5,600.00	1,000.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	120.00
	TO TRANSFER OF END PANEL FITTINGS AND CONDUCT WATER SEEPAGE TEST. }		170.00	60.00
	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS AND CONDUCT WATER SEEPAGE TEST. }		170.00	100.00
	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.		170.00	-
	TO TRANSFER OF BOOT FITTINGS AND CONDUCT WATER SEEPAGE TEST.		170.00	120.00
	TOWING FEES.		170.00	60.00
	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	120.00	50.00
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	380.00	-
			220.00	-
			13,080.00	3,130.00
	GRAND TOTAL		26,607.51	11,830.56
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			8,500.00

Report Ref No. CS/FCI17023139/Kqbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.