

12/09/2011

ASS. REC. BY:

REF: CS/FCI17023169/k19d3n2 Special Instruction:

Surveyor

KALVIN

ASSIGNMENT (Office)

CWS

From (Person):

Karen Tan

of

FCI

Date/Time: 2:37pm 16/12

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHB 8913 H

Insured:

SH 6116 T

at Workshop m/s

Premier Automotive

Tel:

6544 6682

of

23 Changi South Ave 2 #03-02

Policy No:

D15072701MFSH

Claim No:

D17011593MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 15/12/17

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

3:10pm @ 19/12/17

Person Contacted:

Goh Wee dek

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHB 8913 H - CS/FCI1601755/R1gh3m2 D.O.A. : 13/09/2016
	SH 6116 T - CS/FCI16008691/YH1vh3c2 D.O.A. : 10/05/2016
20/12/17 @ 2:46pm	REVISED to Karen Tan by email.

Kalvin

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop no: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Ball or Market Value: _____

DAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Car No: SHB 8913H Page: 31 Mar 2014
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover / 6
 Truck / Trailer or
 Make: KEA Optima 16R
 Colour: Silver A/C Ins Q Std / Nil / NA
 So. Reading: 427688 AT Radio Ins Q Std / Nil / NA
 Eng No: _____
 C No: 1CNAHAM44ME54621R5
 Gen. Cond: Good / B / Poor / Burnt
 Steering: In Q / Jammed / Leaked / Burnt or
 Brakes: In Q / Jammed / Leaked / Burnt or
 Modl: Nil / S/Rim / ST Q / Rim or
 Tyre Size: F: 205 / 65 R16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / QHTSU / PIR / SUMI /
 TOYO / YOKO or Maxxis
 Front: _____ Rear: _____
 R.Bal: 7 mm R.Bal: 7 mm
 L.Bal: 7 mm L.Bal: 7 mm
 D.O.A. 15/12/17 D.O.I. 19/12/17
 Survey held at Premise
 Des. of Damages: Fnt / Rear / C/S / N/S / U/C / Rooftop or
Rear
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

28/12/17 Collected CP \$3250 / 3 Pcs (Red @ 4378.70, 5710)

FCI

RECEIVED 29 DEC 2017

RECEIVED 28 DEC 2017

Date / Time File Pass to?

28/12/17 turnover

Date / Time File Return to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee

Transportation

Food & Bev

Protest

Others

Add Fee:

☐

☐

☐

☐

☐

☐

☐

☐

☐

☐

Report Format:

Lump Sum / TP

3250

150
50
50
34
284



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/FCI17023169/K1qd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 06-12-2017



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 6116T	Veh. Inspected	SHB 8913H
Policy No.		Coverage (\$)	0.00
Claim No.	D17011593MFSH	Excess (\$)	0.00
Assign From	CWS (KAREN TAN)	Assign Date	06/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	15/12/2017	Inspection Date	19/12/2017
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

5a. Remarks

<p>A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.</p> <p>B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.</p> <p>C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.</p>
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17011593MFSH

Date: 20 December 2017

Our Ref: CS/FCI17023169/K1qd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHB 8913H .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 19/12/2017 at the premises of M/s PREMIER AUTOMOTIVE, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>7,628.70</u> .
Revised Estimate Amount	: S\$ <u>3,427.30</u> .
"Check" Items Amount	: S\$ <u>863.10</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

Kalvin Ang
Automotive Assessor

Survey Department Check List (Case Handler)

Reference No. : *Cy/2117073161/Kyds*

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

SHB 8913H

Typist

Admin (*Nivitha*): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		

Surveyor (*Calvin*): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

<input checked="" type="checkbox"/>		
-------------------------------------	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

<input checked="" type="checkbox"/>		
-------------------------------------	--	--

Check By:

[Signature] *24/12/17*
Case Handler Date

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	16-12-2017	Our Ref No. D17011593MFSH
Accident Date	15-12-2017	Claim Type. Third Party
Insured Vehicle	SH6116T	Third Party Vehicle. SHB8913H
Survey Location	23 CHANGI SOUTH AVENUE 2 #03-02	
Contact Person.	GOH WEE DEK	
Contact No.	62148880/ 65446682	Fax No. 62141511
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/232000)



PRI Documents



Close



PRI Header Details

Claim No	D17011593MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & PREMIER , LTD
Workshop Name	PREMIER AUTOMOTIVE SERVICES PTE LTD (Contact Person : GOH WEE DEK)	Survey Location & Contact Details	23 CHANGI SOUTH AVENUE 2 #03-02 Mobile: 65446682 , Phone: 62148880 , Fax: 6214151: EmailId: WEEDEK.GOH@PREMIERTAXI.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH6116T	TP Vehicle No	SHB8913H
PRI Recieved Date	18-12-2017 02:03:00 PM	Surveyor Appointed Date	19-12-2017 02:36:08 PM	Surveyor Accept Date	19-12-2017 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	19-12-2017	Upload Survey Report *:	<input type="button" value="Choose File"/>
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 20 December, 2017 2:46 PM
To: 'Claim Workflow System'; assignments
Cc: KARENTAN@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17011593MFSH/1
Attachments: CSFCI17023169K1qd3.pdf

Dear Karen,

Enclosed herewith preliminary advice of SHB 8913H.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 19 December, 2017 3:11 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17011593MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Tuesday, 19 December, 2017 2:36 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; KARENTAN@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17011593MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	31 Mar 2014 / 09:54:35	Receipt No.:	AACCK001-AX239-140331-000011
Asset Type:	Vehicle	Transaction Amount:	\$71,161.00
Asset ID:	SHB8913H	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20140331095435065675		

Vehicle No.:	SHB8913H
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	31 Mar 2014
Original Registration Date:	31 Mar 2014
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414ME5462145
Engine No.:	D4FDDH308350
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2013
Open Market Value:	\$19,776.00
Minimum PARF Benefit:	\$7,365.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	31 Mar 2014 09:54:35
COE No.:	2014033101001235C
COE Expiry Date:	30 Mar 2022
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$58,745.00
Lifespan Expiry Date:	30 Mar 2022
Owner ID Type:	Company

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

18-Dec-17

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8913 H

1 pc	Boot lid — <i>Pat</i>	\$	1,119.00
1 pc	Boot lid lock <i>X su</i>	\$	99.00
1 pc	Bootlid lock cable <i>X su</i>	\$	35.00
1 pc	Bootlid striker <i>X su</i>	\$	21.00
1 pc	Bootlid emblem — <i>su</i>	\$	27.00
1 pc	Bootlid CRDi — <i>su</i>	\$	29.00
1 pc	Boot lid rubber weatherstrip <i>X su</i>	\$	96.00
1 pc	Boot lid lower garnish <i>X su</i>	\$	290.00
2 pcs	Bootlid hinge @ \$66.00 <i>X su</i>	\$	132.00
2 pcs	Rear o/s & n/s tail lamp @ \$421.00 <i>X su</i>	\$	842.00
2 pcs	Bootlid n/s & o/s reflector @ \$350.00 <i>X su</i>	\$	700.00
1 pc	Rear bumper — <i>Pat</i>	\$	696.00
1 pc	Rear bumper lower cover — <i>crq</i>	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 <i>X su</i>	\$	58.00
1 pc	Rear bumper inner sponge <i>✓ su</i>	\$	114.00
1 pc	Rear bumper reinforcement <i>✓ su</i>	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 <i>X su</i>	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 <i>✓ su</i>	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 <i>✓ su</i>	\$	36.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00 <i>X su</i>	\$	92.00
		\$	5,343.00
Less 10%		\$	534.30
		\$	4,808.70

S/NETT

1 set	Rear bumper clips — <i>su</i>	\$	48.00
1 set	End panel inner garnish clips <i>X su</i>	\$	30.00
1 set	Bootlid inner trim clips <i>X su</i>	\$	52.00
1 set	Bootlid lower garnish clips <i>X su</i>	\$	60.00
1 set	Bootlid stickers — <i>su</i>	\$	100.00
1 set	Reverse sensor — <i>shard</i>	\$	280.00 200

18-Dec-17

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8913 H

Sundry

new

\$

~~50.00~~ ²⁰

To dismantle / replace reverse sensor to new bumper and reset to the same

\$

~~120.00~~ ²⁰

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

\$

~~180.00~~ ²⁰

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel etc

\$

~~900.00~~ ⁴⁰⁰

To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end panel

\$

~~800.00~~ ⁷²⁰

To apply rustproofing on the repaired and replaced panels.

\$

~~200.00~~ ⁵⁰

\$

7,628.70

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalvin 16/12/17

19/12/17 1620hr

3 Days

4/5

After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final appraisal from Insurance Company

Acknowledged by repairer:

Signature:

Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17023169/K1qd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 04-01-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 6116T	Veh. Inspected	SHB 8913H	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17011593MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	16/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	KNAGM414ME5462145	Colour	SILVER	
Odometer	427688	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	MAXXIS	7 mm	
L/H Front Tyre	205/65 R16	MAXXIS	7 mm	
R/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
L/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/12/2017	Inspection Date	19/12/2017	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 8913H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOT LID	DENTED	1,119.00	1,119.00
1	BOOT LID LOCK	SERVICEABLE	99.00	-
1	BOOTLID LOCK CABLE	SERVICEABLE	35.00	-
1	BOOTLID STRIKER	SERVICEABLE	21.00	-
1	BOOTLID EMBLEM	NECESSARY	27.00	27.00
1	BOOTLID CRDI	NECESSARY	29.00	29.00
1	BOOT LID RUBBER WEATHERSTRIP	SERVICEABLE	96.00	-
1	BOOT LID LOWER GARNISH	TO REPAIR SEE LABOUR	290.00	-
2	BOOTLID HINGE @\$66.00	SERVICEABLE	132.00	-
2	REAR O/S & N/S TAIL LAMP @\$421.00	SERVICEABLE	842.00	-
2	BOOTLID N/S & O/S REFLECTOR @\$350.00	SERVICEABLE	700.00	-
1	REAR BUMPER	DEFORMED	696.00	696.00
1	REAR BUMPER LOWER COVER	CRACKED	206.00	206.00
2	REAR BUMPER SIDE BRACKET O/S & N/S @\$29.00	SERVICEABLE	58.00	-
1	REAR BUMPER INNER SPONGE	TORN	114.00	114.00
1	REAR BUMPER REINFORCEMENT	CRACKED	607.00	607.00
2	REAR BUMPER STAY O/S & N/S	SERVICEABLE	108.00	-
2	REAR BUMPER REINFORCEMENT LOWER BRACKET @\$18.00	CRACKED	36.00	36.00
2	REAR BUMPER REINFORCEMENT UPPER BRACKET @\$18.00	CRACKED	36.00	36.00
2	REAR BUMPER REFLECTOR N/S & O/S @\$46.00	SERVICEABLE	92.00	-
	LESS 10% DISCOUNT		-534.30	-287.00
			4,808.70	2,583.00
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET END PANEL INNER GARNISH CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET BOOTLID INNER TRIM CLIPS (SN)	NOT NECESSARY	52.00	-
1	SET BOOTLID LOWER GARNISH CLIPS (SN)	NOT NECESSARY	60.00	-
1	SET BOOTLID STICKERS (SN)	NECESSARY	100.00	100.00

Report Ref No. CS/FCI17023169/K1qd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			620.00	368.00
	LABOUR			
	TO DISMANTLE/REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.		120.00	20.00
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEATS, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE END PANEL ETC. INCLUSIVE OF THE REPAIR OF BOOT LID LOWER GARNISH.		900.00	400.00
	TO PUTTY AND SPRAY PAINTING ON BOOTLID, BOOTLID LOWER GARNISH, REAR BUMPER, END PANEL.		800.00	720.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		200.00	50.00
			2,200.00	1,190.00
GRAND TOTAL			7,628.70	4,141.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,250.00

Report Ref No. CS/FCI17023169/K1qd3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.